



2940 Westlake Ave N #200
Seattle, WA 98109
206-528-4670

Seattle Public Schools -
Woodland Park Field 2
5201 Green Lake Way N
Seattle, WA 98103
Parcel: 0725049002

Legend

- Assessed Trees
- King County Parcels

Tree Site Map

Date: August 29, 2025

Arborist:
Shannon O'Bent
ISA PN-8468A

Holly Iosso, RCA
ISA PN-6298A,
TRAQ

Parcel boundaries and trees are located approximately.

Table of Trees
Woodland Park Field 2, Seattle, WA

SPR ID as accessed in City of Seattle GIS Tree database (seattlecitygis.maps.arcgis.com)

DSH (Diameter at Standard Height) is measured 4.5 feet above grade, or as specified in the [Guide for Plant Appraisal, 10th Edition](#), published by the Council of Tree and Landscape Appraisers.

Multi-stem measurements are listed under DSH Multistem. The value listed under the DSH column for these trees is a single stem equivalent, calculated as the square root of the sum of the DSH for each individual stem squared.

Tier is based on SMC 25.11 and Director's Rule 7-2023.

Basic Tree Protection Area is an area with a radius calculated as 12 times DSH.

Tree Protection Area is calculated as 10 times DSH or greater depending on tree species, health, and age.

Dripline is measured from the center of the tree to the outermost extent of the canopy.

SPR ID	Tree ID	Scientific Name	Common Name	DSH (inches)	DSH Multistem	Health Condition	Structural Condition	Dripline	Tier 2 Threshold	Grove	Tier Level	Tree Protection Area (feet)	Replacement Trees Required (if removed)	Notes
32053	1	<i>Tilia cordata</i>	Littleleaf linden	31.5		Good	Good	28	24.0		2	26	3	
14131	2	<i>Tilia cordata</i>	Littleleaf linden	23.5		Fair	Good	27	24.0		3	20	3	Extreme dieback; distance from trunk edge to concrete field edge 20 feet, distance to concrete fence foundation 10 feet
14130	3	<i>Tilia cordata</i>	Littleleaf linden	27.5		Good	Good	27	24.0		2	23	3	
14129	4	<i>Tilia cordata</i>	Littleleaf linden	25.5		Fair	Good	26	24.0		2	21	3	Dead branch
14128	5	<i>Tilia cordata</i>	Littleleaf linden	23.1		Good	Good	28	24.0		3	19	3	
14127	6	<i>Tilia cordata</i>	Littleleaf linden	33.3		Good	Good	30	24.0		2	28	3	
	7	<i>Tilia cordata</i>	Littleleaf linden	31.3		Good	Good	35	24.0		2	26	3	Drip measured on field
14126	8	<i>Tilia cordata</i>	Littleleaf linden	28.4		Good	Good	34	24.0		2	24	3	Substantial scaffold branch clearing would be required for adequate clearance; trunk approx 16 feet from field edge
	9	<i>Tilia cordata</i>	Littleleaf linden	21.0		Fair	Good	27	24.0		3	18	3	Stunted growth
	10	<i>Tilia cordata</i>	Littleleaf linden	28.6		Good	Good	32	24.0		2	24	3	Existing tag tree 557; significant pruning would be required for clearance over new field, pruning cuts would be smaller than required on tree 8
	11	<i>Tilia cordata</i>	Littleleaf linden	23.9		Good	Fair	23	24.0		3	20	3	Basal hollow
	12	<i>Pseudotsuga menziesii</i>	Douglas-fir	26.5		Good	Good	21	24.0		2	22	3	Growing 10 feet higher than field grade
	13	<i>Prunus avium</i>	Wild cherry	11.4	7, 9	Poor	Poor		not applicable		4	10	3	Estimate 70% dead
	14	<i>Pseudotsuga menziesii</i>	Douglas-fir	9.0		Good	Good	11	24.0		4	8	3	
	15	<i>Acer macrophyllum</i>	Bigleaf maple	33.0	25.3, 16, 14	Fair	Poor	27	24.0		2	28	3	Kretzschmaria at base; previous failures/tear outs, weak union
	16	<i>Fraxinus latifolia</i>	Oregon ash	8.0		Fair	Fair	16	24.0		4	7	3	
	17	<i>Fraxinus latifolia</i>	Oregon ash	8.0		Fair	Fair	15	24.0		4	7	3	
	18	<i>Acer macrophyllum</i>	Bigleaf maple	14.0		Good	Good	19	24.0		3	12	3	Debris pile at base of all trees in area, limited assessment
	19	<i>Prunus cerasifera</i>	Cherry plum	10.0		Good	Good	14	21.0		4	8	3	Measured below union
	20	<i>Pseudotsuga menziesii</i>	Douglas-fir	6.0		Good	Good	8	24.0		4	5	3	
	21	<i>Pseudotsuga menziesii</i>	Douglas-fir	14.1		Good	Good	15	24.0		3	12	3	In bike mounds, trunk buried

Table of Trees
Woodland Park Field 2, Seattle, WA

SPR ID	Tree ID	Scientific Name	Common Name	DSH (inches)	DSH Multistem	Health Condition	Structural Condition	Dripline	Tier 2 Threshold	Grove	Tier Level	Tree Protection Area (feet)	Replacement Trees Required (if removed)	Notes
	22	<i>Pseudotsuga menziesii</i>	Douglas-fir	17.7		Good	Good	15	24.0		3	15	3	In bike mounds, roots cut
	23	<i>Pseudotsuga menziesii</i>	Douglas-fir	16.9		Good	Good	15	24.0		3	14	3	In bike mounds
	24	<i>Acer campestre</i>	Hedge maple	16.6	9.1,11,8.5	Good	Good	23	24.0		3	14	3	In bike mounds
	25	<i>Acer macrophyllum</i>	Bigleaf maple	23.5		Fair	Good	30	24.0		3	20	3	Sparse canopy
	26	<i>Pseudotsuga menziesii</i>	Douglas-fir	18.1		Good	Good	20	24.0		3	15	3	
	27	<i>Acer campestre</i>	Hedge maple	15.4	10.8,11			18	24.0		3	13	3	Half buried; bench beneath trunk, canopy asymmetrical to east
	28	<i>Acer macrophyllum</i>	Bigleaf maple	10.0		Good	Fair	20	24.0		4	8	3	Broken top
	29	<i>Prunus domestica</i>	Common plum	8.8	6.5,6	Fair	Fair	12	24.0		4	7	3	
	30	<i>Acer macrophyllum</i>	Bigleaf maple	10.5		Fair	Fair	25	24.0		4	9	3	Lost top
	31	<i>Pseudotsuga menziesii</i>	Douglas-fir	15.1		Good	Good	16	24.0		3	13	3	
	32	<i>Ulmus minor</i>	Field elm	10.0	7,6,4	Good	Good	12	24.0		4	8	3	Many suckers from adjacent trunk. In general, there are lots of standing dead trees and trees with significant dead wood in area, we did not assess for risk