

Results

Member of	Facility	Describe the capital project being nominated	Will Dollar Amount be	2011	2012	2013	2014	2015	2016	Comments	Potential Funding
Staff	All Elementary Classrooms	Promised Ceiling Mounted Projectors	Not sure	2011	2012	2013	2014	2015	2016	DoTs promised ceiling mounted projectors to elementary classrooms in BTA III.	Being Considered
Staff	All existing schools, except recent BEX II and III remodeled schools, that do not have a electronic lock card reader system.	District Maintenance Dept. is requesting all new schools and remodeled schools have card reader lock sytem installed at certain exterior doors. System would be compatable and interfaced with system at Stanford Center.	Not sure	2011	2012	2013	2014	2015	2016		Being Considered
Staff	All SSD Elementary Schools	Since the Elementary Classrooms were promised that the ceiling mounting for our LCD projectors would be included on the next levy, which meant it was promised for the BTA III levy, it would be appreciated and aproprate for the Seattle School District to follow through on their commitment to us since SSD ran out of funds in the year it was first intended, and now we have been told it is not in the current levy projects funded for the BTA III. Thank you for your consideration.	One time	2011						It was initially promised that we would have ceiling mounted LCD projectors in the BTA II tech levy rollout until they realized they were running out of funds to implement it for all the schools. They had a group of district tech personnel meet in October of 2002 or 2003 to which I was invited to participate. At that meeting it was decided that each elementary teacher classroom would receive a document camera and a LCD projector (and not have to share it between two classrooms), but that we would have to provide our own carts in the interim until we would get them ceiling mounted which was promised to be funded in the next BTA III levy. I spoke with Barbara about that promise last spring at the ET meeting when ET's were asked to suggest what should be funded for the BTA III levy projects. Manny was director and head of the special district meeting when this decision was made and promised to the elementary teachers.	Being Considered
Public	Arbor Heights	Install a synthetic turf sports feild, fix existing drainage systme, re-coat existing asphalt, and re-paint basketball court and asphalt play area.	One time	2011						There are many organizations that are willing to rent fields to play sports on. I'm proposing a new field that you could play soccer, baseball and football on. A new turf field would bring revenue back to the district to subsidize the cost. The YMCA has currently rented the Arbor Heights elementary gym for their indoor soccer games. please contact me for more information, thank you John john.christensen@esmccivil.com	No Turf but upgrading play ground being considered

Results

Public	Blaine	Electrical Systems Upgrade	One time	2011						<p>Some outlets are not grounded (not 3 prong). Some rooms depend on extension cords for permanent installations, a fire code violation. There are nuisance fuse and breaker openings, a sign of overloading. Some rooms need active monitoring to ensure two appliances used simultaneously do not blow a fuse. The 2005 Meng Report does not document these problems.</p> <p>The 2005 Meng Report says: Outlets and Wiremold "Good - Branch circuits are in good condition."</p> <p>There are nuisance fuse or breaker openings, a sign of overloading. Four additional rooms to be added in summer 2009 will increase the loading problem.</p> <p>The 2005 Meng Report: Panel and Breakers "Poor -Panelboards are old and some are still using fuses. They need to be replaced."</p>	Being Considered
Public	Blaine	Interior Systems Upgrades	One time	2011						<p>Stairs need compliant hand rails.</p> <p>The 2005 Meng Report says: Stairs and Handrails "Fair - Stairs require compliant handrails."</p> <p>Any deferred maintenance in Meng Report. Any maintenance or upgrades not fully funded in BTAll.</p>	Being Considered

Results

											<p>Windows replacement are needed.</p> <p>The Meng Report says: Frames "Fair - Some windows in good condition though aluminum frame, single pane glazing. Classroom windows appear to have been re-sealed recently. Some windows steel frame and in poor condition." Sills - "Fair - Some sills masonry and in good condition. Some alternate materials and require repair."</p> <p>Brick Veneer - sealing to keep graffiti from sticking - painted-over graffiti needs to be removed without damaging the brick glaze/finish.</p> <p>The Meng Report says: Brick Veneer "Fair - All brick requires repointing and sealing"</p> <p>Other deferred maintenance. Paint exterior walls not addressed by 2008 Self-Help Project.</p> <p>The Meng Report says: (Multiple entries)</p>	
Public	Blaine	Exterior Systems Upgrades				2013						Being Considered
Public	Blaine	Six additional classrooms are needed, some by 2011	One time	2011	2012	2013					<p>Due to increased enrollment and a School board decision, Blaine is remodeling to obtain three extra classrooms in the summer of 2009. To build the school into the desired "chimney" model, six additional classrooms are needed to allow three classes per grade level from 1st through 8th grades. The middle school grade level rooms would be best located near the existing 6-8 classrooms. For the middle school rooms, specialized facilities for subjects such as science may be needed.</p> <p>Some flexibility may be obtained by progressively adding/modifying space.</p>	Being Considered
Staff	Brighton	I suggest that Flight I and II elementary schools receive an extra prep period for teachers in the form of a Science/Outdoor Education/Math teacher who could teach Science units with great skill while integrating Math and Outdoor Education. Our students would benefit from often improved Science instruction, as well as improvement throughout their day. Teachers might be required to collaborate for some of these periods.	Annual	2011	2012	2013	2014	2015	2016		<p>Teachers need more planning time at schools with large populations of underachieving students. While teachers are dedicated and put in many more hours than they are paid for, we need to be able to collaborate more. If improving Science education is our goal, we need Scientists teaching Science in our Elementary schools. While some teachers are well-rounded as Mathematicians, Scientists, Readers and Writers, not all teachers are or can be; this must be recognized and addressed. Go to the English department at any High School, then the Science and Math departments, you will find great differences in their staffs' dispositions and strengths.</p>	N/A

Results

										Other deferred maintenance. Repave playground and restripe. Address areas not addressed by 2008 Self-Help Project. The 2005 Meng Report says: "Pavement cracking" "Court markings faded" "Re-stripe playground" Chain link fence and gates. Address areas not addressed by 2008 Self-Help Project. The 2005 Meng Report says: Gates "Gate worn out" Fence "Fence in poor condition".	
Public	Catharine Blaine K-8	Paving Systems Upgrades - Landscape Upgrades	One time		2012						Being Considered
										Water pipes are mostly original galvanized. Drinking fountains are original too. Not ADA compliant. We have ADA dependent teachers and students. The 2005 Meng Report: Piping "Poor - The majority of the piping is original galvanized" Drinking Fountains "Fair - Fixtures are generally dated and worn. Some are not ADA." Toilet Rooms - not wheelchair compatible - not ADA compliant means poor condition to me. Not all restrooms are functional, north end of building. This will be needed with additional students in 2009-10 school year. An additional teacher restroom is needed at this end of the school. The Meng Report says: Toilet Rooms "Fair - All public restrooms require new finishes, fixtures and ADA compliance"	
Public	Catharine Blaine K-8	Plumbing Systems Upgrades - Piping and Restrooms	One time		2011						Being Considered
Staff	Coe	Projectors mounted on the ceiling	Not sure								Being Considered
Staff	Coe	Projectors on the ceiling for classrooms.	Not sure							Classrooms need ceiling mounted projectors.	Being Considered
Public	Coe	Projectors on the ceiling for classrooms.	Not sure							Classrooms need ceiling mounted projectors.	Being Considered

Results

Staff	Dearborn Park	<p>There is no covered play area for the children when there is inclement weather. Our children need to be able to go outside and play!</p> <p>2. New heating system-We presently have 2 systems, one for each "building". The heat in the new building needs to be re-routed to vents on the floor as opposed to vents in the ceiling. Ceiling vents have a warmer temperature, thus cold air comes out of them in the winter, when the room is still too cool. This is an adverse learning environment for the students. Neither building has any good ventilation during the summer. There are not enough windows in the pods, and built in fans. A heat pump for cooling, or built in ceiling fans may help. It can get stifling, and the pods are so big, fans are of little help.</p> <p>*3. Ramp from the school to the play area. Presently there is no way for children in a wheel chair to safely access the playground. This is probably against ADA rules, and needs to be fixed.</p> <p>*4. Walkway from the end of the sidewalk to the gym. Presently students have to walk in the load zone and this is a safety issue.</p> <p>*5. Locks on the cabinets in the gym-</p>	One time	2011						<p>Dearborn Park was part of the last BEX. The workmanship on the building is substandard, and equipment in the kitchen continues to malfunction, the heat does not work correctly, the plumbing has had problems, etc. Promises were made to the staff that were not kept, and many parts of the new building were not adequately finished. We are requesting that our school be included in the next BEX in order to "finish" the job and complete a few upgrades due to increased enrollment.</p>	No
Public	Eckstein	Major facility renovations	One time		2012					<p>Eckstein should be renovated in particular to accommodate the growing student population on the north end of the District.</p>	Being Considered
Staff	Flight Elementary Schools	<p>I suggest that Flight I and II elementary schools receive an extra prep period for teachers in the form of a Science/Outdoor Education/Math teacher who could teach Science units with great skill while integrating Math and Outdoor Education. Our students would benefit from often improved Science instruction, as well as improvement throughout their day. Teachers might be required to collaborate for some of these periods.</p>	Annual	2011	2012	2013	2014	2015	2016	<p>Teachers need more planning time at schools with large populations of underachieving students. While teachers are dedicated and put in many more hours than they are paid for, we need to be able to collaborate more. If improving Science education is our goal, we need Scientists teaching Science in our Elementary schools. While some teachers are well-rounded as Mathematicians, Scientists, Readers and Writers, not all teachers are or can be; this must be recognized and addressed. Go to the English department at any High School, then the Science and Math departments, you will find great differences in their staffs' dispositions and strengths.</p>	N/A

Results

Public	Green Lake	Remodel the current building which houses Green Lake Elementary and add classroom space to replace the portables, include a cafeteria, and accommodate the special needs of Team A.	One time	2011							The physical structure of Green Lake Elementary is functionally obsolescent and the overall aesthetic of the building is in poor condition. The open concept classrooms at Green Lake Elementary are not being utilized as such, but rather as traditional classrooms without walls. This creates a disruptive learning environment. In addition, the school's population exceeds the intended size of the building. It was originally built as a K-4 school but is now being used as a K-5 school. It's not meant to house six grade levels, as well as the Team A special education program. The portables which house the excess number of classes look extremely old and are in very poor condition. Lastly, Team A doesn't even have a regular classroom; it's program is housed in the cafeteria, which, in turn means there is no functioning cafeteria for all of the students. Green Lake's building has been ignored for too long. It is time to update the school and bring it to the standards that many other schools in the district enjoy.	Being Considered
Staff	Hay (New)	Projectors on the ceiling for classrooms.	Not sure								Classrooms need ceiling mounted projectors.	Being Considered
Staff	Highland Park, Roxhill, Brighton and other Flight Elementary Schools	I suggest that Flight I and II elementary schools receive an extra prep period for teachers in the form of a Science/Outdoor Education/Math teacher who could teach Science units with great skill while integrating Math and Outdoor Education. Our students would benefit from often improved Science instruction, as well as improvement throughout their day. Teachers might be required to collaborate for some of these periods.	Annual	2011	2012	2013	2014	2015	2016		Teachers need more planning time at schools with large populations of underachieving students. While teachers are dedicated and put in many more hours than they are paid for, we need to be able to collaborate more. If improving Science education is our goal, we need Scientists teaching Science in our Elementary schools. While some teachers are well-rounded as Mathematicians, Scientists, Readers and Writers, not all teachers are or can be; this must be recognized and addressed. Go to the English department at any High School, then the Science and Math departments, you will find great differences in their staffs' dispositions and strengths.	N/A
Staff	McClure	Projectors on the ceiling for classrooms.	Not sure								Classrooms need ceiling mounted projectors.	Being Considered
Public	McClure	Projectors on the ceiling for classrooms.	Not sure								Classrooms need ceiling mounted projectors.	Being Considered

Results

Staff	Roxhill	I suggest that Flight I and II elementary schools receive an extra prep period for teachers in the form of a Science/Outdoor Education/Math teacher who could teach Science units with great skill while integrating Math and Outdoor Education. Our students would benefit from often improved Science instruction, as well as improvement throughout their day. Teachers might be required to collaborate for some of these periods.	Annual	2011	2012	2013	2014	2015	2016	Teachers need more planning time at schools with large populations of underachieving students. While teachers are dedicated and put in many more hours than they are paid for, we need to be able to collaborate more. If improving Science education is our goal, we need Scientists teaching Science in our Elementary schools. While some teachers are well-rounded as Mathematicians, Scientists, Readers and Writers, not all teachers are or can be; this must be recognized and addressed. Go to the English department at any High School, then the Science and Math departments, you will find great differences in their staffs' dispositions and strengths.	N/A
Public	Mann	Modifications to the kitchen to allow for the preparation of meals at the school.	One time	2011						NOVA students used to have access to wholesome, nutritious vegetarian meals cooked on site with local produce (some of it grown at the school). These meals are no longer available, in part due to inadequacies in the kitchen facilities. Fix it. Bring back the good food.	N/A
Public	Interbay High School (to serve the QA and Magnolia neighborhoods).	Construction of a new high school building at Interbay to serve Queen Anne/Magnolia (to replace QA High School sold by the District). Property at Interbay obtained by a trade with the city involving the 2 acres of District property at Interbay plus additional Memorial Stadium property. A High School site could be carved out of the north edge of the golf course, or appended to the north side of the existing athletic complex through an additional swap with private property owners. A new high school would provide a long-term fix for the error made when the Board sold off QAHS, rather than the short-term fix proposed by busing. Please examine a map and create a permanent viable long-term solution to this capacity problem.	One time		2012	2013	2014	2015		The scope assumes two years for planning and design development plus two years for construction. New construction is less expensive than remodeling of existing structures, so a new facility would be less expensive to the District and start to take the Seattle School District into the 21st Century. The City is undertaking planning for Interbay now, so a timely response and District involvement in the process is called for. Thank you.	N/A
Public	Jane Adams	expanded playground	One time	2011						The playground at Jane Adams is incredibly small. The playfields are in huge demand by a wide variety of groups and playstructures would benefit the entire community.	Being Considered
Public	Jane Adams	Replace all of the blinds.	One time	2011						The blinds are severely damaged throughout the entire building. The street appeal of the building looks like nobody cares about the building. One set of blind would greatly improve the overall appearance of the building inside and out.	Being Considered

Results

Public	John Hay (New)	reseeding/sodding/irrigation of playfield replace play structure purchase/installation of ceiling mounts for classroom projectors	Not sure								sorry, not sure of the years. thanks.	Being Considered
Public	John Hay (New)	Installation of ceiling mounts for classroom projectors sounds like a good project. Perhaps donations of/for the 'mounts' themselves on a per-classroom basis to get parents motivated.	One time	2011							Given the chance, I would vote against improving the play structure. Also, I think that, absent fences, it's unrealistic to think that grass (whether re-seeded or re-sod, irrigated or not, and with or without better drainage) will survive on the play-field with so many children. Let the kids play.	Partially Being Considered
Public	John Hay (New)	purchase and installation of ceiling mounts of classroom projectors	One time	2011								Being Considered
Public	John Hay (New)	BTAll	Annual	2011								N/A
Public	Hay (New)	reseeding/sodding and irrigation of the playfield; also the purchase and installation of ceiling mounts for classroom projectors	Not sure	2011	2012	2013	2014				The playing field needs attention as soon as possible, to make it safer for the children before and after school and at recess. Classroom projectors would relieve equipment clutter and also update a necessary tool for teachers. Thanks for your consideration of these projects.	Partially Being Considered
Public	Hay (New)	Re-sodding the playfield. It is in very bad shape.	One time	2011							The field as it stands now is dangerous to run on as it is pitted and bumpy. This would be an excellent renovation project - new sod is badly needed.	No
Public	Hay (New)	The grass playfield at John is mostly weeds and mud during the school year. I'd like to suggest that it be aerated and seeded to make it more kid friendly. In addition, it should be watered in the summer.	Annual								Thank you for your consideration.	No
Staff	Hay (New)	irrigation and sodding of the playfield and replacement of play structure. The field is full of dirt, holes and mesh and very dangerous to the children.	One time	2011								No
Public	Hay (New)	Replace the current play structure with a larger one.	One time	2011							The school is full and the play structure is so popular that the grades have to alternate days on which they are allowed to use the play structure. It would be nice to allow the kids to use it more than one day a week per grade.	No
Public	Hay (New)	Purchase and install ceiling mounts for classroom projectors similar to those installed in SPS middle and high schools.	One time	2011								Being Considered
Public	Hay (New)	reseeding/sodding playfield and irrigation of playfield, replacement of the plays structure, purchase and installation of ceiling mounts for classroom projectors	One time	2011							thank you or your consideration	Partially Being Considered

Results

Public	Hay (New)	John Hay (New) Capital improvements- reseeding/sodding playfield and irrigation of playfield, replacement of the plays structure, purchase and installation of ceiling mounts for classroom projectors.	Not sure	2011	2012	2013							Partially Being Considered
Public	Hay (New)	resodding and irrigation of playfield ceiling mounts for classroom projectors new playstructure	One time	2011								Thanks for asking for input!	Partially Being Considered
Public	Hay (New)	Play structure replacement/enlargement - the school is too large for the structure to accomodate the kids wanting to use it and there are regularly injuries because kids crash into eachother. Reseeding and irrigation of the playfield, which is a big dirt field during most of the year.	One time	2011								see above. John Hay (New) is one of the most overcrowded schools, and the projection is for it to grow even more - we need more money to enhance our school!	No
Public	Hay (New)	reseeding grass playfield	One time	2011									No
Public	Hay (New)	reseeding/sodding playfield and irrigation of playfield	Annual	2011								Much of the playfield is pure dirt with no grass.	No
Public	Hay (New)	aerate, re-seed, sod, and irrigate the John Hay (New) playfield. There are large patches of mud and weeds when it rains, and dust storms when its dry	Annual	2011	2012	2013	2014	2015	2016			Thank you for considering this project. There may be other elementary school grass playsfields that would benefit from similar work.	No
Public	Hay (New)	purchase and install ceiling mounts for classroom projectors.	One time	2011	2012	2013	2014	2015	2016				Being Considered
Public	Hay (New)	purchase new play structure	One time	2011	2012	2013	2014	2015	2016			any one of the above years would be great	No
Public	Hay (New)	reseeding/sodding the playfield	One time	2011								I do not think the play equipment needs to be replaced. It works just fine. Another one could be added. But grass would be a better way to spend the money. It gets pretty muddy. How about a covered play barn (like schools had in the old days) so kids can still go outside when its raining?	No
Public	Hay (New)	Reseeding/sodding and irrigation of playfield purchase and installation fo ceiling mounts for classroom projectors replacement of playground play structure	One time	2011	2012	2013							Partially Being Considered

Results

Public	Muir	The nominated project is to complete much needed yard and playground improvements at John Muir Elementary. John Muir is in a residential neighborhood. The school's large backyard is the immediate neighborhood's largest piece of open public space and is used by students, children in the Camp Fire before/after school and vacation programs, and neighborhood families after school, and on weekends and vacations. The yard is largely asphalt and is not very function or inviting. A master plan was recently developed with school, student, and community input to plan an upgrade to the school's yard to make it more inviting, functional and attractive. The plan has strong support from the school and community. Capital levy funding is requested to fund construction of the improvements called for by the masterplan. This improvements include landscaping, a playground for younger children, paths, additional playground enhancements for older children, and a vareity of other features.	One time	2011														No	
Staff	Kimball	A workable Lunch Room	One time	2011														Carpets are cleaned once a year only. Students eat in the carpeted classrooms. This creates an unhealthy environment. Students lose valuable learning time doing lunch duty.	Being Considered
Staff	Kimball	Construction of a multi-ppurpose sapce to serve as a cafeteria and an auditorium/ assembly space	One time	2011														Kimbell is an open concept school. The students eat lunch in the classroom, a situation that has raised concerns. There is currently no feasible alternative to this arrangement. Furthermore, there is no space with the technical capacity to hold the entire student bocy for all-school functions in the current facility.	Being Considered
Staff	Kimball	Build a new building from aging portable classroom	One time	2011														The old portablle classroom is too old and not safe. We need two stories building that connect to the main old bulding. The new building can be use also for the student a place they can eat and also auditoriom that kimball dont have at present.	Being Considered
Staff	Kimbell	Need Lunch Room Eight stall with all same comments	One time	2011														Kids eat in their classroom at spill thing on the carpets. This has caused mold, mice, ants etc.	Being Considered
Staff	Kimbell	12 staff commented need for multi purpose room that could be used as cafeteria / stage / auditorium	One time	2011														Need more classrooms and need to get rid of old run down portables.	Being Considered

Results

Public	Kimbell	22 persons from the public commented need lunchroom.	One time	2011						Unhealthy situation!	Being Considered
Public	Kimbell	14 persons commented on the poor condition of the portables and the need for additional classrooms	One time	2011						Need better quality learning environment.	Being Considered
Staff	Kimball	Lunchroom / Auditorium, additional classrooms	One time	2011						Some of Kimbell instructional classes are housed in portables that were installed on the grounds when the main building was constructed in 1965. the most vulnerable students (self-contained Sp Ed) 1sr - 3rd. in a portable away from the building. The students must leave their room go outside to a different portable.	Being Considered
Staff	Hale	Capital equipment to complete the BEX II construction of the new home of the radio station (KNHC)	One time	2011						Capital equipment project for on-air control rooms, production rooms, technical operations center (TOC) and student/staff work areas. This is to complete the digital conversion of the station.	N/A
Staff	Laurelhurst	Replace failing old boilers. Heating system is unstable.	One time							Heating system is unstable.	Being Considered
Public	Laurelhurst	New windows and doors	One time	2011						Need functioning windows. Need to replace old, chipping, likely plate glass windows with no insulation!	Being Considered
Staff	Laurelhurst	Replacement of Windows	One time							Laurelhurst was overlooked before. Built in 1927, it is way overdue for renovation!	Being Considered
Public	Laurelhurst	Playground Renovation	One time	2011						We've been involved in raising funds to renovate our 2 playgrounds. They are greatly in need. The South is being done now and we're going to start raising \$ for the North. Our parents are tapped out. It's a great project for the kids. Check it out on our school web site.	Being Considered
Public	Laurelhurst	Remodel the bathrooms	One time	2011							Partially Being Considered
Public	Laurelhurst	New windows for the school	One time	2011						Many windows at our school do not open and all are single-pane which is very inefficient.	Being Considered
Staff	Laurelhurst	Windows (with shades) and boiler	One time	2011						Most rooms in the building have windows that cannot open, and shades that are inoperable. In addition, our boiler regularly breaks down.	Being Considered
Public	Laurelhurst	Resurfacing of the North playground. The current concrete surface is broken and very uneven posing a real danger to our students. We really need it torn out and redone.	One time	2011						Outdoor play and exercise is crucial to our children's health and success in school. This project would go a long way to improve our student's outdoor time and keep them safe from falling on uneven and broken surfaces.	Being Considered
Public	Laurelhurst	New bathrooms and boiler for the school	One time	2011						The current facility is sub-standard, the boiler needs to be replaced to provide adequate heat. The bathrooms have outdated sinks/towel dispensers and the toilet paper rolls do not turn. This makes it especially hard for small children to use TP and then adequately wash their hands afterwards.	Being Considered
Staff	Laurelhurst	Water Pipes	One time							ASAP	Being Considered

Results

Staff	Laurelhurst	<p>The boiler here routinely breaks down, the heating units regularly do not work properly and require repairs and parts are not readily available due to the extreme age of the units.</p> <p>New windows for the building. The windows in several rooms that I have been in have not been operable, got nailed shut because they had a tendency to not close properly or securely. In addition to safety and security concerns, the windows are not energy efficient.</p> <p>With replacement of the windows, replacement of window coverings. The roller shades that we have now have deteriorated and those that have been replaced catch dust and cannot be cleaned contributing to aggravated asthma and allergy conditions due to poor air quality.</p> <p>Replacement/renovation of bathrooms and the water system- the old plumbing regularly requires repair, fixtures are ancient, the restrooms are musty/moldy smelling, and water fixtures for drinking purposes have water purifiers attached.</p>	One time	2011					<p>infrastructure. Why hasn't the building received significant renovation to address those things to date? An architect that visited our building about 6 years ago made a statement that in the District's BEX plan, all the buildings that were built in the 1920's and older were targeted for renovation first, as well as select south end schools for equity. He indicated that since all the 1920 era buildings were already targeted, and/or the renovation work completed, future projects would begin renovating buildings of "younger eras". I pointed out that Laurelhurst was built in 1927 (as stamped into the masonry in the exterior school entrance) and the school given only emergency building repairs. The embarrassed architect's answer was that he had only just begun working for the district and did not have the background to answer that question but perhaps they could be included in the next round (2010) of BEX planning. I would like a straight answer as to why this historic building has not been included in the renovation schedule. I have asked this question several times of several people and have never gotten an answer. Could you or someone from your department please give me an answer. I'm not only a school employee but also a Seattle resident, so it does get difficult to talk to colleagues, neighbors and other residents about the importance of supporting capital levies when commitments do not appear to be honored or clear answers given as to when those commitments will be honored.</p> <p>Lynne Carroll Laurelhurst Elementary</p>	Being Considered
Public	Laurelhurst	<p>Facilities improvement including: Construction of additional classroom space to accommodate increased enrollment; extend second floor over current unused first floor roof Bathroom upgrade Water fountains upgrade Heating system upgrade</p>	One time	2011					<p>This school is long overdue for renovation, but is not on the current capital projects schedule. In the absence of renovation, the improvements suggested above are necessary to accommodate increased enrollment and improve the health and hygiene of the school environment.</p>	Being Considered
Public	Laurelhurst	<p>Bathrooms, playcourt, windows, heating, etc</p>	One time	2011					<p>Laurelhurst is an extremely old building. It is a wonderful school and over capacity. It needs major renovations. The bathrooms are in the worst condition, but many other parts of the building need renovation or repair, too.</p>	Being Considered

Results

		<p>Replace or update all windows and doors so that they work correctly and improve climate control.</p> <p>Remodel/update all bathrooms in the school (main, gym, K-room, nurse office, etc.). Water leaks around toilet seat seals; faucets working sporadically - need updated sinks, faucets, etc. so that there is warm water to wash with and so that there is less water wasted.</p> <p>Indoor playcourt needs complete re-do.</p>																	
Public	Laurelhurst	Resurface North Playground.	Not sure	2011	2012	2013	2014	2015	2016	Laurelhurst Elementary does not appear to have had any capital improvements beyond the most rudimentary maintenance for decades.	Being Considered								
Public	Laurelhurst	PLEASE Fix all potholes and completely resurface the North playground with new 2"+ of asphalt across the entire play area to create a level play surface.	One time	2011	2012					<p>The PTA has raised funds to completely renovate the south playground at the school ourselves and it is currently being done. But the North playground where there K-2 graders play and all enter and exit the school grounds in the morning and afternoon.. is a disaster and unsafe.</p> <p>Besides the huge potholes that exist.. since there are so many quick fixes that have been made with previous potholes, the ground is so uneven that several children each day fall while playing. The kids are even throwing chunks of the potholed asphalt around, creating even bigger problems. We don't have a grass area for the kids to play at our school so the safety of the asphalt area is imperative.</p> <p>PLEASE consider this for 2011 or 2012 at the least.</p> <p>Thank you in advance.</p> <p>Mary Craig, Concerned parent of 1st grade and 2010-11 Kindergartener</p>	Being Considered								
Public	Laurelhurst	Additional classroom capacity.	One time	2011						Laurelhurst needs additional classroom capacity since a new kindergarten class was added in the 2008-09 school year.	Being Considered								
Public	Marshall, John	All repairs, updates and remodels (interior and exterior) necessary to bring the building and outdoor spaces up to code and fit to occupy middle or elementary school students.	One time	2011						John Marshall building is an asset that should be used to ease existing and future overcapacity in the Northeast and North Central Cluster of the District. Repairs and upgrades should begin immediately in order to prepare it for immediate occupancy.	No								
Public	McGilvra	Boys and girls bathroom upgrades.	One time							New toilets that automatically flush, new sinks and new stalls in both the boys and girls ground floor bathrooms. Levy dollars could be spent anytime between 2011-2016.	Partially Being Considered								

Results

Public	McGilvra	resurfacing of the pavement on the north end of the elementary school. The asphalt is cracked and broken and presents a real safety hazard for the children. There are basketball hoops in that area and children routinely trip and fall when running during recess and before and after school.	One time	2011						again, not sure if this is a capital project or a maintenance/safety issue.	Being Considered
Public	SBOC, aka, Old John Hay	I understand that the facility needs about \$16 million of renovations. For example, it needs a proper library and gym. And I understand it has the original furnace, etc.	One time	2011						Whether or not the SBOC stays at the Old John Hay (New) facility, it should be upgraded to benefit the students and maintain the property, plant and equipment.	No
Public	Olympic View	new disabled access ramp from asphalt playground to play field; concrete wall around existing playground equipment; new irrigation system for grass field.	One time							I'm not sure about the year the dollars are needed. We just replaced some outdated playground equipment and these things would truly complete the project.	No
Public	Olympic View	1) a new ramp to the lower field, 2) new irrigation and a new grass field 3) new concrete border around the play area	One time	2011							No
Public	Olympic View	New ADA ramp from asphalt playground to lower field. New irrigation and grass field Concrete border around play toy/wood chip area	Not sure	2011						The current ramp to lower field is rotting. The grass fields is mostly mud and holes. The Olympic View PTA just replaced the 18 year-old play toy but there was not enough money to build a concrete retaining wall around the play area. Thank you for your attention. Lucia Regan radiolu@comcast.net Olympic View PTA member	No
Public	Olympic View	New grass field and an irrigation / maintenance plan to keep it looking great!	Annual	2011						I own a home in the Maple Leaf neighborhood and have children that attend this fantastic school... and the field is almost not usable... all mud and rocks and patchy grass. I dream of a time when the kids of this school and the people in the Maple Leaf community could play soccer, baseball, kickball and other fun sports on a lush green field!	No
Public	Rogers	Replace all the existing windows, school-wide with modern, energy efficient, insulated windows.	One time	2011						See comments on faxed in form.	Partially Being Considered
Staff	Rogers	Upgrade/remodel of student and staff bathroom/restroom facilities, school-wide	One time	2011						See comments on faxed in form.	Partially Being Considered
Staff	Rogers	Front office remodel	One time	2012						See comments on faxed in form.	No
Staff	Rogers	New classroom furniture - All classrooms	One time	2011						See comments on faxed in form.	No
Staff	Rogers	Re-engineering the curbs approaching the school on 40th Ave. NE	One time	2011						See comments on faxed in form.	No

Results

Staff	Rogers	District maintains the grounds on both sides of 40th	One time	2011						See comments on faxed in form.	No
Public	Rogers	Upgrade/remodel of student and staff bathroom/restroom facilities, school-wide	One time	2011						See comments on faxed in form.	Partially Being Considered
Public	Rogers	Front office remodel	One time	2011						See comments on faxed in form.	No
Public	Rogers	New classroom furniture - All classrooms	One time	2011						See comments on faxed in form.	No
Public	Rogers	Re-engineering the curbs approaching the school on 40th Ave. NE	One time	2011						See comments on faxed in form.	No
Public	Roosevelt	Security cameras and installation of them for Roosevelt High School	Not sure	2011						<p>For whatever reason, district staff allowed the RHS BDT to make a security decision, namely, to not put in security cameras in RHS. We are the largest comprehensive high school in Seattle. We are the only comprehensive high school in Seattle without cameras. We NEED to have the cameras to protect our buildings and the people in them.</p> <p>This was a terrible oversight that needs to be corrected.</p> <p>The RHS PTSA is working with community to fund some of this but we need help from the district. Please call me (206-524-4733) or e-mail me to discuss this (melrhs@hotmail.com).</p>	Being Considered
Staff	Roxhill	I nominate a remodel to include expansion of two more full-sized kindergarten classrooms, a specialized autism classroom, tutoring/conference rooms attached to and shared by 2 to 3 rooms for use by classroom teachers, tutors, IAs and support teachers at Roxhill Elementary, which would eliminate the use of the hall or portables for most support services. I also recommend that the office be expanded to include a conference room, not occupied as an office for SLP, psychologist, nurse or principal, and more space for families to comfortably gather in the office.	One time		2012	2013				Attention to Roxhill Elementary is long overdue. It is the only unremodeled school in the area.	Partially Being Considered
Staff	Roxhill	Renovation	One time							Roxhill is rundown and worn out, the heating system is inconsistent. It serves very poor children who would be thrilled to be in a nice, fixed-up building. The staff at Roxhill work so hard for their students. I am a clerical sub for the district and I would like to see Roxhill in a nice building.	Partially Being Considered

Results

Staff	Salmon Bay	The non-functioning boiler will be replaced.	One time	2011					<p>The school has two boilers for heating. One is unreliable (boiler #1) and the other (boiler #2) does not work at all. The functioning boiler has been repaired at least four (4) times this school year.</p> <p>The water tank (condensation) that serves both boilers leaks constantly and loses water every day. We were told this could not be repaired because the District did not have funds to do so. A valve that controls heat to the main office is also leaking and we have been told it could not be repaired because of asbestos, which has since been removed, but we still have the leak. Repair or replacement of Boiler #2 at the school is required to provide reliable heating.</p>	Being Considered
Staff	Salmon Bay	Replace the remaining old windows, skylights and shade throughout the school with new, seismically safe and energy efficient ones.	One time	2011					<p>school, as well as the skylights, are old and need replacement. Currently, District workers tell us that some windows are so fragile they are in danger of falling out (or in). Many of the old windows are in such disrepair that they can not be repaired because of the deterioration of the casements. Additionally, they present dangers in the event of a wind, or hail storm and, of course, an earthquake. The condition of the windows also impedes any effort the school tries to make in energy conservation. The skylights currently leak during any bad rain storm.</p> <p>Many of the existing shades are in poor condition and are not functional. When windows on the east and west side were replaced two years ago, the shades, which were fragile to begin with, were not all replaced. Many that were barely working then do not work at all now. Most teachers are unable to darken the room adequately to make good use of District installed projector and document camera equipment. Additionally, functioning shades are a key element in both a lock down and shelter-in-place event. The school is not in compliance in this regard and this was realized specifically last year with an actual shelter-in-place incident.</p> <p>The district inspector concurs with this assessment.</p>	Partially Being Considered

Results

Staff	Salmon Bay School	Upgrade or replacement of the existing school-wide public address system.	One time	2011						<p>The current PA system is outdated and incomplete. It does not offer the function to communicate with an individual classroom, only a selected floor. There are no functioning speakers in the main hall, main office, principal's office, or day care center.</p> <p>During a recent shelter-in-place incident, runners had to be sent to the day care. An emergency announcement from another part of the building would not broadcast in the main office or principal's office.</p> <p>This project poses an imminent security and safety hazard and should be addressed as soon as possible.</p>	Partially Being Considered
Staff	Salmon Bay	The existing lighting and electrical system will be upgraded.	One time	2011					<p>Current lighting is sub-standard in both the classrooms and hallways. Hallway lighting is so poor that it is not possible for an administrator to see to the end of a hall to identify students or strangers in the building. Hall lighting is not even sufficient to read student work displayed on hall bulletin boards, which impedes teacher implementation of current writing curriculum standards.</p> <p>Classroom electrical outlets in many rooms are not sufficient to support District required technology. Some classrooms have the old standard light tubes and these can no longer be purchased from the District. Consequently, the school has to use the more modern type, which results in a flickering light in the classrooms. Hallway outlets are also lacking and make it difficult with any kind of maintenance project, which requires extension cords into classrooms, leaving the possibility of students/staff tripping. Kitchen outlets are outdated and can not be used for modern appliances. The stage panel box is also outdated and is connected to other rooms in the building. If it is "tripped" because of a stage lighting problem, it shuts off office equipment and classrooms. Ideally, it should be separated from the building panel.</p> <p>Improvements will bring the learning environment to</p>	Partially Being Considered	

Results

Staff	Salmon Bay	A fire suppression system (sprinklers) will be installed as a fire safety measure.	One time	2011					<p>Concerns have been raised about the danger of fire in the building due to the absence of a sprinkler system. The Meng inspector suggested perhaps this is because we have a brick building. However, a sprinkler system would reduce the risk to students and staff, and also reduce the risk of major damage to the building itself in the event of a fire.</p> <p>There are many wooden structures and finishes in the interior of the building. Limitation of damage due to functional sprinklers would mean less probability of an internal fire, as well as a disruption to the student's learning and school functioning.</p>	No
Staff	Salmon Bay	Relocate the dumpster containers to a safer, more convenient location.	One time	2011					<p>This project would be a relatively small cost, with a great benefit, but one outside the parameters of our building base-line budget. Currently the school's garbage, compost and recycling dumpsters are located on the playground. Due to the terrain of our site, the dumpsters are located one flight up from the main floor of the school building. Garbage has to be lifted/carried up this flight, or rolled up a half city block over difficult, root-ravaged sidewalks. At least two custodians have experienced back injuries due to this arrangement.</p> <p>Although garbage pick up has always been requested to happen in early morning or late afternoon hours to avoid trucks coming on to the playground while children are playing there, it is a constant negotiation whenever there is a new company, substitute driver, or new driver. The dumpsters are located near the stairs to limit the distance the garbage must be transported. This also means the dumpsters are located right next to the children's play structure and pose further risk. Since our playfield cannot be secured at night, the dumpsters are constant targets of graffiti poised in a primary location on our school grounds.</p> <p>There is a suitable location where a concrete pad could be located, fenced and secured on the same level as the main building. This would eliminate the concerns</p>	N/A
Staff	Salmon Bay	The restrooms will be updated.	One time	2011					<p>The school restrooms are outdated. Urinals are chipped and cracked and most stalls are not ADA-accessible. The school has only one ADA-accessible stall on the first floor of a three story building, located in a men's room. There is no women's ADA accessible stall anywhere in the building.</p>	Partially Being Considered

Results

Staff	Salmon Bay	Air Quality Improvements	One time	2011						The District inspector recently raised concerns about air quality in the school. Salmon Bay was scheduled for an air quality project to be done this year, but the funds were assigned instead to the Denny/Sealth project. The Salmon Bay air quality project should be put back on the list of needed improvements.	Partially Being Considered
Staff	Salmon Bay	The aging and deteriorating ceiling tiles will be replaced (including abatement of potential asbestos hazard if crumbling tiles contain asbestos fibers).	One time	2011						Existing ceiling tiles are deteriorated and regularly fall to the floor. Often when we request repair and replacement, we are told the District no longer provides this service and that we should remodel the ceilings. Whenever tiles have been replaced, they fall again more quickly than the older tiles. There is a danger of falling tiles injuring students or staff, as well as the possibility that the tiles contain asbestos fibers which could be released to the air, particularly in the case of crumbling or falling tiles.	Partially Being Considered
Public	Sand Point	All repairs, updates and remodels (interior and exterior) necessary to bring the building and outdoor spaces up to code and fit to occupy elementary school students.	One time	2011						The Sand Point Elementary School building is an asset that should be used to ease existing and future overcapacity in the Northeast Cluster of the Seattle Public Schools District. Repairs and upgrades should begin immediately in order to prepare it for immediate occupancy.	Partially Being Considered
Public	SBOC, aka, Old John Hay	I understand that the Old John Hay (New) building needs approximately \$16 million in upgrades. Please include all the necessary upgrades and renovations in the next BTA III Levy allocation.	One time								Partially Being Considered
Public	Thornton Creek	Improved security lighting near the parking lots.	One time	2011							Partially Being Considered
Public	Toilet stalls for the disabled District-wide	Install in all restroom for the disabled. Bobrick B-2740 so that people with disabilities don't have to struggle accessing toilet paper with every use of the facility.	One time	2011						Give disabled people a little consideration. Some don't have the fine motor skills it takes to access the paper you have in a majority of the bathroom stalls. In fact even non-disabled people struggle with getting paper out.	Partially Being Considered
Public	TT Minor	I would like to see TT Minor's roof fixed it has leaks towards the front end of the building. Additionally the plumbing needs to be fixed as some of the toilets back up during bad rainstorms. Also, the kitchen needs remodeling to accommodate fresh food. This would include I believe larger sinks and a larger refrigerator.	Not sure	2011						I have been unable to find specific remodeling needs for the school on this website, so I realize my synopsis of repairs is not detailed enough. I believe that there is information at the district that would provide more detail as to the exact repairs that need to be made to the TT Minor building.	Being Considered

Results

Staff	Van Asselt	Provide new desks, chairs and computer tables for classrooms. Provide 2 student computers for each classroom that is compatible to interact with district adopted curriculum. Replace original linoleum floors and linoleum counter tops, Improve outside lighting for security of building and employees. Provide two additional play structures. Resurface unsafe asphalt in play area. Retile stairs to match the new retiling of the floors.	One time	2011	2012						This school has original desks and chairs from the 60's. If we do not find items we need from surplus we have to go without. It is a shame that surplus has newer chairs etc than we have. Unfortunately, there usually is not enough for a classroom.	No
Staff	Washington	Construction of a field-turf field or renovation of the existing black-top field on the lower "play ground" (directly south of the building); addition of solar panels, including all structural work necessary, to utilize the massive unrestricted roof "collection" area; complet rebuild of the school (probably not going to happen, but...)	One time	2011	2013				2016		The new "field" would increase the PE instructional program, reduce to safety issues faced with playing on asphalt, and could be utilized by community mod-soccer or mod-football (younger age programs); we already have two sets of solar panels on our southern roof. Even on hazy days, the meter runs backwards. Utilizing the massive flat surface that makes up our spit-level roof to decrease our electrical "foot-print" would be a smart move all around; Rebuilding the school, which by 2016 will be nearly 70 years old, would be great. Clearly our school was not constructed as a middle school, and while it has adapted to the middle school model, a better building, built green and with middle school learning in mind, would be well received by all.	No
Staff	Whittier	I recognize Whittier is a relatively new building. However, because of the skill level of custodial staff, the building is in need of tremendous repair from the floor to the ceiling. Parents often comment on some of the features of the structure that are in need of repair (such as the neon lights not working in the Wave located near the library, floors chipping and cracking in many places, base boards loose from the walls, and other objects that should be fixed on the walls are falling down and/or apart. Many of these items create a safety hazard (tripping, falling, illness). There is limited, if any heat in the northwest section of the building. Therefore, students and teachers often become ill.	One time	2011								Partially Being Considered

Results

Public	Whitworth	<p>expanding from K-5 to K-8, moved from Columbia to Whitworth over the summer of 2007. The move to a larger, newer building allowed the school to begin adding middle school grades without waiting for costly renovations to the historic Columbia building in order to accommodate the additional students and staff. However, since the move, several problems with the Whitworth building have become very apparent to Orca staff, students and families.</p> <p>We have identified two major areas of concern. Security & Wayfinding relate to the building's confusing, inconvenient entrances. Collaboration & Connection relate to the poor connections between different areas of the building, and the lack of common spaces that can support Orca's collaborative, community-based alternative curriculum. Below is a short description of the issues and a brief proposal for addressing them. Further details, including floor plans, photographs, and background information about Orca's alternative program, are available as attachments.</p>	One time	2011						<p>1. This proposal grew out of a staff/parent facilities committee and the nomination was endorsed by the Leadership Council, a body of staff & parents that represents the school community as a whole.</p> <p>2. The following attachments are available online:</p> <p>Orca Vision Statement: www.orcapta.org/about_orca/The_Orca_K-8_Vision.shtml.</p> <p>Drawings showing existing and proposed floor plan for second floor: http://columbiaschoolsong.blogspot.com/2008/12/whitworth-proposal-for-2010-capital.html</p>	Partially Being Considered
Staff	All	<p>More accessible / Universal toilet paper dispensers in every toilet stall which is intended for use by people with disabilities in the Seattle Public School District. I would like to nominate replacing our less accessible toilet dispensers with Bobrick model B-2740 which has no controlled delivery, is Universal / Barrier Free and projects 4 7/7" from wall as opposed to other styles that project farther from the wall.</p>	One time	2011						<p>This model is installed in the View Ridge staff bathroom. I can be reached via e-mail clpalmner@seattleschools.org or 206-523-6087 Cindy Palmer</p>	Partially Being Considered