

Results of Water Quality Testing
For
Ballard High School

Updated April 29, 2009

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria:

The school has one source that does not meet the policy criteria. Signs will be posted at Kitchen, double faucets sink – left (#56).

Drinking fountain at 233 gym (#21) need to be tested. Will be disabled till finish the testing.

Follow-up monitoring: Will be performed in 2012.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	hallway, first floor, SW, left	P	None	P	None	P	None	P	None	Yes
02	B	hallway, first floor, SW, right	P	None	P	None	P	None			Yes
03	B	hallway, first floor, South, left	P	None	P	None	P	None			Yes
04	B	hallway, first floor, South, left	P	None	P	None	P	None			Yes
05	B	commons, left	P	None	P	None	P	None			Yes
06	B	commons, right	P	None	P	None	P	None			Yes
07	B	hallway, first floor, by gym, left	P	None	P	None	P	None			Yes
08	B	hallway, first floor, by gym, right	P	None	P	None	P	None			Yes
09	B	corridor near men's locker room, first floor, left	P	None	P	None	P	None			Yes
10	B	corridor near men's locker room, first floor, right	P	None	P	None	P	None			Yes
11	B	near 218, left	P	None	P	None	P	None			Yes
12	B	near 217, right	P	None	P	None	P	None			Yes
13	B	near 209, left	P	None	P	None	P	None			Yes
14	B	near 209, right	P	None	P	None	P	None			Yes
15	B	231 gym	P	None	P	None	P	None	P	None	Yes
16	B	232 gym	P	None	P	None	P	None			Yes
17	B	233 gym	P	None	P	None	P	None			Yes
18	B	233 gym	P	None	P	None	P	None			Yes
21	B	233 gym	smapple	DIS	smapple	DIS	smapple	DIS			DIS
22	B	233 gym	P	None	P	None	P	None	P	None	Yes
27	S	staff lounge. SE201	P	None	P	None	P	None	P	None	Yes
28	S	nurse's office	P	None	P	None	P	None	P	None	Yes
29	S	kitchen - single sink	P	None	P	None	P	None	P	None	Yes
30	S	kitchen - office	P	None	P	None	P	None	P	None	Yes
31	S	Home Ec, room 220	P	None	P	None	P	None			Yes
32	S	Home Ec, room 220	P	None	P	None	P	None			Yes
34	S	Home Ec, room 220	P	None	P	None	P	None			Yes
35	S	Home Ec, room 220	P	None	P	None	P	None			Yes
36	S	Home Ec, room 220	P	None	P	None	P	None			Yes
37	S	Home Ec, room 220	P	None	P	None	P	None			Yes
38	S	Home Ec, room 220	P	None	P	None	P	None			Yes
40	S	Custodian lunch room NE120	P	None	P	None	P	None			Yes
41	S	teen Health center	P	None	P	None	P	None			Yes
42	S	teen Health center, SE122	P	None	P	None	P	None			Yes
43	S	teen Health center, Janna	P	None	P	None	P	None			Yes
44	S	student store	P	None	P	None	P	None			Yes
45	S	student store	P	None	P	None	P	None			Yes
46	S	main office workroom SE126	P	None	P	None	P	None			Yes
47	S	SW209	P	None	P	None	P	None			Yes
48	S	SW209	P	None	P	None	P	None			Yes
49	S	daycare N215	P	None	P	None	P	None			Yes
50	S	daycare N215	P	None	P	None	P	None			Yes
51	S	daycare N215 kitchen	P	None	P	None	P	None			Yes
52	S	N205 library office	P	None	P	None	P	None			Yes
53	B	2nd floor, SE, left	P	None	P	None	P	None			Yes
54	B	2nd floor, SE, right	P	None	P	None	P	None			Yes
55	S	1st floor, training room	P	None	P	None	P	None			Yes
56	S	Kitchen, double faucets sink -- left	F	PS	P	None	P	None			PS

57	S	Kitchen, double faucets sink -- right	P	None	P	None	P	None			Yes
----	---	---------------------------------------	---	------	---	------	---	------	--	--	-----

Table 2. Lead Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1 st Draw	Flush 30s	Pass/ Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
01	B	hallway, first floor, SW, left	5/13/2004	<1	<1	P					5/9/2006	1	<1	P					4/4/2009	<1	<1	P	P	None
02	B	hallway, first floor, SW, right	5/13/2004	2	1	P					5/9/2006	2	<1	P					4/4/2009	<1	<1	P	P	None
03	B	hallway, first floor, South, left	5/13/2004	<1	<1	P					5/9/2006	1	<1	P					4/4/2009	<1	<1	P	P	None
04	B	hallway, first floor, South, left	5/13/2004	<1	<1	P					5/9/2006	2	<1	P					4/4/2009	<1	<1	P	P	None
05	B	commons, left					8/12/2004	6	4	P	5/9/2006	1	1	P					4/4/2009	<1	<1	P	P	None
06	B	commons, right	5/13/2004								5/9/2006		<1	P					4/4/2009	<1	<1	P	P	None
07	B	hallway, first floor, by gym, left	5/13/2004								5/9/2006	3	<1	P					4/4/2009	<1	<1	P	P	None
08	B	hallway, first floor, by gym, right	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
09	B	corridor near men's locker room, first floor, left	5/13/2004	<1	<1	P					5/9/2006	2		P					4/4/2009	<1	<1	P	P	None
10	B	corridor near men's locker room, first floor, right	5/13/2004	<1	1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
11	B	near 218, left	5/13/2004	2	1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
12	B	near 217, right	5/13/2004	2	1	P					5/9/2006	3	<1	P					4/4/2009	<1	<1	P	P	None
13	B	near 209, left	5/13/2004	2	2	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
14	B	near 209, right	5/13/2004	2	2	P					5/9/2006	1		P					4/4/2009	<1	<1	P	P	None
15	B	231 gym	5/13/2004	2	1	P					5/9/2006	1	1	P					4/4/2009	<1	<1	P	P	None
16	B	232 gym	5/13/2004	2	2	P					5/9/2006	1	1	P					4/4/2009	<1	<1	P	P	None
17	B	233 gym	5/13/2004	2	1	P					5/9/2006	2	2	P					4/4/2009	1	<1	P	P	None
18	B	233 gym					8/12/2004	3	2	P	5/9/2006	1	2	P					4/4/2009	<1	<1	P	P	None
21	B	233 gym	5/13/2004																				sample	DIS
22	B	233 gym	5/13/2004	2	2	P					5/9/2006	1	4	P									P	None
27	S	staff lounge. SE201	5/13/2004	1	<1	P					5/9/2006	<1	1	P					4/4/2009	<1	<1	P	P	None
28	S	nurse's office	5/13/2004	<1	1	P					5/9/2006	1	1	P					4/4/2009	<1	<1	P	P	None
29	S	kitchen - single sink					8/12/2004	6	7	P	5/9/2006	1	1	P	5/11/2006	91	5		4/4/2009	<1	<1	P	P	None
30	S	kitchen - office					8/12/2004	6	6	P	5/9/2006	12	2		5/11/2006	21	9		4/4/2009	<1	<1	P	P	None
31	S	Home Ec, room 220					8/12/2004	9	4	P	5/9/2006	3	<1	P					4/4/2009	1	<1	P	P	None
32	S	Home Ec, room 220									5/9/2006	2	<1	P					4/4/2009	1	<1	P	P	None
34	S	Home Ec, room 220									5/9/2006	8	1	P					4/4/2009	<1	<1	P	P	None
35	S	Home Ec, room 220									5/9/2006	2	<1	P					4/4/2009	<1	<1	P	P	None
36	S	Home Ec, room 220									5/9/2006	2	1	P					4/4/2009	1	<1	P	P	None
37	S	Home Ec, room 220									5/9/2006	2	<1	P					4/4/2009	<1	<1	P	P	None
38	S	Home Ec, room 220									5/9/2006	5	<1	P					4/4/2009	2	<1	P	P	None
40	S	Custodian lunch room NE120																	4/4/2009	<1	<1	P	P	None
41	S	teen Health center																	4/4/2009	1	<1	P	P	None
42	S	teen Health center, SE122																	4/4/2009	<1	<1	P	P	None
43	S	teen Health center, Janna																	4/4/2009	1	<1	P	P	None
44	S	student store																	4/4/2009	<1	<1	P	P	None
45	S	student store																	4/4/2009	1	1	P	P	None
46	S	main office workroom SE126																	4/4/2009	<1	<1	P	P	None
47	S	SW209																	4/4/2009	2	1	P	P	None
48	S	SW209																	4/4/2009	<1	<1	P	P	None
49	S	daycare N215																	4/4/2009	<1	<1	P	P	None
50	S	daycare N215																	4/4/2009	<1	<1	P	P	None
51	S	daycare N215 kitchen																	4/4/2009	<1	1	P	P	None
52	S	N205 library office																	4/4/2009	<1	<1	P	P	None
53	B	2nd floor, SE, left																	4/4/2009	1	<1	P	P	None
54	B	2nd floor, SE, right																	4/4/2009	<1	<1	P	P	None
55	S	1st floor, training room																	4/4/2009	<1	<1	P	P	None
56	S	Kitchen, double faucets sink -- left																	4/4/2009	16	<1		F	ps
57	S	Kitchen, double faucets sink -- right																	4/4/2009	1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
01	B	hallway, first floor, SW, left	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
02	B	hallway, first floor, SW, right	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
03	B	hallway, first floor, South, left	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
04	B	hallway, first floor, South, left	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
05	B	commons, left					8/12/2004	<1	<1	P	5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
06	B	commons, right									5/9/2006		<1	P					4/4/2009	<1	<1	P	P	None
07	B	hallway, first floor, by gym, left									5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
08	B	hallway, first floor, by gym, right	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
09	B	corridor near men's locker room, first floor, left	5/13/2004	<1	<1	P					5/9/2006	<1		P					4/4/2009	<1	<1	P	P	None
10	B	corridor near men's locker room, first floor, right	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
11	B	near 218, left	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
12	B	near 217, right	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
13	B	near 209, left	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
14	B	near 209, right	5/13/2004	<1	<1	P					5/9/2006	<1		P					4/4/2009	<1	<1	P	P	None
15	B	231 gym	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
16	B	232 gym	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
17	B	233 gym	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
18	B	233 gym					8/12/2004	<1	<1	P	5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
21	B	233 gym																					Sample	DIS
22	B	233 gym	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P									P	None
27	S	staff lounge. SE201	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
28	S	nurse's office	5/13/2004	<1	<1	P					5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
29	S	kitchen - single sink					8/12/2004	1	<1	P	5/9/2006	<1	<1	P	5/11/2006	<1	<1	P	4/4/2009	<1	<1	P	P	None
30	S	kitchen - office					8/12/2004	<1	1	P	5/9/2006	<1	<1	P	5/11/2006	<1	<1	P	4/4/2009	<1	<1	P	P	None
31	S	Home Ec, room 220					8/12/2004	<1	<1	P	5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
32	S	Home Ec, room 220									5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
34	S	Home Ec, room 220									5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
35	S	Home Ec, room 220									5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
36	S	Home Ec, room 220									5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
37	S	Home Ec, room 220									5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
38	S	Home Ec, room 220									5/9/2006	<1	<1	P					4/4/2009	<1	<1	P	P	None
40	S	Custodian lunch room NE120																	4/4/2009	<1	<1	P	P	None
41	S	teen Health center																	4/4/2009	<1	<1	P	P	None
42	S	teen Health center, SE122																	4/4/2009	<1	<1	P	P	None
43	S	teen Health center, Janna																	4/4/2009	<1	<1	P	P	None
44	S	student store																	4/4/2009	<1	<1	P	P	None
45	S	student store																	4/4/2009	<1	<1	P	P	None
46	S	main office workroom SE126																	4/4/2009	<1	<1	P	P	None
47	S	SW209																	4/4/2009	<1	<1	P	P	None
48	S	SW209																	4/4/2009	<1	<1	P	P	None
49	S	daycare N215																	4/4/2009	<1	<1	P	P	None
50	S	daycare N215																	4/4/2009	<1	<1	P	P	None
51	S	daycare N215 kitchen																	4/4/2009	<1	<1	P	P	None
52	S	N205 library office																	4/4/2009	<1	<1	P	P	None
53	B	2nd floor, SE, left																	4/4/2009	<1	<1	P	P	None
54	B	2nd floor, SE, right																	4/4/2009	<1	<1	P	P	None
55	S	1st floor, training room																	4/4/2009	<1	<1	P	P	None
56	S	Kitchen, double faucets sink -- left																	4/4/2009	<1	<1	P	P	None
57	S	Kitchen, double faucets sink -- right																	4/4/2009	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass/ Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
01	B	hallway, first floor, SW, left	5/13/2004	0.1		P					5/9/2006	0.372	0.1	P					4/4/2009	0.054	0.034	P	P	None
02	B	hallway, first floor, SW, right									5/9/2006	0.567	0.125	P					4/4/2009	0.049	0.034	P	P	None
03	B	hallway, first floor, South, left									5/9/2006	0.255	0.095	P					4/4/2009	0.105	0.109	P	P	None
04	B	hallway, first floor, South, left									5/9/2006	0.605	0.106	P					4/4/2009	0.178	0.101	P	P	None
05	B	commons, left									5/9/2006	0.432	0.203	P					4/4/2009	0.174	0.162	P	P	None
06	B	commons, right									5/9/2006		0.357	P					4/4/2009	0.189	0.19	P	P	None
07	B	hallway, first floor, by gym, left									5/9/2006	0.318	0.073	P					4/4/2009	0.078	0.05	P	P	None
08	B	hallway, first floor, by gym, right									5/9/2006	0.549	0.205	P					4/4/2009	0.078	0.052	P	P	None
09	B	corridor near men's locker room, first floor, left									5/9/2006	0.48		P					4/4/2009	0.142	0.037	P	P	None
10	B	corridor near men's locker room, first floor, right									5/9/2006	0.459	0.553	P					4/4/2009	0.188	0.178	P	P	None
11	B	near 218, left									5/9/2006	0.1	0.395	P					4/4/2009	0.122	0.118	P	P	None
12	B	near 217, right	5/13/2004		0.83	P					5/9/2006	0.404	0.102	P					4/4/2009	0.13	0.107	P	P	None
13	B	near 209, left	5/13/2004	0.077	0.073	P					5/9/2006	0.326	0.096	P					4/4/2009	0.119	0.093	P	P	None
14	B	near 209, right	5/13/2004	0.086	0.072	P					5/9/2006	0.687		P					4/4/2009	0.117	0.102	P	P	None
15	B	231 gym	5/13/2004	0.31		P					5/9/2006	1.06	0.878	P					4/4/2009	0.351	0.388	P	P	None
16	B	232 gym									5/9/2006	0.941	0.844	P					4/4/2009	0.336	0.327	P	P	None
17	B	233 gym									5/9/2006	0.934	0.884	P					4/4/2009	0.336	0.336	P	P	None
18	B	233 gym									5/9/2006	1.06	0.894	P					4/4/2009	0.319	0.319	P	P	None
21	B	233 gym																					Sample	DIS
22	B	233 gym	5/13/2004	0.32		P					5/9/2006	0.883	0.85	P									P	None
27	S	staff lounge. SE201	5/13/2004	0.25		P					5/9/2006	0.226	0.291	P					4/4/2009	0.145	0.175	P	P	None
28	S	nurse's office	5/13/2004	0.094		P					5/9/2006	0.225	0.242	P					4/4/2009	0.112	0.114	P	P	None
29	S	kitchen - single sink					8/12/2004	0.62		P	5/9/2006	0.604	0.67	P	5/11/2006	1.12	0.36	P	4/4/2009	0.135	0.019	P	P	None
30	S	kitchen - office					8/12/2004	0.6		P	5/9/2006	0.319	0.392	P	5/11/2006	1.45	1.11		4/4/2009	0.072	0.061	P	P	None
31	S	Home Ec, room 220									5/9/2006	0.394	0.36	P					4/4/2009	0.228	0.105	P	P	None
32	S	Home Ec, room 220									5/9/2006	0.799	0.386	P					4/4/2009	0.248	0.131	P	P	None
34	S	Home Ec, room 220									5/9/2006	0.454	0.3	P					4/4/2009	0.226	0.138	P	P	None
35	S	Home Ec, room 220									5/9/2006	0.408	0.389	P					4/4/2009	0.227	0.152	P	P	None
36	S	Home Ec, room 220									5/9/2006	0.37	0.269	P					4/4/2009	0.187	0.178	P	P	None
37	S	Home Ec, room 220									5/9/2006	0.468	0.388	P					4/4/2009	0.261	0.177	P	P	None
38	S	Home Ec, room 220									5/9/2006	0.623	0.389	P					4/4/2009	0.19	0.199	P	P	None
40	S	Custodian lunch room NE120																	4/4/2009	0.221	0.024	P	P	None
41	S	teen Health center																	4/4/2009	0.14	0.125	P	P	None
42	S	teen Health center, SE122																	4/4/2009	0.181	0.046	P	P	None
43	S	teen Health center, Janna																	4/4/2009	0.304	0.056	P	P	None
44	S	student store																	4/4/2009	0.191	0.122	P	P	None
45	S	student store																	4/4/2009	0.186	0.131	P	P	None
46	S	main office workroom SE126																	4/4/2009	0.196	0.079	P	P	None
47	S	SW209																	4/4/2009	0.095	0.129	P	P	None
48	S	SW209																	4/4/2009	0.289	0.108	P	P	None
49	S	daycare N215																	4/4/2009	0.194	0.089	P	P	None
50	S	daycare N215																	4/4/2009	0.202	0.106	P	P	None
51	S	daycare N215 kitchen																	4/4/2009	0.251	0.129	P	P	None
52	S	N205 library office																	4/4/2009	0.245	0.22	P	P	None
53	B	2nd floor, SE, left																	4/4/2009	0.168	0.124	P	P	None
54	B	2nd floor, SE, right																	4/4/2009	0.108	0.115	P	P	None
55	S	1st floor, training room																	4/4/2009	0.321	0.258	P	P	None
56	S	Kitchen, double faucets sink -- left																	4/4/2009	0.11	0.045	P	P	None
57	S	Kitchen, double faucets sink -- right																	4/4/2009	0.095	0.02	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B	hallway, first floor, SW, left	5/13/2004	0.08	0.09	P									P	None
02	B	hallway, first floor, SW, right														
03	B	hallway, first floor, South, left														
04	B	hallway, first floor, South, left														
05	B	commons, left														
06	B	commons, right														
07	B	hallway, first floor, by gym, left														
08	B	hallway, first floor, by gym, right														
09	B	corridor near men's locker room, first floor, left														
10	B	corridor near men's locker room, first floor, right														
11	B	near 218, left														
12	B	near 217, right														
13	B	near 209, left														
14	B	near 209, right														
15	B	231 gym	5/13/2004	0.12		P									P	None
16	B	232 gym														
17	B	233 gym														
18	B	233 gym														
21	B	233 gym														
22	B	233 gym	5/13/2004	0.13	0.08	P									P	None
27	S	staff lounge. SE201	5/13/2004	0.1		P									P	None
28	S	nurse's office	5/13/2004	0.07		P									P	None
29	S	kitchen - single sink					8/12/2004	0.19		P					P	None
30	S	kitchen - office					8/12/2004	0.18		P					P	None
31	S	Home Ec, room 220														
32	S	Home Ec, room 220														
34	S	Home Ec, room 220														
35	S	Home Ec, room 220														
36	S	Home Ec, room 220														
37	S	Home Ec, room 220														
38	S	Home Ec, room 220														
40	S	Custodian lunch room NE120														
41	S	teen Health center														
42	S	teen Health center, SE122														
43	S	teen Health center, Janna														
44	S	student store														
45	S	student store														
46	S	main office workroom SE126														
47	S	SW209														
48	S	SW209														
49	S	daycare N215														
50	S	daycare N215														
51	S	daycare N215 kitchen														
52	S	N205 library office														
53	B	2nd floor, SE, left														
54	B	2nd floor, SE, right														
55	S	1st floor, training room														
56	S	Kitchen, double faucets sink -- left														
57	S	Kitchen, double faucets sink -- right														

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	fire sprinkler control valve room	Arsenic	04-Apr-09	2 ppb	P
00	SE	fire sprinkler control valve room	Cadmium	04-Apr-09	1 ppb	P
00	SE	fire sprinkler control valve room	Copper	04-Apr-09	0.036 ppm	P
00	SE	fire sprinkler control valve room	Iron	04-Apr-09	0.116 ppm	P
00	SE	fire sprinkler control valve room	Lead	04-Apr-09	1 ppb	P
00	SE	fire sprinkler control valve room	Total Coliforms	04-Apr-09	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.