

Seattle Public Schools
 Drinking Water Quality Program

Summary Status

for

Cleveland High School

Revised January 8, 2008

Status:

All sources meet the policy except:

Signs will be posted at:

Fixture number	Type	Location
121	S	family and consumer sciences lab 2264 center
122	S	family and consumer sciences lab 2264 center
123	S	family and consumer sciences lab 2264 center
125	S	family and consumer sciences lab 2264 west
142	Ice	tickets and concession 3003
146A	S	kitchen: cooking pot fill 3117 left
147	S	kitchen handwash 3117
149	S	kitchen handwash 3117
150	S	kitchen handwash 3117
151	S	kitchen 3117
152	S	kitchen dishwasher sink 3117
153	S	kitchen dishwasher sink 3117
156A	Ice	science prep. Room 1107A
161	S	science prep. Room 1135A
167	S	dressing 1161
168	S	dressing 1167
169	S	Drama classroom 1162
170	S	storage room 1166A
171	S	classroom 1170
172	S	classroom 1172
173	S	classroom 1176
175A	Ice	faculty 1211A
177A	Ice	science prep. 1205A
180	S	student store 1201A
184A	Ice	science prep. 1233A
193	S	Servery Prep handwash 3115A
195A	Ice	room 3029 training room

The school will be flushed after any breaks longer than five days.

Follow-up monitoring: Will be performed in 2010.