

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
COE ELEMENTARY SCHOOL

Updated February 20, 2009

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria:

This school has one source that does not meet the policy criteria. Signs will be posted in the kitchen, Rinse Sink for dishwasher (#13).

Follow-up monitoring: Will be performed in 2012.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S	outside classroom 108	P	None	P	None	P	None	P	None	Yes
02	S	outside classroom 103	P	None	P	None	P	None			Yes
03	B	Childcare, classroom 110	P	None	P	None	P	None			Yes
04	B	Childcare, classroom 109	P	None	P	None	P	None			Yes
05	B	hallway near room 203, 2nd floor, S. hall	P	None	P	None	P	None			Yes
06	B	hallway near room 209, 2nd floor, N. hall	P	None	P	None	P	None			Yes
07	B	hallway near room 309, 3rd floor, N. Hall	P	None	P	None	P	None			Yes
08	B	hallway near room 303, 3rd floor, S. Hall	P	None	P	None	P	None	P	None	Yes
09	B	gym entrance	P	None	P	None	P	None	P	None	Yes
10	S	nurses office	P	None	P	None	P	None	P	None	Yes
11	S	staff lounge, room 301	P	None	P	None	P	None	P	None	Yes
13	S	kitchen, Rinse Sink for dishwasher	F	PS	P	None	P	None	P	None	PS
14	S	kitchen (LH Fixture), 3 compartment sink	P	None	P	None	P	None	P	None	Yes
14.5	S	kitchen (RH Fixture), 3 compartment sink	P	None	P	None	P	None			Yes
14.6	B	KITCHEN, salad prep sink	P	None	P	None	P	None	P	None	Yes
14.7	B	KITCHEN, hand wash sink	P	None	P	None	P	None			Yes
15	S	day care kitchen	P	None	P	None	P	None			Yes
16	S	room 110 - north sink, left	P	None	P	None	P	None			Yes
16A	S	room 110, north sink, right	P	None	P	None	P	None			Yes
17	S	room 109 south sink	P	None	P	None	P	None			Yes
17A	S	room 109, south sink, right	P	None	P	None	P	None			Yes
18	S	room 104	P	None	P	None	P	None			Yes
19	S	room 105	P	None	P	None	P	None			Yes
20	S	room 106	P	None	P	None	P	None	P	None	Yes
21	S	room 107	P	None	P	None	P	None			Yes
22	S	room 108	P	None	P	None	P	None			Yes
24	S	room 204	P	None	P	None	P	None			Yes
25	S	room 205	P	None	P	None	P	None			Yes
26	S	room 206	P	None	P	None	P	None	P	None	Yes
27	S	room 207	P	None	P	None	P	None			Yes
28	S	room 208	P	None	P	None	P	None			Yes
29	S	room 209	P	None	P	None	P	None			Yes
30	S	near conf room 214	P	None	P	None	P	None			Yes
31	S	room 302	P	None	P	None	P	None			Yes
32	S	room 303	P	None	P	None	P	None			Yes
33	S	room 304	P	None	P	None	P	None			Yes
34	S	room 305	P	None	P	None	P	None	P	None	Yes
35	S	near room 314	P	None	P	None	P	None			Yes
36	S	room 306	P	None	P	None	P	None			Yes
37	S	room 307	P	None	P	None	P	None			Yes
38	S	room 308	P	None	P	None	P	None			Yes
39	S	room 309	P	None	P	None	P	None			Yes
40	S	room 310	P	None	P	None	P	None	P	None	Yes
41	S	room 103	P	None	P	None	P	None			Yes
42	B	1st floor hall - south side	P	None	P	None	P	None			Yes
43	B	1st floor hall - north side	P	None	P	None	P	None			Yes
44	S	Library office, 201A	P	None	P	None	P	None	P	None	Yes
45	S	Staff work room 101F	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	outside classroom 108	5/19/2004	2	2	P					5/12/2006	2	2	P		<1	<1	P	P	None
02	S	outside classroom 103	5/19/2004	2	1	P					5/12/2006	2	1	P		3	<1	P	P	None
03	B	Childcare, classroom 110	5/19/2004	2	2	P					5/12/2006	2	1	P		<1	<1	P	P	None
04	B	Childcare, classroom 109	5/19/2004	2	3	P					5/12/2006	2	1	P		<1	<1	P	P	None
05	B	hallway near room 203, 2nd floor, S. hall	5/19/2004	3	2	P					5/12/2006	2	2	P		<1	<1	P	P	None
06	B	hallway near room 209, 2nd floor, N. hall	5/19/2004	2	1	P					5/12/2006	5	1	P		<1	<1	P	P	None
07	B	hallway near room 309, 3rd floor, N. Hall	5/19/2004	2	2	P					5/12/2006	8	2	P		<1	<1	P	P	None
08	B	hallway near room 303, 3rd floor, S. Hall	5/19/2004	1	1	P					5/12/2006	3	1	P		<1	<1	P	P	None
09	B	gym entrance	5/19/2004	1	3	P					5/12/2006	3	2	P	1/28/2009	<1	<1	P	P	None
10	S	nurses office	5/19/2004	2	1	P					5/12/2006	3	1	P	1/28/2009	<1	<1	P	P	None
11	S	staff lounge, room 301	5/19/2004	2	2	P					5/12/2006	2	1	P	1/28/2009	<1	<1	P	P	None
13	S	kitchen, Rinse Sink for dishwasher	5/19/2004		2	P	8/13/2004	7		P	5/12/2006	11	3		1/28/2009	11	<1		F	PS
14	S	kitchen (LH Fixture), 3 compartment sink	5/19/2004	24	2						5/12/2006	51	4		1/28/2009	5	<1	P	P	None
14.5	S	kitchen (RH Fixture), 3 compartment sink									5/12/2006	51	6		1/28/2009	7	<1	P	P	None
14.6	B	KITCHEN, salad prep sink					8/13/2004	41	3						1/28/2009	5	<1	P	P	None
14.7	B	KITCHEN, hand wash sink					8/13/2004		2	P					1/28/2009	4	<1	P	P	None
15	S	day care kitchen					8/13/2004	7	7	P	5/12/2006	2	1	P	1/28/2009	<1	<1	P	P	None
16	S	room 110 - north sink, left					8/13/2004	5	6	P	5/12/2006	2	2	P	1/28/2009	1	<1	P	P	None
16A	S	room 110, north sink, right													1/28/2009	<1	<1	P	P	None
17	S	room 109 south sink					8/13/2004	6	6	P	5/12/2006	2	3	P	1/28/2009	1	<1	P	P	None
17A	S	room 109, south sink, right													1/28/2009	<1	<1	P	P	None
18	S	room 104					8/13/2004	3	2	P	5/12/2006	2	1	P	1/28/2009	1	2	P	P	None
19	S	room 105					8/13/2004	4	10	P	5/12/2006	2	1	P	1/28/2009	2	1	P	P	None
20	S	room 106					8/13/2004	6	2	P	5/12/2006	2	<1	P	1/28/2009	1	1	P	P	None
21	S	room 107					8/13/2004	6	2	P	5/12/2006	2	1	P	1/28/2009	3	1	P	P	None
22	S	room 108					8/13/2004	4	2	P	5/12/2006	2	1	P	1/28/2009	<1	2	P	P	None
24	S	room 204					8/13/2004	4	3	P	5/12/2006	3	2	P	1/28/2009	1	<1	P	P	None
25	S	room 205					8/13/2004	7	6	P	5/12/2006	2	1	P	1/28/2009	1	<1	P	P	None
26	S	room 206					8/13/2004	5	3	P	5/12/2006	2	<1	P	1/28/2009	1	<1	P	P	None
27	S	room 207					8/13/2004	3	3	P	5/12/2006	2	1	P	1/28/2009	1	1	P	P	None
28	S	room 208					8/13/2004	6	2	P	5/12/2006	2	1	P	1/28/2009	1	1	P	P	None
29	S	room 209					8/13/2004	9	3	P	5/12/2006	4	1	P	1/28/2009	1	<1	P	P	None
30	S	near conf room 214					8/13/2004	7	3	P	5/12/2006	6	1	P	1/28/2009	3	1	P	P	None
31	S	room 302					8/13/2004	6	2	P	5/12/2006	5	1	P	1/28/2009	1	<1	P	P	None
32	S	room 303					8/13/2004	8	2	P	5/12/2006	4	1	P	1/28/2009	2	1	P	P	None
33	S	room 304					8/13/2004	6	4	P	5/12/2006	4	1	P	1/28/2009	1	1	P	P	None
34	S	room 305					8/13/2004	6	3	P	5/12/2006	3	<1	P	1/28/2009	1	<1	P	P	None
35	S	near room 314					8/13/2004	8	3	P	5/12/2006	4	1	P	1/28/2009	1	<1	P	P	None
36	S	room 306					8/13/2004	6	9	P	5/12/2006	1	3	P	1/28/2009	<1	<1	P	P	None
37	S	room 307					8/13/2004	6	3	P	5/12/2006	4	2	P	1/28/2009	2	<1	P	P	None
38	S	room 308					8/13/2004	4	4	P	5/12/2006	3	1	P	1/28/2009	1	<1	P	P	None
39	S	room 309					8/13/2004	3	4	P	5/12/2006	2	1	P	1/28/2009	1	<1	P	P	None
40	S	room 310					8/13/2004	7	5	P	5/12/2006	3	3	P	1/28/2009	1	1	P	P	None
41	S	room 103					8/13/2004	5	3	P	5/12/2006	3	1	P	1/28/2009	<1	<1	P	P	None
42	B	1st floor hall - south side					8/13/2004	7	3	P	5/12/2006	5	1	P	1/28/2009	<1	<1	P	P	None
43	B	1st floor hall - north side					8/13/2004	9	3	P	5/12/2006	3	1	P	1/28/2009	<1	1	P	P	None
44	S	Library office, 201A													1/28/2009	2	1	P	P	None
45	S	Staff work room 101F													1/28/2009	1	1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	outside classroom 108	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
02	S	outside classroom 103	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
03	B	Childcare, classroom 110	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
04	B	Childcare, classroom 109	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
05	B	hallway near room 203, 2nd floor, S. hall	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
06	B	hallway near room 209, 2nd floor, N. hall	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
07	B	hallway near room 309, 3rd floor, N. Hall	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
08	B	hallway near room 303, 3rd floor, S. Hall	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
09	B	gym entrance	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
10	S	nurses office	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
11	S	staff lounge, room 301	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
13	S	kitchen, Rinse Sink for dishwasher					8/13/2004	<1		P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
14	S	kitchen (LH Fixture), 3 compartment sink	5/19/2004	<1	<1	P					5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
14.5	S	kitchen (RH Fixture), 3 compartment sink									5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
14.6	B	KITCHEN, salad prep sink					8/13/2004	<1	<1	P					1/28/2009	<1	<1	P	P	None
14.7	B	KITCHEN, hand wash sink					8/13/2004		<1	P					1/28/2009	<1	<1	P	P	None
15	S	day care kitchen					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
16	S	room 110 - north sink, left					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
16A	S	room 110, north sink, right													1/28/2009	<1	<1	P	P	None
17	S	room 109 south sink					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
17A	S	room 109, south sink, right													1/28/2009	<1	<1	P	P	None
18	S	room 104					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
19	S	room 105					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
20	S	room 106					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
21	S	room 107					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
22	S	room 108					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
24	S	room 204					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
25	S	room 205					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
26	S	room 206					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
27	S	room 207					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
28	S	room 208					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
29	S	room 209					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
30	S	near conf room 214					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
31	S	room 302					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
32	S	room 303					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
33	S	room 304					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
34	S	room 305					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
35	S	near room 314					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
36	S	room 306					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
37	S	room 307					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
38	S	room 308					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
39	S	room 309					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
40	S	room 310					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
41	S	room 103					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
42	B	1st floor hall - south side					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
43	B	1st floor hall - north side					8/13/2004	<1	<1	P	5/12/2006	<1	<1	P	1/28/2009	<1	<1	P	P	None
44	S	Library office, 201A													1/28/2009	<1	<1	P	P	None
45	S	Staff work room 101F													1/28/2009	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	outside classroom 108	5/19/2004	0.16		P					5/12/2006	0.422	0.143	P	1/28/2009	0.282	0.126	P	P	None
02	S	outside classroom 103	5/19/2004	0.15	0.13	P					5/12/2006	0.333	0.197	P	1/28/2009	0.255	0.156	P	P	None
03	B	Childcare, classroom 110	5/19/2004	0.19	0.14	P					5/12/2006	0.183	0.179	P	1/28/2009	0.292	0.12	P	P	None
04	B	Childcare, classroom 109	5/19/2004	0.11	0.1	P					5/12/2006	0.18	0.151	P	1/28/2009	0.165	0.145	P	P	None
05	B	hallway near room 203, 2nd floor, S. hall	5/19/2004		0.14	P					5/12/2006	0.614	0.378	P	1/28/2009	0.232	0.256	P	P	None
06	B	hallway near room 209, 2nd floor, N. hall	5/19/2004	0.15	0.14	P					5/12/2006	0.397	0.318	P	1/28/2009	0.289	0.14	P	P	None
07	B	hallway near room 309, 3rd floor, N. Hall	5/19/2004	0.16	0.15	P					5/12/2006	0.41	0.072	P	1/28/2009	0.265	0.081	P	P	None
08	B	hallway near room 303, 3rd floor, S. Hall	5/19/2004	0.13		P					5/12/2006	0.336	0.286	P	1/28/2009	0.207	0.222	P	P	None
09	B	gym entrance	5/19/2004	0.16		P					5/12/2006	0.456	0.213	P	1/28/2009	0.214	0.148	P	P	None
10	S	nurses office	5/19/2004	0.19		P					5/12/2006	0.353	0.293	P	1/28/2009	0.315	0.209	P	P	None
11	S	staff lounge, room 301	5/19/2004	0.11		P					5/12/2006	0.289	0.242	P	1/28/2009	0.255	0.207	P	P	None
13	S	kitchen, Rinse Sink for dishwasher	5/19/2004		0.14	P	8/13/2004	0.36		P	5/12/2006	0.413	0.403	P	1/28/2009	0.211	0.163	P	P	None
14	S	kitchen (LH Fixture), 3 compartment sink	5/19/2004	0.17		P					5/12/2006	0.283	0.401	P	1/28/2009	0.264	0.139	P	P	None
14.5	S	kitchen (RH Fixture), 3 compartment sink									5/12/2006	0.231	0.441	P	1/28/2009	0.277	0.13	P	P	None
14.6	B	KITCHEN, salad prep sink					8/13/2004	0.28		P					1/28/2009	0.237	0.165	P	P	None
14.7	B	KITCHEN, hand wash sink													1/28/2009	0.222	0.171	P	P	None
15	S	day care kitchen					8/13/2004	0.18		P	5/12/2006	0.22	0.28	P	1/28/2009	0.214	0.151	P	P	None
16	S	room 110 - north sink, left					8/13/2004	0.19	0.19	P	5/12/2006	0.152	0.157	P	1/28/2009	0.237	0.138	P	P	None
16A	S	room 110, north sink, right													1/28/2009	0.178	0.126	P	P	None
17	S	room 109 south sink					8/13/2004	0.18	0.18	P	5/12/2006	0.204	0.18	P	1/28/2009	0.218	0.149	P	P	None
17A	S	room 109, south sink, right													1/28/2009	0.228	0.146	P	P	None
18	S	room 104									5/12/2006	0.256	0.163	P	1/28/2009	0.322	0.206	P	P	None
19	S	room 105									5/12/2006	0.24	0.233	P	1/28/2009	0.313	0.22	P	P	None
20	S	room 106									5/12/2006	0.28	0.204	P	1/28/2009	0.277	0.301	P	P	None
21	S	room 107					8/13/2004	0.17		P	5/12/2006	0.251	0.16	P	1/28/2009	0.228	0.136	P	P	None
22	S	room 108					8/13/2004	0.14		P	5/12/2006	0.249	0.201	P	1/28/2009	0.162	0.11	P	P	None
24	S	room 204					8/13/2004	0.13		P	5/12/2006	0.391	0.206	P	1/28/2009	0.229	0.173	P	P	None
25	S	room 205									5/12/2006	0.289	0.24	P	1/28/2009	0.283	0.238	P	P	None
26	S	room 206					8/13/2004	0.18		P	5/12/2006	0.275	0.223	P	1/28/2009	0.262	0.213	P	P	None
27	S	room 207					8/13/2004	0.16		P	5/12/2006	0.24	0.184	P	1/28/2009	0.24	0.167	P	P	None
28	S	room 208									5/12/2006	0.36	0.196	P	1/28/2009	0.237	0.159	P	P	None
29	S	room 209									5/12/2006	0.407	0.257	P	1/28/2009	0.263	0.214	P	P	None
30	S	near conf room 214					8/13/2004	0.19		P	5/12/2006	0.238	0.158	P	1/28/2009	0.304	0.142	P	P	None
31	S	room 302					8/13/2004	0.16		P	5/12/2006	0.378	0.34	P	1/28/2009	0.244	0.277	P	P	None
32	S	room 303									5/12/2006	0.424	0.236	P	1/28/2009	0.312	0.148	P	P	None
33	S	room 304					8/13/2004	0.18		P	5/12/2006	0.295	0.205	P	1/28/2009	0.215	0.187	P	P	None
34	S	room 305									5/12/2006	0.277	0.233	P	1/28/2009	0.238	0.312	P	P	None
35	S	near room 314					8/13/2004	0.15		P	5/12/2006	0.266	0.17	P	1/28/2009	0.348	0.181	P	P	None
36	S	room 306									5/12/2006	0.367	0.208	P	1/28/2009	0.246	0.277	P	P	None
37	S	room 307					8/13/2004	0.19		P	5/12/2006	0.409	0.192	P	1/28/2009	0.271	0.052	P	P	None
38	S	room 308					8/13/2004	0.15	0.084	P	5/12/2006	0.241	0.047	P	1/28/2009	0.214	0.037	P	P	None
39	S	room 309					8/13/2004	0.19	0.18	P	5/12/2006	0.146	0.076	P	1/28/2009	0.277	0.142	P	P	None
40	S	room 310					8/13/2004	0.16	0.16	P	5/12/2006	0.243	0.144	P	1/28/2009	0.212	0.171	P	P	None
41	S	room 103					8/13/2004	0.19		P	5/12/2006	0.27	0.198	P	1/28/2009	0.192	0.203	P	P	None
42	B	1st floor hall - south side					8/13/2004	0.18		P	5/12/2006	0.306	0.172	P	1/28/2009	0.306	0.247	P	P	None
43	B	1st floor hall - north side									5/12/2006	0.267	0.161	P	1/28/2009	0.279	0.142	P	P	None
44	S	Library office, 201A													1/28/2009	0.282	0.208	P	P	None
45	S	Staff work room 101F													1/28/2009	0.281	0.169	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Pass/Fail	Status
01	S	outside classroom 108	5/19/2004	0.06		P									P	None
02	S	outside classroom 103														
03	B	Childcare, classroom 110														
04	B	Childcare, classroom 109														
05	B	hallway near room 203, 2nd floor, S. hall														
06	B	hallway near room 209, 2nd floor, N. hall														
07	B	hallway near room 309, 3rd floor, N. Hall														
08	B	hallway near room 303, 3rd floor, S. Hall	5/19/2004	<0.05		P									P	None
09	B	gym entrance	5/19/2004	<0.05		P									P	None
10	S	nurses office	5/19/2004	0.05		P					1/28/2009		0.051	P	P	None
11	S	staff lounge, room 301	5/19/2004	0.05		P									P	None
13	S	kitchen, Rinse Sink for dishwasher	5/19/2004		0.07	P	8/13/2004	0.06		P					P	None
14	S	kitchen (LH Fixture), 3 compartment sink	5/19/2004	0.06		P									P	None
14.5	S	kitchen (RH Fixture), 3 compartment sink														
14.6	B	KITCHEN, salad prep sink					8/13/2004	0.07		P	1/28/2009		0.127	P	P	None
14.7	B	KITCHEN, hand wash sink														
15	S	day care kitchen														
16	S	room 110 - north sink, left														
16A	S	room 110, north sink, right														
17	S	room 109 south sink														
17A	S	room 109, south sink, right														
18	S	room 104														
19	S	room 105														
20	S	room 106									1/28/2009		0.071	P	P	None
21	S	room 107														
22	S	room 108														
24	S	room 204														
25	S	room 205														
26	S	room 206									1/28/2009		0.065	P	P	None
27	S	room 207														
28	S	room 208														
29	S	room 209														
30	S	near conf room 214														
31	S	room 302														
32	S	room 303														
33	S	room 304														
34	S	room 305									1/28/2009		0.069	P	P	None
35	S	near room 314														
36	S	room 306														
37	S	room 307														
38	S	room 308														
39	S	room 309														
40	S	room 310									1/28/2009		0.065	P	P	None
41	S	room 103														
42	B	1st floor hall - south side														
43	B	1st floor hall - north side														
44	S	Library office, 201A									1/28/2009		0.065	P	P	None
45	S	Staff work room 101F														

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	outside S. Wall Boiler room	Arsenic	28-Jan-09	2 ppb	P
00	SE	outside S. Wall Boiler room	Cadmium	28-Jan-09	1 ppb	P
00	SE	outside S. Wall Boiler room	Copper	28-Jan-09	0.016 ppm	P
00	SE	outside S. Wall Boiler room	Iron	28-Jan-09	0.08 ppm	P
00	SE	outside S. Wall Boiler room	Lead	28-Jan-09	1 ppb	P
00	SE	outside S. Wall Boiler room	Total Coliforms	28-Jan-09	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.