

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
Adams Elementary**

Updated September 25, 2019

General Information:

Plumbing piping materials: mainly galvanized steel and copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria:

All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2021-2022.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

| Symbol | Definition |
|------------|--|
| SE | service entry (main) |
| B | bubbler |
| S | sink (faucet) |
| B/S | sink/bubbler combination |
| S/B | sink/bubbler combination |
| ppb | parts per billion |
| ppm | parts per million |
| NA | not applicable |
| None | no action required |
| Unk | unknown status or action |
| Sample | sample needs to be taken |
| Re-test | fixture needs to be resampled |
| Conf | resample to confirm measurement |
| No flush | not flushed before sampling |
| Sink | sampled faucet of S/B combo |
| Used | recently used; no 1st draw sample possible |
| PS | post sign |
| Disable(d) | fixture disabled in response to water quality testing |
| BDSS | Bubbler disabled, sign on sink |
| IF | install filter |
| RB | replace bubbler |
| RB/IF | replace bubbler and/or install filter |
| RF | replace faucet |
| RF/IF | replace faucet and/or install filter |
| BW | disable fixture and provide bottled water until remediated |
| Leaks | leaking fixture |
| NW | not working properly (sample S when B of S/B NW) |
| OS | out of service - disabled until fixed |
| RS | return to service - now passes testing |
| Rem | Removed from system - no longer exists |

Table 1. Summary of Results

| FIXTURE INFORMATION | | | CURRENT STATUS | | | | | | | | OK? |
|---------------------|------|---|----------------|--------|-----------|--------|-----------|--------|-----------|--------|---------------|
| | | | LEAD | | CADMIUM | | COPPER | | IRON | | |
| Fixture ID | Type | Location | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Yes/No/Status |
| 01 | B | hallway | P | None | P | None | P | None | P | None | Yes |
| 02 | B | hallway, outside gym | P | None | P | None | P | None | P | None | Yes |
| 04 | S/B | room 211 | P | None | P | None | P | None | P | None | Yes |
| 05 | S/B | room 210 | P | None | P | None | P | None | P | None | Yes |
| 06 | S/B | room 213 | P | None | P | None | P | None | P | None | Yes |
| 07 | S/B | room 212 | P | None | P | None | P | None | P | None | Yes |
| 08 | B | hallway | P | None | P | None | P | None | P | None | Yes |
| 09 | S/B | room 209 | P | None | P | None | P | None | P | None | Yes |
| 10 | S/B | room 208 | P | None | P | None | P | None | P | None | Yes |
| 11 | S/B | room 207 | P | None | P | None | P | None | P | None | Yes |
| 12 | S/B | room 206 | P | None | P | None | P | None | P | None | Yes |
| 13 | S/B | room 205 | P | None | P | None | P | None | P | None | Yes |
| 14 | S/B | room 204 | P | None | P | None | P | None | P | None | Yes |
| 15 | S/B | room 203 | P | None | P | None | P | None | P | None | Yes |
| 16 | S/B | room 202 | P | None | P | None | P | None | P | None | Yes |
| 17 | S/B | room 201 | P | None | P | None | P | None | P | None | Yes |
| 18 | B | hallway, outside library | P | None | P | None | P | None | P | None | Yes |
| 19 | S/B | room 109 | P | None | P | None | P | None | P | None | Yes |
| 20 | S/B | room 108 | P | None | P | None | P | None | P | None | Yes |
| 21 | S/B | room 107 | P | None | P | None | P | None | P | None | Yes |
| 22 | S/B | room 106 | P | None | P | None | P | None | P | None | Yes |
| 23 | S/B | room 105 | P | None | P | None | P | None | P | None | Yes |
| 24 | S/B | room 104 | P | None | P | None | P | None | P | None | Yes |
| 25 | S/B | room 103 | P | None | P | None | P | None | P | None | Yes |
| 26 | S/B | room 102 | P | None | P | None | P | None | P | None | Yes |
| 27 | S/B | room 101 | P | None | P | None | P | None | P | None | Yes |
| 36 | S | nurses office | P | None | P | None | P | None | P | None | Yes |
| 37 | S | kitchen - pr | P | None | P | None | P | None | P | None | Yes |
| 38 | S | teachers lounge | P | None | P | None | P | None | P | None | Yes |
| 39 | S | kitchen sink, SE corner, left side | P | None | P | None | P | None | P | None | Yes |
| 40 | S | kitchen sink, to the right of 39 | P | None | P | None | P | None | P | None | Yes |
| 42 | S | room 214 | P | None | P | None | P | None | P | None | Yes |
| 43 | S/B | office | P | None | P | None | P | None | | | Yes |
| 44 | B | hallway, outside library, bottle filler | P | None | P | None | P | None | | | Yes |

Table 2. Lead Test Results

| Test Results (Lead/Pb, ppb) | | | | | | | | | | | | | | | | | | | |
|-----------------------------|------|---|-----------|-----------|-----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| FIXTURE INFORMATION | | | 1/14/2009 | | | 2/2/2012 | | | 5/20/2015 | | | 1/31/2019 | | | 8/31/2019 | | | Summary Status | |
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway | 2 | 1 | P | 1 | <1 | P | 2 | 2 | P | 1 | <1 | P | | | | P | None |
| 02 | B | hallway, outside gym | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 04 | S/B | room 211 | 2 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 05 | S/B | room 210 | <1 | <1 | P | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 06 | S/B | room 213 | 2 | <1 | P | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 07 | S/B | room 212 | 2 | <1 | P | <1 | <1 | P | 1 | <1 | P | <1 | <1 | P | | | | P | None |
| 08 | B | hallway | <1 | <1 | P | 2 | 2 | P | 2 | 2 | P | 1 | <1 | P | | | | P | None |
| 09 | S/B | room 209 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 10 | S/B | room 208 | 1 | <1 | P | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 11 | S/B | room 207 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 12 | S/B | room 206 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 13 | S/B | room 205 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 14 | S/B | room 204 | 2 | <1 | P | 2 | <1 | P | 1 | <1 | P | <1 | <1 | P | | | | P | None |
| 15 | S/B | room 203 | 1 | <1 | P | 1 | 1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 16 | S/B | room 202 | 2 | <1 | P | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 17 | S/B | room 201 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 18 | B | hallway, outside library | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 19 | S/B | room 109 | 3 | <1 | P | 4 | <1 | P | 2 | <1 | P | 2 | <1 | P | | | | P | None |
| 20 | S/B | room 108 | <1 | <1 | P | 2 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 21 | S/B | room 107 | <1 | <1 | P | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 22 | S/B | room 106 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 23 | S/B | room 105 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 24 | S/B | room 104 | 2 | <1 | P | <1 | <1 | P | <1 | 2 | P | <1 | 2 | P | | | | P | None |
| 25 | S/B | room 103 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 26 | S/B | room 102 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 27 | S/B | room 101 | <1 | <1 | P | 1 | <1 | P | 1 | <1 | P | 1 | <1 | P | | | | P | None |
| 36 | S | nurses office | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 37 | S | kitchen - pr | 3 | <1 | P | 4 | <1 | P | 1 | <1 | P | <1 | <1 | P | | | | P | None |
| 38 | S | teachers lounge | <1 | <1 | P | <1 | <1 | P | 1 | <1 | P | <1 | <1 | P | | | | P | None |
| 39 | S | kitchen sink, SE corner, left side | 5 | <1 | P | 5 | <1 | P | 5 | <1 | P | 4 | <1 | P | | | | P | None |
| 40 | S | kitchen sink, to the right of 39 | 3 | <1 | P | 4 | <1 | P | <1 | <1 | P | 5 | <1 | P | | | | P | None |
| 42 | S | room 214 | 14 | 1 | | 20 | 2 | | 17 | 2 | | 3 | 2 | P | <1 | <1 | P | P | None |
| 43 | S/B | office | | | | | | | | | | <1 | <1 | P | | | | P | None |
| 44 | B | hallway, outside library, bottle filler | | | | | | | | | | <1 | <1 | P | | | | P | None |

Table 3. Cadmium Test Results

| Test Results (Cadmium/Cd, ppb) | | | | | | | | | | | | | | | | |
|--------------------------------|------|---|-----------|-----------|-----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| FIXTURE INFORMATION | | | 1/14/2009 | | | 2/2/2012 | | | 5/20/2015 | | | 1/31/2019 | | | Summary Status | |
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 02 | B | hallway, outside gym | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 04 | S/B | room 211 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 05 | S/B | room 210 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 06 | S/B | room 213 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 07 | S/B | room 212 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 08 | B | hallway | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 09 | S/B | room 209 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 10 | S/B | room 208 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 11 | S/B | room 207 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 12 | S/B | room 206 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 13 | S/B | room 205 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 14 | S/B | room 204 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 15 | S/B | room 203 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 16 | S/B | room 202 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 17 | S/B | room 201 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 18 | B | hallway, outside library | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 19 | S/B | room 109 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 20 | S/B | room 108 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 21 | S/B | room 107 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 22 | S/B | room 106 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 23 | S/B | room 105 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 24 | S/B | room 104 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 25 | S/B | room 103 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 26 | S/B | room 102 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 27 | S/B | room 101 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 36 | S | nurses office | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 37 | S | kitchen - pr | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 38 | S | teachers lounge | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 39 | S | kitchen sink, SE corner, left side | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 40 | S | kitchen sink, to the right of 39 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 42 | S | room 214 | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 43 | S/B | office | | | | | | | | | | <1 | <1 | P | P | None |
| 44 | B | hallway, outside library, bottle filler | | | | | | | | | | <1 | <1 | P | P | None |

Table 4. Copper Test Results

| Test Results (Copper/Cu, ppm) | | | | | | | | | | | | | | | | |
|-------------------------------|------|---|-----------|-----------|-----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| FIXTURE INFORMATION | | | 1/14/2009 | | | 2/2/2012 | | | 5/20/2015 | | | 1/31/2019 | | | Summary Status | |
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway | 0.006 | 0.002 | P | 0.027 | 0.003 | P | 0.034 | 0.005 | P | 0.028 | 0.003 | P | P | None |
| 02 | B | hallway, outside gym | 0.137 | 0.1 | P | 0.097 | 0.119 | P | 0.101 | 0.107 | P | 0.163 | 0.149 | P | P | None |
| 04 | S/B | room 211 | 0.1 | 0.072 | P | 0.059 | 0.054 | P | 0.046 | 0.061 | P | 0.063 | 0.058 | P | P | None |
| 05 | S/B | room 210 | 0.141 | 0.11 | P | 0.066 | 0.05 | P | 0.064 | 0.059 | P | 0.081 | 0.064 | P | P | None |
| 06 | S/B | room 213 | 0.176 | 0.15 | P | 0.105 | 0.107 | P | 0.133 | 0.124 | P | 0.1 | 0.081 | P | P | None |
| 07 | S/B | room 212 | 0.191 | 0.22 | P | 0.111 | 0.118 | P | 0.012 | 0.122 | P | 0.087 | 0.097 | P | P | None |
| 08 | B | hallway | 0.056 | 0.059 | P | 0.008 | 0.027 | P | 0.008 | 0.009 | P | 0.005 | 0.006 | P | P | None |
| 09 | S/B | room 209 | 0.105 | 0.079 | P | 0.07 | 0.068 | P | 0.065 | 0.06 | P | 0.058 | 0.028 | P | P | None |
| 10 | S/B | room 208 | 0.15 | 0.122 | P | 0.099 | 0.101 | P | 0.098 | 0.082 | P | 0.081 | 0.062 | P | P | None |
| 11 | S/B | room 207 | 0.122 | 0.063 | P | 0.084 | 0.071 | P | 0.059 | 0.036 | P | 0.05 | 0.044 | P | P | None |
| 12 | S/B | room 206 | 0.134 | 0.06 | P | 0.077 | 0.07 | P | 0.063 | 0.054 | P | 0.055 | 0.046 | P | P | None |
| 13 | S/B | room 205 | 0.154 | 0.083 | P | 0.085 | 0.084 | P | 0.084 | 0.061 | P | 0.006 | 0.043 | P | P | None |
| 14 | S/B | room 204 | 0.114 | 0.047 | P | 0.074 | 0.08 | P | 0.051 | 0.028 | P | 0.043 | 0.033 | P | P | None |
| 15 | S/B | room 203 | 0.135 | 0.079 | P | 0.082 | 0.077 | P | 0.061 | 0.043 | P | 0.047 | 0.03 | P | P | None |
| 16 | S/B | room 202 | 0.133 | 0.101 | P | 0.092 | 0.093 | P | 0.094 | 0.083 | P | 0.067 | 0.058 | P | P | None |
| 17 | S/B | room 201 | 0.143 | 0.109 | P | 0.096 | 0.09 | P | 0.098 | 0.085 | P | 0.08 | 0.068 | P | P | None |
| 18 | B | hallway, outside library | 0.098 | 0.093 | P | 0.08 | 0.057 | P | 0.062 | 0.05 | P | 0.055 | 0.052 | P | P | None |
| 19 | S/B | room 109 | 0.13 | 0.123 | P | 0.125 | 0.068 | P | 0.075 | 0.072 | P | 0.072 | 0.072 | P | P | None |
| 20 | S/B | room 108 | 0.174 | 0.177 | P | 0.116 | 0.102 | P | 0.079 | 0.102 | P | 0.084 | 0.075 | P | P | None |
| 21 | S/B | room 107 | 0.174 | 0.116 | P | 0.094 | 0.054 | P | 0.075 | 0.077 | P | 0.056 | 0.064 | P | P | None |
| 22 | S/B | room 106 | 0.139 | 0.097 | P | 0.084 | 0.069 | P | 0.065 | 0.054 | P | 0.051 | 0.05 | P | P | None |
| 23 | S/B | room 105 | 0.168 | 0.144 | P | 0.098 | 0.089 | P | 0.081 | 0.087 | P | 0.065 | 0.069 | P | P | None |
| 24 | S/B | room 104 | 0.154 | 0.112 | P | 0.094 | 0.049 | P | 0.079 | 0.074 | P | 0.061 | 0.051 | P | P | None |
| 25 | S/B | room 103 | 0.134 | 0.095 | P | 0.09 | 0.072 | P | 0.074 | 0.073 | P | 0.054 | 0.053 | P | P | None |
| 26 | S/B | room 102 | 0.178 | 0.152 | P | 0.11 | 0.071 | P | 0.104 | 0.11 | P | 0.098 | 0.082 | P | P | None |
| 27 | S/B | room 101 | 0.154 | 0.166 | P | 0.099 | 0.096 | P | 0.108 | 0.107 | P | 0.088 | 0.089 | P | P | None |
| 36 | S | nurses office | 0.023 | 0.017 | P | 0.014 | 0.005 | P | 0.019 | 0.004 | P | 0.004 | 0.003 | P | P | None |
| 37 | S | kitchen - pr | 0.098 | 0.012 | P | 0.081 | 0.046 | P | 0.061 | 0.069 | P | 0.075 | 0.066 | P | P | None |
| 38 | S | teachers lounge | 0.01 | 0.008 | P | 0.006 | 0.006 | P | 0.007 | 0.007 | P | 0.005 | 0.008 | P | P | None |
| 39 | S | kitchen sink, SE corner, left side | 0.096 | 0.009 | P | 0.088 | 0.016 | P | 0.063 | 0.031 | P | 0.062 | 0.036 | P | P | None |
| 40 | S | kitchen sink, to the right of 39 | 0.124 | 0.011 | P | 0.116 | 0.014 | P | 0.042 | 0.033 | P | 0.088 | 0.031 | P | P | None |
| 42 | S | room 214 | 0.078 | 0.01 | P | 0.068 | 0.109 | P | 0.09 | 0.056 | P | 0.116 | 0.037 | P | P | None |
| 43 | S/B | office | | | | | | | | | | 0.012 | <0.002 | P | P | None |
| 44 | B | hallway, outside library, bottle filler | | | | | | | | | | 0.059 | 0.05 | P | P | None |

Table 5. Iron Test Results

| Test Results (Iron/Fe, ppm) | | | | | | | | | | | | | | |
|-----------------------------|------|---|-----------|-----------|-----------|-----------|----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| FIXTURE INFORMATION | | | 3/14/2007 | | 1/14/2009 | | 2/2/2012 | | 5/20/2015 | | 1/31/2019 | | Summary Status | |
| Fixture ID | Type | Location | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway | | | | | | | | | | | P | None |
| 02 | B | hallway, outside gym | 0.118 | P | | | | | | | | | P | RS |
| 04 | S/B | room 211 | | | | | 0.05 | P | <0.05 | P | | | P | None |
| 05 | S/B | room 210 | | | | | | | | | <0.05 | P | P | None |
| 06 | S/B | room 213 | | | | | | | | | | | P | None |
| 07 | S/B | room 212 | | | | | | | | | | | P | None |
| 08 | B | hallway | | | | | | | | | | | P | None |
| 09 | S/B | room 209 | | | 0.128 | P | | | | | | | P | None |
| 10 | S/B | room 208 | | | | | | | | | | | P | None |
| 11 | S/B | room 207 | | | | | | | | | | | P | None |
| 12 | S/B | room 206 | | | | | | | | | | | P | None |
| 13 | S/B | room 205 | | | | | | | | | | | P | None |
| 14 | S/B | room 204 | | | | | | | | | <0.05 | P | P | None |
| 15 | S/B | room 203 | | | | | | | | | | | P | None |
| 16 | S/B | room 202 | | | | | <0.05 | P | | | | | P | None |
| 17 | S/B | room 201 | | | 0.055 | P | | | | | | | P | None |
| 18 | B | hallway, outside library | | | | | | | <0.05 | P | | | P | None |
| 19 | S/B | room 109 | | | 0.213 | P | | | | | 0.063 | P | P | None |
| 20 | S/B | room 108 | | | | | <0.05 | P | | | | | P | None |
| 21 | S/B | room 107 | | | | | | | | | | | P | None |
| 22 | S/B | room 106 | | | | | | | | | | | P | None |
| 23 | S/B | room 105 | | | | | | | | | | | P | None |
| 24 | S/B | room 104 | | | | | | | | | | | P | None |
| 25 | S/B | room 103 | | | | | | | | | | | P | None |
| 26 | S/B | room 102 | | | | | <0.05 | P | | | | | P | None |
| 27 | S/B | room 101 | | | 0.061 | P | | | <0.05 | P | | | P | None |
| 36 | S | nurses office | | | | | | | | | <0.05 | P | P | None |
| 37 | S | kitchen - pr | | | | | | | | | | | P | None |
| 38 | S | teachers lounge | | | | | | | | | | | P | None |
| 39 | S | kitchen sink, SE corner, left side | | | 0.073 | P | 0.074 | P | | | | | P | None |
| 40 | S | kitchen sink, to the right of 39 | | | | | | | | | | | P | None |
| 42 | S | room 214 | | | | | | | | | 0.05 | P | P | None |
| 43 | S/B | office | | | | | | | | | | | | |
| 44 | B | hallway, outside library, bottle filler | | | | | | | | | | | | |

Table 6. Service Entry Test Results

| Test Results (Service Entry/SE, Units as Shown) | | | | | | |
|---|------|-------------------------------------|----------------------|-----------|-------------|-----------|
| SOURCE INFORMATION | | | Most Recent Sampling | | | |
| Fixture ID | Type | Location | Item | Sampled | Max Value | Pass/Fail |
| 00 | SE | exterior - north wall - boiler room | Arsenic | 31-Jan-19 | 2 ppb | P |
| 00 | SE | exterior - north wall - boiler room | Cadmium | 31-Jan-19 | 1 ppb | P |
| 00 | SE | exterior - north wall - boiler room | Chlorine | 01-Apr-04 | 0.1 ppm | P |
| 00 | SE | exterior - north wall - boiler room | Copper | 31-Jan-19 | 0.048 ppm | P |
| 00 | SE | exterior - north wall - boiler room | E coli | 01-Apr-04 | <1 Colonies | P |
| 00 | SE | exterior - north wall - boiler room | Iron | 31-Jan-19 | <0.05 ppm | P |
| 00 | SE | exterior - north wall - boiler room | Lead | 31-Jan-19 | 1 ppb | P |
| 00 | SE | exterior - north wall - boiler room | Total Coliforms | 01-Apr-04 | <1 Colonies | P |

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.