

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
For
Ballard High School**

Updated September 2, 2019

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria:

All sources meet the policy criteria,

Follow-up monitoring: Will be performed in school year 2021-2022.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	hallway, first floor, SW,	P	None	P	None	P	None	P	None	Yes
02	BF	hallway, first floor, SW,	P	None	P	None	P	None	P	None	Yes
03	B	hallway, first floor, South, left	P	None	P	None	P	None	P	None	Yes
04	B	hallway, first floor, South, left	P	None	P	None	P	None			Yes
05	B	commons, left	P	None	P	None	P	None			Yes
06	B	commons, right	P	None	P	None	P	None			Yes
07	B	hallway, first floor, by gym, left	P	None	P	None	P	None			Yes
08	B	hallway, first floor, by gym, right	P	None	P	None	P	None			Yes
09	B	corridor near men's locker room, first floor, left	P	None	P	None	P	None	P	None	Yes
10	B	corridor near men's locker room, first floor, right	P	None	P	None	P	None	P	None	Yes
11	B	near 218,	P	None	P	None	P	None	P	None	Yes
12	BF	near 217,	P	None	P	None	P	None			Yes
13	B	near 209, left	P	None	P	None	P	None			Yes
14	B	near 209, right	P	None	P	None	P	None			Yes
15	B	231 gym	P	None	P	None	P	None	P	None	Yes
16	B	232 gym	P	None	P	None	P	None			Yes
17	B	233 gym	P	None	P	None	P	None			Yes
18	B	233 gym	P	None	P	None	P	None	P	None	Yes
21	B	233 gym	P	None	P	None	P	None			Yes
22	B	233 gym	P	None	P	None	P	None	P	None	Yes
27	S	staff lounge. SE201	P	None	P	None	P	None	P	None	Yes
28	S	nurse's office	P	None	P	None	P	None	P	None	Yes
29	S	kitchen - single sink	P	None	P	None	P	None	P	None	Yes
30	S	kitchen - office	P	None	P	None	P	None	P	None	Yes
31	S	Home Ec, room 220	P	None	P	None	P	None	P	None	Yes
32	S	Home Ec, room 220	P	None	P	None	P	None	P	None	Yes
34	S	Home Ec, room 220	P	None	P	None	P	None	P	None	Yes
35	S	Home Ec, room 220	P	None	P	None	P	None			Yes
36	S	Home Ec, room 220	P	None	P	None	P	None			Yes
37	S	Home Ec, room 220	P	None	P	None	P	None			Yes
38	S	Home Ec, room 220	P	None	P	None	P	None			Yes
40	S	Custodian lunch room NE120	P	None	P	None	P	None			Yes
41	S	teen Health center	P	None	P	None	P	None			Yes
42	S	teen Health center, SE122	P	None	P	None	P	None			Yes
43	S	teen Health center, Janna	P	None	P	None	P	None			Yes
44	S	student store	P	None	P	None	P	None			Yes
45	S	student store	P	None	P	None	P	None			Yes
46	S	main office workroom SE126	P	None	P	None	P	None			Yes
47	S	SW209	P	None	P	None	P	None	P	None	Yes
48	S	SW209	P	None	P	None	P	None			Yes
52	S	N205 library office	P	None	P	None	P	None	P	None	Yes
53	B	2nd floor, SE, left	P	None	P	None	P	None			Yes
54	B	2nd floor, SE, right	P	None	P	None	P	None			Yes
55	S	1st floor, training room	P	None	P	None	P	None			Yes
56	S	Kitchen, double faucets sink -- left	P	None	P	None	P	None			Yes
57	S	Kitchen, double faucets sink -- right	P	None	P	None	P	None			Yes
58	K	kitchen -- kettle	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			4/4/2009			2/23/2012			4/15/2015			8/20/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	hallway, first floor, SW,	<1	<1	P	2	1	P	2	2	P	1	1	P	P	None
02	BF	hallway, first floor, SW,	<1	<1	P	1	1	P	2	2	P	1	1	P	P	None
03	B	hallway, first floor, South, left	<1	<1	P	1	2	P	2	2	P	1	1	P	P	None
04	B	hallway, first floor, South, left	<1	<1	P	1	2	P	2	2	P	1	1	P	P	None
05	B	commons, left	<1	<1	P	<1	<1	P	1	2	P	<1	<1	P	P	None
06	B	commons, right	<1	<1	P	<1	<1	P	1	1	P	<1	<1	P	P	None
07	B	hallway, first floor, by gym, left	<1	<1	P	<1	<1	P	1	1	P	<1	<1	P	P	None
08	B	hallway, first floor, by gym, right	<1	<1	P	<1	1	P	<1	<1	P	<1	<1	P	P	None
09	B	corridor near men's locker room, first floor, left	<1	<1	P	1	2	P	<1	<1	P	<1	<1	P	P	None
10	B	corridor near men's locker room, first floor, right	<1	<1	P	<1	1	P	<1	<1	P	<1	<1	P	P	None
11	B	near 218,	<1	<1	P	2	2	P	3	2	P	1	1	P	P	None
12	BF	near 217,	<1	<1	P	2	2	P	1	2	P	1	1	P	P	None
13	B	near 209, left	<1	<1	P	1	1	P	1	1	P	<1	<1	P	P	None
14	B	near 209, right	<1	<1	P	<1	1	P	2	2	P	<1	<1	P	P	None
15	B	231 gym	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	B	232 gym	<1	<1	P	<1	<1	P	1	<1	P	<1	<1	P	P	None
17	B	233 gym	1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
18	B	233 gym	<1	<1	P	<1	<1	P	<1	<1	P	1	<1	P	P	None
21	B	233 gym				6	1	P	2	<1	P	<1	<1	P	P	None
22	B	233 gym				1	<1	P	1	<1	P	<1	<1	P	P	None
27	S	staff lounge. SE201	<1	<1	P	1	<1	P	1	2	P	<1	<1	P	P	None
28	S	nurse's office	<1	<1	P	<1	<1	P							P	None
29	S	kitchen - single sink	<1	<1	P	1	<1	P	1	<1	P	<1	<1	P	P	None
30	S	kitchen - office	<1	<1	P	<1	1	P				<1	<1	P	P	None
31	S	Home Ec, room 220	1	<1	P	1	<1	P	<1	<1	P	2	<1	P	P	None
32	S	Home Ec, room 220	1	<1	P	1	<1	P	<1	<1	P	1	<1	P	P	None
34	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
35	S	Home Ec, room 220	<1	<1	P	1	<1	P	<1	<1	P	1	1	P	P	None
36	S	Home Ec, room 220	1	<1	P	1	<1	P	<1	<1	P	1	<1	P	P	None
37	S	Home Ec, room 220	<1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
38	S	Home Ec, room 220	2	<1	P	2	<1	P	1	9	P	<1	<1	P	P	None
40	S	Custodian lunch room NE120	<1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
41	S	teen Health center	1	<1	P	2	2	P							P	None
42	S	teen Health center, SE122	<1	<1	P	<1	1	P							P	None
43	S	teen Health center, Janna	1	<1	P	<1	1	P							P	None
44	S	student store	<1	<1	P	<1	<1	P							P	None
45	S	student store	1	1	P	2	<1	P							P	None
46	S	main office workroom SE126	<1	<1	P	<1	<1	P				<1	<1	P	P	None
47	S	SW209	2	1	P	3	2	P							P	None
48	S	SW209	<1	<1	P	2	1	P							P	None
52	S	N205 library office	<1	<1	P				1	1	P	<1	<1	P	P	None
53	B	2nd floor, SE, left	1	<1	P	2	1	P	2	2	P	1	<1	P	P	None
54	B	2nd floor, SE, right	<1	<1	P				2	2	P	<1	<1	P	P	None
55	S	1st floor, training room	<1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
56	S	Kitchen, double faucets sink -- left	16	<1		7	1	P	8	<1	P	<1	<1	P	P	None
57	S	Kitchen, double faucets sink -- right	1	<1	P	9	1	P	17	<1		1	1	P	P	None
58	K	kitchen -- kettle				15	3		4	<1	P	<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			4/4/2009			2/23/2012			4/15/2015			8/20/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	hallway, first floor, SW,	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
02	BF	hallway, first floor, SW,	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
03	B	hallway, first floor, South, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
04	B	hallway, first floor, South, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
05	B	commons, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
06	B	commons, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
07	B	hallway, first floor, by gym, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
08	B	hallway, first floor, by gym, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
09	B	corridor near men's locker room, first floor, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
10	B	corridor near men's locker room, first floor, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
11	B	near 218,	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
12	BF	near 217,	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
13	B	near 209, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
14	B	near 209, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
15	B	231 gym	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	B	232 gym	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
17	B	233 gym	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
18	B	233 gym	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
21	B	233 gym				<1	<1	P	<1	<1	P	<1	<1	P	P	None
22	B	233 gym				<1	<1	P	<1	<1	P	<1	<1	P	P	None
27	S	staff lounge. SE201	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
28	S	nurse's office	<1	<1	P	<1	<1	P							P	None
29	S	kitchen - single sink	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
30	S	kitchen - office	<1	<1	P	<1	<1	P				<1	<1	P	P	None
31	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
32	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
34	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
35	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
36	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
37	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
38	S	Home Ec, room 220	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
40	S	Custodian lunch room NE120	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
41	S	teen Health center	<1	<1	P	<1	<1	P							P	None
42	S	teen Health center, SE122	<1	<1	P	<1	<1	P							P	None
43	S	teen Health center, Janna	<1	<1	P	<1	<1	P							P	None
44	S	student store	<1	<1	P	<1	<1	P							P	None
45	S	student store	<1	<1	P	<1	<1	P							P	None
46	S	main office workroom SE126	<1	<1	P	<1	<1	P				<1	<1	P	P	None
47	S	SW209	<1	<1	P	<1	<1	P							P	None
48	S	SW209	<1	<1	P	<1	<1	P							P	None
52	S	N205 library office	<1	<1	P				<1	<1	P	<1	<1	P	P	None
53	B	2nd floor, SE, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
54	B	2nd floor, SE, right	<1	<1	P				<1	<1	P	<1	<1	P	P	None
55	S	1st floor, training room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
56	S	Kitchen, double faucets sink -- left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
57	S	Kitchen, double faucets sink -- right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
58	K	kitchen -- kettle				<1	<1	P	<1	<1	P	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			4/4/2009			2/23/2012			4/15/2015			8/20/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	hallway, first floor, SW,	0.054	0.034	P	0.516	0.529	P	0.38	0.373	P	0.403	0.344	P	P	None
02	BF	hallway, first floor, SW,	0.049	0.034	P	0.504	0.538	P	0.374	0.372	P	0.378	0.367	P	P	None
03	B	hallway, first floor, South, left	0.105	0.109	P	0.422	0.472	P	0.35	0.346	P	0.289	0.299	P	P	None
04	B	hallway, first floor, South, left	0.178	0.101	P	0.444	0.482	P	0.341	0.353	P	0.303	0.304	P	P	None
05	B	commons, left	0.174	0.162	P	0.476	0.477	P	0.599	0.442	P	0.29	0.286	P	P	None
06	B	commons, right	0.189	0.19	P	0.413	0.502	P	0.575	0.543	P	0.282	0.271	P	P	None
07	B	hallway, first floor, by gym, left	0.078	0.05	P	0.481	0.306	P	0.288	0.249	P	0.297	0.142	P	P	None
08	B	hallway, first floor, by gym, right	0.078	0.052	P	0.448	0.295	P	0.312	0.29	P	0.202	0.128	P	P	None
09	B	corridor near men's locker room, first floor, left	0.142	0.037	P	0.386	0.255	P	0.216	0.19	P	0.126	0.116	P	P	None
10	B	corridor near men's locker room, first floor, right	0.188	0.178	P	0.463	0.443	P	0.186	0.154	P	0.125	0.125	P	P	None
11	B	near 218,	0.122	0.118	P	0.489	0.492	P	0.348	0.341	P	0.288	0.317	P	P	None
12	BF	near 217,	0.13	0.107	P	0.512	0.514	P	0.343	0.361	P	0.31	0.284	P	P	None
13	B	near 209, left	0.119	0.093	P	0.456	0.455	P	0.37	0.322	P	0.288	0.165	P	P	None
14	B	near 209, right	0.117	0.102	P	0.428	0.464	P	0.335	0.323	P	0.225	0.16	P	P	None
15	B	231 gym	0.351	0.388	P	0.619	0.67	P	0.416	0.438	P	0.393	0.419	P	P	None
16	B	232 gym	0.336	0.327	P	0.639	0.659	P	0.42	0.411	P	0.422	0.406	P	P	None
17	B	233 gym	0.336	0.336	P	0.539	0.534	P	0.356	0.366	P	0.316	0.352	P	P	None
18	B	233 gym	0.319	0.319	P	0.54	0.472	P	0.424	0.361	P	0.322	0.345	P	P	None
21	B	233 gym				0.484	0.464	P	0.443	0.333	P	0.357	0.331	P	P	None
22	B	233 gym				0.539	0.478	P	0.373	0.348	P	0.353	0.332	P	P	None
27	S	staff lounge. SE201	0.145	0.175	P	0.447	0.447	P	0.312	0.369	P	0.296	0.308	P	P	None
28	S	nurse's office	0.112	0.114	P	0.377	0.391	P							P	None
29	S	kitchen - single sink	0.135	0.019	P	0.54	0.584	P	0.226	0.212	P	0.219	0.241	P	P	None
30	S	kitchen - office	0.072	0.061	P	0.415	0.273	P				0.218	0.254	P	P	None
31	S	Home Ec, room 220	0.228	0.105	P	0.607	0.504	P	0.036	0.036	P	0.218	0.236	P	P	None
32	S	Home Ec, room 220	0.248	0.131	P	0.495	0.366	P	0.036	0.029	P	0.241	0.218	P	P	None
34	S	Home Ec, room 220	0.226	0.138	P	0.433	0.443	P	0.033	0.032	P	0.265	0.176	P	P	None
35	S	Home Ec, room 220	0.227	0.152	P	0.452	0.446	P	0.033	0.033	P	0.176	0.262	P	P	None
36	S	Home Ec, room 220	0.187	0.178	P	0.424	0.393	P	0.047	0.042	P	0.263	0.268	P	P	None
37	S	Home Ec, room 220	0.261	0.177	P	0.488	0.564	P	0.089	0.051	P	0.272	0.255	P	P	None
38	S	Home Ec, room 220	0.19	0.199	P	0.432	0.468	P	0.096	0.203	P	0.249	0.225	P	P	None
40	S	Custodian lunch room NE120	0.221	0.024	P	0.328	0.245	P	0.171	0.145	P	0.238	0.125	P	P	None
41	S	teen Health center	0.14	0.125	P	0.395	0.442	P							P	None
42	S	teen Health center, SE122	0.181	0.046	P	0.465	0.375	P							P	None
43	S	teen Health center, Janna	0.304	0.056	P	0.527	0.324	P							P	None
44	S	student store	0.191	0.122	P	0.392	0.535	P							P	None
45	S	student store	0.186	0.131	P	0.276	0.415	P							P	None
46	S	main office workroom SE126	0.196	0.079	P	0.509	0.564	P				0.318	0.273	P	P	None
47	S	SW209	0.095	0.129	P	0.535	0.536	P							P	None
48	S	SW209	0.289	0.108	P	0.499	0.482	P							P	None
52	S	N205 library office	0.245	0.22	P				0.461	0.45	P	0.297	0.315	P	P	None
53	B	2nd floor, SE, left	0.168	0.124	P	0.628	0.469	P	0.382	0.377	P	0.321	0.339	P	P	None
54	B	2nd floor, SE, right	0.108	0.115	P				0.394	0.333	P	0.259	0.206	P	P	None
55	S	1st floor, training room	0.321	0.258	P	0.457	0.431	P	0.248	0.201	P	0.207	0.197	P	P	None
56	S	Kitchen, double faucets sink -- left	0.11	0.045	P	0.299	0.194	P	0.181	0.225	P	0.223	0.214	P	P	None
57	S	Kitchen, double faucets sink -- right	0.095	0.02	P	0.345	0.187	P	0.158	0.229	P	0.201	0.215	P	P	None
58	K	kitchen -- kettle				0.456	0.514	P	0.245	0.228	P	0.278	0.261	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			2/23/2012		4/15/2015		8/20/2019		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B	hallway, first floor, SW,							P	None
02	BF	hallway, first floor, SW,	0.06	P					P	None
03	B	hallway, first floor, South, left			0.107	P			P	None
04	B	hallway, first floor, South, left								
05	B	commons, left								
06	B	commons, right								
07	B	hallway, first floor, by gym, left								
08	B	hallway, first floor, by gym, right								
09	B	corridor near men's locker room, first floor, left					0.051	P	P	None
10	B	corridor near men's locker room, first floor, right	0.077	P					P	None
11	B	near 218,			0.088	P			P	None
12	BF	near 217,								
13	B	near 209, left								
14	B	near 209, right								
15	B	231 gym							P	None
16	B	232 gym								
17	B	233 gym								
18	B	233 gym					0.066	P	P	None
21	B	233 gym								
22	B	233 gym							P	None
27	S	staff lounge. SE201	0.077	P					P	None
28	S	nurse's office	0.082	P					P	None
29	S	kitchen - single sink			0.085	P			P	None
30	S	kitchen - office							P	None
31	S	Home Ec, room 220	0.079	P					P	None
32	S	Home Ec, room 220			0.066	P			P	None
34	S	Home Ec, room 220					0.064	P	P	None
35	S	Home Ec, room 220								
36	S	Home Ec, room 220								
37	S	Home Ec, room 220								
38	S	Home Ec, room 220								
40	S	Custodian lunch room NE120								
41	S	teen Health center								
42	S	teen Health center, SE122								
43	S	teen Health center, Janna								
44	S	student store								
45	S	student store								
46	S	main office workroom SE126								
47	S	SW209	0.095	P					P	None
48	S	SW209								
52	S	N205 library office					<0.05	P	P	None
53	B	2nd floor, SE, left								
54	B	2nd floor, SE, right								
55	S	1st floor, training room								
56	S	Kitchen, double faucets sink -- left								
57	S	Kitchen, double faucets sink -- right								
58	K	kitchen -- kettle								

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	fire sprinkler control valve room	Arsenic	20-Aug-19	2 ppb	P
00	SE	fire sprinkler control valve room	Cadmium	20-Aug-19	1 ppb	P
00	SE	fire sprinkler control valve room	Chlorine	13-May-04	<0.02 ppm	P
00	SE	fire sprinkler control valve room	Copper	20-Aug-19	0.107 ppm	P
00	SE	fire sprinkler control valve room	E coli	13-May-04	<1 Colonies	P
00	SE	fire sprinkler control valve room	Iron	20-Aug-19	0.06 ppm	P
00	SE	fire sprinkler control valve room	Lead	20-Aug-19	1 ppb	P
00	SE	fire sprinkler control valve room	Total Coliforms	04-Apr-09	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.