

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
Denny middle School

Updated January 25, 2019

General Information:

Plumbing piping materials: mainly cooper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria: There is one fixture that doesn't meet the policy criteria. A sign will be posted at concession, room 174 (#49).

Follow-up monitoring: Will be performed in 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	Bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			CURRENT STATUS								
			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	GYM	P	None	P	None	P	None			Yes
02	B	GYM, by boys	P	None	P	None	P	None	P	None	Yes
03	B	GYM, by girls	P	None	P	None	P	None	P	None	Yes
12	S	1st floor staff lounge, 177	P	None	P	None	P	None			Yes
13	S	2ND floor staff lounge, 278	P	None	P	None	P	None			Yes
14	S	3RD floor staff lounge, 378	P	None	P	None	P	None			Yes
15	B	3rd floor, north, flex, by 344	P	None	P	None	P	None			Yes
16	B	3rd floor, north, by restroom, left	P	None	P	None	P	None			Yes
17	B	3rd floor, north, by restroom, right	P	None	P	None	P	None			Yes
18	B	3rd floor south flex by 354	P	None	P	None	P	None			Yes
19	B	3rd floor south by restroom, left	P	None	P	None	P	None			Yes
20	B	3rd floor south by restroom, right	P	None	P	None	P	None	P	None	Yes
21	S	LIBRARY OFFICE	P	None	P	None	P	None	P	None	Yes
23	S	ROOM 284A	P	None	P	None	P	None			Yes
24	B	2nd floor by room 281, fitness, left	P	None	P	None	P	None			Yes
25	B	2nd floor by room 281, fitness, right	P	None	P	None	P	None			Yes
26	S	MAIN OFFICE	P	None	P	None	P	None			Yes
27	B	2nd floor, flex, south by 254	P	None	P	None	P	None			Yes
28	B	2nd floor Sorth, by restroom, left	P	None	P	None	P	None			Yes
29	B	2nd floor Sorth, by restroom, right	P	None	P	None	P	None			Yes
30	B	2nd floor north, by restroom, left	P	None	P	None	P	None			Yes
31	B	2nd floor north, by restroom, right	P	None	P	None	P	None			Yes
32	B	2nd floor flex area, north, by 244	P	None	P	None	P	None			Yes
33	B	ROOM 148, LEFT	P	None	P	None	P	None			Yes
34	B	ROOM 148, RIGHT	P	None	P	None	P	None			Yes
35	B	ROOM 144, LEFT	P	None	P	None	P	None	P	None	Yes
36	B	ROOM 144, RIGHT	P	None	P	None	P	None	P	None	Yes
37	B	first floor flex area north, cross 144	P	None	P	None	P	None			Yes
38	B	first floor restroom area, north, right	P	None	P	None	P	None			Yes
39	B	first floor restroom area, north, right	P	None	P	None	P	None			Yes
40	B	ROOM 154, LEFT	P	None	P	None	P	None			Yes
41	B	ROOM 154, RIGHT	P	None	P	None	P	None			Yes
42	B	room 158, left	P	None	P	None	P	None	P	None	Yes
43	B	room 158, right	P	None	P	None	P	None	P	None	Yes
44	B	first floor flex area, south, by 154	P	None	P	None	P	None			Yes
45	B	first floor hallway, south, restroom, left	P	None	P	None	P	None			Yes
46	B	first floor hallway, south, restroom, right	P	None	P	None	P	None			Yes
47	B	OUTSIDE CONCESSION, LEFT	P	None	P	None	P	None			Yes
48	B	OUTSIDE CONCESSION, RIGHT	P	None	P	None	P	None			Yes
49	S	concession, ROOM 174	F	PS	P	None	F	PS			PS
50	S	concession, ROOM 174	P	None	P	None	P	None	P	None	Yes
63	S	KITCHEN	P	None	P	None	P	None	P	None	Yes
65	K	KITCHEN, KETTLE	P	None	P	None	P	None			Yes
66	S	KITCHEN	P	None	P	None	P	None			Yes

70	K	KITCHEN, KETTLE	P	None	P	None	P	None			Yes
71	S	KITCHEN	P	None	P	None	P	None			Yes
72	S	KITCHEN	P	None	P	None	P	None			Yes
74	S	KITCHEN	P	None	P	None	P	None			Yes
75	S	KITCHEN, LEFT	P	None	P	None	P	None			Yes
76	S	KITCHEN, RIGHT	P	None	P	None	P	None			Yes
82	S	TEEN HEALTH -287C	P	None	P	None	P	None	P	None	Yes
83	S	TEEN HEALTH -287E	P	None	P	None	P	None			Yes
84	S	TEEN HEALTH -287J	P	None	P	None	P	None			Yes
85	S	TEEN HEALTH -287L	P	None	P	None	P	None			Yes
86	S	TEEN HEALTH -289J	P	None	P	None	P	None			Yes
87	S	TEEN HEALTH - 289E	P	None	P	None	P	None			Yes
88	S	TEEN HEALTH - 289C	P	None	P	None	P	None			Yes
89	S	TEACHER'S LOUNGE, 288	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

Test Results (Lead/Pb, ppb)																			
FIXTURE INFORMATION			8/17/2010			9/3/2010			9/20/2010			4/17/2014			8/17/2017			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	GYM										<1	<1	P	<1	<1	P	P	None
02	B	GYM, by boys										<1	<1	P	<1	<1	P	P	None
03	B	GYM, by girls										<1	<1	P	<1	<1	P	P	None
12	S	1st floor staff lounge, 177													2	<1	P	P	None
13	S	2ND floor staff lounge, 278													<1	<1	P	P	None
14	S	3RD floor staff lounge, 378													2	<1	P	P	None
15	B	3rd floor, north, flex, by 344										2	<1	P	3	<1	P	P	None
16	B	3rd floor, north, by restroom, left										<1	<1	P				P	None
17	B	3rd floor, north, by restroom, right										1	<1	P	1	<1	P	P	None
18	B	3rd floor south flex by 354										1	<1	P	2	<1	P	P	None
19	B	3rd floor south by restroom, left										1	<1	P	<1	<1	P	P	None
20	B	3rd floor south by restroom, right										<1	<1	P	<1	<1	P	P	None
21	S	LIBRARY OFFICE										2	<1	P	2	<1	P	P	None
23	S	ROOM 284A										2	1	P	2	<1	P	P	None
24	B	2nd floor by room 281, fitness, left										<1	<1	P	<1	<1	P	P	None
25	B	2nd floor by room 281, fitness, right										1	<1	P	1	<1	P	P	None
26	S	MAIN OFFICE										<1	<1	P	<1	<1	P	P	None
27	B	2nd floor, flex, south by 254										<1	<1	P	1	<1	P	P	None
28	B	2nd floor Sorth, by restroom, left										<1	<1	P	<1	<1	P	P	None
29	B	2nd floor Sorth, by restroom, right										<1	<1	P	<1	<1	P	P	None
30	B	2nd floor north, by restroom, left										<1	<1	P	<1	<1	P	P	None
31	B	2nd floor north, by restroom, right										<1	<1	P	<1	<1	P	P	None
32	B	2nd floor flex area, north, by 244										2	<1	P	3	<1	P	P	None
33	B	ROOM 148, LEFT										<1	<1	P	2	<1	P	P	None
34	B	ROOM 148, RIGHT										2	<1	P	4	<1	P	P	None
35	B	ROOM 144, LEFT										1	<1	P	1	<1	P	P	None
36	B	ROOM 144, RIGHT										2	<1	P	2	<1	P	P	None
37	B	first floor flex area north, cross 144										2	<1	P	1	<1	P	P	None
38	B	first floor restroom area, north, right										<1	<1	P	<1	<1	P	P	None
39	B	first floor restroom area, north, right										<1	<1	P	<1	<1	P	P	None
40	B	ROOM 154, LEFT										2	<1	P	2	<1	P	P	None
41	B	ROOM 154, RIGHT										3	<1	P	2	<1	P	P	None
42	B	room 158, left										<1	<1	P	3	<1	P	P	None
43	B	room 158, right										2	<1	P	4	<1	P	P	None
44	B	first floor flex area, south, by 154										2	<1	P	2	<1	P	P	None
45	B	first floor hallway, south, restroom, left										<1	<1	P	<1	<1	P	P	None
46	B	first floor hallway, south, restroom, right										<1	<1	P	<1	<1	P	P	None
47	B	OUTSIDE CONCESSION, LEFT										<1	<1	P	<1	<1	P	P	None
48	B	OUTSIDE CONCESSION, RIGHT										<1	<1	P	<1	<1	P	P	None
49	S	concession, ROOM 174				4	1	P				20	5					F	PS
50	S	concession, ROOM 174				4	3	P				9	8	P				P	None
63	S	KITCHEN	1	<1	P							1	<1	P	<1	<1	P	P	None
65	K	KITCHEN, KETTLE	4	<1	P							<1	<1	P	<1	<1	P	P	None
66	S	KITCHEN	3	<1	P							1	<1	P	<1	<1	P	P	None
70	K	KITCHEN, KETTLE	1	<1	P							<1	<1	P	<1	<1	P	P	None
71	S	KITCHEN	<1	<1	P							1	<1	P	<1	<1	P	P	None

72	S	KITCHEN	<1	<1	P							<1	<1	P	<1	<1	P	P	None	
74	S	KITCHEN	<1	<1	P								<1	P	<1	<1	P	P	None	
75	S	KITCHEN, LEFT	1	<1	P							1	<1	P	<1	<1	P	P	None	
76	S	KITCHEN, RIGHT	4	<1	P							1	<1	P	<1	<1	P	P	None	
82	S	TEEN HEALTH -287C	2	4	P							<1	<1	P				P	None	
83	S	TEEN HEALTH -287E	4	<1	P							<1	<1	P				P	None	
84	S	TEEN HEALTH -287J	4	<1	P							4	<1	P				P	None	
85	S	TEEN HEALTH -287L	7	4	P							2	<1	P				P	None	
86	S	TEEN HEALTH -289J	6	1	P							3	<1	P				P	None	
87	S	TEEN HEALTH - 289E	17	4						<1	P	1	<1	P				P	None	
88	S	TEEN HEALTH - 289C	14	2					2	<1	P	2	<1	P				P	None	
89	S	TEACHER'S LOUNGE, 288								<1	<1	P	3	<1	P	<1	<1	P	P	None

Table 3. Cadmium Test Results

Test Results (Cadmium/Cd, ppb)																			
FIXTURE INFORMATION			8/17/2010			9/3/2010			9/20/2010			4/17/2014			8/17/2017			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	GYM										<1	<1	P	<1	<1	P	P	None
02	B	GYM, by boys										<1	<1	P	<1	<1	P	P	None
03	B	GYM, by girls										<1	<1	P	<1	<1	P	P	None
12	S	1st floor staff lounge, 177													<1	<1	P	P	None
13	S	2ND floor staff lounge, 278													<1	<1	P	P	None
14	S	3RD floor staff lounge, 378													<1	<1	P	P	None
15	B	3rd floor, north, flex, by 344										<1	<1	P	<1	<1	P	P	None
16	B	3rd floor, north, by restroom, left										<1	<1	P				P	None
17	B	3rd floor, north, by restroom, right										<1	<1	P	<1	<1	P	P	None
18	B	3rd floor south flex by 354										<1	<1	P	<1	<1	P	P	None
19	B	3rd floor south by restroom, left										<1	<1	P	<1	<1	P	P	None
20	B	3rd floor south by restroom, right										<1	<1	P	<1	<1	P	P	None
21	S	LIBRARY OFFICE										<1	<1	P	<1	<1	P	P	None
23	S	ROOM 284A										<1	<1	P	<1	<1	P	P	None
24	B	2nd floor by room 281, fitness, left										<1	<1	P	<1	<1	P	P	None
25	B	2nd floor by room 281, fitness, right										<1	<1	P	<1	<1	P	P	None
26	S	MAIN OFFICE										<1	<1	P	<1	<1	P	P	None
27	B	2nd floor, flex, south by 254										<1	<1	P	<1	<1	P	P	None
28	B	2nd floor Sorth, by restroom, left										<1	<1	P	<1	<1	P	P	None
29	B	2nd floor Sorth, by restroom, right										<1	<1	P	<1	<1	P	P	None
30	B	2nd floor north, by restroom, left										<1	<1	P	<1	<1	P	P	None
31	B	2nd floor north, by restroom, right										<1	<1	P	<1	<1	P	P	None
32	B	2nd floor flex area, north, by 244										<1	<1	P	<1	<1	P	P	None
33	B	ROOM 148, LEFT										<1	<1	P	<1	<1	P	P	None
34	B	ROOM 148, RIGHT										<1	<1	P	<1	<1	P	P	None
35	B	ROOM 144, LEFT										<1	<1	P	<1	<1	P	P	None
36	B	ROOM 144, RIGHT										<1	<1	P	<1	<1	P	P	None
37	B	first floor flex area north, cross 144										<1	<1	P	<1	<1	P	P	None
38	B	first floor restroom area, north, right										<1	<1	P	<1	<1	P	P	None
39	B	first floor restroom area, north, right										<1	<1	P	<1	<1	P	P	None
40	B	ROOM 154, LEFT										<1	<1	P	<1	<1	P	P	None
41	B	ROOM 154, RIGHT										<1	<1	P	<1	<1	P	P	None
42	B	room 158, left										<1	<1	P	<1	<1	P	P	None
43	B	room 158, right										<1	<1	P	<1	<1	P	P	None
44	B	first floor flex area, south, by 154										<1	<1	P	<1	<1	P	P	None
45	B	first floor hallway, south, restroom, left										<1	<1	P	<1	<1	P	P	None
46	B	first floor hallway, south, restroom, right										<1	<1	P	<1	<1	P	P	None
47	B	OUTSIDE CONCESSION, LEFT										<1	<1	P	<1	<1	P	P	None
48	B	OUTSIDE CONCESSION, RIGHT										<1	<1	P	<1	<1	P	P	None
49	S	concession, ROOM 174				<1	<1	P				<1	<1	P				P	None
50	S	concession, ROOM 174				<1	<1	P				<1	<1	P				P	None
63	S	KITCHEN	<1	<1	P							<1	<1	P	<1	<1	P	P	None
65	K	KITCHEN, KETTLE	<1	<1	P							<1	<1	P	<1	<1	P	P	None
66	S	KITCHEN	<1	<1	P							<1	<1	P	<1	<1	P	P	None
70	K	KITCHEN, KETTLE	<1	<1	P							<1	<1	P	<1	<1	P	P	None
71	S	KITCHEN	<1	<1	P							<1	<1	P	<1	<1	P	P	None

72	S	KITCHEN	<1	<1	P							<1	<1	P	<1	<1	P	P	None	
74	S	KITCHEN	<1	<1	P								<1	P	<1	<1	P	P	None	
75	S	KITCHEN, LEFT	<1	<1	P							<1	<1	P	<1	<1	P	P	None	
76	S	KITCHEN, RIGHT	<1	<1	P							<1	<1	P	<1	<1	P	P	None	
82	S	TEEN HEALTH -287C	<1	<1	P							<1	<1	P				P	None	
83	S	TEEN HEALTH -287E	<1	<1	P							<1	<1	P				P	None	
84	S	TEEN HEALTH -287J	<1	<1	P							<1	<1	P				P	None	
85	S	TEEN HEALTH -287L	<1	<1	P							<1	<1	P				P	None	
86	S	TEEN HEALTH -289J	<1	<1	P							<1	<1	P				P	None	
87	S	TEEN HEALTH - 289E	<1	<1	P					<1	P	<1	<1	P				P	None	
88	S	TEEN HEALTH - 289C	<1	<1	P					<1	<1	P	<1	<1	P			P	None	
89	S	TEACHER'S LOUNGE, 288								<1	<1	P	<1	<1	P	<1	<1	P	P	None

Table 4. Copper Test Results

Test Results (Copper/Cu, ppm)																			
FIXTURE INFORMATION			8/17/2010			9/3/2010			9/20/2010			4/17/2014			8/17/2017			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	GYM										0.35	0.337	P	0.265	0.243	P	P	None
02	B	GYM, by boys										0.36	0.35	P	0.263	0.268	P	P	None
03	B	GYM, by girls										0.323	0.327	P	0.229	0.099	P	P	None
12	S	1st floor staff lounge, 177													0.254	0.257	P	P	None
13	S	2ND floor staff lounge, 278													0.263	0.284	P	P	None
14	S	3RD floor staff lounge, 378													0.262	0.277	P	P	None
15	B	3rd floor, north, flex, by 344										0.288	0.306	P	0.239	0.136	P	P	None
16	B	3rd floor, north, by restroom, left										0.417	0.322	P				P	None
17	B	3rd floor, north, by restroom, right										0.376	0.374	P	0.416	0.363	P	P	None
18	B	3rd floor south flex by 354										0.272	0.244	P	0.224	0.164	P	P	None
19	B	3rd floor south by restroom, left										0.336	0.232	P	0.286	0.209	P	P	None
20	B	3rd floor south by restroom, right										0.323	0.293	P	0.302	0.201	P	P	None
21	S	LIBRARY OFFICE										0.228	0.299	P	0.216	0.071	P	P	None
23	S	ROOM 284A										0.344	0.49	P	0.264	0.342	P	P	None
24	B	2nd floor by room 281, fitness, left										0.348	0.348	P	0.344	0.471	P	P	None
25	B	2nd floor by room 281, fitness, right										0.354	0.432	P	0.399	0.424	P	P	None
26	S	MAIN OFFICE										0.29	0.298	P	0.236	0.244	P	P	None
27	B	2nd floor, flex, south by 254										0.258	0.236	P	0.203	0.236	P	P	None
28	B	2nd floor Sorth, by restroom, left										0.19	0.174	P	0.262	0.159	P	P	None
29	B	2nd floor Sorth, by restroom, right										0.178	0.164	P	0.208	0.15	P	P	None
30	B	2nd floor north, by restroom, left										0.227	0.233	P	0.175	0.126	P	P	None
31	B	2nd floor north, by restroom, right										0.261	0.243	P	0.208	0.133	P	P	None
32	B	2nd floor flex area, north, by 244										0.239	0.311	P	0.179	0.146	P	P	None
33	B	ROOM 148, LEFT										0.313	0.271	P	0.315	0.344	P	P	None
34	B	ROOM 148, RIGHT										0.366	0.255	P	0.55	0.317	P	P	None
35	B	ROOM 144, LEFT										0.26	0.29	P	0.268	0.251	P	P	None
36	B	ROOM 144, RIGHT										0.262	0.274	P	0.271	0.295	P	P	None
37	B	first floor flex area north, cross 144										0.21	0.326	P	0.157	0.247	P	P	None
38	B	first floor restroom area, north, right										0.258	0.217	P	0.196	0.122	P	P	None
39	B	first floor restroom area, north, right										0.283	0.245	P	0.181	0.117	P	P	None
40	B	ROOM 154, LEFT										0.224	0.277	P	0.234	0.262	P	P	None
41	B	ROOM 154, RIGHT										0.28	0.304	P	0.257	0.274	P	P	None
42	B	room 158, left										0.291	0.25	P	0.256	0.282	P	P	None
43	B	room 158, right										0.269	0.296	P	0.264	0.33	P	P	None
44	B	first floor flex area, south, by 154										0.18	0.277	P	0.175	0.268	P	P	None
45	B	first floor hallway, south, restroom, left										0.239	0.197	P	0.24	0.166	P	P	None
46	B	first floor hallway, south, restroom, right										0.256	0.22	P	0.174	0.154	P	P	None
47	B	OUTSIDE CONCESSION, LEFT										0.207	0.194	P	0.136	0.084	P	P	None
48	B	OUTSIDE CONCESSION, RIGHT										0.226	0.216	P	0.099	0.083	P	P	None
49	S	concession, ROOM 174				0.218	0.23	P				1.34	0.462					F	PS
50	S	concession, ROOM 174				0.217	0.242	P				0.816	0.749	P				P	None
63	S	KITCHEN	0.093	0.054	P							0.552	0.278	P	0.129	0.117	P	P	None
65	K	KITCHEN, KETTLE	0.12	0.136	P							0.416	0.207	P	0.229	0.11	P	P	None
66	S	KITCHEN	0.075	0.067	P							0.548	0.2	P	0.216	0.092	P	P	None
70	K	KITCHEN, KETTLE	0.085	0.071	P							0.195	0.194	P	0.129	0.09	P	P	None
71	S	KITCHEN	0.103	0.053	P							0.193	0.193	P	0.101	0.086	P	P	None

72	S	KITCHEN	0.105	0.106	P							0.232	0.183	P	0.223	0.09	P	P	None	
74	S	KITCHEN	0.116	0.056	P								0.192	P	0.104	0.102	P	P	None	
75	S	KITCHEN, LEFT	0.132	0.064	P							0.286	0.186	P	0.134	0.103	P	P	None	
76	S	KITCHEN, RIGHT	0.105	0.061	P							0.267	0.193	P	0.194	0.107	P	P	None	
82	S	TEEN HEALTH -287C	0.125	0.126	P							0.253	0.233	P				P	None	
83	S	TEEN HEALTH -287E	0.136	0.112	P							0.245	0.21	P				P	None	
84	S	TEEN HEALTH -287J	0.202	0.247	P							0.307	0.343	P				P	None	
85	S	TEEN HEALTH -287L	0.249	0.37	P							0.27	0.248	P				P	None	
86	S	TEEN HEALTH -289J	0.265	0.308	P							0.366	0.359	P				P	None	
87	S	TEEN HEALTH - 289E	2.2	0.904						0.17	P	0.334	0.381	P				P	None	
88	S	TEEN HEALTH - 289C	1.11	0.603	P					0.364	0.145	P	0.232	0.37	P			P	None	
89	S	TEACHER'S LOUNGE, 288								0.166	0.084	P	0.271	0.338	P	0.249	0.189	P	P	None

Table 5. Iron Test Results

Test Results (Iron/Fe, ppm)								
FIXTURE INFORMATION			4/17/2014		8/17/2017		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B	GYM						
02	B	GYM, by boys	<0.05	P			P	None
03	B	GYM, by girls			<0.05	P	P	None
12	S	1st floor staff lounge, 177						
13	S	2ND floor staff lounge, 278						
14	S	3RD floor staff lounge, 378						
15	B	3rd floor, north, flex, by 344						
16	B	3rd floor, north, by restroom, left						
17	B	3rd floor, north, by restroom, right						
18	B	3rd floor south flex by 354						
19	B	3rd floor south by restroom, left						
20	B	3rd floor south by restroom, right	<0.05	P			P	None
21	S	LIBRARY OFFICE			<0.05	P	P	None
23	S	ROOM 284A						
24	B	2nd floor by room 281, fitness, left						
25	B	2nd floor by room 281, fitness, right						
26	S	MAIN OFFICE						
27	B	2nd floor, flex, south by 254						
28	B	2nd floor Sorth, by restroom, left						
29	B	2nd floor Sorth, by restroom, right						
30	B	2nd floor north, by restroom, left						
31	B	2nd floor north, by restroom, right						
32	B	2nd floor flex area, north, by 244						
33	B	ROOM 148, LEFT						
34	B	ROOM 148, RIGHT						
35	B	ROOM 144, LEFT	<0.05	P			P	None
36	B	ROOM 144, RIGHT			<0.05	P	P	None
37	B	first floor flex area north, cross 144						
38	B	first floor restroom area, north, right						
39	B	first floor restroom area, north, right						
40	B	ROOM 154, LEFT						
41	B	ROOM 154, RIGHT						
42	B	room 158, left	<0.05	P			P	None
43	B	room 158, right			<0.05	P	P	None
44	B	first floor flex area, south, by 154						
45	B	first floor hallway, south, restroom, left						
46	B	first floor hallway, south, restroom, right						
47	B	OUTSIDE CONCESSION, LEFT						
48	B	OUTSIDE CONCESSION, RIGHT						
49	S	concession, ROOM 174						
50	S	concession, ROOM 174	<0.05	P			P	None
63	S	KITCHEN			<0.05	P	P	None
65	K	KITCHEN, KETTLE						
66	S	KITCHEN						
70	K	KITCHEN, KETTLE						
71	S	KITCHEN						
72	S	KITCHEN						

74	S	KITCHEN					
75	S	KITCHEN, LEFT					
76	S	KITCHEN, RIGHT					
82	S	TEEN HEALTH -287C	<0.05	P		P	None
83	S	TEEN HEALTH -287E					
84	S	TEEN HEALTH -287J					
85	S	TEEN HEALTH -287L					
86	S	TEEN HEALTH -289J					
87	S	TEEN HEALTH - 289E					
88	S	TEEN HEALTH - 289C					
89	S	TEACHER'S LOUNGE, 288					

Table 6. Service Entry Test Results

No testing data for service entry.

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.