

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
Loyal Heights Elementary

Updated July 19, 2018

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria: All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

CURRENT STATUS											
FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S	ROOM 100A, NURSE OFFICE	P	None	P	None	P	None	P	None	Yes
02	S/B	ROOM 101, SPEC. ED.	P	None	P	None	P	None	P	None	Yes
03	S	ROOM 101A	P	None	P	None	P	None	P	None	Yes
04	S/B	ROOM 102, SPEC. ED	P	None	P	None	P	None	P	None	Yes
05	B	FIRST FLOOR HALLWAY, BY 105, LEFT	P	None	P	None	P	None	P	None	Yes
06	B	FIRST FLOOR HALLWAY, BY 105, RIGHT	P	None	P	None	P	None	P	None	Yes
07	B	FIRST FLOOR HALLWAY, BY 105, BOTTLE FILLER	P	None	P	None	P	None	P	None	Yes
08	S	WORK ROOM 105	P	None	P	None	P	None	P	None	Yes
09	S/B	ROOM 109, SPEC. ED.	P	None	P	None	P	None	P	None	Yes
10	S/B	ROOM 110, SPEC. ED.	P	None	P	None	P	None			Yes
11	S	ROOM 114B, LIBRARY OFFICE	P	None	P	None	P	None	P	None	Yes
12	S/B	ROOM 118, COMPUTER ROOM	P	None	P	None	P	None	P	None	Yes
13	S/B	ROOM 119, COMPUTER ROOM	P	None	P	None	P	None	P	None	Yes
14	B	FIRST FLOOR HALLWAY, BY 182	P	None	P	None	P	None	P	None	Yes
15	S/B	ROOM 122, KINDERGARTEN	P	None	P	None	P	None	P	None	Yes
16	S/B	ROOM 124, KINDERGARTEN	P	None	P	None	P	None	P	None	Yes
17	S/B	ROOM 123	P	None	P	None	P	None	P	None	Yes
18	S/B	ROOM 121	P	None	P	None	P	None	P	None	Yes
19	S/B	ROOM 005, MUSIC ROOM	P	None	P	None	P	None	P	None	Yes
20	S/B	STAGE	P	None	P	None	P	None	P	None	Yes
21	B	CAFETERIA, LEFT	P	None	P	None	P	None	P	None	Yes
22	B	CAFETERIA, RIGHT	P	None	P	None	P	None	P	None	Yes
23	B	CAFETERIA, BOTTLE FILLER	P	None	P	None	P	None	P	None	Yes
24	S	ROOM 001B, BEFORE AND AFTER SCHOOL DAYCARE	P	None	P	None	P	None	P	None	Yes
25	S	KITCHEN	P	None	P	None	P	None	P	None	Yes
26	S	KITCHEN, LEFT	P	None	P	None	P	None	P	None	Yes
27	S	KITCHEN, RIGHT	P	None	P	None	P	None	P	None	Yes
28	S	093B, CE OFFICE	P	None	P	None	P	None	P	None	Yes
29	S/B	ROOM 233	P	None	P	None	P	None	P	None	Yes
30	S/B	ROOM 232	P	None	P	None	P	None	P	None	Yes
31	S/B	ROOM 230	P	None	P	None	P	None	P	None	Yes
32	S/B	ROOM 228	P	None	P	None	P	None	P	None	Yes
33	S/B	ROOM 229	P	None	P	None	P	None	P	None	Yes
34	S/B	ROOM 226	P	None	P	None	P	None	P	None	Yes
35	S/B	ROOM 224	P	None	P	None	P	None	P	None	Yes
36	S/B	ROOM 225	P	None	P	None	P	None	P	None	Yes
37	B	2ND FLOOR HALLWAY, LEFT	P	None	P	None	P	None	P	None	Yes
38	B	2ND FLOOR HALLWAY, RIGHT	P	None	P	None	P	None	P	None	Yes
39	B	2ND FLOOR HALLWAY, BOTTLE FILLER	P	None	P	None	P	None	P	None	Yes
40	S/B	ROOM 221	P	None	P	None	P	None	P	None	Yes
41	S	ROOM 220	P	None	P	None	P	None	P	None	Yes
42	S/B	ROOM 219	P	None	P	None	P	None	P	None	Yes
43	S/B	ROOM 218	P	None	P	None	P	None	P	None	Yes
44	S/B	ROOM 216	P	None	P	None	P	None	P	None	Yes

45	S/B	ROOM 215	P	None	P	None	P	None	P	None	Yes
46	S/B	ROOM 213	P	None	P	None	P	None	P	None	Yes
47	S/B	ROOM 212	P	None	P	None	P	None	P	None	Yes
48	S/B	ROOM 211	P	None	P	None	P	None	P	None	Yes
49	S/B	ROOM 208	P	None	P	None	P	None	P	None	Yes
50	S/B	ROOM 207	P	None	P	None	P	None	P	None	Yes
51	S/B	ROOM 206	P	None	P	None	P	None	P	None	Yes
52	S/B	ROOM 205	P	None	P	None	P	None	P	None	Yes
53	S/B	ROOM 204	P	None	P	None	P	None	P	None	Yes
54	S/B	ROOM 201	P	None	P	None	P	None	P	None	Yes
55	S/B	ROOM 202	P	None	P	None	P	None	P	None	Yes
56	B	2ND FLOOR HALLWAY, LEFT	P	None	P	None	P	None	P	None	Yes
57	B	2ND FLOOR HALLWAY, RIGHT	P	None	P	None	P	None	P	None	Yes

Table 2. Lead Test Results

Test Results (Lead/Pb, ppb)										
FIXTURE INFORMATION			Initial Sampling					Summary Status		
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 100A, NURSE OFFICE	7/12/2018	<1	<1		P	Sample	P	None
02	S/B	ROOM 101, SPEC. ED.	7/12/2018	<1	<1		P	Sample	P	None
03	S	ROOM 101A	7/12/2018	<1	<1		P	Sample	P	None
04	S/B	ROOM 102, SPEC. ED	7/12/2018	<1	<1		P	Sample	P	None
05	B	FIRST FLOOR HALLWAY, BY 105, LEFT	7/12/2018	<1	<1		P	Sample	P	None
06	B	FIRST FLOOR HALLWAY, BY 105, RIGHT	7/12/2018	<1	<1		P	Sample	P	None
07	B	FIRST FLOOR HALLWAY, BY 105, BOTTLE FILLER	7/12/2018	<1	<1		P	Sample	P	None
08	S	WORK ROOM 105	7/12/2018	<1	<1		P	Sample	P	None
09	S/B	ROOM 109, SPEC. ED.	7/12/2018	<1	<1		P	Sample	P	None
10	S/B	ROOM 110, SPEC. ED.	7/12/2018	<1	<1		P	Sample	P	None
11	S	ROOM 114B, LIBRARY OFFICE	7/12/2018	<1	<1		P	Sample	P	None
12	S/B	ROOM 118, COMPUTER ROOM	7/12/2018	<1	<1		P	Sample	P	None
13	S/B	ROOM 119, COMPUTER ROOM	7/12/2018	<1	<1		P	Sample	P	None
14	B	FIRST FLOOR HALLWAY, BY 182	7/12/2018	<1	<1		P	Sample	P	None
15	S/B	ROOM 122, KINDERGARTEN	7/12/2018	<1	<1		P	Sample	P	None
16	S/B	ROOM 124, KINDERGARTEN	7/12/2018	<1	<1		P	Sample	P	None
17	S/B	ROOM 123	7/12/2018	<1	<1		P	Sample	P	None
18	S/B	ROOM 121	7/12/2018	<1	<1		P	Sample	P	None
19	S/B	ROOM 005, MUSIC ROOM	7/12/2018	<1	<1		P	Sample	P	None
20	S/B	STAGE	7/12/2018	<1	<1		P	Sample	P	None
21	B	CAFETERIA, LEFT	7/12/2018	<1	<1		P	Sample	P	None
22	B	CAFETERIA, RIGHT	7/12/2018	<1	<1		P	Sample	P	None
23	B	CAFETERIA, BOTTLE FILLER	7/12/2018	<1	<1		P	Sample	P	None
24	S	ROOM 001B, BEFORE AND AFTER SCHOOL DAYCARE	7/12/2018	<1	<1		P	Sample	P	None
25	S	KITCHEN	7/12/2018	<1	<1		P	Sample	P	None
26	S	KITCHEN, LEFT	7/12/2018	<1	<1		P	Sample	P	None
27	S	KITCHEN, RIGHT	7/12/2018	<1	<1		P	Sample	P	None
28	S	093B, CE OFFICE	7/12/2018	<1	<1		P	Sample	P	None
29	S/B	ROOM 233	7/12/2018	<1	<1		P	Sample	P	None
30	S/B	ROOM 232	7/12/2018	<1	<1		P	Sample	P	None
31	S/B	ROOM 230	7/12/2018	<1	<1		P	Sample	P	None
32	S/B	ROOM 228	7/12/2018	<1	<1		P	Sample	P	None
33	S/B	ROOM 229	7/12/2018	<1	<1		P	Sample	P	None
34	S/B	ROOM 226	7/12/2018	<1	<1		P	Sample	P	None
35	S/B	ROOM 224	7/12/2018	<1	<1		P	Sample	P	None
36	S/B	ROOM 225	7/12/2018	<1	<1		P	Sample	P	None
37	B	2ND FLOOR HALLWAY, LEFT	7/12/2018	<1	<1		P	Sample	P	None
38	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018	<1	<1		P	Sample	P	None
39	B	2ND FLOOR HALLWAY, BOTTLE FILLER	7/12/2018	<1	<1		P	Sample	P	None
40	S/B	ROOM 221	7/12/2018	<1	<1		P	Sample	P	None
41	S	ROOM 220	7/12/2018	<1	<1		P	Sample	P	None
42	S/B	ROOM 219	7/12/2018	<1	<1		P	Sample	P	None
43	S/B	ROOM 218	7/12/2018	<1	<1		P	Sample	P	None
44	S/B	ROOM 216	7/12/2018	<1	<1		P	Sample	P	None
45	S/B	ROOM 215	7/12/2018	<1	<1		P	Sample	P	None
46	S/B	ROOM 213	7/12/2018	<1	<1		P	Sample	P	None
47	S/B	ROOM 212	7/12/2018	<1	<1		P	Sample	P	None

48	S/B	ROOM 211	7/12/2018	<1	<1		P	Sample	P	None
49	S/B	ROOM 208	7/12/2018	<1	<1		P	Sample	P	None
50	S/B	ROOM 207	7/12/2018	<1	<1		P	Sample	P	None
51	S/B	ROOM 206	7/12/2018	<1	<1		P	Sample	P	None
52	S/B	ROOM 205	7/12/2018	<1	<1		P	Sample	P	None
53	S/B	ROOM 204	7/12/2018	<1	<1		P	Sample	P	None
54	S/B	ROOM 201	7/12/2018	<1	<1		P	Sample	P	None
55	S/B	ROOM 202	7/12/2018	<1	<1		P	Sample	P	None
56	B	2ND FLOOR HALLWAY, LEFT	7/12/2018	<1	<1		P	Sample	P	None
57	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018	<1	<1		P	Sample	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling					Summary Status		
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 100A, NURSE OFFICE	7/12/2018	<1	<1		P		P	None
02	S/B	ROOM 101, SPEC. ED.	7/12/2018	<1	<1		P		P	None
03	S	ROOM 101A	7/12/2018	<1	<1		P		P	None
04	S/B	ROOM 102, SPEC. ED	7/12/2018	<1	<1		P		P	None
05	B	FIRST FLOOR HALLWAY, BY 105, LEFT	7/12/2018	<1	<1		P		P	None
06	B	FIRST FLOOR HALLWAY, BY 105, RIGHT	7/12/2018	<1	<1		P		P	None
07	B	FIRST FLOOR HALLWAY, BY 105, BOTTLE FILLER	7/12/2018	<1	<1		P		P	None
08	S	WORK ROOM 105	7/12/2018	<1	<1		P		P	None
09	S/B	ROOM 109, SPEC. ED.	7/12/2018	<1	<1		P		P	None
10	S/B	ROOM 110, SPEC. ED.	7/12/2018	<1	<1		P		P	None
11	S	ROOM 114B, LIBRARY OFFICE	7/12/2018	<1	<1		P		P	None
12	S/B	ROOM 118, COMPUTER ROOM	7/12/2018	<1	<1		P		P	None
13	S/B	ROOM 119, COMPUTER ROOM	7/12/2018	<1	<1		P		P	None
14	B	FIRST FLOOR HALLWAY, BY 182	7/12/2018	<1	<1		P		P	None
15	S/B	ROOM 122, KINDERGARTEN	7/12/2018	<1	<1		P		P	None
16	S/B	ROOM 124, KINDERGARTEN	7/12/2018	<1	<1		P		P	None
17	S/B	ROOM 123	7/12/2018	<1	<1		P		P	None
18	S/B	ROOM 121	7/12/2018	<1	<1		P		P	None
19	S/B	ROOM 005, MUSIC ROOM	7/12/2018	<1	<1		P		P	None
20	S/B	STAGE	7/12/2018	<1	<1		P		P	None
21	B	CAFETERIA, LEFT	7/12/2018	<1	<1		P		P	None
22	B	CAFETERIA, RIGHT	7/12/2018	<1	<1		P		P	None
23	B	CAFETERIA, BOTTLE FILLER	7/12/2018	<1	<1		P		P	None
24	S	ROOM 001B, BEFORE AND AFTER SCHOOL DAYCARE	7/12/2018	<1	<1		P		P	None
25	S	KITCHEN	7/12/2018	<1	<1		P		P	None
26	S	KITCHEN, LEFT	7/12/2018	<1	<1		P		P	None
27	S	KITCHEN, RIGHT	7/12/2018	<1	<1		P		P	None
28	S	093B, CE OFFICE	7/12/2018	<1	<1		P		P	None
29	S/B	ROOM 233	7/12/2018	<1	<1		P		P	None
30	S/B	ROOM 232	7/12/2018	<1	<1		P		P	None
31	S/B	ROOM 230	7/12/2018	<1	<1		P		P	None
32	S/B	ROOM 228	7/12/2018	<1	<1		P		P	None
33	S/B	ROOM 229	7/12/2018	<1	<1		P		P	None
34	S/B	ROOM 226	7/12/2018	<1	<1		P		P	None
35	S/B	ROOM 224	7/12/2018	<1	<1		P		P	None
36	S/B	ROOM 225	7/12/2018	<1	<1		P		P	None
37	B	2ND FLOOR HALLWAY, LEFT	7/12/2018	<1	<1		P		P	None
38	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018	<1	<1		P		P	None
39	B	2ND FLOOR HALLWAY, BOTTLE FILLER	7/12/2018	<1	<1		P		P	None
40	S/B	ROOM 221	7/12/2018	<1	<1		P		P	None
41	S	ROOM 220	7/12/2018	<1	<1		P		P	None
42	S/B	ROOM 219	7/12/2018	<1	<1		P		P	None
43	S/B	ROOM 218	7/12/2018	<1	<1		P		P	None
44	S/B	ROOM 216	7/12/2018	<1	<1		P		P	None
45	S/B	ROOM 215	7/12/2018	<1	<1		P		P	None
46	S/B	ROOM 213	7/12/2018	<1	<1		P		P	None
47	S/B	ROOM 212	7/12/2018	<1	<1		P		P	None

48	S/B	ROOM 211	7/12/2018	<1	<1		P		P	None
49	S/B	ROOM 208	7/12/2018	<1	<1		P		P	None
50	S/B	ROOM 207	7/12/2018	<1	<1		P		P	None
51	S/B	ROOM 206	7/12/2018	<1	<1		P		P	None
52	S/B	ROOM 205	7/12/2018	<1	<1		P		P	None
53	S/B	ROOM 204	7/12/2018	<1	<1		P		P	None
54	S/B	ROOM 201	7/12/2018	<1	<1		P		P	None
55	S/B	ROOM 202	7/12/2018	<1	<1		P		P	None
56	B	2ND FLOOR HALLWAY, LEFT	7/12/2018	<1	<1		P		P	None
57	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018	<1	<1		P		P	None

Table 4. Copper Test Results

Test Results (Copper/Cu, ppm)										
FIXTURE INFORMATION			Initial Sampling					Summary Status		
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 100A, NURSE OFFICE	7/12/2018	0.216	0.194		P		P	None
02	S/B	ROOM 101, SPEC. ED.	7/12/2018	0.199	0.214		P		P	None
03	S	ROOM 101A	7/12/2018	0.188	0.234		P		P	None
04	S/B	ROOM 102, SPEC. ED	7/12/2018	0.267	0.25		P		P	None
05	B	FIRST FLOOR HALLWAY, BY 105, LEFT	7/12/2018	0.365	0.267		P		P	None
06	B	FIRST FLOOR HALLWAY, BY 105, RIGHT	7/12/2018	0.4	0.242		P		P	None
07	B	FIRST FLOOR HALLWAY, BY 105, BOTTLE FILLER	7/12/2018	<0.002	0.004		P		P	None
08	S	WORK ROOM 105	7/12/2018	0.273	0.272		P		P	None
09	S/B	ROOM 109, SPEC. ED.	7/12/2018	0.328	0.232		P		P	None
10	S/B	ROOM 110, SPEC. ED.	7/12/2018	0.31	0.958		P		P	None
11	S	ROOM 114B, LIBRARY OFFICE	7/12/2018	0.204	0.19		P		P	None
12	S/B	ROOM 118, COMPUTER ROOM	7/12/2018	0.18	0.211		P		P	None
13	S/B	ROOM 119, COMPUTER ROOM	7/12/2018	0.212	0.22		P		P	None
14	B	FIRST FLOOR HALLWAY, BY 182	7/12/2018	0.222	0.208		P		P	None
15	S/B	ROOM 122, KINDERGARTEN	7/12/2018	0.334	0.191		P		P	None
16	S/B	ROOM 124, KINDERGARTEN	7/12/2018	0.25	0.136		P		P	None
17	S/B	ROOM 123	7/12/2018	0.203	0.144		P		P	None
18	S/B	ROOM 121	7/12/2018	0.182	0.236		P		P	None
19	S/B	ROOM 005, MUSIC ROOM	7/12/2018	0.198	0.15		P		P	None
20	S/B	STAGE	7/12/2018	0.157	0.195		P		P	None
21	B	CAFETERIA, LEFT	7/12/2018	0.003	0.013		P		P	None
22	B	CAFETERIA, RIGHT	7/12/2018	0.009	0.012		P		P	None
23	B	CAFETERIA, BOTTLE FILLER	7/12/2018	0.008	0.01		P		P	None
24	S	ROOM 001B, BEFORE AND AFTER SCHOOL DAYCARE	7/12/2018	0.17	0.196		P		P	None
25	S	KITCHEN	7/12/2018	0.302	0.216		P		P	None
26	S	KITCHEN, LEFT	7/12/2018	0.118	0.216		P		P	None
27	S	KITCHEN, RIGHT	7/12/2018	0.116	0.214		P		P	None
28	S	093B, CE OFFICE	7/12/2018	0.16	0.183		P		P	None
29	S/B	ROOM 233	7/12/2018	0.186	0.248		P		P	None
30	S/B	ROOM 232	7/12/2018	0.118	0.122		P		P	None
31	S/B	ROOM 230	7/12/2018	0.209	0.244		P		P	None
32	S/B	ROOM 228	7/12/2018	0.184	0.207		P		P	None
33	S/B	ROOM 229	7/12/2018	0.237	0.202		P		P	None
34	S/B	ROOM 226	7/12/2018	0.266	0.224		P		P	None
35	S/B	ROOM 224	7/12/2018	0.295	0.239		P		P	None
36	S/B	ROOM 225	7/12/2018	0.193	0.145		P		P	None
37	B	2ND FLOOR HALLWAY, LEFT	7/12/2018	0.005	0.016		P		P	None
38	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018	0.02	0.017		P		P	None
39	B	2ND FLOOR HALLWAY, BOTTLE FILLER	7/12/2018	0.013	0.017		P		P	None
40	S/B	ROOM 221	7/12/2018	0.223	0.127		P		P	None
41	S	ROOM 220	7/12/2018	0.186	0.171		P		P	None
42	S/B	ROOM 219	7/12/2018	0.167	0.123		P		P	None
43	S/B	ROOM 218	7/12/2018	0.216	0.124		P		P	None
44	S/B	ROOM 216	7/12/2018	0.173	0.154		P		P	None
45	S/B	ROOM 215	7/12/2018	0.282	0.134		P		P	None
46	S/B	ROOM 213	7/12/2018	0.181	0.187		P		P	None

47	S/B	ROOM 212	7/12/2018	0.182	0.184		P		P	None
48	S/B	ROOM 211	7/12/2018	0.217	0.203		P		P	None
49	S/B	ROOM 208	7/12/2018	0.35	1.22		P		P	None
50	S/B	ROOM 207	7/12/2018	0.279	0.207		P		P	None
51	S/B	ROOM 206	7/12/2018	0.348	0.221		P		P	None
52	S/B	ROOM 205	7/12/2018	0.28	0.254		P		P	None
53	S/B	ROOM 204	7/12/2018	0.228	0.195		P		P	None
54	S/B	ROOM 201	7/12/2018	0.224	0.22		P		P	None
55	S/B	ROOM 202	7/12/2018	0.244	0.216		P		P	None
56	B	2ND FLOOR HALLWAY, LEFT	7/12/2018	0.334	0.282		P		P	None
57	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018	0.26	0.223		P		P	None

Table 5. Iron Test Results

Test Results (Iron/Fe, ppm)										
FIXTURE INFORMATION			Initial Sampling					Summary Status		
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 100A, NURSE OFFICE	7/12/2018			<0.05	P		P	None
02	S/B	ROOM 101, SPEC. ED.	7/12/2018			0.061	P		P	None
03	S	ROOM 101A	7/12/2018			0.115	P		P	None
04	S/B	ROOM 102, SPEC. ED	7/12/2018			0.327	P		P	None
05	B	FIRST FLOOR HALLWAY, BY 105, LEFT	7/12/2018			0.338	P		P	None
06	B	FIRST FLOOR HALLWAY, BY 105, RIGHT	7/12/2018			0.36	P		P	None
07	B	FIRST FLOOR HALLWAY, BY 105, BOTTLE FILLER	7/12/2018			<0.05	P		P	None
08	S	WORK ROOM 105	7/12/2018			0.396	P		P	None
09	S/B	ROOM 109, SPEC. ED.	7/12/2018			0.329	P		P	None
10	S/B	ROOM 110, SPEC. ED.	7/12/2018							
11	S	ROOM 114B, LIBRARY OFFICE	7/12/2018			<0.05	P		P	None
12	S/B	ROOM 118, COMPUTER ROOM	7/12/2018			<0.05	P		P	None
13	S/B	ROOM 119, COMPUTER ROOM	7/12/2018			<0.05	P		P	None
14	B	FIRST FLOOR HALLWAY, BY 182	7/12/2018			0.061	P		P	None
15	S/B	ROOM 122, KINDERGARTEN	7/12/2018			<0.05	P		P	None
16	S/B	ROOM 124, KINDERGARTEN	7/12/2018			<0.05	P		P	None
17	S/B	ROOM 123	7/12/2018			<0.05	P		P	None
18	S/B	ROOM 121	7/12/2018			<0.05	P		P	None
19	S/B	ROOM 005, MUSIC ROOM	7/12/2018			<0.05	P		P	None
20	S/B	STAGE	7/12/2018			<0.05	P		P	None
21	B	CAFETERIA, LEFT	7/12/2018			<0.05	P		P	None
22	B	CAFETERIA, RIGHT	7/12/2018			<0.05	P		P	None
23	B	CAFETERIA, BOTTLE FILLER	7/12/2018			<0.05	P		P	None
24	S	ROOM 001B, BEFORE AND AFTER SCHOOL DAYCARE	7/12/2018			<0.05	P		P	None
25	S	KITCHEN	7/12/2018			<0.05	P		P	None
26	S	KITCHEN, LEFT	7/12/2018			<0.05	P		P	None
27	S	KITCHEN, RIGHT	7/12/2018			<0.05	P		P	None
28	S	093B, CE OFFICE	7/12/2018			0.051	P		P	None
29	S/B	ROOM 233	7/12/2018			<0.05	P		P	None
30	S/B	ROOM 232	7/12/2018			<0.05	P		P	None
31	S/B	ROOM 230	7/12/2018			<0.05	P		P	None
32	S/B	ROOM 228	7/12/2018			<0.05	P		P	None
33	S/B	ROOM 229	7/12/2018			<0.05	P		P	None
34	S/B	ROOM 226	7/12/2018			<0.05	P		P	None
35	S/B	ROOM 224	7/12/2018			<0.05	P		P	None
36	S/B	ROOM 225	7/12/2018			<0.05	P		P	None
37	B	2ND FLOOR HALLWAY, LEFT	7/12/2018			<0.05	P		P	None
38	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018			<0.05	P		P	None
39	B	2ND FLOOR HALLWAY, BOTTLE FILLER	7/12/2018			<0.05	P		P	None
40	S/B	ROOM 221	7/12/2018			<0.05	P		P	None
41	S	ROOM 220	7/12/2018			<0.05	P		P	None
42	S/B	ROOM 219	7/12/2018			<0.05	P		P	None
43	S/B	ROOM 218	7/12/2018			<0.05	P		P	None
44	S/B	ROOM 216	7/12/2018			<0.05	P		P	None
45	S/B	ROOM 215	7/12/2018			<0.05	P		P	None
46	S/B	ROOM 213	7/12/2018			0.051	P		P	None
47	S/B	ROOM 212	7/12/2018			0.234	P		P	None

48	S/B	ROOM 211	7/12/2018			0.135	P		P	None
49	S/B	ROOM 208	7/12/2018			0.329	P		P	None
50	S/B	ROOM 207	7/12/2018			0.063	P		P	None
51	S/B	ROOM 206	7/12/2018			0.17	P		P	None
52	S/B	ROOM 205	7/12/2018			0.285	P		P	None
53	S/B	ROOM 204	7/12/2018			<0.05	P		P	None
54	S/B	ROOM 201	7/12/2018			0.15	P		P	None
55	S/B	ROOM 202	7/12/2018			<0.05	P		P	None
56	B	2ND FLOOR HALLWAY, LEFT	7/12/2018			0.14	P		P	None
57	B	2ND FLOOR HALLWAY, RIGHT	7/12/2018			0.075	P		P	None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	Basement B07	Arsenic	12-Jul-18	2 ppb	P
00	SE	Basement B07	Cadmium	12-Jul-18	1 ppb	P
00	SE	Basement B07	Copper	12-Jul-18	0.165 ppm	P
00	SE	Basement B07	Iron	12-Jul-18	0.147 ppm	P
00	SE	Basement B07	Lead	12-Jul-18	1 ppb	P
00	SE	Basement B07	Total Coliforms	12-Jul-18	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.