

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
Mercer Middle school**

Updated April 28, 2016

General Information:

Plumbing piping materials: galvanized steel

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

| Symbol | Definition |
|------------|--|
| SE | service entry (main) |
| B | bubbler |
| S | sink (faucet) |
| B/S | sink/bubbler combination |
| S/B | sink/bubbler combination |
| ppb | parts per billion |
| ppm | parts per million |
| NA | not applicable |
| None | no action required |
| Unk | unknown status or action |
| Sample | sample needs to be taken |
| Re-test | fixture needs to be resampled |
| Conf | resample to confirm measurement |
| No flush | not flushed before sampling |
| Sink | sampled faucet of S/B combo |
| Used | recently used; no 1st draw sample possible |
| PS | post sign |
| Disable(d) | fixture disabled in response to water quality testing |
| BDSS | Bubbler disabled, sign on sink |
| IF | install filter |
| RB | replace bubbler |
| RB/IF | replace bubbler and/or install filter |
| RF | replace faucet |
| RF/IF | replace faucet and/or install filter |
| BW | disable fixture and provide bottled water until remediated |
| Leaks | leaking fixture |
| NW | not working properly (sample S when B of S/B NW) |
| OS | out of service - disabled until fixed |
| RS | return to service - now passes testing |
| Rem | Removed from system - no longer exists |

Table 1. Summary of Results

| FIXTURE INFORMATION | | | CURRENT STATUS | | | | | | | | OK? |
|---------------------|------|-------------------------------------|----------------|--------|-----------|--------|-----------|--------|-----------|--------|---------------|
| | | | LEAD | | CADMIUM | | COPPER | | IRON | | |
| Fixture ID | Type | Location | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Yes/No/Status |
| 01 | B | hallway, outside room 109, left | P | None | P | None | P | None | P | None | Yes |
| 02 | B | hallway, outside room 109, right | P | None | P | None | P | None | P | None | Yes |
| 03 | B | hallway, by room 117 | P | None | P | None | P | None | P | None | Yes |
| 04 | BF | hallway, by room 117 | P | None | P | None | P | None | P | None | Yes |
| 05 | B | hallway, outside main office, left | P | None | P | None | P | None | P | None | Yes |
| 06 | B | hallway, outside main office, right | P | None | P | None | P | None | P | None | Yes |
| 07 | B | hallway, by room 125, left | P | None | P | None | P | None | P | None | Yes |
| 08 | B | hallway, by room 125, right | P | None | P | None | P | None | P | None | Yes |
| 09 | B | gym hallway, left side, left | P | None | P | None | P | None | P | None | Yes |
| 10 | B | gym hallway, left side, right | P | None | P | None | P | None | P | None | Yes |
| 11 | B | gym hallway, right side, left | P | None | P | None | P | None | P | None | Yes |
| 12 | B | gym hallway, right side, right | P | None | P | None | P | None | P | None | Yes |
| 13 | S | room 212 | P | None | P | None | P | None | P | None | Yes |
| 14 | B | hallway, left | P | None | P | None | P | None | P | None | Yes |
| 15 | B | hallway, right | P | None | P | None | P | None | P | None | Yes |
| 16 | B | gym | P | None | P | None | P | None | P | None | Yes |
| 17 | B | gym | P | None | P | None | P | None | P | None | Yes |
| 18 | B | Girls locker room | P | None | P | None | P | None | | | Yes |
| 19 | B | boys locker room | P | None | P | None | P | None | P | None | Yes |
| 20 | S/B | room 213 | P | None | P | None | P | None | P | None | Yes |
| 21 | S | room 214 A | P | None | P | None | P | None | P | None | Yes |
| 22 | S/B | room 215 | P | None | P | None | P | None | P | None | Yes |
| 23 | S | room 214 | P | None | P | None | P | None | P | None | Yes |
| 25 | S | room 204 - right | P | None | P | None | P | None | P | None | Yes |
| 33 | S | room 201 | P | None | P | None | P | None | P | None | Yes |
| 34 | S | room 203 | P | None | P | None | P | None | P | None | Yes |
| 35 | S | nurses office | P | None | P | None | P | None | P | None | Yes |
| 36 | S | room 101 | P | None | P | None | P | None | P | None | Yes |
| 37 | S | room 103 | P | None | | | | | | | Yes |
| 38 | S | room 105, left | P | None | P | None | P | None | P | None | Yes |
| 40 | S | room 107, left | P | None | P | None | P | None | P | None | Yes |
| 50 | S | kitchen sink right | P | None | P | None | P | None | P | None | Yes |
| 51 | S | kitchen sink left | P | None | P | None | P | None | P | None | Yes |
| 53 | S | teacher lounge | P | RS | P | None | P | None | P | None | Yes |
| 60 | S | room 202 - special ed | P | None | P | None | P | None | P | None | Yes |
| 61 | S | Kitchen wash sink | P | None | P | None | P | None | | | Yes |
| 65 | S | library office | P | None | P | None | P | None | | | Yes |
| 66 | S | main office | P | None | P | None | P | None | | | Yes |
| 68 | S | Kitchen, sink | P | None | P | None | P | None | | | Yes |

Table 2. Lead Test Results

| FIXTURE INFORMATION | | | 8/20/2009 | | | 1/29/2010 | | | 7/13/2012 | | | 7/7/2015 | | | 8/29/2019 | | | 11/21/2019 | | | Summary Status | |
|---------------------|------|-------------------------------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|----------|-----------|------------|-----------|-----------|------------|------------|-----------|------------|----------------|--------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | Pass/Fail | Status |
| 01 | B | hallway, outside room 109, left | | | | | | | 1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 02 | B | hallway, outside room 109, right | | | | | | | 1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 03 | B | hallway, by room 117 | | | | | | | | | | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 04 | BF | hallway, by room 117 | | | | | | | | | | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 05 | B | hallway, outside main office, left | | | | | | | | | | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 06 | B | hallway, outside main office, right | | | | | | | | | | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 07 | B | hallway, by room 125, left | | | | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 08 | B | hallway, by room 125, right | | | | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 09 | B | gym hallway, left side, left | 1 | 1 | P | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 10 | B | gym hallway, left side, right | <1 | 1 | P | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 11 | B | gym hallway, right side, left | 1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 12 | B | gym hallway, right side, right | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 13 | S | room 212 | | | | 6 | 1 | P | 3 | <1 | P | 1 | <1 | P | | | | <1 | <1 | P | P | None |
| 14 | B | hallway, left | 2 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 15 | B | hallway, right | 1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 16 | B | gym | 12 | 2 | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 17 | B | gym | 4 | 1 | P | | | | 9 | <1 | P | 3 | 1 | P | | | | <1 | <1 | P | P | None |
| 18 | B | Girls locker room | 1 | 1 | P | | | | <1 | <1 | P | 1 | 1 | P | | | | | | | P | None |
| 19 | B | boys locker room | 8 | 2 | P | | | | 4 | 1 | P | 3 | 2 | P | | | | <1 | <1 | P | P | None |
| 20 | S/B | room 213 | | | | 4 | 1 | P | 2 | <1 | P | 2 | 1 | P | | | | | | | P | None |
| 21 | S | room 214 A | 2 | <1 | P | | | | <1 | <1 | P | 6 | <1 | P | | | | 5 | <1 | P | P | None |
| 22 | S/B | room 215 | 7 | 2 | P | | | | 3 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 23 | S | room 214 | 10 | 2 | P | | | | 3 | <1 | P | 3 | <1 | P | | | | <1 | <1 | P | P | None |
| 25 | S | room 204 - right | 4 | 3 | P | | | | 1 | <1 | P | 1 | <1 | P | | | | <1 | <1 | P | P | None |
| 33 | S | room 201 | | | | 3 | 2 | P | 1 | <1 | P | <1 | <1 | P | | | | 1 | <1 | P | P | None |
| 34 | S | room 203 | 10 | 1 | P | | | | <1 | <1 | P | 1 | <1 | P | | | | <1 | <1 | P | P | None |
| 35 | S | nurses office | | | | | | | | | | 2 | 1 | P | | | | <1 | <1 | P | P | None |
| 36 | S | room 101 | | | | | | | 3 | <1 | P | 4 | 3 | P | | | | <1 | 1 | P | P | None |
| 37 | S | room 103 | | | | | | | | | | | | | 3 | 1 | P | | | | P | None |
| 38 | S | room 105, left | | | | | | | 3 | <1 | P | 3 | 2 | P | | | | 1 | 1 | P | P | None |
| 40 | S | room 107, left | | | | | | | 10 | 2 | P | 3 | 2 | P | | | | <1 | <1 | P | P | None |
| 50 | S | kitchen sink right | | | | | | | 3 | <1 | P | 3 | 1 | P | | | | <1 | <1 | P | P | None |
| 51 | S | kitchen sink left | | | | | | | 4 | <1 | P | 6 | 1 | P | | | | <1 | <1 | P | P | None |
| 53 | S | teacher lounge | | | | | | | <1 | <1 | P | <1 | <1 | P | | | | <1 | <1 | P | P | RS |
| 60 | S | room 202 - special ed | 20 | 5 | | 9 | <1 | P | 6 | 5 | P | 8 | 1 | P | | | | 3 | <1 | P | P | None |
| 61 | S | Kitchen wash sink | | | | | | | 3 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 65 | S | library office | | | | | | | 5 | <1 | P | 5 | 1 | P | | | | 6 | <1 | P | P | None |
| 66 | S | main office | | | | | | | | | | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 68 | S | Kitchen, sink | | | | 5 | <1 | P | 4 | <1 | P | 2 | 1 | P | | | | <1 | <1 | P | P | None |

Table 3. Cadmium Test Results

| FIXTURE INFORMATION | | | 8/20/2009 | | | 1/29/2010 | | | 7/13/2012 | | | 7/7/2015 | | | 11/21/2019 | | | Summary Status | |
|---------------------|------|-------------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------|-----------|-----------|------------|-----------|-----------|----------------|--------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway, outside room 109, left | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 02 | B | hallway, outside room 109, right | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 03 | B | hallway, by room 117 | | | | | | | | | | <1 | <1 | P | <1 | <1 | P | P | None |
| 04 | BF | hallway, by room 117 | | | | | | | | | | <1 | <1 | P | <1 | <1 | P | P | None |
| 05 | B | hallway, outside main office, left | | | | | | | | | | <1 | <1 | P | <1 | <1 | P | P | None |
| 06 | B | hallway, outside main office, right | | | | | | | | | | <1 | <1 | P | <1 | <1 | P | P | None |
| 07 | B | hallway, by room 125, left | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 08 | B | hallway, by room 125, right | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 09 | B | gym hallway, left side, left | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 10 | B | gym hallway, left side, right | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 11 | B | gym hallway, right side, left | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 12 | B | gym hallway, right side, right | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 13 | S | room 212 | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 14 | B | hallway, left | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 15 | B | hallway, right | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 16 | B | gym | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 17 | B | gym | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 18 | B | Girls locker room | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 19 | B | boys locker room | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 20 | S/B | room 213 | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | | | | P | None |
| 21 | S | room 214 A | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 22 | S/B | room 215 | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 23 | S | room 214 | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 25 | S | room 204 - right | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 33 | S | room 201 | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 34 | S | room 203 | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 35 | S | nurses office | | | | | | | | | | <1 | <1 | P | <1 | <1 | P | P | None |
| 36 | S | room 101 | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 37 | S | room 103 | | | | | | | | | | | | | | | | | |
| 38 | S | room 105, left | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 40 | S | room 107, left | | | | | | | <1 | <1 | P | 1 | <1 | P | <1 | <1 | P | P | None |
| 50 | S | kitchen sink right | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 51 | S | kitchen sink left | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 53 | S | teacher lounge | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 60 | S | room 202 - special ed | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 61 | S | Kitchen wash sink | | | | | | | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 65 | S | library office | | | | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 66 | S | main office | | | | | | | | | | <1 | <1 | P | <1 | <1 | P | P | None |
| 68 | S | Kitchen, sink | | | | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |

Table 4. Copper Test Results

| FIXTURE INFORMATION | | | 8/20/2009 | | | 1/29/2010 | | | 7/13/2012 | | | 7/7/2015 | | | 11/21/2019 | | | Summary Status | |
|---------------------|------|-------------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------|-----------|-----------|------------|-----------|-----------|----------------|--------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway, outside room 109, left | | | | | | | 0.315 | 0.19 | P | 0.225 | 0.224 | P | 0.463 | 0.448 | P | P | None |
| 02 | B | hallway, outside room 109, right | | | | | | | 0.197 | 0.172 | P | 0.216 | 0.214 | P | 0.407 | 0.388 | P | P | None |
| 03 | B | hallway, by room 117 | | | | | | | | | | 0.148 | 0.146 | P | 0.14 | 0.118 | P | P | None |
| 04 | BF | hallway, by room 117 | | | | | | | | | | 0.148 | 0.148 | P | 0.135 | 0.129 | P | P | None |
| 05 | B | hallway, outside main office, left | | | | | | | | | | 0.13 | 0.124 | P | 0.195 | 0.197 | P | P | None |
| 06 | B | hallway, outside main office, right | | | | | | | | | | 0.123 | 0.118 | P | 0.205 | 0.21 | P | P | None |
| 07 | B | hallway, by room 125, left | | | | | | | 0.193 | 0.199 | P | 0.152 | 0.15 | P | 0.141 | 0.146 | P | P | None |
| 08 | B | hallway, by room 125, right | | | | | | | 0.174 | 0.21 | P | 0.146 | 0.143 | P | 0.144 | 0.143 | P | P | None |
| 09 | B | gym hallway, left side, left | 0.186 | 0.202 | P | | | | 0.258 | 0.265 | P | 0.25 | 0.272 | P | 0.369 | 0.398 | P | P | None |
| 10 | B | gym hallway, left side, right | 0.194 | 0.186 | P | | | | 0.249 | 0.27 | P | 0.262 | 0.25 | P | 0.317 | 0.318 | P | P | None |
| 11 | B | gym hallway, right side, left | 0.14 | 0.144 | P | | | | 0.239 | 0.258 | P | 0.226 | 0.242 | P | 0.355 | 0.363 | P | P | None |
| 12 | B | gym hallway, right side, right | 0.147 | 0.137 | P | | | | 0.267 | 0.26 | P | 0.24 | 0.243 | P | 0.346 | 0.37 | P | P | None |
| 13 | S | room 212 | | | | 0.518 | 0.424 | P | 0.21 | 0.172 | P | 0.186 | 0.19 | P | 0.33 | 0.153 | P | P | None |
| 14 | B | hallway, left | 0.218 | 0.185 | P | | | | 0.201 | 0.246 | P | 0.198 | 0.187 | P | 0.222 | 0.216 | P | P | None |
| 15 | B | hallway, right | 0.194 | 0.176 | P | | | | 0.151 | 0.136 | P | 0.154 | 0.115 | P | 0.165 | 0.158 | P | P | None |
| 16 | B | gym | 0.248 | 0.185 | P | 0.452 | 0.436 | P | 0.207 | 0.22 | P | 0.185 | 0.187 | P | 0.294 | 0.259 | P | P | None |
| 17 | B | gym | 0.319 | 0.251 | P | | | | 0.196 | 0.199 | P | 0.178 | 0.2 | P | 0.36 | 0.248 | P | P | None |
| 18 | B | Girls locker room | 0.229 | 0.243 | P | | | | 0.216 | 0.209 | P | 0.195 | 0.191 | P | | | | P | None |
| 19 | B | boys locker room | 0.243 | 0.235 | P | | | | 0.186 | 0.229 | P | 0.261 | 0.436 | P | 0.345 | 0.391 | P | P | None |
| 20 | S/B | room 213 | | | | 0.405 | 0.436 | P | 0.243 | 0.243 | P | 0.189 | 0.184 | P | | | | P | None |
| 21 | S | room 214 A | 0.194 | 0.259 | P | | | | 0.233 | 0.234 | P | 0.219 | 0.21 | P | 0.338 | 0.29 | P | P | None |
| 22 | S/B | room 215 | 0.147 | 0.292 | P | | | | 0.212 | 0.195 | P | 0.21 | 0.212 | P | 0.312 | 0.294 | P | P | None |
| 23 | S | room 214 | 0.191 | 0.26 | P | | | | 0.197 | 0.131 | P | 0.177 | 0.206 | P | 0.495 | 0.255 | P | P | None |
| 25 | S | room 204 - right | 0.146 | 0.244 | P | | | | 0.196 | 0.273 | P | 0.184 | 0.258 | P | 0.308 | 0.318 | P | P | None |
| 33 | S | room 201 | | | | 0.689 | 0.64 | P | 0.215 | 0.247 | P | 0.175 | 0.269 | P | 0.29 | 0.41 | P | P | None |
| 34 | S | room 203 | 0.14 | 0.31 | P | | | | 0.218 | 0.316 | P | 0.209 | 0.27 | P | 0.334 | 0.424 | P | P | None |
| 35 | S | nurses office | | | | | | | | | | 0.187 | 0.157 | P | 0.368 | 0.297 | P | P | None |
| 36 | S | room 101 | | | | | | | 0.133 | 0.208 | P | 0.106 | 0.334 | P | 0.368 | 0.145 | P | P | None |
| 37 | S | room 103 | | | | | | | | | | | | | | | | | |
| 38 | S | room 105, left | | | | | | | 0.257 | 0.237 | P | 0.156 | 0.203 | P | 0.49 | 0.45 | P | P | None |
| 40 | S | room 107, left | | | | | | | 0.174 | 0.213 | P | 0.183 | 0.177 | P | 0.349 | 0.208 | P | P | None |
| 50 | S | kitchen sink right | | | | | | | 0.22 | 0.177 | P | 0.136 | 0.103 | P | 0.151 | 0.122 | P | P | None |
| 51 | S | kitchen sink left | | | | | | | 0.196 | 0.131 | P | 0.129 | 0.101 | P | 0.113 | 0.108 | P | P | None |
| 53 | S | teacher lounge | | | | | | | 0.199 | 0.135 | P | 0.161 | 0.101 | P | 0.155 | 0.109 | P | P | None |
| 60 | S | room 202 - special ed | 0.144 | 0.192 | P | 0.483 | 0.354 | P | 0.155 | 0.324 | P | 0.203 | 0.189 | P | 0.237 | 0.192 | P | P | None |
| 61 | S | Kitchen wash sink | | | | | | | 0.187 | 0.145 | P | | | | 0.184 | 0.121 | P | P | None |
| 65 | S | library office | | | | | | | 0.143 | 0.307 | P | 0.172 | 1.26 | P | 0.325 | 0.215 | P | P | None |
| 66 | S | main office | | | | | | | | | | 0.116 | 0.114 | P | 0.196 | 0.151 | P | P | None |
| 68 | S | Kitchen, sink | | | | 0.431 | 0.364 | P | 0.177 | 0.128 | P | 0.15 | 0.136 | P | 0.124 | 0.122 | P | P | None |

Table 5. Iron Test Results

| FIXTURE INFORMATION | | | 7/13/2012 | | 7/7/2015 | | 11/21/2019 | | Summary Status | |
|---------------------|------|-------------------------------------|-----------|-----------|----------|-----------|------------|-----------|----------------|--------|
| Fixture ID | Type | Location | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway, outside room 109, left | | | | | | | P | None |
| 02 | B | hallway, outside room 109, right | | | | | | | P | None |
| 03 | B | hallway, by room 117 | | | | | | | P | None |
| 04 | BF | hallway, by room 117 | | | | | | | P | None |
| 05 | B | hallway, outside main office, left | | | | | | | P | None |
| 06 | B | hallway, outside main office, right | | | | | | | P | None |
| 07 | B | hallway, by room 125, left | | | | | | | P | None |
| 08 | B | hallway, by room 125, right | | | | | | | P | None |
| 09 | B | gym hallway, left side, left | <0.05 | P | | | | | P | None |
| 10 | B | gym hallway, left side, right | | | <0.05 | P | | | P | None |
| 11 | B | gym hallway, right side, left | | | | | | | P | None |
| 12 | B | gym hallway, right side, right | | | | | | | P | None |
| 13 | S | room 212 | | | | | | | P | None |
| 14 | B | hallway, left | | | | | | | P | None |
| 15 | B | hallway, right | | | | | | | P | None |
| 16 | B | gym | | | | | | | P | None |
| 17 | B | gym | | | | | <0.05 | P | P | None |
| 18 | B | Girls locker room | | | | | | | | |
| 19 | B | boys locker room | <0.05 | P | | | | | P | None |
| 20 | S/B | room 213 | | | <0.05 | P | | | P | None |
| 21 | S | room 214 A | | | | | | | P | None |
| 22 | S/B | room 215 | | | | | | | P | None |
| 23 | S | room 214 | <0.05 | P | | | | | P | None |
| 25 | S | room 204 - right | | | <0.05 | P | | | P | None |
| 33 | S | room 201 | <0.05 | P | | | | | P | None |
| 34 | S | room 203 | | | <0.05 | P | | | P | None |
| 35 | S | nurses office | | | | | <0.05 | P | P | None |
| 36 | S | room 101 | | | | | | | P | None |
| 37 | S | room 103 | | | | | | | | |
| 38 | S | room 105, left | | | | | | | P | None |
| 40 | S | room 107, left | | | | | | | P | None |
| 50 | S | kitchen sink right | | | | | <0.05 | P | P | None |
| 51 | S | kitchen sink left | | | | | | | P | None |
| 53 | S | teacher lounge | <0.05 | P | | | | | P | None |
| 60 | S | room 202 - special ed | | | <0.05 | P | | | P | None |
| 61 | S | Kitchen wash sink | | | | | | | | |
| 65 | S | library office | | | | | | | | |
| 66 | S | main office | | | | | | | | |
| 68 | S | Kitchen, sink | | | | | | | | |

Table 6. Service Entry Test Results

| Test Results (Service Entry/SE, Units as Shown) | | | | | | |
|---|------|-------------|----------------------|-----------|-------------|-----------|
| SOURCE INFORMATION | | | Most Recent Sampling | | | |
| Fixture ID | Type | Location | Item | Sampled | Max Value | Pass/Fail |
| 00 | SE | boiler room | Arsenic | 07-Jul-15 | 2 ppb | P |
| 00 | SE | boiler room | Cadmium | 07-Jul-15 | 1 ppb | P |
| 00 | SE | boiler room | Copper | 07-Jul-15 | 0.172 ppm | P |
| 00 | SE | boiler room | E coli | 02-Jun-04 | <1 Colonies | P |
| 00 | SE | boiler room | Iron | 07-Jul-15 | <0.05 ppm | P |
| 00 | SE | boiler room | Lead | 07-Jul-15 | 1 ppb | P |
| 00 | SE | boiler room | Total Coliforms | 05-Sep-08 | <1 Colonies | P |

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.