

**Seattle Public Schools  
Drinking Water Quality Program**

**Results of Water Quality Testing  
for  
Pinehurst**

Updated September 24, 2020

**General Information:**

Plumbing piping materials: mainly copper

**Remediation plan:**

*This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.*

**Sinks (S in the report) are not considered drinking water sources.** We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All tested sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023.

Service: The school will be flushed after any breaks longer than five days.

## Water Quality Testing Results:

### Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S	NURSE, ROOM 11	P	None	P	None	P	None			Yes
02	S	TEACHER'S LOUNGE, ROOM 20	P	None	P	None	P	None			Yes
03	S	TEACHER'S WORK ROOM 19	P	None	P	None	P	None			Yes
04	B	FIRST FLOOR HALLWAY, ADMIN AREA, LEFT	P	None	P	None	P	None			Yes
05	B	FIRST FLOOR HALLWAY, ADMIN AREA, RIGHT	P	None	P	None	P	None	P	None	Yes
06	S	CONFERENCE ROOM 13	P	None	P	None	P	None			Yes
07	S	CLASSROOM 101	P	None	P	None	P	None	P	None	Yes
08	S/B	CLASSROOM 102	P	None	P	None	P	None			Yes
09	S/B	CLASSROOM 103	P	None	P	None	P	None			Yes
10	S/B	CLASSROOM 104	P	None	P	None	P	None			Yes
11	B	FIRST FLOOR HALLWAY, LEFT	P	None	P	None	P	None			Yes
12	B	FIRST FLOOR HALLWAY, RIGHT	P	None	P	None	P	None	P	None	Yes
13	S/B	CLASSROOM 105	P	None	P	None	P	None			Yes
14	S/B	CLASSROOM 106	P	None	P	None	P	None	P	None	Yes
15	S/B	CLASSROOM 107	P	None	P	None	P	None			Yes
16	S/B	CLASSROOM 108	P	None	P	None	P	None	P	None	Yes
17	S/B	CLASSROOM 109	P	None	P	None	P	None			Yes
18	S/B	CLASSROOM 110	P	None	P	None	P	None			Yes
19	B	FIRST FLOOR HALLWAY, LEFT	P	None	P	None	P	None			Yes
20	B	FIRST FLOOR HALLWAY, RIGHT	P	None	P	None	P	None			Yes
21	S	CUSTODIAN OFFICE	P	None	P	None	P	None	P	None	Yes
22	B	FIRST FLOOR HALLWAY BY ART, LEFT	P	None	P	None	P	None			Yes
23	B	FIRST FLOOR HALLWAY BY ART, RIGHT	P	None	P	None	P	None			Yes
24	S	ART CLASSROOM 111	P	None	P	None	P	None	P	None	Yes
25	S	ART CLASSROOM 111, LEFT	P	None	P	None	P	None			Yes
26	S	ART CLASSROOM 111, RIGHT	P	None	P	None	P	None			Yes
27	S	KITCHEN	P	None	P	None	P	None			Yes
28	S	KITCHEN, LEFT	P	None	P	None	P	None			Yes
29	S	KITCHEN, RIGHT	P	None	P	None	P	None	P	None	Yes
30	S/B	BAND ROOM 113	P	None	P	None	P	None			Yes
31	S/B	COMMONS	P	None	P	None	P	None	P	None	Yes
32	B	GYM, LEFT	P	None	P	None	P	None			Yes
33	B	GYM, RIGHT	P	None	P	None	P	None			Yes
34	S/B	DAYCARE, ROOM 258	P	None	P	None	P	None			Yes
35	S	DAYCARE, ROOM 258	P	None	P	None	P	None			Yes
36	S	DAYCARE, ROOM 258	P	None	P	None	P	None			Yes
37	S	DAYCARE, ROOM 258	P	None	P	None	P	None			Yes
38	S	LIBRARY OFFICE	P	None	P	None	P	None			Yes
39	S/B	OT/PT ROOM 212	P	None	P	None	P	None			Yes
40	S/B	CLASSROOM 211	P	None	P	None	P	None			Yes
41	B	SECOND FLOOR HALLWAY, LEFT	P	None	P	None	P	None	P	None	Yes
42	B	SECOND FLOOR HALLWAY, RIGHT	P	None	P	None	P	None			Yes
43	S/B	CLASSROOM 210	P	None	P	None	P	None			Yes
44	S/B	CLASSROOM 209	P	None	P	None	P	None			Yes
45	S/B	CLASSROOM 208	P	None	P	None	P	None			Yes
46	S/B	CLASSROOM 207	P	None	P	None	P	None			Yes

47	S/B	CLASSROOM 206	P	None	P	None	P	None			Yes
48	B	SECOND FLOOR HALLWAY, LEFT	P	None	P	None	P	None	P	None	Yes
49	B	SECOND FLOOR HALLWAY, RIGHT	P	None	P	None	P	None			Yes
50	S/B	CLASSROOM 205	P	None	P	None	P	None	P	None	Yes
51	S/B	CLASSROOM 204	P	None	P	None	P	None			Yes
52	S/B	CLASSROOM 203	P	None	P	None	P	None			Yes
53	S/B	CLASSROOM 202	P	None	P	None	P	None			Yes
54	S/B	CLASSROOM 201	P	None	P	None	P	None			Yes
55	S	ROOM 344	P	None	P	None	P	None	P	None	Yes
56	S/B	CLASSROOM 304	P	None	P	None	P	None			Yes
57	S/B	CLASSROOM 305	P	None	P	None	P	None			Yes
58	B	THIRD FLOOR HALLWAY, LEFT	P	None	P	None	P	None			Yes
59	B	THIRD FLOOR HALLWAY, RIGHT	P	None	P	None	P	None			Yes
60	S/B	CLASSROOM 306	P	None	P	None	P	None	P	None	Yes
61	S/B	CLASSROOM 307	P	None	P	None	P	None			Yes
62	S/B	CLASSROOM 308	P	None	P	None	P	None	P	None	Yes
63	S/B	CLASSROOM 309	P	None	P	None	P	None			Yes
64	S	CLASSROOM 311	P	None	P	None	P	None			Yes
65	B	THIRD FLOOR HALLWAY, LEFT	P	None	P	None	P	None			Yes
66	B	THIRD FLOOR HALLWAY, RIGHT	P	None	P	None	P	None			Yes
67	S/B	DAYCARE, ROOM 258	P	None	P	None	P	None	P	None	Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			8/23/2016			9/11/2016		9/17/2016			7/31/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	NURSE, ROOM 11	<1	<1	P						<1	<1	P	P	None
02	S	TEACHER'S LOUNGE, ROOM 20	1	1	P						<1	<1	P	P	None
03	S	TEACHER'S WORK ROOM 19	<1	<1	P			1	1	P	<1	<1	P	P	None
04	B	FIRST FLOOR HALLWAY, ADMIN AREA, LEFT	<1	1	P						<1	<1	P	P	None
05	B	FIRST FLOOR HALLWAY, ADMIN AREA, RIGHT	<1	1	P						<1	<1	P	P	None
06	S	CONFERENCE ROOM 13	<1	<1	P						<1	<1	P	P	None
07	S	CLASSROOM 101	2	2	P						<1	<1	P	P	None
08	S/B	CLASSROOM 102	<1	<1	P						<1	<1	P	P	None
09	S/B	CLASSROOM 103	1	1	P						<1	<1	P	P	None
10	S/B	CLASSROOM 104	2	1	P						<1	<1	P	P	None
11	B	FIRST FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
12	B	FIRST FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
13	S/B	CLASSROOM 105				<1	P		<1	P	<1	<1	P	P	None
14	S/B	CLASSROOM 106						<1	<1	P	<1	<1	P	P	None
15	S/B	CLASSROOM 107	<1	<1	P						<1	<1	P	P	None
16	S/B	CLASSROOM 108	<1	<1	P						<1	<1	P	P	None
17	S/B	CLASSROOM 109	<1	<1	P						<1	<1	P	P	None
18	S/B	CLASSROOM 110	<1	<1	P						<1	<1	P	P	None
19	B	FIRST FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
20	B	FIRST FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
21	S	CUSTODIAN OFFICE	<1	<1	P						<1	<1	P	P	None
22	B	FIRST FLOOR HALLWAY BY ART, LEFT	<1	1	P						<1	<1	P	P	None
23	B	FIRST FLOOR HALLWAY BY ART, RIGHT	<1	1	P						<1	<1	P	P	None
24	S	ART CLASSROOM 111	<1	<1	P						<1	<1	P	P	None
25	S	ART CLASSROOM 111, LEFT	<1	<1	P						<1	<1	P	P	None
26	S	ART CLASSROOM 111, RIGHT	<1	<1	P						<1	<1	P	P	None
27	S	KITCHEN	<1	<1	P						<1	<1	P	P	None
28	S	KITCHEN, LEFT	2	<1	P						<1	<1	P	P	None
29	S	KITCHEN, RIGHT	<1	<1	P						<1	<1	P	P	None
30	S/B	BAND ROOM 113	<1	<1	P						<1	<1	P	P	None
31	S/B	COMMONS	<1	<1	P						<1	<1	P	P	None
32	B	GYM, LEFT	<1	<1	P						<1	<1	P	P	None
33	B	GYM, RIGHT	<1	<1	P						<1	<1	P	P	None
34	S/B	DAYCARE, ROOM 258	1	<1	P									P	None
35	S	DAYCARE, ROOM 258	1	<1	P									P	None
36	S	DAYCARE, ROOM 258	1	<1	P									P	None
37	S	DAYCARE, ROOM 258	2	<1	P									P	None
38	S	LIBRARY OFFICE	<1	<1	P						<1	<1	P	P	None
39	S/B	OT/PT ROOM 212	<1	<1	P						<1	<1	P	P	None
40	S/B	CLASSROOM 211	<1	<1	P						<1	<1	P	P	None
41	B	SECOND FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
42	B	SECOND FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
43	S/B	CLASSROOM 210	<1	<1	P						<1	<1	P	P	None
44	S/B	CLASSROOM 209	<1	<1	P						2	<1	P	P	None
45	S/B	CLASSROOM 208	<1	<1	P						<1	<1	P	P	None
46	S/B	CLASSROOM 207	<1	<1	P						<1	<1	P	P	None
47	S/B	CLASSROOM 206	<1	<1	P						<1	<1	P	P	None
48	B	SECOND FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None

49	B	SECOND FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
50	S/B	CLASSROOM 205	<1	<1	P						<1	<1	P	P	None
51	S/B	CLASSROOM 204	1	<1	P						<1	<1	P	P	None
52	S/B	CLASSROOM 203	<1	<1	P						<1	<1	P	P	None
53	S/B	CLASSROOM 202	<1	<1	P						<1	<1	P	P	None
54	S/B	CLASSROOM 201						<1	<1	P	<1	<1	P	P	None
55	S	ROOM 344	<1	<1	P						<1	<1	P	P	None
56	S/B	CLASSROOM 304	<1	<1	P						<1	<1	P	P	None
57	S/B	CLASSROOM 305	<1	<1	P						<1	<1	P	P	None
58	B	THIRD FLOOR HALLWAY, LEFT	<1	<1	P						<1	2	P	P	None
59	B	THIRD FLOOR HALLWAY, RIGHT	<1	<1	P						2	2	P	P	None
60	S/B	CLASSROOM 306	1	<1	P						<1	<1	P	P	None
61	S/B	CLASSROOM 307						<1	<1	P	<1	<1	P	P	None
62	S/B	CLASSROOM 308	<1	<1	P						<1	<1	P	P	None
63	S/B	CLASSROOM 309						<1	<1	P	<1	<1	P	P	None
64	S	CLASSROOM 311	<1	<1	P						<1	<1	P	P	None
65	B	THIRD FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
66	B	THIRD FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
67	S/B	DAYCARE, ROOM 258	<1	<1	P									P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			8/23/2016			9/11/2016		9/17/2016			7/31/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	NURSE, ROOM 11	<1	<1	P						<1	<1	P	P	None
02	S	TEACHER'S LOUNGE, ROOM 20	<1	<1	P						<1	<1	P	P	None
03	S	TEACHER'S WORK ROOM 19	<1	<1	P			<1	<1	P	<1	<1	P	P	None
04	B	FIRST FLOOR HALLWAY, ADMIN AREA, LEFT	<1	<1	P						<1	<1	P	P	None
05	B	FIRST FLOOR HALLWAY, ADMIN AREA, RIGHT	<1	<1	P						<1	<1	P	P	None
06	S	CONFERENCE ROOM 13	<1	<1	P						<1	<1	P	P	None
07	S	CLASSROOM 101	<1	<1	P						<1	<1	P	P	None
08	S/B	CLASSROOM 102	<1	<1	P						<1	<1	P	P	None
09	S/B	CLASSROOM 103	<1	<1	P						<1	<1	P	P	None
10	S/B	CLASSROOM 104	<1	<1	P						<1	<1	P	P	None
11	B	FIRST FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
12	B	FIRST FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
13	S/B	CLASSROOM 105				<1	P		<1	P	<1	<1	P	P	None
14	S/B	CLASSROOM 106						<1	<1	P	<1	<1	P	P	None
15	S/B	CLASSROOM 107	<1	<1	P						<1	<1	P	P	None
16	S/B	CLASSROOM 108	<1	<1	P						<1	<1	P	P	None
17	S/B	CLASSROOM 109	<1	<1	P						<1	<1	P	P	None
18	S/B	CLASSROOM 110	<1	<1	P						<1	<1	P	P	None
19	B	FIRST FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
20	B	FIRST FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
21	S	CUSTODIAN OFFICE	<1	<1	P						<1	<1	P	P	None
22	B	FIRST FLOOR HALLWAY BY ART, LEFT	<1	<1	P						<1	<1	P	P	None
23	B	FIRST FLOOR HALLWAY BY ART, RIGHT	<1	<1	P						<1	<1	P	P	None
24	S	ART CLASSROOM 111	<1	<1	P						<1	<1	P	P	None
25	S	ART CLASSROOM 111, LEFT	<1	<1	P						<1	<1	P	P	None
26	S	ART CLASSROOM 111, RIGHT	<1	<1	P						<1	<1	P	P	None
27	S	KITCHEN	<1	<1	P						<1	<1	P	P	None
28	S	KITCHEN, LEFT	<1	<1	P						<1	<1	P	P	None
29	S	KITCHEN, RIGHT	<1	<1	P						<1	<1	P	P	None
30	S/B	BAND ROOM 113	<1	<1	P						<1	<1	P	P	None
31	S/B	COMMONS	<1	<1	P						<1	<1	P	P	None
32	B	GYM, LEFT	<1	<1	P						<1	<1	P	P	None
33	B	GYM, RIGHT	<1	<1	P						<1	<1	P	P	None
34	S/B	DAYCARE, ROOM 258	<1	<1	P									P	None
35	S	DAYCARE, ROOM 258	<1	<1	P									P	None
36	S	DAYCARE, ROOM 258	<1	<1	P									P	None
37	S	DAYCARE, ROOM 258	<1	<1	P									P	None
38	S	LIBRARY OFFICE	<1	<1	P						<1	<1	P	P	None
39	S/B	OT/PT ROOM 212	<1	<1	P						<1	<1	P	P	None
40	S/B	CLASSROOM 211	<1	<1	P						<1	<1	P	P	None
41	B	SECOND FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
42	B	SECOND FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
43	S/B	CLASSROOM 210	<1	<1	P						<1	<1	P	P	None
44	S/B	CLASSROOM 209	<1	<1	P						<1	<1	P	P	None
45	S/B	CLASSROOM 208	<1	<1	P						<1	<1	P	P	None
46	S/B	CLASSROOM 207	<1	<1	P						<1	<1	P	P	None
47	S/B	CLASSROOM 206	<1	<1	P						<1	<1	P	P	None

48	B	SECOND FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
49	B	SECOND FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
50	S/B	CLASSROOM 205	<1	<1	P						<1	<1	P	P	None
51	S/B	CLASSROOM 204	<1	<1	P						<1	<1	P	P	None
52	S/B	CLASSROOM 203	<1	<1	P						<1	<1	P	P	None
53	S/B	CLASSROOM 202	<1	<1	P						<1	<1	P	P	None
54	S/B	CLASSROOM 201					<1	<1	P		<1	<1	P	P	None
55	S	ROOM 344	<1	<1	P						<1	<1	P	P	None
56	S/B	CLASSROOM 304	<1	<1	P						<1	<1	P	P	None
57	S/B	CLASSROOM 305	<1	<1	P						<1	<1	P	P	None
58	B	THIRD FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
59	B	THIRD FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
60	S/B	CLASSROOM 306	<1	<1	P						<1	<1	P	P	None
61	S/B	CLASSROOM 307					<1	<1	P		<1	<1	P	P	None
62	S/B	CLASSROOM 308	<1	<1	P						<1	<1	P	P	None
63	S/B	CLASSROOM 309					<1	<1	P		<1	<1	P	P	None
64	S	CLASSROOM 311	<1	<1	P						<1	<1	P	P	None
65	B	THIRD FLOOR HALLWAY, LEFT	<1	<1	P						<1	<1	P	P	None
66	B	THIRD FLOOR HALLWAY, RIGHT	<1	<1	P						<1	<1	P	P	None
67	S/B	DAYCARE, ROOM 258	<1	<1	P									P	None



Table 4. Copper Test Results

FIXTURE INFORMATION			8/23/2016			9/11/2016		9/17/2016			7/31/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	NURSE, ROOM 11	0.263	0.264	P						0.275	0.337	P	P	None
02	S	TEACHER'S LOUNGE, ROOM 20	0.19	0.16	P						0.295	0.279	P	P	None
03	S	TEACHER'S WORK ROOM 19	2.51	0.274				1.02	0.213	P	0.314	0.325	P	P	None
04	B	FIRST FLOOR HALLWAY, ADMIN AREA, LEFT	0.216	0.205	P						0.28	0.263	P	P	None
05	B	FIRST FLOOR HALLWAY, ADMIN AREA, RIGHT	0.222	0.175	P						0.352	0.269	P	P	None
06	S	CONFERENCE ROOM 13	0.215	0.216	P						0.352	0.324	P	P	None
07	S	CLASSROOM 101	0.198	0.298	P						0.291	0.349	P	P	None
08	S/B	CLASSROOM 102	0.446	0.133	P						0.319	0.366	P	P	None
09	S/B	CLASSROOM 103	0.215	0.159	P						0.272	0.306	P	P	None
10	S/B	CLASSROOM 104	0.189	0.12	P						0.321	0.308	P	P	None
11	B	FIRST FLOOR HALLWAY, LEFT	0.13	0.126	P						0.276	0.244	P	P	None
12	B	FIRST FLOOR HALLWAY, RIGHT	0.221	0.135	P						0.343	0.277	P	P	None
13	S/B	CLASSROOM 105				0.229	P		0.219	P	0.244	0.319	P	P	None
14	S/B	CLASSROOM 106						0.222	0.225	P	0.248	0.28	P	P	None
15	S/B	CLASSROOM 107	0.295	0.215	P						0.262	0.302	P	P	None
16	S/B	CLASSROOM 108	0.18	0.223	P						0.25	0.368	P	P	None
17	S/B	CLASSROOM 109	0.192	0.148	P						0.247	0.313	P	P	None
18	S/B	CLASSROOM 110	0.17	0.145	P						0.26	0.282	P	P	None
19	B	FIRST FLOOR HALLWAY, LEFT	0.184	0.156	P						0.383	0.238	P	P	None
20	B	FIRST FLOOR HALLWAY, RIGHT	0.258	0.133	P						0.429	0.388	P	P	None
21	S	CUSTODIAN OFFICE	0.145	0.022	P						0.282	0.071	P	P	None
22	B	FIRST FLOOR HALLWAY BY ART, LEFT	0.181	0.094	P						0.3	0.316	P	P	None
23	B	FIRST FLOOR HALLWAY BY ART, RIGHT	0.237	0.048	P						0.326	0.296	P	P	None
24	S	ART CLASSROOM 111	0.12	0.179	P						0.267	0.161	P	P	None
25	S	ART CLASSROOM 111, LEFT	0.104	0.164	P						0.24	0.204	P	P	None
26	S	ART CLASSROOM 111, RIGHT	0.091	0.192	P						0.217	0.17	P	P	None
27	S	KITCHEN	0.178	0.178	P						0.27	0.404	P	P	None
28	S	KITCHEN, LEFT	0.452	0.119	P						0.227	0.087	P	P	None
29	S	KITCHEN, RIGHT	0.418	0.3	P						0.291	0.094	P	P	None
30	S/B	BAND ROOM 113	0.311	0.262	P						0.375	0.259	P	P	None
31	S/B	COMMONS	0.36	0.247	P						0.282	0.377	P	P	None
32	B	GYM, LEFT	0.26	0.196	P						0.298	0.244	P	P	None
33	B	GYM, RIGHT	0.324	0.184	P						0.309	0.262	P	P	None
34	S/B	DAYCARE, ROOM 258	0.254	0.098	P									P	None
35	S	DAYCARE, ROOM 258	0.214	0.127	P									P	None
36	S	DAYCARE, ROOM 258	0.378	0.125	P									P	None
37	S	DAYCARE, ROOM 258	0.24	0.097	P									P	None
38	S	LIBRARY OFFICE	0.102	0.122	P						0.272	0.259	P	P	None
39	S/B	OT/PT ROOM 212	0.142	0.14	P						0.306	0.315	P	P	None
40	S/B	CLASSROOM 211	0.137	0.126	P						0.216	0.32	P	P	None
41	B	SECOND FLOOR HALLWAY, LEFT	0.138	0.146	P						0.385	0.381	P	P	None
42	B	SECOND FLOOR HALLWAY, RIGHT	0.145	0.121	P						0.405	0.358	P	P	None
43	S/B	CLASSROOM 210	0.184	0.145	P						0.308	0.321	P	P	None
44	S/B	CLASSROOM 209	0.367	0.155	P						0.352	0.311	P	P	None
45	S/B	CLASSROOM 208	0.179	0.151	P						0.252	0.421	P	P	None
46	S/B	CLASSROOM 207	0.168	0.124	P						0.315	0.292	P	P	None

47	S/B	CLASSROOM 206	0.192	0.189	P						0.473	0.35	P	P	None
48	B	SECOND FLOOR HALLWAY, LEFT	0.203	0.126	P						0.362	0.423	P	P	None
49	B	SECOND FLOOR HALLWAY, RIGHT	0.175	0.128	P						0.361	0.421	P	P	None
50	S/B	CLASSROOM 205	0.173	0.123	P						0.388	0.333	P	P	None
51	S/B	CLASSROOM 204	0.15	0.165	P						0.31	0.557	P	P	None
52	S/B	CLASSROOM 203	0.165	0.153	P						0.281	0.34	P	P	None
53	S/B	CLASSROOM 202	0.358	0.414	P						0.401	0.498	P	P	None
54	S/B	CLASSROOM 201						0.239	0.224	P	0.32	0.415	P	P	None
55	S	ROOM 344	0.408	0.257	P						0.381	0.352	P	P	None
56	S/B	CLASSROOM 304	0.372	0.193	P						0.56	0.432	P	P	None
57	S/B	CLASSROOM 305	0.334	0.148	P						0.506	0.387	P	P	None
58	B	THIRD FLOOR HALLWAY, LEFT	0.355	0.139	P						0.452	0.323	P	P	None
59	B	THIRD FLOOR HALLWAY, RIGHT	0.326	0.156	P						0.424	0.338	P	P	None
60	S/B	CLASSROOM 306	0.242	0.11	P						0.412	0.302	P	P	None
61	S/B	CLASSROOM 307						0.242	0.218	P	0.352	0.313	P	P	None
62	S/B	CLASSROOM 308	0.162	0.133	P						0.395	0.304	P	P	None
63	S/B	CLASSROOM 309						0.243	0.213	P	0.43	0.32	P	P	None
64	S	CLASSROOM 311	0.198	0.127	P						0.375	0.265	P	P	None
65	B	THIRD FLOOR HALLWAY, LEFT	0.298	0.189	P						0.392	0.369	P	P	None
66	B	THIRD FLOOR HALLWAY, RIGHT	0.221	0.183	P						0.376	0.36	P	P	None
67	S/B	DAYCARE, ROOM 258	0.168	0.214	P									P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			8/23/2016					7/31/2020					Summary Status		
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Pass/Fail	Status
01	S	NURSE, ROOM 11													
02	S	TEACHER'S LOUNGE, ROOM 20													
03	S	TEACHER'S WORK ROOM 19													
04	B	FIRST FLOOR HALLWAY, ADMIN AREA, LEFT													
05	B	FIRST FLOOR HALLWAY, ADMIN AREA, RIGHT	8/23/2016			0.19	P							P	None
06	S	CONFERENCE ROOM 13													
07	S	CLASSROOM 101							7/31/2020			0.363	P	P	None
08	S/B	CLASSROOM 102													
09	S/B	CLASSROOM 103													
10	S/B	CLASSROOM 104													
11	B	FIRST FLOOR HALLWAY, LEFT													
12	B	FIRST FLOOR HALLWAY, RIGHT	8/23/2016			<0.05	P							P	None
13	S/B	CLASSROOM 105													
14	S/B	CLASSROOM 106							7/31/2020			<0.05	P	P	None
15	S/B	CLASSROOM 107													
16	S/B	CLASSROOM 108	8/23/2016			<0.05	P							P	None
17	S/B	CLASSROOM 109													
18	S/B	CLASSROOM 110													
19	B	FIRST FLOOR HALLWAY, LEFT													
20	B	FIRST FLOOR HALLWAY, RIGHT													
21	S	CUSTODIAN OFFICE							7/31/2020			<0.05	P	P	None
22	B	FIRST FLOOR HALLWAY BY ART, LEFT													
23	B	FIRST FLOOR HALLWAY BY ART, RIGHT													
24	S	ART CLASSROOM 111	8/23/2016			0.161	P							P	None
25	S	ART CLASSROOM 111, LEFT													
26	S	ART CLASSROOM 111, RIGHT													
27	S	KITCHEN													
28	S	KITCHEN, LEFT													
29	S	KITCHEN, RIGHT							7/31/2020			<0.05	P	P	None
30	S/B	BAND ROOM 113													
31	S/B	COMMONS	8/23/2016			0.054	P							P	None
32	B	GYM, LEFT													
33	B	GYM, RIGHT													
34	S/B	DAYCARE, ROOM 258													
35	S	DAYCARE, ROOM 258													
36	S	DAYCARE, ROOM 258													
37	S	DAYCARE, ROOM 258													
38	S	LIBRARY OFFICE													
39	S/B	OT/PT ROOM 212													
40	S/B	CLASSROOM 211													
41	B	SECOND FLOOR HALLWAY, LEFT	8/23/2016			<0.05	P		7/31/2020			<0.05	P	P	None
42	B	SECOND FLOOR HALLWAY, RIGHT													
43	S/B	CLASSROOM 210													
44	S/B	CLASSROOM 209													
45	S/B	CLASSROOM 208													
46	S/B	CLASSROOM 207													
47	S/B	CLASSROOM 206													
48	B	SECOND FLOOR HALLWAY, LEFT	8/23/2016			0.061	P							P	None

49	B	SECOND FLOOR HALLWAY, RIGHT												
50	S/B	CLASSROOM 205						7/31/2020			<0.05	P	P	None
51	S/B	CLASSROOM 204												
52	S/B	CLASSROOM 203												
53	S/B	CLASSROOM 202												
54	S/B	CLASSROOM 201												
55	S	ROOM 344	8/23/2016			<0.05	P						P	None
56	S/B	CLASSROOM 304												
57	S/B	CLASSROOM 305												
58	B	THIRD FLOOR HALLWAY, LEFT												
59	B	THIRD FLOOR HALLWAY, RIGHT												
60	S/B	CLASSROOM 306						7/31/2020			<0.05	P	P	None
61	S/B	CLASSROOM 307												
62	S/B	CLASSROOM 308	8/23/2016			0.21	P						P	None
63	S/B	CLASSROOM 309												
64	S	CLASSROOM 311												
65	B	THIRD FLOOR HALLWAY, LEFT												
66	B	THIRD FLOOR HALLWAY, RIGHT												
67	S/B	DAYCARE, ROOM 258	8/23/2016			0.148	P						P	None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	OUTSIDE LOADING DOCK	Arsenic	31-Jul-20	2 ppb	P
00	SE	OUTSIDE LOADING DOCK	Cadmium	31-Jul-20	1 ppb	P
00	SE	OUTSIDE LOADING DOCK	Copper	31-Jul-20	0.066 ppm	P
00	SE	OUTSIDE LOADING DOCK	Iron	31-Jul-20	<0.05 ppm	P
00	SE	OUTSIDE LOADING DOCK	Lead	31-Jul-20	1 ppb	P
00	SE	OUTSIDE LOADING DOCK	Total Coliforms	23-Aug-16	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

**Bacteriological Characteristics**

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.