

**Seattle Public Schools  
Drinking Water Quality Program**

**Results of Water Quality Testing  
for  
Sealth High School**

Updated October 1, 2020

**General Information:**

Plumbing piping materials: mainly cooper

**Remediation plan:**

*This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.*

**Sinks (S in the report) are not considered drinking water sources.** We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All fixtures meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023

Service: The school will be flushed after any breaks longer than five days.

## Water Quality Testing Results:

### Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	2ND FLOOR, HALLWAY, OUTSIDE 279,	P	None	P	None	P	None	P	None	Yes
02	BF	2ND FLOOR, HALLWAY, OUTSIDE279,bottle filler	P	None	P	None	P	None	P	None	Yes
03	BF	2ND FLOOR, HALLWAY, OUTSIDE 257, LEFT, bottle filler	P	None	P	None	P	None	P	None	Yes
04	B	2ND FLOOR, HALLWAY, OUTSIDE 257,	P	None	P	None	P	None			Yes
05	B	2ND FLOOR, HALLWAY, OUTSIDE 239, LEFT, bottle filler	P	None	P	None	P	None			Yes
06	BF	2ND FLOOR, HALLWAY, OUTSIDE 239,	P	None	P	None	P	None			Yes
07	B	2ND FLOOR, HALLWAY, OUTSIDE 232	P	None	P	None	P	None	P	None	Yes
08	S	SPECIAL ED. 230	P	None	P	None	P	None			Yes
09	S	SPECIAL ED.	P	None	P	None	P	None			Yes
10	B	2ND FLOOR, HALLWAY, OUTSIDE 206	P	None	P	None	P	None			Yes
11	S	BOOK ROOM 207	P	None	P	None	P	None			Yes
12	S	ROOM 203A	P	None	P	None	P	None			Yes
13	B	AUDITORIUM 200E, LEFT	P	None	P	None	P	None	P	None	Yes
14	B	AUDITORIUM 200E, RIGHT	P	None	P	None	P	None			Yes
15	S	204C	P	None	P	None	P	None			Yes
16	S	214B concession	P	None	P	None	P	None			Yes
17	S	214B concession	P	None	P	None	P	None			Yes
18	S	214B concession	P	None	P	None	P	None			Yes
19	S	214B concession	P	None	P	None	P	None			Yes
20	B	2ND FLOOR, HALLWAY, 214D, LEFT	P	None	P	None	P	None	P	None	Yes
21	B	2ND FLOOR, HALLWAY, 214D, RIGHT	P	None	P	None	P	None	P	None	Yes
22	S	201B	P	None	P	None	P	None			Yes
23	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, LEFT	P	None	P	None	P	None			Yes
24	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, RIGHT	P	None	P	None	P	None			Yes
25	S	222	P	None	P	None	P	None			Yes
26	S	225G COPY ROOM	P	None	P	None	P	None			Yes
27	S	225H TEACHER WORK ROOM	P	None	P	None	P	None			Yes
28	S	HOME EC. 228	P	None	P	None	P	None			Yes
29	S	HOME EC. 228	P	None	P	None	P	None			Yes
30	S	HOME EC. 228	P	None	P	None	P	None			Yes
31	S	HOME EC. 228	P	None	P	None	P	None			Yes
32	S	HOME EC. 228	P	None	P	None	P	None			Yes
33	S	HOME EC. 228	P	None	P	None	P	None			Yes
34	S	HOME EC. 228	P	None	P	None	P	None			Yes
35	BF	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228, bottle filler	P	None	P	None	P	None	P	None	Yes
36	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228,	P	None	P	None	P	None	P	None	Yes
37	B	2ND FLOOR, HALLWAY, OUTSIDE LIBRARY, ROOM 252	P	None	P	None	P	None	P	None	Yes
38	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 263	P	None	P	None	P	None			Yes
39	B	1ST FLOOR, HALLWAY, NORTH STAIRWAY, LEFT	P	None	P	None	P	None			Yes
40	B	1ST FLOOR, HALLWAY, NORTH STAIRWAY, RIGHT	P	None	P	None	P	None	P	None	Yes
45	S	Home Ec room 228	P	None	P	None	P	None	P	None	Yes
46	S	ROOM 147	P	None	P	None	P	None			Yes
47	S	ROOM 143	P	None	P	None	P	None			Yes
49	BF	BUILDING A, COMMONS, LEFT, bottle filler	P	None	P	None	P	None	P	None	Yes
50	B	BUILDING A, COMMONS, RIGHT	P	None	P	None	P	None			Yes
51	B	GYM LOBBY, LEFT	P	None	P	None	P	None	P	None	Yes

52	B	GYM LOBBY, RIGHT	P	None	P	None	P	None			Yes
53	B	GYM LOBBY, LEFT	P	None	P	None	P	None			Yes
54	B	GYM LOBBY, RIGHT	P	None	P	None	P	None	P	None	Yes
55	B	MAIN GYM, LEFT	P	None	P	None	P	None	P	None	Yes
56	B	MAIN GYM, RIGHT	P	None	P	None	P	None			Yes
57	B	MAIN GYM, LEFT	P	None	P	None	P	None			Yes
58	B	MAIN GYM, RIGHT	P	None	P	None	P	None			Yes
59	B	GIRL'S LOCKER, LEFT	P	None	P	None	P	None			Yes
60	B	GIRL'S LOCKER, RIGHT	P	None	P	None	P	None			Yes
61	B	BOY'S LOCKER, LEFT	P	None	P	None	P	None			Yes
62	B	BOY'S LOCKER, RIGHT	P	None	P	None	P	None			Yes
63	B	2nd floor, hallway, outside 201G, bottled filler	P	None	P	None	P	None			Yes
64	BF	2nd floor hallway, outside 201G, bottle filler	P	None	P	None	P	None			Yes
65	BF	1st floor, hallway, north stairway, bottle filler	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			8/17/2010			8/31/2010			9/3/2010			9/20/2010			2/19/2014			6/29/2017			8/12/2020				Summary Status		
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Flush 2m	Pass /Fail	Pass /Fail	Status	
01	B	2ND FLOOR, HALLWAY, OUTSIDE 279,	18	15		8	10	P							<1	<1	P	<1	2	P	2	<1		P	P	None	
02	BF	2ND FLOOR, HALLWAY, OUTSIDE279,bottle filler	13	13		9	15		8	13		2	<1	P	<1	<1	P	1	<1	P					P	None	
03	BF	2ND FLOOR, HALLWAY, OUTSIDE 257, LEFT, bottle filler	1	<1	P										1	<1	P	<1	<1	P	<1	<1		P	P	None	
04	B	2ND FLOOR, HALLWAY, OUTSIDE 257,	<1	<1	P										3	<1	P	1	<1	P	2	<1		P	P	None	
05	B	2ND FLOOR, HALLWAY, OUTSIDE 239, LEFT, bottle filler	3	<1	P										1	<1	P	1	<1	P	3	<1		P	P	None	
06	BF	2ND FLOOR, HALLWAY, OUTSIDE 239,	1	<1	P										2	<1	P	2	<1	P	3	<1		P	P	None	
07	B	2ND FLOOR, HALLWAY, OUTSIDE 232	2	<1	P										2	<1	P	<1	<1	P	<1	<1		P	P	None	
08	S	SPECIAL ED. 230	5	<1	P										<1	<1	P	<1	<1	P	<1	<1		P	P	None	
09	S	SPECIAL ED.	5	3	P										1	<1	P	<1	<1	P	<1	<1		P	P	None	
10	B	2ND FLOOR, HALLWAY, OUTSIDE 206	2	<1	P										1	<1	P	<1	<1	P	<1	<1		P	P	None	
11	S	BOOK ROOM 207	5	<1	P										1	<1	P	1	<1	P	2	<1		P	P	None	
12	S	ROOM 203A	4	<1	P										<1	<1	P	1	<1	P	<1	<1		P	P	None	
13	B	AUDITORIUM 200E, LEFT	<1	<1	P													<1	<1	P	<1	<1		P	P	None	
14	B	AUDITORIUM 200E, RIGHT	2	<1	P													<1	<1	P	<1	<1	<1	P	P	None	
15	S	204C	6	<1	P													1	<1	P	3	1		P	P	None	
16	S	214B concession																2	<1	P	2	<1		P	P	None	
17	S	214B concession																2	<1	P	<1	<1		P	P	None	
18	S	214B concession																<1	<1	P	<1	<1		P	P	None	
19	S	214B concession																1	<1	P	<1	<1		P	P	None	
20	B	2ND FLOOR, HALLWAY, 214D, LEFT	<1	<1	P										<1	<1	P	<1	<1	P	2	<1		P	P	None	
21	B	2ND FLOOR, HALLWAY, 214D, RIGHT	1	<1	P										<1	<1	P	<1	<1	P	1	<1		P	P	None	
22	S	201B	2	<1	P										<1	<1	P	<1	<1	P	2	<1		P	P	None	
23	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, LEFT	<1	<1	P										<1	<1	P	<1	<1	P	<1	<1		P	P	None	
24	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, RIGHT	1	<1	P										<1	<1	P	<1	<1	P	<1	<1		P	P	None	
25	S	222	3	2	P										1	<1	P	<1	<1	P	<1	<1		P	P	None	
26	S	225G COPY ROOM	2	<1	P										2	<1	P	<1	<1	P	1	<1		P	P	None	
27	S	225H TEACHER WORK ROOM	4	2	P										1	<1	P	<1	<1	P	1	<1		P	P	None	
28	S	HOME EC. 228	3	<1	P										1	<1	P	<1	<1	P					P	None	
29	S	HOME EC. 228	2	<1	P										<1	<1	P	<1	<1	P					P	None	
30	S	HOME EC. 228	2	<1	P										<1	<1	P	<1	<1	P					P	None	
31	S	HOME EC. 228	4	<1	P										1	<1	P	<1	<1	P					P	None	
32	S	HOME EC. 228	1	<1	P										<1	<1	P	<1	<1	P					P	None	
33	S	HOME EC. 228										<1	<1	P	<1	<1	P	<1	<1	P					P	None	
34	S	HOME EC. 228													2	<1	P	<1	<1	P						P	None
35	BF	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228, bottle filler	1	1	P										<1	<1	P	<1	<1	P	2	<1		P	P	None	
36	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228,	1	<1	P										<1	<1	P	<1	<1	P	2	<1		P	P	None	
37	B	2ND FLOOR, HALLWAY, OUTSIDE LIBRARY, ROOM 252	2	2	P										<1	<1	P	<1	<1	P	2	1		P	P	None	
38	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 263	3	3	P										<1	<1	P	<1	<1	P	1	<1		P	P	None	
39	B	IST FLOOR, HALLWAY, NORTH STAIRWAY, LEFT	<1	<1	P										<1	<1	P				<1	<1		P	P	None	
40	B	IST FLOOR, HALLWAY, NORTH STAIRWAY, RIGHT	<1	<1	P										<1	<1	P				<1	<1		P	P	None	
45	S	Home Ec room 228	4	<1	P										1	<1	P	<1	<1	P					P	None	
46	S	ROOM 147	<1	<1	P																					P	None
47	S	ROOM 143	7	2	P										1	<1	P	<1	<1	P					P	None	
49	BF	BUILDING A, COMMONS, LEFT, bottle filler	4	6	P										<1	<1	P	<1	<1	P	2	<1		P	P	None	
50	B	BUILDING A, COMMONS, RIGHT	2	2	P										1	<1	P	<1	<1	P	2	1		P	P	None	
51	B	GYM LOBBY, LEFT	1	<1	P													<1	<1	P	<1	<1		P	P	None	
52	B	GYM LOBBY, RIGHT	1	<1	P													<1	<1	P	<1	<1		P	P	None	

53	B	GYM LOBBY, LEFT	4	<1	P												<1	<1	P	5	<1		P	P	None	
54	B	GYM LOBBY, RIGHT	4	<1	P												<1	<1	P	3	<1		P	P	None	
55	B	MAIN GYM, LEFT	<1	<1	P												<1	<1	P	3	<1		P	P	None	
56	B	MAIN GYM, RIGHT	<1	<1	P												<1	<1	P	<1	<1		P	P	None	
57	B	MAIN GYM, LEFT	<1	<1	P												<1	<1	P	1	<1		P	P	None	
58	B	MAIN GYM, RIGHT	<1	<1	P												<1	<1	P	<1	<1		P	P	None	
59	B	GIRL'S LOCKER, LEFT	<1	<1	P												<1	<1	P					P	None	
60	B	GIRL'S LOCKER, RIGHT	<1	<1	P												<1	<1	P					P	None	
61	B	BOY'S LOCKER, LEFT	1	1	P												<1	<1	P					P	None	
62	B	BOY'S LOCKER, RIGHT	2	<1	P												<1	<1	P					P	None	
63	B	2nd floor, hallway, outside 201G, bottled filler															<1	<1	P					P	None	
64	BF	2nd floor hallway, outside 201G, bottle filler																			<1	<1		P	P	None
65	BF	1st floor, hallway, north stairway, bottle filler																			<1	<1		P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			8/17/2010			9/20/2010			2/19/2014			6/29/2017			8/12/2020				Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Flush 2m	Pass /Fail	Pass/ Fail	Status
01	B	2ND FLOOR, HALLWAY, OUTSIDE 279,	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
02	BF	2ND FLOOR, HALLWAY, OUTSIDE279,bottle filler	<1	<1	P				<1	<1	P	<1	<1	P					P	None
03	BF	2ND FLOOR, HALLWAY, OUTSIDE 257, LEFT, bottle filler	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
04	B	2ND FLOOR, HALLWAY, OUTSIDE 257,	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
05	B	2ND FLOOR, HALLWAY, OUTSIDE 239, LEFT, bottle filler	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
06	BF	2ND FLOOR, HALLWAY, OUTSIDE 239,	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
07	B	2ND FLOOR, HALLWAY, OUTSIDE 232	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
08	S	SPECIAL ED. 230	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
09	S	SPECIAL ED.	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
10	B	2ND FLOOR, HALLWAY, OUTSIDE 206	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
11	S	BOOK ROOM 207	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
12	S	ROOM 203A	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
13	B	AUDITORIUM 200E, LEFT	<1	<1	P							<1	<1	P	<1	<1		P	P	None
14	B	AUDITORIUM 200E, RIGHT	<1	<1	P							<1	<1	P	<1	<1	<1	P	P	None
15	S	204C	<1	<1	P							<1	<1	P	<1	<1		P	P	None
16	S	214B concession										<1	<1	P	<1	<1		P	P	None
17	S	214B concession										<1	<1	P	<1	<1		P	P	None
18	S	214B concession										<1	<1	P	<1	<1		P	P	None
19	S	214B concession										<1	<1	P	<1	<1		P	P	None
20	B	2ND FLOOR, HALLWAY, 214D, LEFT	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
21	B	2ND FLOOR, HALLWAY, 214D, RIGHT	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
22	S	201B	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
23	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, LEFT	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
24	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, RIGHT	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
25	S	222	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
26	S	225G COPY ROOM	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
27	S	225H TEACHER WORK ROOM	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
28	S	HOME EC. 228	<1	<1	P				<1	<1	P	<1	<1	P					P	None
29	S	HOME EC. 228	<1	<1	P				<1	<1	P	<1	<1	P					P	None
30	S	HOME EC. 228	<1	<1	P				<1	<1	P	<1	<1	P					P	None
31	S	HOME EC. 228	<1	<1	P				<1	<1	P	<1	<1	P					P	None
32	S	HOME EC. 228	<1	<1	P				<1	<1	P	<1	<1	P					P	None
33	S	HOME EC. 228				<1	<1	P	<1	<1	P	<1	<1	P					P	None
34	S	HOME EC. 228							<1	<1	P	<1	<1	P					P	None
35	BF	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228, bottle filler	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
36	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228,	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
37	B	2ND FLOOR, HALLWAY, OUTSIDE LIBRARY, ROOM 252	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
38	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 263	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
39	B	IST FLOOR, HALLWAY, NORTH STAIRWAY, LEFT	<1	<1	P				<1	<1	P				<1	<1		P	P	None
40	B	IST FLOOR, HALLWAY, NORTH STAIRWAY, RIGHT	<1	<1	P				<1	<1	P				<1	<1		P	P	None
45	S	Home Ec room 228	<1	<1	P				<1	<1	P	<1	<1	P					P	None
46	S	ROOM 147	<1	<1	P														P	None
47	S	ROOM 143	<1	<1	P				<1	<1	P	<1	<1	P					P	None
49	BF	BUILDING A, COMMONS, LEFT, bottle filler	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
50	B	BUILDING A, COMMONS, RIGHT	<1	<1	P				<1	<1	P	<1	<1	P	<1	<1		P	P	None
51	B	GYM LOBBY, LEFT	<1	<1	P							<1	<1	P	<1	<1		P	P	None

52	B	GYM LOBBY, RIGHT	<1	<1	P						<1	<1	P	<1	<1		P	P	None	
53	B	GYM LOBBY, LEFT	<1	<1	P						<1	<1	P	<1	<1		P	P	None	
54	B	GYM LOBBY, RIGHT	<1	<1	P						<1	<1	P	<1	<1		P	P	None	
55	B	MAIN GYM, LEFT	<1	<1	P						<1	<1	P	<1	<1		P	P	None	
56	B	MAIN GYM, RIGHT	<1	<1	P						<1	<1	P	<1	<1		P	P	None	
57	B	MAIN GYM, LEFT	<1	<1	P						<1	<1	P	<1	<1		P	P	None	
58	B	MAIN GYM, RIGHT	<1	<1	P						<1	<1	P	<1	<1		P	P	None	
59	B	GIRL'S LOCKER, LEFT	<1	<1	P						<1	<1	P					P	None	
60	B	GIRL'S LOCKER, RIGHT	<1	<1	P						<1	<1	P					P	None	
61	B	BOY'S LOCKER, LEFT	<1	<1	P						<1	<1	P					P	None	
62	B	BOY'S LOCKER, RIGHT	<1	<1	P						<1	<1	P					P	None	
63	B	2nd floor, hallway, outside 201G, bottled filler									<1	<1	P					P	None	
64	BF	2nd floor hallway, outside 201G, bottle filler												<1	<1			P	P	None
65	BF	1st floor, hallway, north stairway, bottle filler												<1	<1			P	P	None



Table 4. Copper Test Results

FIXTURE INFORMATION			8/17/2010			9/20/2010			2/19/2014			6/29/2017			8/12/2020				Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass/ Fail	1st Draw	Flush 30s	Flush 2m	Pass/ Fail	Pass /Fail	Status
01	B	2ND FLOOR, HALLWAY, OUTSIDE 279,	0.502	0.494	P				0.36	0.256	P	0.177	0.42	P	0.245	0.249		P	P	None
02	BF	2ND FLOOR, HALLWAY, OUTSIDE279,bottle filler	0.446	0.573	P				0.285	0.321	P	0.347	0.334	P					P	None
03	BF	2ND FLOOR, HALLWAY, OUTSIDE 257, LEFT, bottle filler	0.219	0.192	P				0.39	0.345	P	0.178	0.161	P	0.15	0.071		P	P	None
04	B	2ND FLOOR, HALLWAY, OUTSIDE 257,	0.24	0.222	P				0.368	0.248	P	0.225	0.18	P	0.178	0.074		P	P	None
05	B	2ND FLOOR, HALLWAY, OUTSIDE 239, LEFT, bottle filler	0.197	0.161	P				0.41	0.294	P	0.177	0.129	P	0.522	0.13		P	P	None
06	BF	2ND FLOOR, HALLWAY, OUTSIDE 239,	0.163	0.142	P				0.339	0.311	P	0.205	0.139	P	0.152	0.123		P	P	None
07	B	2ND FLOOR, HALLWAY, OUTSIDE 232	0.087	0.076	P				0.458	0.346	P	0.432	0.392	P	0.353	0.4		P	P	None
08	S	SPECIAL ED. 230	0.098	0.177	P				0.106	0.105	P	0.153	0.209	P	0.086	0.043		P	P	None
09	S	SPECIAL ED.	0.087	0.16	P				0.154	0.231	P	0.15	0.162	P	0.012	0.011		P	P	None
10	B	2ND FLOOR, HALLWAY, OUTSIDE 206	0.297	0.219	P				0.715	0.542	P	0.398	0.37	P	0.205	0.163		P	P	None
11	S	BOOK ROOM 207	0.146	0.192	P				0.241	0.289	P	0.175	0.215	P	0.093	0.069		P	P	None
12	S	ROOM 203A	0.094	0.117	P				0.125	0.089	P	0.096	0.059	P	0.059	0.04		P	P	None
13	B	AUDITORIUM 200E, LEFT	0.305	0.25	P							0.264	0.244	P	0.268	0.197		P	P	None
14	B	AUDITORIUM 200E, RIGHT	0.291	0.228	P							0.23	0.219	P	0.224	0.205	0.153	P	P	None
15	S	204C	0.145	0.222	P							0.395	0.303	P	0.151	0.303		P	P	None
16	S	214B concession										0.142	0.048	P	0.115	0.048		P	P	None
17	S	214B concession										0.145	0.046	P	0.085	0.033		P	P	None
18	S	214B concession										0.18	0.044	P	0.123	0.08		P	P	None
19	S	214B concession										0.07	0.043	P	0.043	0.032		P	P	None
20	B	2ND FLOOR, HALLWAY, 214D, LEFT	0.256	0.03	P				0.286	0.253	P	0.162	0.066	P	0.18	0.051		P	P	None
21	B	2ND FLOOR, HALLWAY, 214D, RIGHT	0.089	0.023	P				0.229	0.181	P	0.087	0.046	P	0.279	0.046		P	P	None
22	S	201B	0.101	0.016	P				0.231	0.236	P	0.144	0.137	P	0.096	0.111		P	P	None
23	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, LEFT	0.238	0.04	P				0.243	0.228	P	0.053	0.064	P	0.084	0.079		P	P	None
24	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, RIGHT	0.209	0.172	P				0.265	0.23	P	0.086	0.096	P	0.068	0.066		P	P	None
25	S	222	0.093	0.157	P				0.143	0.176	P	0.891	0.127	P	0.026	0.012		P	P	None
26	S	225G COPY ROOM	0.104	0.13	P				0.126	0.132	P	0.038	0.031	P	0.077	0.067		P	P	None
27	S	225H TEACHER WORK ROOM	0.084	0.127	P				0.163	0.127	P	0.033	0.032	P	0.076	0.074		P	P	None
28	S	HOME EC. 228	0.045	0.013	P				0.185	0.068	P	0.133	0.023	P					P	None
29	S	HOME EC. 228	0.194	0.015	P				0.102	0.048	P	0.283	0.144	P					P	None
30	S	HOME EC. 228	0.098	0.028	P				0.061	0.048	P	0.078	0.024	P					P	None
31	S	HOME EC. 228	0.991	0.164	P				0.132	0.051	P	0.206	0.189	P					P	None
32	S	HOME EC. 228	0.218	0.303	P				0.196	0.052	P	0.285	0.22	P					P	None
33	S	HOME EC. 228				0.084	0.034	P	0.213	0.068	P	0.32	0.215	P					P	None
34	S	HOME EC. 228							0.392	0.26	P	0.227	0.221	P					P	None
35	BF	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228, bottle filler	0.262	0.225	P				0.3	0.222	P	0.197	0.169	P	0.191	0.073		P	P	None
36	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228,	0.122	0.041	P				0.195	0.114	P	0.148	0.076	P	0.268	0.142		P	P	None
37	B	2ND FLOOR, HALLWAY, OUTSIDE LIBRARY, ROOM 252	0.423	0.195	P				0.18	0.136	P	0.106	0.074	P	0.158	0.046		P	P	None
38	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 263	0.179	0.12	P				0.227	0.046	P	0.096	0.058	P	0.143	0.123		P	P	None
39	B	IST FLOOR, HALLWAY, NORTH STAIRWAY, LEFT	0.089	0.112	P				0.041	0.095	P				0.031	0.039		P	P	None
40	B	IST FLOOR, HALLWAY, NORTH STAIRWAY, RIGHT	0.118	0.105	P				0.123	0.145	P				0.042	0.042		P	P	None
45	S	Home Ec room 228	0.144	0.05	P				0.255	0.324	P	0.303	0.238	P					P	None
46	S	ROOM 147	0.07	0.066	P														P	None
47	S	ROOM 143	0.432	0.459	P				0.438	0.33	P	0.181	0.155	P					P	None
49	BF	BUILDING A, COMMONS, LEFT, bottle filler	1.09	0.278	P				0.183	0.194	P	0.196	0.191	P	0.228	0.258		P	P	None
50	B	BUILDING A, COMMONS, RIGHT	0.761	0.679	P				0.235	0.263	P	0.238	0.224	P	0.223	0.211		P	P	None
51	B	GYM LOBBY, LEFT	0.127	0.063	P							0.159	0.157	P	0.206	0.163		P	P	None
52	B	GYM LOBBY, RIGHT	0.109	0.079	P							0.166	0.15	P	0.211	0.185		P	P	None

53	B	GYM LOBBY, LEFT	0.195	0.067	P						0.147	0.121	P	0.149	0.122		P	P	None
54	B	GYM LOBBY, RIGHT	0.232	0.072	P						0.114	0.115	P	0.139	0.118		P	P	None
55	B	MAIN GYM, LEFT	0.16	0.083	P						0.078	0.08	P	0.169	0.07		P	P	None
56	B	MAIN GYM, RIGHT	0.144	0.144	P						0.078	0.076	P	0.076	0.072		P	P	None
57	B	MAIN GYM, LEFT	0.135	0.055	P						0.169	0.228	P	0.117	0.287		P	P	None
58	B	MAIN GYM, RIGHT	0.055	0.049	P						0.177	0.176	P	0.16	0.11		P	P	None
59	B	GIRL'S LOCKER, LEFT	0.092	0.12	P						0.226	0.222	P					P	None
60	B	GIRL'S LOCKER, RIGHT	0.121	0.075	P						0.248	0.209	P					P	None
61	B	BOY'S LOCKER, LEFT	0.115	0.09	P						0.305	0.318	P					P	None
62	B	BOY'S LOCKER, RIGHT	0.12	0.09	P						0.338	0.298	P					P	None
63	B	2nd floor, hallway, outside 201G, bottled filler									0.106	0.111	P					P	None
64	BF	2nd floor hallway, outside 201G, bottle filler												0.036	0.029		P	P	None
65	BF	1st floor, hallway, north stairway, bottle filler												0.076	0.028		P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			8/17/2010		2/19/2014		6/29/2017		8/12/2020		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B	2ND FLOOR, HALLWAY, OUTSIDE 279,	<0.05	P							P	None
02	BF	2ND FLOOR, HALLWAY, OUTSIDE279,bottle filler			<0.05	P					P	None
03	BF	2ND FLOOR, HALLWAY, OUTSIDE 257, LEFT, bottle filler					<0.05	P			P	None
04	B	2ND FLOOR, HALLWAY, OUTSIDE 257,										
05	B	2ND FLOOR, HALLWAY, OUTSIDE 239, LEFT, bottle filler										
06	BF	2ND FLOOR, HALLWAY, OUTSIDE 239,										
07	B	2ND FLOOR, HALLWAY, OUTSIDE 232							<0.05	P	P	None
08	S	SPECIAL ED. 230										
09	S	SPECIAL ED.										
10	B	2ND FLOOR, HALLWAY, OUTSIDE 206										
11	S	BOOK ROOM 207										
12	S	ROOM 203A										
13	B	AUDITORIUM 200E, LEFT	<0.05	P							P	None
14	B	AUDITORIUM 200E, RIGHT										
15	S	204C										
16	S	214B concession										
17	S	214B concession										
18	S	214B concession										
19	S	214B concession										
20	B	2ND FLOOR, HALLWAY, 214D, LEFT					<0.05	P			P	None
21	B	2ND FLOOR, HALLWAY, 214D, RIGHT							<0.05	P	P	None
22	S	201B										
23	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, LEFT										
24	B	2ND FLOOR, HALLWAY, OUTSIDE 201G, RIGHT										
25	S	222										
26	S	225G COPY ROOM										
27	S	225H TEACHER WORK ROOM										
28	S	HOME EC. 228										
29	S	HOME EC. 228										
30	S	HOME EC. 228										
31	S	HOME EC. 228										
32	S	HOME EC. 228										
33	S	HOME EC. 228										
34	S	HOME EC. 228										
35	BF	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228, bottle filler	<0.05	P							P	None
36	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 228,			<0.05	P					P	None
37	B	2ND FLOOR, HALLWAY, OUTSIDE LIBRARY, ROOM 252					<0.05	P			P	None
38	B	2ND FLOOR, HALLWAY, OUTSIDE ROOM 263										
39	B	1ST FLOOR, HALLWAY, NORTH STAIRWAY, LEFT										
40	B	1ST FLOOR, HALLWAY, NORTH STAIRWAY, RIGHT	<0.05	P							P	None
45	S	Home Ec room 228			<0.05	P					P	None
46	S	ROOM 147										
47	S	ROOM 143										
49	BF	BUILDING A, COMMONS, LEFT, bottle filler	<0.05	P					<0.05	P	P	None
50	B	BUILDING A, COMMONS, RIGHT										
51	B	GYM LOBBY, LEFT	<0.05	P							P	None
52	B	GYM LOBBY, RIGHT										
53	B	GYM LOBBY, LEFT										

54	B	GYM LOBBY, RIGHT					<0.05	P			P	None
55	B	MAIN GYM, LEFT	<0.05	P					<0.05	P	P	None
56	B	MAIN GYM, RIGHT										
57	B	MAIN GYM, LEFT										
58	B	MAIN GYM, RIGHT										
59	B	GIRL'S LOCKER, LEFT										
60	B	GIRL'S LOCKER, RIGHT										
61	B	BOY'S LOCKER, LEFT										
62	B	BOY'S LOCKER, RIGHT										
63	B	2nd floor, hallway, outside 201G, bottled filler										
64	BF	2nd floor hallway, outside 201G, bottle filler										
65	BF	1st floor, hallway, north stairway, bottle filler										

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	Location description pending	Arsenic	12-Aug-20	2 ppb	P
00	SE	Location description pending	Cadmium	12-Aug-20	1 ppb	P
00	SE	Location description pending	Copper	12-Aug-20	0.039 ppm	P
00	SE	Location description pending	Iron	12-Aug-20	<0.05 ppm	P
00	SE	Location description pending	Lead	12-Aug-20	1 ppb	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.