

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
Stevens Elementary School**

Updated July 9, 2020

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria:

All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

| Symbol | Definition |
|------------|--|
| SE | service entry (main) |
| B | bubbler |
| S | sink (faucet) |
| B/S | sink/bubbler combination |
| S/B | sink/bubbler combination |
| ppb | parts per billion |
| ppm | parts per million |
| NA | not applicable |
| None | no action required |
| Unk | unknown status or action |
| Sample | sample needs to be taken |
| Re-test | fixture needs to be resampled |
| Conf | resample to confirm measurement |
| No flush | not flushed before sampling |
| Sink | sampled faucet of S/B combo |
| Used | recently used; no 1st draw sample possible |
| PS | post sign |
| Disable(d) | fixture disabled in response to water quality testing |
| BDSS | Bubbler disabled, sign on sink |
| IF | install filter |
| RB | replace bubbler |
| RB/IF | replace bubbler and/or install filter |
| RF | replace faucet |
| RF/IF | replace faucet and/or install filter |
| BW | disable fixture and provide bottled water until remediated |
| Leaks | leaking fixture |
| NW | not working properly (sample S when B of S/B NW) |
| OS | out of service - disabled until fixed |
| RS | return to service - now passes testing |
| Rem | Removed from system - no longer exists |

Table 1. Summary of Results

| FIXTURE INFORMATION | | | LEAD | | CADMIUM | | COPPER | | IRON | | OK? |
|---------------------|------|---------------------------|-----------|--------|-----------|--------|-----------|--------|-----------|--------|---------------|
| Fixture ID | Type | Location | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Yes/No/Status |
| 03 | B | 1st floor hall, left | P | None | P | None | P | None | | | Yes |
| 04 | B | 1st floor hall, right | P | None | P | None | P | None | | | Yes |
| 05 | B | 2nd floor hall, left | P | None | P | None | P | None | | | Yes |
| 06 | B | 2nd floor hall, right | P | None | P | None | P | None | | | Yes |
| 07 | B | cafeteria, left | P | None | P | None | P | None | | | Yes |
| 08 | B | cafeteria, right | P | None | P | None | P | None | P | None | Yes |
| 11 | B | ground floor hall, left | P | None | P | None | P | None | P | None | Yes |
| 12 | B | ground floor hall, right | P | None | P | None | P | None | P | None | Yes |
| 13 | S | office work room | P | None | P | None | P | None | | | Yes |
| 14 | S | teachers lounge | P | None | P | None | P | None | P | None | Yes |
| 15 | S | nurse's office | P | None | P | None | P | None | P | None | Yes |
| 16 | S | room 101, 1st | P | None | P | None | P | None | | | Yes |
| 17 | S | room 102, 2nd | P | None | P | None | P | None | | | Yes |
| 18 | S | room 103, special ed. | P | None | P | None | P | None | | | Yes |
| 19 | S | room 104, special ed | P | None | P | None | P | None | | | Yes |
| 20 | S | room 105, kindergarten | P | None | P | None | P | None | P | None | Yes |
| 21 | S | room 106, kindergarten | P | None | P | None | P | None | P | None | Yes |
| 22 | S | room 202, reading support | P | None | P | None | P | None | P | None | Yes |
| 23 | S | room 203, reading support | P | None | P | None | P | None | P | None | Yes |
| 24 | S | library work room | P | None | P | None | P | None | | | Yes |
| 25 | S | room 204, 1st | P | None | P | None | P | None | | | Yes |
| 26 | S | room 205, 2nd | P | None | P | None | P | None | | | Yes |
| 27 | S | room 206, math/special | P | None | P | None | P | None | P | None | Yes |
| 28 | S | room 207, math/special | P | None | P | None | P | None | P | None | Yes |
| 29 | S | room 301, 4th | P | None | P | None | P | None | P | None | Yes |
| 30 | S | room 303, 4th | P | None | P | None | P | None | P | None | Yes |
| 31 | S | room 304, 5th | P | None | P | None | P | None | P | None | Yes |
| 32 | S | room 305, 5th | P | None | P | None | P | None | P | None | Yes |
| 33 | S | room 306, 3rd | P | None | P | None | P | None | P | None | Yes |
| 34 | S | room 307, 3rd | P | None | P | None | P | None | P | None | Yes |
| 40 | S | Kitchen Left | P | None | P | None | P | None | P | None | Yes |
| 41 | S | Kitchen Right | P | None | P | None | P | None | P | None | Yes |
| 42 | S | room 302, PTA office | P | None | P | None | P | None | | | Yes |
| 46 | S | kitchen, spray | P | None | P | None | P | None | | | Yes |

Table 2. Lead Test Results

| FIXTURE INFORMATION | | | 7/16/2010 | | | 2/15/2013 | | | 8/16/2016 | | | 5/20/2020 | | | Summary Status | |
|---------------------|------|---------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 03 | B | 1st floor hall, left | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 04 | B | 1st floor hall, right | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 05 | B | 2nd floor hall, left | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 06 | B | 2nd floor hall, right | 1 | <1 | P | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 07 | B | cafeteria, left | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 08 | B | cafeteria, right | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 11 | B | ground floor hall, left | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 12 | B | ground floor hall, right | 2 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 13 | S | office work room | | 1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 14 | S | teachers lounge | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 15 | S | nurse's office | 2 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 16 | S | room 101, 1st | 2 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 17 | S | room 102, 2nd | 3 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 18 | S | room 103, special ed. | 2 | 1 | P | 2 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 19 | S | room 104, special ed | 7 | 1 | P | 1 | <1 | P | 3 | 1 | P | <1 | <1 | P | P | None |
| 20 | S | room 105, kindergarten | 2 | 1 | P | 1 | <1 | P | 2 | 1 | P | <1 | <1 | P | P | None |
| 21 | S | room 106, kindergarten | 4 | 1 | P | 2 | 1 | P | 2 | <1 | P | <1 | <1 | P | P | None |
| 22 | S | room 202, reading support | 3 | 1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 23 | S | room 203, reading support | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | 1 | <1 | P | P | None |
| 24 | S | library work room | 9 | 1 | P | 2 | 1 | P | 5 | 1 | P | <1 | <1 | P | P | None |
| 25 | S | room 204, 1st | 1 | 2 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 26 | S | room 205, 2nd | 1 | 1 | P | <1 | <1 | P | <1 | <1 | P | <1 | 1 | P | P | None |
| 27 | S | room 206, math/special | 3 | 1 | P | 4 | <1 | P | 2 | <1 | P | <1 | 1 | P | P | None |
| 28 | S | room 207, math/special | 8 | 3 | P | 3 | 1 | P | 4 | <1 | P | <1 | <1 | P | P | None |
| 29 | S | room 301, 4th | 2 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 30 | S | room 303, 4th | 4 | 1 | P | 3 | | P | 3 | <1 | P | 1 | <1 | P | P | None |
| 31 | S | room 304, 5th | 1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 32 | S | room 305, 5th | 1 | <1 | P | <1 | <1 | P | 2 | <1 | P | <1 | <1 | P | P | None |
| 33 | S | room 306, 3rd | 3 | 1 | P | 2 | <1 | P | 3 | <1 | P | <1 | <1 | P | P | None |
| 34 | S | room 307, 3rd | 2 | 1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 40 | S | Kitchen Left | 9 | 1 | P | 2 | 2 | P | 3 | <1 | P | 1 | <1 | P | P | None |
| 41 | S | Kitchen Right | 6 | 1 | P | 7 | 1 | P | 3 | <1 | P | <1 | <1 | P | P | None |
| 42 | S | room 302, PTA office | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 46 | S | kitchen, spray | 3 | <1 | P | 2 | 2 | P | 6 | <1 | P | <1 | <1 | P | P | None |

Table 3. Cadmium Test Results

| FIXTURE INFORMATION | | | 7/16/2010 | | | 2/15/2013 | | | 8/16/2016 | | | 5/20/2020 | | | Summary Status | |
|---------------------|------|---------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 03 | B | 1st floor hall, left | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 04 | B | 1st floor hall, right | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 05 | B | 2nd floor hall, left | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 06 | B | 2nd floor hall, right | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 07 | B | cafeteria, left | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 08 | B | cafeteria, right | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 11 | B | ground floor hall, left | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 12 | B | ground floor hall, right | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 13 | S | office work room | | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 14 | S | teachers lounge | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 15 | S | nurse's office | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 16 | S | room 101, 1st | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 17 | S | room 102, 2nd | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 18 | S | room 103, special ed. | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 19 | S | room 104, special ed | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 20 | S | room 105, kindergarten | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 21 | S | room 106, kindergarten | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 22 | S | room 202, reading support | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 23 | S | room 203, reading support | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 24 | S | library work room | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 25 | S | room 204, 1st | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 26 | S | room 205, 2nd | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 27 | S | room 206, math/special | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 28 | S | room 207, math/special | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 29 | S | room 301, 4th | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 30 | S | room 303, 4th | <1 | <1 | P | <1 | | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 31 | S | room 304, 5th | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 32 | S | room 305, 5th | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 33 | S | room 306, 3rd | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 34 | S | room 307, 3rd | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 40 | S | Kitchen Left | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 41 | S | Kitchen Right | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 42 | S | room 302, PTA office | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |
| 46 | S | kitchen, spray | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | <1 | <1 | P | P | None |

Table 4. Copper Test Results

| FIXTURE INFORMATION | | | 7/16/2010 | | | 2/15/2013 | | | 8/16/2016 | | | 5/20/2020 | | | Summary Status | |
|---------------------|------|---------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 03 | B | 1st floor hall, left | 0.689 | 0.752 | P | 0.83 | 0.982 | P | 0.325 | 0.31 | P | 0.242 | 0.213 | P | P | None |
| 04 | B | 1st floor hall, right | 0.744 | 0.8 | P | 0.852 | 0.845 | P | 0.252 | 0.237 | P | 0.157 | 0.093 | P | P | None |
| 05 | B | 2nd floor hall, left | 0.59 | 0.121 | P | 0.581 | 0.54 | P | 0.251 | 0.185 | P | 0.101 | 0.072 | P | P | None |
| 06 | B | 2nd floor hall, right | 0.294 | 0.102 | P | 0.722 | 0.756 | P | 0.222 | 0.181 | P | 0.275 | 0.07 | P | P | None |
| 07 | B | cafeteria, left | 0.521 | 0.193 | P | 0.464 | 0.559 | P | 0.177 | 0.182 | P | 0.054 | 0.088 | P | P | None |
| 08 | B | cafeteria, right | 0.799 | 0.847 | P | 0.524 | 0.35 | P | 0.153 | 0.145 | P | 0.121 | 0.038 | P | P | None |
| 11 | B | ground floor hall, left | 0.658 | 0.796 | P | 0.753 | 0.801 | P | 0.216 | 0.24 | P | 0.201 | 0.102 | P | P | None |
| 12 | B | ground floor hall, right | 0.744 | 0.761 | P | 0.792 | 0.72 | P | 0.151 | 0.15 | P | 0.209 | 0.264 | P | P | None |
| 13 | S | office work room | | 0.708 | P | 0.762 | 0.87 | P | 0.26 | 0.361 | P | 0.291 | 0.41 | P | P | None |
| 14 | S | teachers lounge | 0.716 | 0.806 | P | 0.994 | 1 | P | 0.313 | 0.284 | P | 0.253 | 0.357 | P | P | None |
| 15 | S | nurse's office | 0.725 | 0.91 | P | 0.871 | 0.933 | P | 0.271 | 0.35 | P | 0.308 | 0.377 | P | P | None |
| 16 | S | room 101, 1st | 0.779 | 0.968 | P | 0.977 | 0.669 | P | 0.235 | 0.259 | P | 0.237 | 0.091 | P | P | None |
| 17 | S | room 102, 2nd | 0.525 | 0.87 | P | 0.976 | 1.05 | P | 0.226 | 0.307 | P | 0.18 | 0.236 | P | P | None |
| 18 | S | room 103, special ed. | 0.782 | 0.55 | P | 0.83 | 0.598 | P | 0.198 | 0.191 | P | 0.16 | 0.061 | P | P | None |
| 19 | S | room 104, special ed | 0.5 | 0.706 | P | 0.777 | 0.895 | P | 0.283 | 0.32 | P | 0.137 | 0.191 | P | P | None |
| 20 | S | room 105, kindergarten | 0.654 | 0.675 | P | 0.668 | 0.627 | P | 0.255 | 0.209 | P | 0.173 | 0.146 | P | P | None |
| 21 | S | room 106, kindergarten | 0.502 | 0.645 | P | 0.72 | 0.566 | P | 0.183 | 0.128 | P | 0.115 | 0.07 | P | P | None |
| 22 | S | room 202, reading support | 0.771 | 0.122 | P | 1.03 | 0.918 | P | 0.248 | 0.207 | P | 0.336 | 0.351 | P | P | None |
| 23 | S | room 203, reading support | 0.025 | 0.007 | P | 0.099 | 0.006 | P | 0.037 | 0.006 | P | 0.082 | 0.01 | P | P | None |
| 24 | S | library work room | 0.706 | 0.109 | P | 1.11 | 0.501 | P | 0.235 | 0.191 | P | 0.089 | 0.004 | P | P | None |
| 25 | S | room 204, 1st | 0.821 | 0.726 | P | 0.928 | 0.757 | P | 0.005 | 0.004 | P | <0.002 | 0.216 | P | P | None |
| 26 | S | room 205, 2nd | 0.731 | 0.76 | P | 1.03 | 1.03 | P | 0.21 | 0.273 | P | 0.202 | 0.279 | P | P | None |
| 27 | S | room 206, math/special | 0.806 | 0.778 | P | 0.869 | 0.959 | P | 0.257 | 0.334 | P | 0.204 | 0.265 | P | P | None |
| 28 | S | room 207, math/special | 0.747 | 0.61 | P | 0.976 | 0.791 | P | 0.213 | 0.297 | P | 0.149 | 0.008 | P | P | None |
| 29 | S | room 301, 4th | 0.515 | 0.118 | P | 0.929 | 0.79 | P | 0.318 | 0.294 | P | 0.344 | 0.15 | P | P | None |
| 30 | S | room 303, 4th | 0.588 | 0.127 | P | 0.742 | | P | 0.282 | 0.405 | P | 0.31 | 0.169 | P | P | None |
| 31 | S | room 304, 5th | 0.739 | 0.802 | P | 0.968 | 1.1 | P | 0.187 | 0.252 | P | 0.298 | 0.224 | P | P | None |
| 32 | S | room 305, 5th | 0.768 | 0.596 | P | 1.05 | 1.09 | P | 0.574 | 0.704 | P | 0.36 | 0.216 | P | P | None |
| 33 | S | room 306, 3rd | 0.589 | 0.186 | P | 0.827 | 1.11 | P | 0.313 | 0.402 | P | 0.387 | 0.401 | P | P | None |
| 34 | S | room 307, 3rd | 0.701 | 0.649 | P | 0.913 | 0.708 | P | 0.279 | 0.332 | P | 0.332 | 0.083 | P | P | None |
| 40 | S | Kitchen Left | 0.5 | 0.751 | P | 0.741 | 0.403 | P | 0.249 | 0.248 | P | 0.293 | 0.25 | P | P | None |
| 41 | S | Kitchen Right | 0.729 | 0.737 | P | 0.68 | 0.495 | P | 0.262 | 0.173 | P | 0.218 | 0.062 | P | P | None |
| 42 | S | room 302, PTA office | 0.108 | 0.106 | P | 0.838 | 0.557 | P | 0.236 | 0.121 | P | 0.288 | 0.116 | P | P | None |
| 46 | S | kitchen, spray | 0.599 | 0.873 | P | 0.946 | 0.452 | P | 0.166 | 0.187 | P | 0.205 | 0.239 | P | P | None |

Table 5. Iron Test Results

| FIXTURE INFORMATION | | | 7/16/2010 | | 2/15/2013 | | 8/16/2016 | | 5/20/2020 | | Summary Status | |
|---------------------|------|---------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|--------|
| Fixture ID | Type | Location | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Flush 2m | Pass/Fail | Pass/Fail | Status |
| 03 | B | 1st floor hall, left | | | | | | | | | | |
| 04 | B | 1st floor hall, right | | | | | | | | | | |
| 05 | B | 2nd floor hall, left | | | | | | | | | | |
| 06 | B | 2nd floor hall, right | | | | | | | | | | |
| 07 | B | cafeteria, left | | | | | | | | | | |
| 08 | B | cafeteria, right | | | | | | 0.06 | P | P | | None |
| 11 | B | ground floor hall, left | | | | | | | | P | | None |
| 12 | B | ground floor hall, right | | | | | | | | P | | None |
| 13 | S | office work room | | | | | | | | | | |
| 14 | S | teachers lounge | | | | | | | | P | | None |
| 15 | S | nurse's office | | | | | | | | P | | None |
| 16 | S | room 101, 1st | | | | | | | | | | |
| 17 | S | room 102, 2nd | | | | | | | | | | |
| 18 | S | room 103, special ed. | | | | | | | | | | |
| 19 | S | room 104, special ed | | | | | | | | | | |
| 20 | S | room 105, kindergarten | <0.05 | P | | | | | | | P | None |
| 21 | S | room 106, kindergarten | | | 0.055 | P | | | | | P | None |
| 22 | S | room 202, reading support | <0.05 | P | | | <0.05 | P | | | P | None |
| 23 | S | room 203, reading support | | | <0.05 | P | | | <0.05 | P | P | None |
| 24 | S | library work room | | | | | | | | | | |
| 25 | S | room 204, 1st | | | | | | | | | | |
| 26 | S | room 205, 2nd | | | | | | | | | | |
| 27 | S | room 206, math/special | <0.05 | P | | | | | | | P | None |
| 28 | S | room 207, math/special | | | <0.05 | P | | | | | P | None |
| 29 | S | room 301, 4th | | | | | <0.05 | P | | | P | None |
| 30 | S | room 303, 4th | | | | | | | <0.05 | P | P | None |
| 31 | S | room 304, 5th | <0.05 | P | | | | | | | P | None |
| 32 | S | room 305, 5th | | | <0.05 | P | | | | | P | None |
| 33 | S | room 306, 3rd | | | | | <0.05 | P | | | P | None |
| 34 | S | room 307, 3rd | | | | | | | <0.05 | P | P | None |
| 40 | S | Kitchen Left | <0.05 | P | | | | | | | P | None |
| 41 | S | Kitchen Right | | | <0.05 | P | | | | | P | None |
| 42 | S | room 302, PTA office | | | | | | | | | | |
| 46 | S | kitchen, spray | | | | | | | | | | |

Table 6. Service Entry Test Results

| SOURCE INFORMATION | | | <i>Most Recent Sampling</i> | | | |
|--------------------|------|---------------------|-----------------------------|-----------|-------------|-----------|
| Fixture ID | Type | Location | Item | Sampled | Max Value | Pass/Fail |
| 00 | SE | fire sprinkler room | Arsenic | 20-May-20 | 2 ppb | P |
| 00 | SE | fire sprinkler room | Cadmium | 20-May-20 | 1 ppb | P |
| 00 | SE | fire sprinkler room | Chlorine | 20-May-04 | 0.02 ppm | P |
| 00 | SE | fire sprinkler room | Copper | 20-May-20 | 0.082 ppm | P |
| 00 | SE | fire sprinkler room | E coli | 20-May-04 | <1 Colonies | P |
| 00 | SE | fire sprinkler room | Iron | 20-May-20 | 0.064 ppm | P |
| 00 | SE | fire sprinkler room | Lead | 20-May-20 | 1 ppb | P |
| 00 | SE | fire sprinkler room | Total Coliforms | 16-Jul-10 | <1 Colonies | P |

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.