

**Seattle Public Schools  
Drinking Water Quality Program**

**Results of Water Quality Testing  
for**

**Thornton Creek Elementary school**

Updated September 24, 2020

**General Information:**

Plumbing piping materials: mainly copper

**Remediation plan:**

*This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.*

**Sinks (S in the report) are not considered drinking water sources.** We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023.

Service: The school will be flushed after any breaks longer than five days.

## Water Quality Testing Results:

### Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S/B	ROOM 1619	P	None	P	None	P	None			Yes
02	S/B	ROOM 1622	P	None	P	None	P	None			Yes
03	S/B	ROOM 1620	P	None	P	None	P	None			Yes
04	S/B	ROOM 1617	P	None	P	None	P	None			Yes
05	S/B	ROOM 1613	P	None	P	None	P	None			Yes
06	S/B	ROOM 1612	P	None	P	None	P	None			Yes
07	S/B	ROOM 1610	P	None	P	None	P	None	P	None	Yes
08	S/B	ROOM 1611	P	None	P	None	P	None			Yes
09	S/B	ROOM 1606	P	None	P	None	P	None			Yes
10	S/B	ROOM 1604	P	None	P	None	P	None			Yes
11	S	LIBRARY OFFICE 1410	P	None	P	None	P	None			Yes
12	S/B	ROOM 1501	P	None	P	None	P	None			Yes
13	S/B	ROOM 1502	P	None	P	None	P	None			Yes
14	S/B	ROOM 1504	P	None	P	None	P	None	P	None	Yes
15	S/B	ROOM 1503	P	None	P	None	P	None	P	None	Yes
16	S/B	ROOM 1505	P	None	P	None	P	None			Yes
17	S/B	ROOM 1506	P	None	P	None	P	None			Yes
18	S/B	ROOM 1508	P	None	P	None	P	None			Yes
19	S/B	ROOM 1507	P	None	P	None	P	None			Yes
20	S/B	ROOM 1509	P	None	P	None	P	None			Yes
21	S/B	ROOM 2509	P	None	P	None	P	None			Yes
22	S/B	ROOM 2507	P	None	P	None	P	None			Yes
23	S/B	ROOM 2508	P	None	P	None	P	None			Yes
24	S/B	ROOM 2506	P	None	P	None	P	None			Yes
25	S/B	ROOM 2505	P	None	P	None	P	None			Yes
26	S/B	ROOM 2503	P	None	P	None	P	None			Yes
27	S/B	ROOM 2504	P	None	P	None	P	None			Yes
28	S/B	ROOM 2502	P	None	P	None	P	None	P	None	Yes
29	S/B	ROOM 2501	P	None	P	None	P	None			Yes
30	S	ROOM 2402, left	P	None	P	None	P	None			Yes
31	S	ROOM 2402, right	P	None	P	None	P	None			Yes
32	S/B	ROOM 2402	P	None	P	None	P	None			Yes
33	B	ROOM 2102, teacher's lounge	P	None	P	None	P	None			Yes
34	S/B	ROOM 1402	P	None	P	None	P	None			Yes
35	S	ROOM 1402, left	P	None	P	None	P	None			Yes
36	B	COMMONS, LEFT	P	None	P	None	P	None			Yes
37	B	COMMONS, RIGHT	P	None	P	None	P	None			Yes
39	S	DEMO KITCHEN	P	None	P	None	P	None			Yes
41	S	KITCHEN, LEFT	P	None	P	None	P	None			Yes
42	S	KITCHEN, RIGHT	P	None	P	None	P	None	P	None	Yes
43	S	KITCHEN	P	None	P	None	P	None			Yes
46	S	NURSE, 1102	P	None	P	None	P	None			Yes
47	S	NURSE, 1102	P	None	P	None	P	None	P	None	Yes
48	S/B	ROOM 1702	P	None	P	None	P	None			Yes
49	S/B	ROOM 1701	P	None	P	None	P	None	P	None	Yes

50	S	room 1314	P	None	P	None	P	None			Yes
55	S	KITHCEN, PRE-K	P	None	P	None	P	None			Yes
56	S	KITCHEN, PRE-K	P	None	P	None	P	None			Yes
57	B	GYM 1309, LEFT	P	None	P	None	P	None			Yes
58	B	GYM 1309, RIGHT	P	None	P	None	P	None			Yes
60	Unk	outside by playground (for ER preparation)	P	None	P	None	P	None			Yes
77	B	first floor hallway, bottle filler	P	None	P	None	P	None	P	None	Yes
78	B	First Floor hallway, left	P	None	P	None	P	None			Yes
79	B	First Floor hallway, right	P	None	P	None	P	None			Yes
80	S	room 1402, right	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			8/30/2016			9/11/2016			8/22/2017		10/11/2019			8/5/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	ROOM 1619	<1	<1	P									<1	<1	P	P	None
02	S/B	ROOM 1622	<1	<1	P									<1	<1	P	P	None
03	S/B	ROOM 1620	<1	<1	P									<1	<1	P	P	None
04	S/B	ROOM 1617	<1	<1	P									<1	<1	P	P	None
05	S/B	ROOM 1613	<1	<1	P									<1	<1	P	P	None
06	S/B	ROOM 1612	<1	<1	P									<1	<1	P	P	None
07	S/B	ROOM 1610	<1	<1	P									<1	<1	P	P	None
08	S/B	ROOM 1611	<1	<1	P									<1	<1	P	P	None
09	S/B	ROOM 1606	<1	<1	P									<1	<1	P	P	None
10	S/B	ROOM 1604	<1	<1	P									<1	<1	P	P	None
11	S	LIBRARY OFFICE 1410				<1	<1	P						<1	<1	P	P	None
12	S/B	ROOM 1501	<1	<1	P									<1	<1	P	P	None
13	S/B	ROOM 1502	<1	<1	P									<1	<1	P	P	None
14	S/B	ROOM 1504	<1	<1	P									<1	<1	P	P	None
15	S/B	ROOM 1503	<1	<1	P									<1	<1	P	P	None
16	S/B	ROOM 1505	<1	<1	P									<1	<1	P	P	None
17	S/B	ROOM 1506	<1	<1	P									<1	<1	P	P	None
18	S/B	ROOM 1508	<1	<1	P									<1	<1	P	P	None
19	S/B	ROOM 1507	<1	<1	P									<1	<1	P	P	None
20	S/B	ROOM 1509	<1	<1	P									<1	<1	P	P	None
21	S/B	ROOM 2509				<1	<1	P						<1	<1	P	P	None
22	S/B	ROOM 2507				<1	<1	P						<1	<1	P	P	None
23	S/B	ROOM 2508				<1	<1	P						<1	<1	P	P	None
24	S/B	ROOM 2506				<1	<1	P						<1	<1	P	P	None
25	S/B	ROOM 2505				<1	<1	P						<1	<1	P	P	None
26	S/B	ROOM 2503				<1	<1	P						<1	<1	P	P	None
27	S/B	ROOM 2504				<1	<1	P						<1	<1	P	P	None
28	S/B	ROOM 2502				<1	<1	P						<1	<1	P	P	None
29	S/B	ROOM 2501				<1	<1	P						<1	<1	P	P	None
30	S	ROOM 2402, left				<1	<1	P						<1	<1	P	P	None
31	S	ROOM 2402, right				<1	<1	P						<1	<1	P	P	None
32	S/B	ROOM 2402									<1	<1	P	<1	<1	P	P	None
33	B	ROOM 2102, teacher's lounge									<1	<1	P	<1	<1	P	P	None
34	S/B	ROOM 1402				<1	<1	P						<1	<1	P	P	None
35	S	ROOM 1402, left				<1	<1	P						<1	<1	P	P	None
36	B	COMMONS, LEFT				<1	<1	P						<1	<1	P	P	None
37	B	COMMONS, RIGHT				<1	<1	P						<1	<1	P	P	None
39	S	DEMO KITCHEN				<1	<1	P						<1	<1	P	P	None
41	S	KITCHEN, LEFT	<1	<1	P									<1	<1	P	P	None
42	S	KITCHEN, RIGHT	<1	<1	P									<1	<1	P	P	None
43	S	KITCHEN	<1	<1	P									<1	<1	P	P	None
46	S	NURSE, 1102				<1	<1	P						<1	<1	P	P	None
47	S	NURSE, 1102				<1	<1	P						<1	<1	P	P	None
48	S/B	ROOM 1702	<1	<1	P									<1	<1	P	P	None
49	S/B	ROOM 1701	<1	<1	P									<1	<1	P	P	None
50	S	room 1314	<1	<1	P									<1	<1	P	P	None
55	S	KITHCEN, PRE-K				<1	<1	P						<1	<1	P	P	None
56	S	KITCHEN, PRE-K				<1	<1	P						<1	<1	P	P	None

57	B	GYM 1309, LEFT	<1	<1	P								<1	<1	P	P	None
58	B	GYM 1309, RIGHT	<1	<1	P								<1	<1	P	P	None
60	Unk	outside by playground (for ER preparation)						<1	P							P	None
77	B	first floor hallway, bottle filler				<1	<1	P					<1	<1	P	P	None
78	B	First Floor hallway, left				<1	<1	P					<1	<1	P	P	None
79	B	First Floor hallway, right				<1	<1	P					<1	<1	P	P	None
80	S	room 1402, right				<1	<1	P					<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			8/30/2016			9/11/2016			8/22/2017		10/11/2019			8/5/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	ROOM 1619	<1	<1	P									<1	<1	P	P	None
02	S/B	ROOM 1622	<1	<1	P									<1	<1	P	P	None
03	S/B	ROOM 1620	<1	<1	P									<1	<1	P	P	None
04	S/B	ROOM 1617	<1	<1	P									<1	<1	P	P	None
05	S/B	ROOM 1613	<1	<1	P									<1	<1	P	P	None
06	S/B	ROOM 1612	<1	<1	P									<1	<1	P	P	None
07	S/B	ROOM 1610	<1	<1	P									<1	<1	P	P	None
08	S/B	ROOM 1611	<1	<1	P									<1	<1	P	P	None
09	S/B	ROOM 1606	<1	<1	P									<1	<1	P	P	None
10	S/B	ROOM 1604	<1	<1	P									<1	<1	P	P	None
11	S	LIBRARY OFFICE 1410				<1	<1	P						<1	<1	P	P	None
12	S/B	ROOM 1501	<1	<1	P									<1	<1	P	P	None
13	S/B	ROOM 1502	<1	<1	P									<1	<1	P	P	None
14	S/B	ROOM 1504	<1	<1	P									<1	<1	P	P	None
15	S/B	ROOM 1503	<1	<1	P									<1	<1	P	P	None
16	S/B	ROOM 1505	<1	<1	P									<1	<1	P	P	None
17	S/B	ROOM 1506	<1	<1	P									<1	<1	P	P	None
18	S/B	ROOM 1508	<1	<1	P									<1	<1	P	P	None
19	S/B	ROOM 1507	<1	<1	P									<1	<1	P	P	None
20	S/B	ROOM 1509	<1	<1	P									<1	<1	P	P	None
21	S/B	ROOM 2509				<1	<1	P						<1	<1	P	P	None
22	S/B	ROOM 2507				<1	<1	P						<1	<1	P	P	None
23	S/B	ROOM 2508				<1	<1	P						<1	<1	P	P	None
24	S/B	ROOM 2506				<1	<1	P						<1	<1	P	P	None
25	S/B	ROOM 2505				<1	<1	P						<1	<1	P	P	None
26	S/B	ROOM 2503				<1	<1	P						<1	<1	P	P	None
27	S/B	ROOM 2504				<1	<1	P						<1	<1	P	P	None
28	S/B	ROOM 2502				<1	<1	P						<1	<1	P	P	None
29	S/B	ROOM 2501				<1	<1	P						<1	<1	P	P	None
30	S	ROOM 2402, left				<1	<1	P						<1	<1	P	P	None
31	S	ROOM 2402, right				<1	<1	P						<1	<1	P	P	None
32	S/B	ROOM 2402									<1	<1	P	<1	<1	P	P	None
33	B	ROOM 2102, teacher's lounge									<1	<1	P	<1	<1	P	P	None
34	S/B	ROOM 1402				<1	<1	P						<1	<1	P	P	None
35	S	ROOM 1402, left				<1	<1	P						<1	<1	P	P	None
36	B	COMMONS, LEFT				<1	<1	P						<1	<1	P	P	None
37	B	COMMONS, RIGHT				<1	<1	P						<1	<1	P	P	None
39	S	DEMO KITCHEN				<1	<1	P						<1	<1	P	P	None
41	S	KITCHEN, LEFT	<1	<1	P									<1	<1	P	P	None
42	S	KITCHEN, RIGHT	<1	<1	P									<1	<1	P	P	None
43	S	KITCHEN	<1	<1	P									<1	<1	P	P	None
46	S	NURSE, 1102				<1	<1	P						<1	<1	P	P	None
47	S	NURSE, 1102				<1	<1	P						<1	<1	P	P	None
48	S/B	ROOM 1702	<1	<1	P									<1	<1	P	P	None
49	S/B	ROOM 1701	<1	<1	P									<1	<1	P	P	None
50	S	room 1314	<1	<1	P									<1	<1	P	P	None
55	S	KITHCEN, PRE-K				<1	<1	P						<1	<1	P	P	None

56	S	KITCHEN, PRE-K				<1	<1	P					<1	<1	P	P	None
57	B	GYM 1309, LEFT	<1	<1	P								<1	<1	P	P	None
58	B	GYM 1309, RIGHT	<1	<1	P								<1	<1	P	P	None
60	Unk	outside by playground (for ER preparation)							<1	P						P	None
77	B	first floor hallway, bottle filler				<1	<1	P					<1	<1	P	P	None
78	B	First Floor hallway, left				<1	<1	P					<1	<1	P	P	None
79	B	First Floor hallway, right				<1	<1	P					<1	<1	P	P	None
80	S	room 1402, right				<1	<1	P					<1	<1	P	P	None



Table 4. Copper Test Results

FIXTURE INFORMATION			8/30/2016			9/11/2016			8/22/2017		10/11/2019			8/5/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	ROOM 1619	0.178	0.188	P									0.146	0.16	P	P	None
02	S/B	ROOM 1622	0.203	0.192	P									0.189	0.17	P	P	None
03	S/B	ROOM 1620	0.211	0.189	P									0.148	0.136	P	P	None
04	S/B	ROOM 1617	0.198	0.168	P									0.143	0.126	P	P	None
05	S/B	ROOM 1613	0.21	0.201	P									0.176	0.128	P	P	None
06	S/B	ROOM 1612	0.213	0.218	P									0.056	0.102	P	P	None
07	S/B	ROOM 1610	0.205	0.214	P									0.152	0.107	P	P	None
08	S/B	ROOM 1611	0.217	0.166	P									0.15	0.105	P	P	None
09	S/B	ROOM 1606	0.227	0.213	P									0.065	0.064	P	P	None
10	S/B	ROOM 1604	0.199	0.188	P									0.204	0.18	P	P	None
11	S	LIBRARY OFFICE 1410				0.254	0.18	P						0.155	0.158	P	P	None
12	S/B	ROOM 1501	0.215	0.218	P									0.163	0.099	P	P	None
13	S/B	ROOM 1502	0.164	0.158	P									0.1	0.132	P	P	None
14	S/B	ROOM 1504	0.163	0.154	P									0.186	0.095	P	P	None
15	S/B	ROOM 1503	0.166	0.158	P									0.133	0.058	P	P	None
16	S/B	ROOM 1505	0.16	0.173	P									0.089	0.07	P	P	None
17	S/B	ROOM 1506	0.16	0.157	P									0.206	0.127	P	P	None
18	S/B	ROOM 1508	0.166	0.175	P									0.062	0.053	P	P	None
19	S/B	ROOM 1507	0.175	0.192	P									0.069	0.057	P	P	None
20	S/B	ROOM 1509	0.15	0.171	P									0.06	0.053	P	P	None
21	S/B	ROOM 2509				0.171	0.157	P						0.053	0.049	P	P	None
22	S/B	ROOM 2507				0.159	0.129	P						0.088	0.072	P	P	None
23	S/B	ROOM 2508				0.15	0.172	P						0.067	0.067	P	P	None
24	S/B	ROOM 2506				0.17	0.171	P						0.14	0.077	P	P	None
25	S/B	ROOM 2505				0.166	0.12	P						0.127	0.066	P	P	None
26	S/B	ROOM 2503				0.172	0.131	P						0.064	0.068	P	P	None
27	S/B	ROOM 2504				0.174	0.165	P						0.147	0.076	P	P	None
28	S/B	ROOM 2502				0.175	0.169	P						0.048	0.045	P	P	None
29	S/B	ROOM 2501				0.2	0.158	P						0.077	0.041	P	P	None
30	S	ROOM 2402, left				0.174	0.196	P						0.097	0.069	P	P	None
31	S	ROOM 2402, right				0.173	0.197	P						0.083	0.068	P	P	None
32	S/B	ROOM 2402									0.154	0.121	P	0.233	0.101	P	P	None
33	B	ROOM 2102, teacher's lounge									0.143	0.138	P	0.06	0.057	P	P	None
34	S/B	ROOM 1402				0.238	0.196	P						0.18	0.146	P	P	None
35	S	ROOM 1402, left				0.171	0.204	P						0.131	0.103	P	P	None
36	B	COMMONS, LEFT				0.192	0.149	P						0.161	0.129	P	P	None
37	B	COMMONS, RIGHT				0.264	0.209	P						0.165	0.124	P	P	None
39	S	DEMO KITCHEN				0.217	0.26	P						0.106	0.107	P	P	None
41	S	KITCHEN, LEFT	0.2	0.124	P									0.13	0.071	P	P	None
42	S	KITCHEN, RIGHT	0.209	0.175	P									0.076	0.04	P	P	None
43	S	KITCHEN	0.209	0.209	P									0.15	0.153	P	P	None
46	S	NURSE, 1102				0.208	0.136	P						0.128	0.055	P	P	None
47	S	NURSE, 1102				0.208	0.215	P						0.071	0.063	P	P	None
48	S/B	ROOM 1702	0.169	0.19	P									0.04	0.046	P	P	None
49	S/B	ROOM 1701	0.135	0.154	P									0.049	0.058	P	P	None
50	S	room 1314	0.174	0.201	P									0.101	0.075	P	P	None

55	S	KITHCEN, PRE-K				0.178	0.153	P					0.073	0.043	P	P	None
56	S	KITCHEN, PRE-K				0.16	0.15	P					0.064	0.048	P	P	None
57	B	GYM 1309, LEFT	0.226	0.233	P								0.067	0.072	P	P	None
58	B	GYM 1309, RIGHT	0.19	0.195	P								0.068	0.065	P	P	None
60	Unk	outside by playground (for ER preparation)							0.03	P						P	None
77	B	first floor hallway, bottle filler				0.049	0.05	P					0.193	0.049	P	P	None
78	B	First Floor hallway, left				0.132	0.081	P					0.042	0.043	P	P	None
79	B	First Floor hallway, right				0.243	0.259	P					0.039	0.043	P	P	None
80	S	room 1402, right				0.182	0.164	P					0.135	0.103	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			8/30/2016		8/5/2020		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	S/B	ROOM 1619						Sample
02	S/B	ROOM 1622						Sample
03	S/B	ROOM 1620						Sample
04	S/B	ROOM 1617						Sample
05	S/B	ROOM 1613						Sample
06	S/B	ROOM 1612						Sample
07	S/B	ROOM 1610	<0.05	P	<0.05	P	P	None
08	S/B	ROOM 1611						
09	S/B	ROOM 1606						
10	S/B	ROOM 1604						
11	S	LIBRARY OFFICE 1410						
12	S/B	ROOM 1501						
13	S/B	ROOM 1502						
14	S/B	ROOM 1504	<0.05	P			P	None
15	S/B	ROOM 1503			<0.05	P	P	None
16	S/B	ROOM 1505						
17	S/B	ROOM 1506						
18	S/B	ROOM 1508						
19	S/B	ROOM 1507						
20	S/B	ROOM 1509						
21	S/B	ROOM 2509						
22	S/B	ROOM 2507						
23	S/B	ROOM 2508						
24	S/B	ROOM 2506						
25	S/B	ROOM 2505						
26	S/B	ROOM 2503						
27	S/B	ROOM 2504						
28	S/B	ROOM 2502			<0.05	P	P	None
29	S/B	ROOM 2501						
30	S	ROOM 2402, left						
31	S	ROOM 2402, right						
32	S/B	ROOM 2402						
33	B	ROOM 2102, teacher's lounge						
34	S/B	ROOM 1402						
35	S	ROOM 1402, left						
36	B	COMMONS, LEFT						
37	B	COMMONS, RIGHT						
39	S	DEMO KITCHEN						
41	S	KITCHEN, LEFT						
42	S	KITCHEN, RIGHT	0.206	P			P	None
43	S	KITCHEN						
46	S	NURSE, 1102						
47	S	NURSE, 1102			0.056	P	P	None
48	S/B	ROOM 1702						
49	S/B	ROOM 1701	<0.05	P			P	None
50	S	room 1314						
55	S	KITHCEN, PRE-K						
56	S	KITCHEN, PRE-K						

57	B	GYM 1309, LEFT						
58	B	GYM 1309, RIGHT						
60	Unk	outside by playground (for ER preparation)						
77	B	first floor hallway, bottle filler			<0.05	P	P	None
78	B	First Floor hallway, left						
79	B	First Floor hallway, right						
80	S	room 1402, right						

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	BOILER ROOM SINK 1205	Arsenic	05-Aug-20	2 ppb	P
00	SE	BOILER ROOM SINK 1205	Cadmium	05-Aug-20	1 ppb	P
00	SE	BOILER ROOM SINK 1205	Copper	05-Aug-20	0.024 ppm	P
00	SE	BOILER ROOM SINK 1205	Iron	05-Aug-20	0.139 ppm	P
00	SE	BOILER ROOM SINK 1205	Lead	05-Aug-20	1 ppb	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

**Bacteriological Characteristics**

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.