

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
Van Asselt Elementary school

Updated September 24, 2018

General Information:

Plumbing piping materials: galvanized steel

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria: All sources in the new building meet the policy criteria.

The Old (wood) building is not being used and was not tested, all fixtures in the Old building will be disabled or post signs.

Follow-up monitoring: Will be performed in school year 2021-2022.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

| Symbol | Definition |
|------------|--|
| SE | service entry (main) |
| B | bubbler |
| S | sink (faucet) |
| B/S | sink/bubbler combination |
| S/B | sink/bubbler combination |
| ppb | parts per billion |
| ppm | parts per million |
| NA | not applicable |
| None | no action required |
| Unk | unknown status or action |
| Sample | sample needs to be taken |
| Re-test | fixture needs to be resampled |
| Conf | resample to confirm measurement |
| No flush | not flushed before sampling |
| Sink | sampled faucet of S/B combo |
| Used | recently used; no 1st draw sample possible |
| PS | post sign |
| Disable(d) | fixture disabled in response to water quality testing |
| IF | install filter |
| RB | replace bubbler |
| RB/IF | replace bubbler and/or install filter |
| RF | replace faucet |
| RF/IF | replace faucet and/or install filter |
| BW | disable fixture and provide bottled water until remediated |
| Leaks | leaking fixture |
| NW | not working properly (sample S when B of S/B NW) |
| OS | out of service - disabled until fixed |
| RS | return to service - now passes testing |
| Rem | Removed from system - no longer exists |

Table 1. Summary of Results

| FIXTURE INFORMATION | | | CURRENT STATUS | | | | | | | | |
|---------------------|------|--|----------------|---------|-----------|---------|-----------|--------|-----------|--------|---------------|
| | | | LEAD | | CADMIUM | | COPPER | | IRON | | OK? |
| Fixture ID | Type | Location | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Pass/Fail | Status | Yes/No/Status |
| 01 | B | hallway, by room 20 | P | None | P | None | P | None | P | None | Yes |
| 02 | B | hallway. By room 17 | P | None | P | None | P | None | P | None | Yes |
| 03 | B | hallway, by room 14 | P | None | P | None | P | None | P | None | Yes |
| 04 | B | hallway, by library | P | None | P | None | P | None | P | None | Yes |
| 05 | B | hallway, by room 10 | P | None | P | None | P | None | P | None | Yes |
| 06 | B | hallway near office | P | None | P | None | P | None | P | None | Yes |
| 07 | B | hallway near office | P | None | P | None | P | None | P | None | Yes |
| 08 | B | next to gym boy's restroom | P | None | P | None | P | None | P | None | Yes |
| 09 | B | next to gym girl's restroom | P | None | P | None | P | None | | | Yes |
| 10 | B | hallway, by room 8, left | P | None | P | None | P | None | P | None | Yes |
| 11 | B | hallway, by room 8, right | P | None | P | None | P | None | | | Yes |
| 12 | B | hallway (top stairs), by room 6 | P | None | P | None | P | None | | | Yes |
| 13 | B | hallway, by room 7 | P | None | P | None | P | None | P | None | Yes |
| 14 | B | room # 2 | P | None | P | None | P | None | P | None | Yes |
| 15 | B | hallway, by room 3 | P | None | P | None | P | None | P | None | Yes |
| 16 | B | room # 1 | P | None | P | None | P | None | P | None | Yes |
| 17 | B | old bldg basement room 22 | | OS | | Pending | P | None | P | None | #NAME? |
| 18 | B | old bldg main floor | P | None | P | None | P | None | P | None | Yes |
| 20 | S | nurse's office, old bldg. Resource | | Pending | P | None | P | None | P | None | #NAME? |
| 21 | S | kitchen (rear wall), East wall, left | P | None | P | None | P | None | P | None | Yes |
| 26 | S | Brick Bld, Rm 1 (West on South Wall), right | P | None | P | None | P | None | P | None | Yes |
| 27 | S | Brick Bld, Rm 2 (South Wall) | P | None | P | None | P | None | P | None | Yes |
| 28 | S | Brick Bld, Rm 2 (East on North Wall), right | P | None | P | None | P | None | P | None | Yes |
| 29 | S | Brick Bld, Rm 2 (West on North Wall), left | P | None | P | None | P | None | P | None | Yes |
| 30 | S | Brick Bld, Rm 3, North Wall | P | None | P | None | P | None | P | None | Yes |
| 31 | S | Brick Bld, Rm 4, South Wall | P | None | P | None | P | None | P | None | Yes |
| 32 | S | Brick Bld, Rm 5, North Wall | P | None | P | None | P | None | P | None | Yes |
| 33 | S | Brick Bld, Rm 6, South Wall | P | None | P | None | P | None | P | None | Yes |
| 34 | S | Brick Bld, Rm 7, North Wall | P | None | P | None | P | None | P | None | Yes |
| 35 | S | Brick Bld, Rm 8, South Wall | P | None | P | None | P | None | P | None | Yes |
| 36 | S | Brick Bld, Nurses Office, West Wall | P | None | P | None | P | None | P | None | Yes |
| 37 | S | Brick Bld, Faculty Lounge, North Wall | P | None | P | None | P | None | P | None | Yes |
| 38 | S | Brick Bld, Library, North Wall | P | None | P | None | P | None | P | None | Yes |
| 39 | S | Brick Bld, Rm 10, South Wall | P | None | P | None | P | None | P | None | Yes |
| 40 | S | Brick Bld, Rm 12, South Wall | P | None | P | None | P | None | P | None | Yes |
| 41 | S | Brick Bld, Rm 13, North Wall | P | None | P | None | P | None | P | None | Yes |
| 42 | S | Brick Bld, Rm 14, South Wall | P | None | P | None | P | None | P | None | Yes |
| 43 | S | Brick Bld, Rm 15, North Wall | P | None | P | None | P | None | P | None | Yes |
| 44 | S | Brick Bld, Rm 16, South Wall | P | None | P | None | P | None | P | None | Yes |
| 45 | S | Brick Bld, Rm 17, North Wall | P | None | P | None | P | None | P | None | Yes |
| 46 | S | Brick Bld, Rm 18, South Wall | P | None | P | None | P | None | P | None | Yes |
| 47 | S | Brick Bld, Rm 19, North Wall | P | None | P | None | P | None | P | None | Yes |
| 48 | S | Brick Bld, Rm 20, South Wall | P | None | P | None | | | P | None | Yes |
| 49 | B | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | P | None | P | None | P | None | P | None | Yes |
| 50 | S | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | P | None | P | None | P | None | P | None | Yes |

| | | | | | | | | | | | |
|----|---|---|---|---------|---|------|---|------|---|------|--------|
| 51 | S | Old (Wood) Bld, Rm 23 (Main Level), West Closet | P | None | P | None | P | None | P | None | Yes |
| 52 | S | Old (Wood) Bld, Rm 24 (Main Level), West Closet | P | None | P | None | P | None | P | None | Yes |
| 53 | S | Old (Wood) Bld, Rm 25 (Top Level), West Closet | | Pending | P | None | P | None | P | None | #NAME? |
| 54 | S | Old (Wood) Bld, Rm 26 (Top Level), West Closet | P | None | P | None | P | None | P | None | Yes |
| 56 | S | kitchen (rear wall), East wall, right | P | None | P | None | P | None | P | None | Yes |
| 58 | S | kitchen, handwash | P | None | P | None | P | None | | | Yes |
| 59 | S | main office | P | None | P | None | P | None | P | None | Yes |
| 65 | S | room 1, kitchenette, left | P | None | P | None | P | None | | | Yes |
| 66 | S | room 1, kitchenette, middle | P | None | P | None | P | None | | | Yes |
| 67 | S | room 1, kitchenette, right | P | None | P | None | P | None | | | Yes |

Table 2. Lead Test Results

| FIXTURE INFORMATION | | | 6/28/2008 | | | 8/22/2008 | | | 9/12/2014 | | | 10/7/2014 | | | 1/21/2015 | | | 10/8/2015 | | | 9/11/2018 | | | Summary Status | |
|---------------------|------|--|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|----------------|---------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | Pass/Fail | Status |
| 01 | B | hallway, by room 20 | <1 | <1 | P | | | | 1 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 02 | B | hallway. By room 17 | | | | <1 | <1 | P | 2 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 03 | B | hallway, by room 14 | <1 | <1 | P | | | | 1 | <1 | P | | | | | | | 2 | 2 | P | <1 | <1 | P | P | None |
| 04 | B | hallway, by library | | | | <1 | <1 | P | 3 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 05 | B | hallway, by room 10 | <1 | 1 | P | | | | <1 | <1 | P | | | | | | | | | | 1 | <1 | P | P | None |
| 06 | B | hallway near office | <1 | <1 | P | | | | 1 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 07 | B | hallway near office | <1 | <1 | P | | | | 2 | <1 | P | | | | | | | | | | 1 | <1 | P | P | None |
| 08 | B | next to gym boy's restroom | | | | <1 | <1 | P | 4 | 2 | P | | | | | | | | | | 1 | <1 | P | P | None |
| 09 | B | next to gym girl's restroom | | | | 4 | <1 | P | 1 | 1 | P | | | | | | | | | | 2 | <1 | P | P | None |
| 10 | B | hallway, by room 8, left | <1 | <1 | P | | | | <1 | 1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 11 | B | hallway, by room 8, right | | | | | | | 4 | 2 | P | | | | | | | | | | 3 | 1 | P | P | None |
| 12 | B | hallway (top stairs), by room 6 | <1 | 1 | P | | | | 3 | 1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 13 | B | hallway, by room 7 | <1 | <1 | P | | | | 1 | 2 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 14 | B | room # 2 | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 15 | B | hallway, by room 3 | | | | 3 | <1 | P | 2 | 1 | P | | | | | | | | | | 2 | <1 | P | P | None |
| 16 | B | room # 1 | <1 | <1 | P | | | | 5 | 2 | P | | | | | | | | | | 2 | <1 | P | P | None |
| 17 | B | old bldg basement room 22 | 27 | <1 | | | | | | | | | | | | | | | | | | | | | OS |
| 18 | B | old bldg main floor | <1 | <1 | P | | | | | | | | | | | | | | | | | | | P | None |
| 20 | S | nurse's office, old bldg. Resource | 15 | 2 | | | | | | | | | | | | | | | | | | | | | Pending |
| 21 | S | kitchen (rear wall), East wall, left | 13 | <1 | | | | | 13 | 8 | | 22 | 2 | | | | | | | | 5 | <1 | P | P | None |
| 24 | S | Brick Bld, Rm 1 (North Wall) | <1 | <1 | P | | | | 7 | 3 | P | | | | | | | | | | 3 | <1 | P | P | None |
| 27 | S | Brick Bld, Rm 2 (South Wall) | 1 | <1 | P | | | | 1 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 28 | S | Brick Bld, Rm 2 (East on North Wall), right | 1 | <1 | P | | | | 4 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 29 | S | Brick Bld, Rm 2 (West on North Wall), left | 2 | <1 | P | | | | 3 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 30 | S | Brick Bld, Rm 3, North Wall | 2 | <1 | P | | | | 4 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 31 | S | Brick Bld, Rm 4, South Wall | 2 | <1 | P | | | | 4 | <1 | P | | | | | | | | | | 3 | <1 | P | P | None |
| 32 | S | Brick Bld, Rm 5, North Wall | 1 | <1 | P | | | | 3 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 33 | S | Brick Bld, Rm 6, South Wall | 1 | <1 | P | | | | 3 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 34 | S | Brick Bld, Rm 7, North Wall | 3 | <1 | P | | | | 3 | <1 | P | | | | | | | | | | 2 | <1 | P | P | None |
| 35 | S | Brick Bld, Rm 8, South Wall | 4 | <1 | P | | | | 12 | 1 | | 6 | <1 | P | | | | | | | 4 | <1 | P | P | None |
| 36 | S | Brick Bld, Nurses Office, West Wall | <1 | <1 | P | | | | 2 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 37 | S | Brick Bld, Faculty Lounge, North Wall | <1 | <1 | P | | | | | | | | | | 1 | <1 | P | | | | <1 | <1 | P | P | None |
| 38 | S | Brick Bld, Library, North Wall | 2 | <1 | P | | | | 13 | <1 | | 12 | 10 | | | | | | | | 2 | 2 | P | P | None |
| 39 | S | Brick Bld, Rm 10, South Wall | <1 | <1 | P | | | | 9 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 40 | S | Brick Bld, Rm 12, South Wall | <1 | <1 | P | | | | 38 | 9 | | | | | | | | | | | <1 | <1 | P | P | None |
| 41 | S | Brick Bld, Rm 13, North Wall | <1 | <1 | P | | | | 6 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 42 | S | Brick Bld, Rm 14, South Wall | 2 | <1 | P | | | | 1 | <1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 43 | S | Brick Bld, Rm 15, North Wall | <1 | <1 | P | | | | 5 | <1 | P | | | | | | | | | | 2 | <1 | P | P | None |
| 44 | S | Brick Bld, Rm 16, South Wall | 6 | <1 | P | | | | 9 | <1 | P | | | | | | | | | | 3 | <1 | P | P | None |
| 45 | S | Brick Bld, Rm 17, North Wall | 1 | <1 | P | | | | 3 | <1 | P | | | | | | | | | | 1 | <1 | P | P | None |
| 46 | S | Brick Bld, Rm 18, South Wall | <1 | <1 | P | | | | 4 | 1 | P | | | | | | | | | | <1 | <1 | P | P | None |
| 47 | S | Brick Bld, Rm 19, North Wall | 1 | <1 | P | | | | 27 | 36 | | 7 | 4 | P | | | | | | | 7 | <1 | P | P | None |
| 48 | S | Brick Bld, Rm 20, South Wall | <1 | <1 | P | | | | | | | | | | | | | | | | 9 | <1 | P | P | None |
| 49 | B | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | <1 | <1 | P | | | | | | | | | | | | | | | | | | | P | None |
| 50 | S | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | <1 | 1 | P | | | | | | | | | | | | | | | | | | | P | None |
| 51 | S | Old (Wood) Bld, Rm 23 (Main Level), West Closet | 5 | <1 | P | | | | | | | | | | | | | | | | | | | P | None |
| 52 | S | Old (Wood) Bld, Rm 24 (Main Level), West Closet | 5 | 1 | P | | | | | | | | | | | | | | | | | | | P | None |
| 53 | S | Old (Wood) Bld, Rm 25 (Top Level), West Closet | 14 | 2 | | | | | | | | | | | | | | | | | | | | | Pending |

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|---|--|----|----|---|--|--|----|----|---|----|---|--|--|--|--|--|--|--|--|--|----|------|---|---|------|
| 54 | S | Old (Wood) Bld, Rm 26 (Top Level), West Closet | 3 | 2 | P | | | | | | | | | | | | | | | | | P | None | | | |
| 56 | S | kitchen (rear wall), East wall, right | 6 | 1 | P | | | 18 | 2 | | 12 | 6 | | | | | | | | | | 3 | <1 | P | P | None |
| 58 | S | kitchen, handwash | 2 | <1 | P | | | | | | | | | | | | | | | | | 1 | 1 | P | P | None |
| 59 | S | main office | <1 | <1 | P | | | 8 | <1 | P | | | | | | | | | | | | 1 | 1 | P | P | None |
| 65 | S | room 1, kitchenette, left | | | | | | 5 | 2 | P | | | | | | | | | | | | <1 | <1 | P | P | None |
| 66 | S | room 1, kitchenette, middle | | | | | | 7 | 2 | P | | | | | | | | | | | | 3 | <1 | P | P | None |
| 67 | S | room 1, kitchenette, right | | | | | | 5 | 2 | P | | | | | | | | | | | | <1 | <1 | P | P | None |

Table 3. Cadmium Test Results

| FIXTURE INFORMATION | | | 6/28/2008 | | | 8/22/2008 | | | 9/12/2014 | | | 1/21/2015 | | | 10/8/2015 | | | 9/11/2018 | | | Summary Status | |
|---------------------|------|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|---------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | 1st Draw | Flush 30s | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway, by room 20 | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 02 | B | hallway. By room 17 | | | | <1 | <1 | P | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 03 | B | hallway, by room 14 | <1 | <1 | P | | | | <1 | <1 | P | | | | <1 | <1 | P | <1 | <1 | P | P | None |
| 04 | B | hallway, by library | | | | <1 | <1 | P | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 05 | B | hallway, by room 10 | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 06 | B | hallway near office | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 07 | B | hallway near office | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 08 | B | next to gym boy's restroom | | | | <1 | <1 | P | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 09 | B | next to gym girl's restroom | | | | <1 | <1 | P | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 10 | B | hallway, by room 8, left | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 11 | B | hallway, by room 8, right | | | | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 12 | B | hallway (top stairs), by room 6 | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 13 | B | hallway, by room 7 | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 14 | B | room # 2 | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 15 | B | hallway, by room 3 | | | | <1 | <1 | P | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 16 | B | room # 1 | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 17 | B | old bldg basement room 22 | 9 | <1 | | | | | | | | | | | | | | | | | | Pending |
| 18 | B | old bldg main floor | <1 | <1 | P | | | | | | | | | | | | | | | | | P None |
| 20 | S | nurse's office, old bldg. Resource | 5 | 1 | P | | | | | | | | | | | | | | | | | P None |
| 21 | S | kitchen (rear wall), East wall, left | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 24 | S | Brick Bld, Rm 1 (North Wall) | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 27 | S | Brick Bld, Rm 2 (South Wall) | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 28 | S | Brick Bld, Rm 2 (East on North Wall), right | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 29 | S | Brick Bld, Rm 2 (West on North Wall), left | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 30 | S | Brick Bld, Rm 3, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 31 | S | Brick Bld, Rm 4, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 32 | S | Brick Bld, Rm 5, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 33 | S | Brick Bld, Rm 6, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 34 | S | Brick Bld, Rm 7, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 35 | S | Brick Bld, Rm 8, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 36 | S | Brick Bld, Nurses Office, West Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 37 | S | Brick Bld, Faculty Lounge, North Wall | <1 | <1 | P | | | | | | | <1 | <1 | P | | | | <1 | <1 | P | P | None |
| 38 | S | Brick Bld, Library, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 39 | S | Brick Bld, Rm 10, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 40 | S | Brick Bld, Rm 12, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 41 | S | Brick Bld, Rm 13, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 42 | S | Brick Bld, Rm 14, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 43 | S | Brick Bld, Rm 15, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 44 | S | Brick Bld, Rm 16, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 45 | S | Brick Bld, Rm 17, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 46 | S | Brick Bld, Rm 18, South Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 47 | S | Brick Bld, Rm 19, North Wall | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 48 | S | Brick Bld, Rm 20, South Wall | <1 | <1 | P | | | | | | | | | | | | | <1 | <1 | P | P | None |
| 49 | B | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | <1 | <1 | P | | | | | | | | | | | | | | | | | P None |
| 50 | S | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | <1 | 1 | P | | | | | | | | | | | | | | | | | P None |
| 51 | S | Old (Wood) Bld, Rm 23 (Main Level), West Closet | <1 | <1 | P | | | | | | | | | | | | | | | | | P None |
| 52 | S | Old (Wood) Bld, Rm 24 (Main Level), West Closet | <1 | <1 | P | | | | | | | | | | | | | | | | | P None |

| | | | | | | | | | | | | | | | | | | | | | | |
|----|---|--|----|----|---|--|--|--|----|----|---|--|--|--|--|--|--|----|----|---|------|------|
| 53 | S | Old (Wood) Bld, Rm 25 (Top Level), West Closet | 2 | <1 | P | | | | | | | | | | | | | | | P | None | |
| 54 | S | Old (Wood) Bld, Rm 26 (Top Level), West Closet | 1 | <1 | P | | | | | | | | | | | | | | | | P | None |
| 56 | S | kitchen (rear wall), East wall, right | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 58 | S | kitchen, handwash | <1 | <1 | P | | | | | | | | | | | | | <1 | <1 | P | P | None |
| 59 | S | main office | <1 | <1 | P | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 65 | S | room 1, kitchenette, left | | | | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 66 | S | room 1, kitchenette, middle | | | | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |
| 67 | S | room 1, kitchenette, right | | | | | | | <1 | <1 | P | | | | | | | <1 | <1 | P | P | None |

Table 4. Copper Test Results

| FIXTURE INFORMATION | | | 6/28/2008 | | | 8/22/2008 | | | 9/12/2014 | | | 1/21/2015 | | | 10/8/2015 | | | 9/11/2018 | | | Summary Status | |
|---------------------|------|--|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|----------------|--------|
| Fixture ID | Type | Location | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | 1st Draw | Flush 30s | Pass /Fail | Pass/Fail | Status |
| 01 | B | hallway, by room 20 | 0.003 | 0.002 | P | | | | 0.14 | 0.135 | P | | | | | | | 0.344 | 0.338 | P | P | None |
| 02 | B | hallway. By room 17 | | | | 0.1 | 0.052 | P | 0.161 | 0.132 | P | | | | | | | 0.308 | 0.28 | P | P | None |
| 03 | B | hallway, by room 14 | 0.003 | 0.002 | P | | | | 0.15 | 0.15 | P | | | | 0.261 | 0.239 | P | 0.207 | 0.209 | P | P | None |
| 04 | B | hallway, by library | | | | 0.145 | 0.034 | P | 1.25 | 0.169 | P | | | | | | | 0.268 | 0.233 | P | P | None |
| 05 | B | hallway, by room 10 | 0.257 | 0.075 | P | | | | 0.132 | 0.114 | P | | | | | | | 0.332 | 0.278 | P | P | None |
| 06 | B | hallway near office | 0.075 | 0.059 | P | | | | 0.149 | 0.133 | P | | | | | | | 0.266 | 0.265 | P | P | None |
| 07 | B | hallway near office | 0.076 | 0.057 | P | | | | 0.136 | 0.118 | P | | | | | | | 0.282 | 0.27 | P | P | None |
| 08 | B | next to gym boy's restroom | | | | <0.002 | <0.002 | P | 0.251 | 0.191 | P | | | | | | | 0.212 | 0.247 | P | P | None |
| 09 | B | next to gym girl's restroom | | | | 0.189 | 0.026 | P | 0.047 | 0.134 | P | | | | | | | 0.182 | 0.27 | P | P | None |
| 10 | B | hallway, by room 8, left | 0.006 | 0.005 | P | | | | 0.12 | 0.11 | P | | | | | | | 0.11 | 0.08 | P | P | None |
| 11 | B | hallway, by room 8, right | | | | | | | 0.116 | 0.116 | P | | | | | | | 0.159 | 0.076 | P | P | None |
| 12 | B | hallway (top stairs), by room 6 | 0.005 | 0.006 | P | | | | 0.092 | 0.084 | P | | | | | | | 0.05 | 0.039 | P | P | None |
| 13 | B | hallway, by room 7 | 0.008 | 0.006 | P | | | | 0.062 | 0.104 | P | | | | | | | 0.17 | 0.168 | P | P | None |
| 14 | B | room # 2 | 0.006 | 0.006 | P | | | | <0.002 | <0.002 | P | | | | | | | <0.002 | <0.002 | P | P | None |
| 15 | B | hallway, by room 3 | | | | 0.14 | 0.021 | P | 0.096 | 0.06 | P | | | | | | | 1.17 | 0.388 | P | P | None |
| 16 | B | room # 1 | 0.008 | 0.008 | P | | | | 0.108 | 0.113 | P | | | | | | | 0.262 | 0.228 | P | P | None |
| 17 | B | old bldg basement room 22 | 0.112 | 0.047 | P | | | | | | | | | | | | | | | | P | None |
| 18 | B | old bldg main floor | 0.01 | 0.011 | P | | | | | | | | | | | | | | | | P | None |
| 20 | S | nurse's office, old bldg. Resource | 0.034 | 0.067 | P | | | | | | | | | | | | | | | | P | None |
| 21 | S | kitchen (rear wall), East wall, left | 0.751 | 0.047 | P | | | | 0.086 | 0.129 | P | | | | | | | 0.136 | 0.088 | P | P | None |
| 24 | S | Brick Bld, Rm 1 (North Wall) | 0.376 | 0.086 | P | | | | 0.308 | 1.84 | | | | | | | | 0.355 | 0.274 | P | P | None |
| 27 | S | Brick Bld, Rm 2 (South Wall) | 0.351 | 0.054 | P | | | | 0.105 | 0.084 | P | | | | | | | 0.166 | 0.188 | P | P | None |
| 28 | S | Brick Bld, Rm 2 (East on North Wall), right | 0.131 | <0.002 | P | | | | 0.136 | 0.043 | P | | | | | | | 0.068 | 0.041 | P | P | None |
| 29 | S | Brick Bld, Rm 2 (West on North Wall), left | 0.066 | 0.028 | P | | | | 0.077 | 0.04 | P | | | | | | | 0.07 | 0.045 | P | P | None |
| 30 | S | Brick Bld, Rm 3, North Wall | 0.25 | 0.075 | P | | | | 0.089 | 0.04 | P | | | | | | | 0.175 | 0.121 | P | P | None |
| 31 | S | Brick Bld, Rm 4, South Wall | 0.204 | 0.146 | P | | | | 0.098 | 0.051 | P | | | | | | | 0.089 | 0.121 | P | P | None |
| 32 | S | Brick Bld, Rm 5, North Wall | 0.205 | 0.174 | P | | | | 0.139 | 0.034 | P | | | | | | | 0.202 | 0.156 | P | P | None |
| 33 | S | Brick Bld, Rm 6, South Wall | 0.188 | <0.002 | P | | | | 0.049 | 0.02 | P | | | | | | | 0.056 | 0.02 | P | P | None |
| 34 | S | Brick Bld, Rm 7, North Wall | 0.302 | 0.043 | P | | | | 0.179 | 0.035 | P | | | | | | | 0.267 | 0.167 | P | P | None |
| 35 | S | Brick Bld, Rm 8, South Wall | 0.198 | 0.148 | P | | | | 0.099 | 0.142 | P | | | | | | | 0.164 | 0.179 | P | P | None |
| 36 | S | Brick Bld, Nurses Office, West Wall | 0.089 | 0.035 | P | | | | 0.042 | 0.025 | P | | | | | | | 0.046 | 0.03 | P | P | None |
| 37 | S | Brick Bld, Faculty Lounge, North Wall | 0.123 | 0.034 | P | | | | | | | 0.083 | 0.065 | P | | | | 0.053 | 0.034 | P | P | None |
| 38 | S | Brick Bld, Library, North Wall | 0.138 | 0.088 | P | | | | 0.176 | 0.154 | P | | | | | | | 0.528 | 0.2 | P | P | None |
| 39 | S | Brick Bld, Rm 10, South Wall | 0.272 | 0.239 | P | | | | 0.214 | 0.201 | P | | | | | | | 0.119 | 0.122 | P | P | None |
| 40 | S | Brick Bld, Rm 12, South Wall | 0.34 | 0.207 | P | | | | 1.26 | 0.324 | P | | | | | | | 0.25 | 0.312 | P | P | None |
| 41 | S | Brick Bld, Rm 13, North Wall | 0.183 | 0.062 | P | | | | 0.108 | 0.196 | P | | | | | | | 0.216 | 0.176 | P | P | None |
| 42 | S | Brick Bld, Rm 14, South Wall | 0.329 | 0.31 | P | | | | 0.195 | 0.06 | P | | | | | | | 0.26 | 0.216 | P | P | None |
| 43 | S | Brick Bld, Rm 15, North Wall | 0.351 | 0.055 | P | | | | 0.145 | 0.066 | P | | | | | | | 0.368 | 0.243 | P | P | None |
| 44 | S | Brick Bld, Rm 16, South Wall | 0.266 | 0.206 | P | | | | 0.346 | 0.185 | P | | | | | | | 0.229 | 0.203 | P | P | None |
| 45 | S | Brick Bld, Rm 17, North Wall | 0.273 | 0.059 | P | | | | 0.092 | 0.173 | P | | | | | | | 0.215 | 0.186 | P | P | None |
| 46 | S | Brick Bld, Rm 18, South Wall | 0.097 | 0.06 | P | | | | 0.173 | 0.132 | P | | | | | | | 0.056 | 0.042 | P | P | None |
| 47 | S | Brick Bld, Rm 19, North Wall | 0.275 | 0.088 | P | | | | 0.835 | 1.16 | P | | | | | | | 0.173 | 0.176 | P | P | None |
| 48 | S | Brick Bld, Rm 20, South Wall | 0.344 | 0.286 | P | | | | | | | | | | | | | | | | P | None |
| 49 | B | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | 0.706 | 0.061 | P | | | | | | | | | | | | | | | | P | None |
| 50 | S | Old (Wood) Bld, Rm 21 (Ground Level), South Closet | 0.173 | 0.027 | P | | | | | | | | | | | | | | | | P | None |
| 51 | S | Old (Wood) Bld, Rm 23 (Main Level), West Closet | 0.058 | 0.049 | P | | | | | | | | | | | | | | | | P | None |
| 52 | S | Old (Wood) Bld, Rm 24 (Main Level), West Closet | 0.058 | 0.062 | P | | | | | | | | | | | | | | | | P | None |

| | | | | | | | | | | | | | | | | | | | | | |
|----|---|--|-------|-------|---|--|--|-------|-------|---|--|--|--|--|--|--|-------|-------|---|------|------|
| 53 | S | Old (Wood) Bld, Rm 25 (Top Level), West Closet | 0.027 | 0.059 | P | | | | | | | | | | | | | | P | None | |
| 54 | S | Old (Wood) Bld, Rm 26 (Top Level), West Closet | 0.024 | 0.056 | P | | | | | | | | | | | | | | P | None | |
| 56 | S | kitchen (rear wall), East wall, right | 0.162 | 0.067 | P | | | 0.079 | 0.12 | P | | | | | | | 0.166 | 0.078 | P | P | None |
| 58 | S | kitchen, handwash | 0.113 | 0.021 | P | | | | | | | | | | | | 0.084 | 0.067 | P | P | None |
| 59 | S | main office | 0.1 | 0.046 | P | | | 0.087 | 0.052 | P | | | | | | | 0.18 | 0.16 | P | P | None |
| 65 | S | room 1, kitchenette, left | | | | | | 0.104 | 0.056 | P | | | | | | | 0.17 | 0.168 | P | P | None |
| 66 | S | room 1, kitchenette, middle | | | | | | 0.195 | 0.075 | P | | | | | | | 0.274 | 0.179 | P | P | None |
| 67 | S | room 1, kitchenette, right | | | | | | 0.125 | 0.065 | P | | | | | | | 0.2 | 0.154 | P | P | None |

Table 5. Iron Test Results

| FIXTURE INFORMATION | | | Initial Sampling | | | | Follow-up Sampling 1 | | | | Follow-up Sampling 2 | | | |
|---------------------|------|---|------------------|----------|----------|-----------|----------------------|----------|----------|-----------|----------------------|----------|----------|-----------|
| Fixture ID | Type | Location | Sampled | 1st Draw | Flush 2m | Pass/Fail | Sampled | 1st Draw | Flush 2m | Pass/Fail | Sampled | 1st Draw | Flush 2m | Pass/Fail |
| 01 | B | hallway, by room 20 | | | | | 5/18/2005 | | <0.05 | P | | | | |
| 02 | B | hallway. By room 17 | | | | | 5/18/2005 | | <0.05 | P | | | | |
| 03 | B | hallway, by room 14 | | | | | 5/18/2005 | | <0.05 | P | 7/27/2005 | | 0.34 | P |
| 04 | B | hallway, by library | | | | | 5/18/2005 | | <0.05 | P | | | | |
| 05 | B | hallway, by room 10 | 3/31/2004 | 0.07 | 0.1 | P | 5/18/2005 | | <0.05 | P | 7/27/2005 | | 0.29 | P |
| 06 | B | hallway near office | | | | | 5/18/2005 | | <0.05 | P | | | | |
| 07 | B | hallway near office | | | | | 5/18/2005 | | <0.05 | P | | | | |
| 08 | B | next to gym boy's restroom | | | | | 5/18/2005 | | 0.06 | P | | | | |
| 09 | B | next to gym girl's restroom | | | | | | | | | | | | |
| 10 | B | hallway, by room 8, left | | | | | | | | | | | | |
| 11 | B | hallway, by room 8, right | | | | | | | | | | | | |
| 12 | B | hallway (top stairs), by room 6 | | | | | | | | | | | | |
| 13 | B | hallway, by room 7 | | | | | 5/18/2005 | | <0.05 | P | 7/27/2005 | | 0.48 | P |
| 14 | B | room # 2 | | | | | | | | | | | | |
| 15 | B | hallway, by room 3 | 3/31/2004 | 0.08 | <0.05 | P | 5/18/2005 | | <0.05 | P | | | | |
| 16 | B | room # 1 | 3/31/2004 | 0.13 | <0.05 | P | 5/18/2005 | | <0.05 | P | 7/27/2005 | | 0.13 | P |
| 21 | S | kitchen (rear wall), East wall | 3/31/2004 | 0.5 | | P | 5/18/2005 | | <0.05 | P | | | | |
| 24 | S | Brick Bld, Rm 1 (North Wall) | | | | | | | | | | | | |
| 25 | S | Brick Bld, Rm 1 (East on South Wall), left | | | | | | | | | | | | |
| 26 | S | Brick Bld, Rm 1 (West on South Wall), right | | | | | | | | | | | | |
| 27 | S | Brick Bld, Rm 2 (South Wall) | | | | | | | | | | | | |
| 28 | S | Brick Bld, Rm 2 (East on North Wall), right | | | | | | | | | | | | |
| 29 | S | Brick Bld, Rm 2 (West on North Wall), left | | | | | | | | | | | | |
| 30 | S | Brick Bld, Rm 3, North Wall | | | | | | | | | | | | |
| 31 | S | Brick Bld, Rm 4, South Wall | | | | | | | | | | | | |
| 32 | S | Brick Bld, Rm 5, North Wall | | | | | | | | | | | | |
| 33 | S | Brick Bld, Rm 6, South Wall | | | | | | | | | | | | |
| 34 | S | Brick Bld, Rm 7, North Wall | | | | | | | | | | | | |
| 35 | S | Brick Bld, Rm 8, South Wall | | | | | | | | | | | | |
| 36 | S | Brick Bld, Nurses Office, West Wall | | | | | | | | | | | | |
| 37 | S | Brick Bld, Faculty Lounge, North Wall | | | | | | | | | | | | |
| 38 | S | Brick Bld, Library, North Wall | | | | | | | | | | | | |
| 39 | S | Brick Bld, Rm 10, South Wall | | | | | | | | | | | | |
| 40 | S | Brick Bld, Rm 12, South Wall | | | | | | | | | | | | |
| 41 | S | Brick Bld, Rm 13, North Wall | | | | | | | | | | | | |
| 42 | S | Brick Bld, Rm 14, South Wall | | | | | | | | | | | | |
| 43 | S | Brick Bld, Rm 15, North Wall | | | | | | | | | | | | |
| 44 | S | Brick Bld, Rm 16, South Wall | | | | | | | | | | | | |
| 45 | S | Brick Bld, Rm 17, North Wall | | | | | | | | | | | | |
| 46 | S | Brick Bld, Rm 18, South Wall | | | | | | | | | | | | |
| 47 | S | Brick Bld, Rm 19, North Wall | | | | | | | | | | | | |
| 48 | S | Brick Bld, Rm 20, South Wall | | | | | | | | | | | | |
| 56 | S | kitchen (rear wall), East wall, right | | | | | | | | | | | | |
| 58 | S | kitchen, handwash | | | | | | | | | | | | |
| 59 | S | main office | | | | | | | | | | | | |
| 65 | S | room 1, kitchenette, left | | | | | | | | | | | | |
| 66 | S | room 1, kitchenette, middle | | | | | | | | | | | | |
| 67 | S | room 1, kitchenette, right | | | | | | | | | | | | |

Table 5. Iron Test Results (continued)

| FIXTURE INFORMATION | | | Follow-up Sampling 3 | | | | Follow-up Sampling 4 | | | | Follow-up Sampling 5 | | | | Summary Status | |
|---------------------|------|---|----------------------|----------|----------|-----------|----------------------|----------|----------|-----------|----------------------|----------|----------|-----------|----------------|--------|
| Fixture ID | Type | Location | Sampled | 1st Draw | Flush 2m | Pass/Fail | Sampled | 1st Draw | Flush 2m | Pass/Fail | Sampled | 1st Draw | Flush 2m | Pass/Fail | Pass/Fail | Status |
| 01 | B | hallway, by room 20 | | | | | | | | | | | | | P | None |
| 02 | B | hallway. By room 17 | | | | | | | | | | | | | P | None |
| 03 | B | hallway, by room 14 | | | | | | | | | | | | | P | None |
| 04 | B | hallway, by library | | | | | | | | | | | | | P | None |
| 05 | B | hallway, by room 10 | | | | | | | | | | | | | P | None |
| 06 | B | hallway near office | | | | | | | | | | | | | P | None |
| 07 | B | hallway near office | | | | | | | | | | | | | P | None |
| 08 | B | next to gym boy's restroom | | | | | | | | | 9/12/2014 | | <0.05 | P | P | None |
| 09 | B | next to gym girl's restroom | | | | | | | | | | | | | | |
| 10 | B | hallway, by room 8, left | 9/1/2005 | | 0.074 | P | | | | | | | | | P | None |
| 11 | B | hallway, by room 8, right | | | | | | | | | | | | | | |
| 12 | B | hallway (top stairs), by room 6 | | | | | | | | | | | | | | |
| 13 | B | hallway, by room 7 | | | | | | | | | | | | | P | None |
| 14 | B | room # 2 | | | | | | | | | 9/12/2014 | | <0.05 | P | P | None |
| 15 | B | hallway, by room 3 | | | | | | | | | | | | | P | None |
| 16 | B | room # 1 | | | | | | | | | | | | | P | None |
| 21 | S | kitchen (rear wall), East wall | | | | | | | | | | | | | P | None |
| 24 | S | Brick Bld, Rm 1 (North Wall) | 9/1/2005 | | 0.056 | P | 6/28/2008 | | <0.05 | P | | | | | P | None |
| 25 | S | Brick Bld, Rm 1 (East on South Wall), left | 9/1/2005 | | <0.05 | P | | | | | | | | | P | None |
| 26 | S | Brick Bld, Rm 1 (West on South Wall), right | 9/1/2005 | | 0.065 | P | | | | | | | | | P | None |
| 27 | S | Brick Bld, Rm 2 (South Wall) | 9/1/2005 | | 0.062 | P | | | | | | | | | P | None |
| 28 | S | Brick Bld, Rm 2 (East on North Wall), right | 9/1/2005 | | 0.067 | P | | | | | 9/12/2014 | | <0.05 | P | P | None |
| 29 | S | Brick Bld, Rm 2 (West on North Wall), left | 9/1/2005 | | <0.05 | P | | | | | | | | | P | None |
| 30 | S | Brick Bld, Rm 3, North Wall | 9/1/2005 | | <0.05 | P | | | | | | | | | P | None |
| 31 | S | Brick Bld, Rm 4, South Wall | 9/1/2005 | | 0.077 | P | | | | | | | | | P | None |
| 32 | S | Brick Bld, Rm 5, North Wall | 9/1/2005 | | <0.05 | P | | | | | | | | | P | None |
| 33 | S | Brick Bld, Rm 6, South Wall | 9/1/2005 | | 0.074 | P | | | | | | | | | P | None |
| 34 | S | Brick Bld, Rm 7, North Wall | 9/1/2005 | | <0.05 | P | | | | | 9/12/2014 | | <0.05 | P | P | None |
| 35 | S | Brick Bld, Rm 8, South Wall | 9/1/2005 | | 0.15 | P | | | | | | | | | P | None |
| 36 | S | Brick Bld, Nurses Office, West Wall | 9/1/2005 | | 0.072 | P | | | | | | | | | P | None |
| 37 | S | Brick Bld, Faculty Lounge, North Wall | 9/1/2005 | | 0.072 | P | | | | | | | | | P | None |
| 38 | S | Brick Bld, Library, North Wall | 9/1/2005 | | 0.166 | P | | | | | | | | | P | None |
| 39 | S | Brick Bld, Rm 10, South Wall | 9/1/2005 | | 0.084 | P | | | | | | | | | P | None |
| 40 | S | Brick Bld, Rm 12, South Wall | 9/1/2005 | | 0.067 | P | | | | | | | | | P | None |
| 41 | S | Brick Bld, Rm 13, North Wall | 9/1/2005 | | 0.057 | P | | | | | | | | | P | None |
| 42 | S | Brick Bld, Rm 14, South Wall | 9/1/2005 | | 0.065 | P | | | | | 9/12/2014 | | <0.05 | P | P | None |
| 43 | S | Brick Bld, Rm 15, North Wall | 9/1/2005 | | 0.06 | P | | | | | | | | | P | None |
| 44 | S | Brick Bld, Rm 16, South Wall | 9/1/2005 | | 0.066 | P | | | | | | | | | P | None |
| 45 | S | Brick Bld, Rm 17, North Wall | 9/1/2005 | | 0.062 | P | | | | | | | | | P | None |
| 46 | S | Brick Bld, Rm 18, South Wall | 9/1/2005 | | 0.078 | P | | | | | | | | | P | None |
| 47 | S | Brick Bld, Rm 19, North Wall | 9/1/2005 | | 0.066 | P | | | | | | | | | P | None |
| 48 | S | Brick Bld, Rm 20, South Wall | 9/1/2005 | | 0.069 | P | 6/28/2008 | | <0.05 | P | | | | | P | None |
| 56 | S | kitchen (rear wall), East wall, right | | | | | 6/28/2008 | | 0.086 | P | 9/12/2014 | | <0.05 | P | P | None |
| 58 | S | kitchen, handwash | | | | | | | | | | | | | | |
| 59 | S | main office | | | | | 6/28/2008 | | 0.05 | P | | | | | P | None |
| 65 | S | room 1, kitchenette, left | | | | | | | | | | | | | | |
| 66 | S | room 1, kitchenette, middle | | | | | | | | | | | | | | |
| 67 | S | room 1, kitchenette, right | | | | | | | | | | | | | | |

Table 6. Service Entry Test Results

| Test Results (Service Entry/SE, Units as Shown) | | | | | | |
|---|------|------------------------------|----------------------|-----------|-------------|-----------|
| SOURCE INFORMATION | | | Most Recent Sampling | | | |
| Fixture ID | Type | Location | Item | Sampled | Max Value | Pass/Fail |
| 00 | SE | boiler room (faucet on main) | Arsenic | 11-Sep-18 | 2 ppb | P |
| 00 | SE | boiler room (faucet on main) | Cadmium | 11-Sep-18 | 1 ppb | P |
| 00 | SE | boiler room (faucet on main) | Chlorine | 31-Mar-04 | 0.2 ppm | P |
| 00 | SE | boiler room (faucet on main) | Copper | 11-Sep-18 | 0.008 ppm | P |
| 00 | SE | boiler room (faucet on main) | E coli | 15-Jun-04 | <1 Colonies | P |
| 00 | SE | boiler room (faucet on main) | Iron | 11-Sep-18 | <0.05 ppm | P |
| 00 | SE | boiler room (faucet on main) | Lead | 11-Sep-18 | 1 ppb | P |
| 00 | SE | boiler room (faucet on main) | Total Coliforms | 12-Sep-14 | <1 Colonies | P |

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.