

**Seattle Public Schools  
Drinking Water Quality Program**

**Results of Water Quality Testing  
for  
View Ridge Elementary**

Updated March 13, 2020

**General Information:**

Plumbing piping materials: copper

**Remediation plan:**

*This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.*

**Sinks (S in the report) are not considered drinking water sources.** We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023.

Service: The school will be flushed after any breaks longer than five days.

**Water Quality Testing Results:**

**Legend**

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S/B	room # 25	P	None	P	None	P	None	P	None	Yes
02	B	hallway	P	None	P	None	P	None	P	None	Yes
03	S/B	room # 26	P	None	P	None	P	None	P	None	Yes
04	S/B	room # 23	P	None	P	None	P	None	P	None	Yes
05	S/B	room # 24	P	None	P	None	P	None	P	None	Yes
06	S/B	room # 22	P	None	P	None	P	None	P	None	Yes
07	S/B	room # 21	P	None	P	None	P	None	P	None	Yes
08	S/B	room # 20	P	None	P	None	P	None	P	None	Yes
09	B	hallway near rm # 20	P	None	P	None	P	None	P	None	Yes
10	S/B	room # 19	P	None	P	None	P	None	P	None	Yes
12	B	hallway - NE wing, near boys lav	P	None	P	None	P	None	P	None	Yes
13	B	boys lav, NE wing	P	None	P	None	P	None	P	None	Yes
15	B	boys lav, NE hall, center	P	None	P	None	P	None	P	None	Yes
16	B	west wing hall	P	None	P	None	P	None	P	None	Yes
17	B	west wing hall	P	None	P	None	P	None	P	None	Yes
18	B	west wing hall	P	None	P	None	P	None	P	None	Yes
19	B	girls lav, hall west, right	P	None	P	None	P	None	P	None	Yes
20	B	west wing, boys lav, center	P	None	P	None	P	None	P	None	Yes
21	B	main hall west	P	None	P	None	P	None	P	None	Yes
22	B	lunch room	P	None	P	None	P	None	P	None	Yes
23	BF	lunch room	P	None	P	None	P	None	P	None	Yes
24	B	hallway, main	P	None	P	None	P	None	P	None	Yes
25	B	preschool	P	None	P	None	P	None	P	None	Yes
25A	S	sink by 25, in preschool	P	None	P	None	P	None			Yes
27	B	girls lav, NE wing, center	P	None	P	None	P	None	P	None	Yes
31	S	teachers lounge	P	None	P	None	P	None	P	None	Yes
32A	S	kitchen, left	P	None	P	None	P	None	P	None	Yes
32B	S	kitchen, right	P	None	P	None	P	None	P	None	Yes
33	S	nurses office	P	None	P	None	P	None	P	None	Yes
34	S	room 17	P	None	P	None	P	None	P	None	Yes
35	S	room 18	P	None	P	None	P	None	P	None	Yes
36	S	room 15	P	None	P	None	P	None	P	None	Yes
37	S	room 16	P	None	P	None	P	None	P	None	Yes
38	S	room 13	P	None	P	None	P	None	P	None	Yes
39	S	room 14	P	None	P	None	P	None	P	None	Yes
40	S	room 12	P	None	P	None	P	None	P	None	Yes
41	S	room 11	P	None	P	None	P	None	P	None	Yes
42	S	room 7	P	None	P	None	P	None	P	None	Yes
43	S	room 6	P	None	P	None	P	None	P	None	Yes
44	S	kindergarten, room 4, left	P	None	P	None	P	None	P	None	Yes
45	S	kindergarten, room 4, right	P	None	P	None	P	None	P	None	Yes
46	S	room 3	P	None	P	None	P	None	P	None	Yes
48	S	room 1	P	None	P	None	P	None	P	None	Yes
49	S	room 5	P	None	P	None	P	None	P	None	Yes
50	S	kitchen handwash	P	None	P	None	P	None			Yes

51	S	computer room	P	None	P	None	P	None	P	None	Yes
52	B	west wing, boys lav, left	P	None	P	None	P	None			Yes
53	B	west wing, boys lav, right	P	None	P	None	P	None			Yes
54	B	girls lav, hall west, middle	P	None	P	None	P	None			Yes
55	B	girls lav, hall west, left	P	None	P	None	P	None	P	None	Yes
56	B	girls lav, NE wing, left	P	None	P	None	P	None	P	None	Yes
57	B	girls lav, NE Wig, right	P	None	P	None	P	None			Yes
58	B	boys lav, NE hall, left	P	None	P	None	P	None			Yes
59	B	boys lav, NE hall, right	P	None	P	None	P	None			Yes
60	S	preschool	P	None	P	None	P	None			Yes
61	S	office	P	None	P	None	P	None	P	None	Yes
62	S	room 8	P	None	P	None	P	None	P	None	Yes
63	S	gym office	P	None	P	None	P	None			Yes
64	S	kitchen	P	None	P	None	P	None			Yes
65	S	Portable 4	P	None	P	None	P	None	P	None	Yes
66	B	Kindergarten	P	None	P	None	P	None			Yes
67	S	portable 3	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			2/18/2010			6/20/2013			7/13/2016			9/15/2016			2/20/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	room # 25	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
02	B	hallway	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
03	S/B	room # 26	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
04	S/B	room # 23	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
05	S/B	room # 24	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
06	S/B	room # 22	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
07	S/B	room # 21	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
08	S/B	room # 20	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
09	B	hallway near rm # 20	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
10	S/B	room # 19	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
12	B	hallway - NE wing, near boys lav	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
13	B	boys lav, NE wing	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
15	B	boys lav, NE hall, center	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
16	B	west wing hall	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
17	B	west wing hall	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
18	B	west wing hall	3	<1	P	3	<1	P	1	<1	P				<1	<1	P	P	None
19	B	girls lav, hall west, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
20	B	west wing, boys lav, center	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
21	B	main hall west	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
22	B	lunch room	1	<1	P	1	<1	P	1	<1	P				<1	<1	P	P	None
23	BF	lunch room	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
24	B	hallway, main	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
25	B	preschool	1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
25A	S	sink by 25, in preschool				<1	2	P	<1	<1	P				<1	<1	P	P	None
27	B	girls lav, NE wing, center	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
31	S	teachers lounge	1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
32A	S	kitchen, left	2	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
32B	S	kitchen, right	2	<1	P	<1	<1	P	<1	2	P				<1	<1	P	P	None
33	S	nurses office	2	<1	P	<1	<1	P	1	<1	P				<1	<1	P	P	None
34	S	room 17	2	<1	P	2	<1	P	3	<1	P				1	<1	P	P	None
35	S	room 18	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
36	S	room 15	<1	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
37	S	room 16	1	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
38	S	room 13	1	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
39	S	room 14	2	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
40	S	room 12	1	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
41	S	room 11	2	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
42	S	room 7	1	<1	P	2	<1	P	1	<1	P				<1	<1	P	P	None
43	S	room 6	2	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
44	S	kindergarten, room 4, left	1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
45	S	kindergarten, room 4, right	1	<1	P	3	<1	P	3	<1	P				1	<1	P	P	None
46	S	room 3	2	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
48	S	room 1	2	<1	P	2	<1	P	1	<1	P				<1	<1	P	P	None
49	S	room 5	2	<1	P		<1	P	3	<1	P				<1	<1	P	P	None
50	S	kitchen handwash	2	<1	P	2	<1	P	1	<1	P				<1	<1	P	P	None
51	S	computer room	2	<1	P	1	<1	P							<1	<1	P	P	None
52	B	west wing, boys lav, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
53	B	west wing, boys lav, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None

54	B	girls lav, hall west, middle	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
55	B	girls lav, hall west, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
56	B	girls lav, NE wing, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
57	B	girls lav, NE Wig, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
58	B	boys lav, NE hall, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
59	B	boys lav, NE hall, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
60	S	preschool	<1	<1	P	1	<1	P	1	<1	P				<1	<1	P	P	None
61	S	office	1	<1	P	2	<1	P	2	<1	P				<1	<1	P	P	None
62	S	room 8	2	<1	P	<1	<1	P	1	<1	P				<1	<1	P	P	None
63	S	gym office	2	<1	P	1	<1	P							1	<1	P	P	None
64	S	kitchen	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
65	S	Portable 4	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
66	B	Kindergarten	1	<1	P				<1	<1	P							P	None
67	S	portable 3				2	<1	P	2	<1	P	8		P	<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			2/18/2010			6/20/2013			7/13/2016			9/15/2016			2/20/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	room # 25	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
02	B	hallway	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
03	S/B	room # 26	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
04	S/B	room # 23	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
05	S/B	room # 24	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
06	S/B	room # 22	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
07	S/B	room # 21	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
08	S/B	room # 20	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
09	B	hallway near rm # 20	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
10	S/B	room # 19	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
12	B	hallway - NE wing, near boys lav	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
13	B	boys lav, NE wing	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
15	B	boys lav, NE hall, center	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
16	B	west wing hall	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
17	B	west wing hall	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
18	B	west wing hall	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
19	B	girls lav, hall west, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
20	B	west wing, boys lav, center	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
21	B	main hall west	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
22	B	lunch room	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
23	BF	lunch room	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
24	B	hallway, main	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
25	B	preschool	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
25A	S	sink by 25, in preschool				<1	<1	P	<1	<1	P				<1	<1	P	P	None
27	B	girls lav, NE wing, center	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
31	S	teachers lounge	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
32A	S	kitchen, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
32B	S	kitchen, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
33	S	nurses office	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
34	S	room 17	<1	<1	P	<1	<1	P	1	<1	P				<1	<1	P	P	None
35	S	room 18	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
36	S	room 15	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
37	S	room 16	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
38	S	room 13	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
39	S	room 14	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
40	S	room 12	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
41	S	room 11	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
42	S	room 7	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
43	S	room 6	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
44	S	kindergarten, room 4, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
45	S	kindergarten, room 4, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
46	S	room 3	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
48	S	room 1	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
49	S	room 5	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
50	S	kitchen handwash	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
51	S	computer room	<1	<1	P	<1	<1	P							<1	<1	P	P	None
52	B	west wing, boys lav, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
53	B	west wing, boys lav, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None

54	B	girls lav, hall west, middle	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
55	B	girls lav, hall west, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
56	B	girls lav, NE wing, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
57	B	girls lav, NE Wig, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
58	B	boys lav, NE hall, left	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
59	B	boys lav, NE hall, right	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
60	S	preschool	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
61	S	office	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
62	S	room 8	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
63	S	gym office	<1	<1	P	<1	<1	P							<1	<1	P	P	None
64	S	kitchen	<1	<1	P	<1	<1	P	<1	<1	P				<1	<1	P	P	None
65	S	Portable 4	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
66	B	Kindergarten	<1	<1	P				<1	<1	P							P	None
67	S	portable 3				<1	<1	P	<1	<1	P	<1		P	<1	<1	P	P	None



Table 4. Copper Test Results

FIXTURE INFORMATION			2/18/2010			6/20/2013			7/13/2016			9/15/2016			2/20/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	room # 25	0.269	0.266	P	0.245	0.253	P	0.253	0.295	P				0.448	0.435	P	P	None
02	B	hallway	0.259	0.254	P	0.268	0.259	P	0.29	0.324	P				0.492	0.447	P	P	None
03	S/B	room # 26	0.259	0.248	P	0.273	0.278	P	0.306	0.326	P				0.443	0.461	P	P	None
04	S/B	room # 23	0.261	0.23	P	0.24	0.219	P	0.235	0.27	P				0.415	0.326	P	P	None
05	S/B	room # 24	0.258	0.218	P	0.24	0.261	P	0.234	0.264	P				0.435	0.398	P	P	None
06	S/B	room # 22	0.264	0.232	P	0.242	0.252	P	0.261	0.258	P				0.456	0.335	P	P	None
07	S/B	room # 21	0.284	0.193	P	0.221	0.241	P	0.223	0.244	P				0.355	0.315	P	P	None
08	S/B	room # 20	0.25	0.169	P	0.222	0.256	P	0.24	0.259	P				0.41	0.353	P	P	None
09	B	hallway near rm # 20	0.278	0.134	P	0.283	0.219	P	0.249	0.227	P				0.424	0.238	P	P	None
10	S/B	room # 19	0.325	0.15	P	0.227	0.23	P	0.258	0.239	P				0.343	0.275	P	P	None
12	B	hallway - NE wing, near boys lav	0.244	0.156	P	0.253	0.176	P	0.249	0.207	P				0.423	0.332	P	P	None
13	B	boys lav, NE wing	0.24	0.162	P	0.259	0.226	P	0.274	0.266	P				0.396	0.229	P	P	None
15	B	boys lav, NE hall, center	0.163	0.179	P	0.202	0.178	P	0.232	0.203	P				0.402	0.365	P	P	None
16	B	west wing hall	0.338	0.292	P	0.249	0.259	P	0.424	0.384	P				0.387	0.388	P	P	None
17	B	west wing hall	0.264	0.218	P	0.225	0.233	P	0.264	0.312	P				0.38	0.422	P	P	None
18	B	west wing hall	0.306	0.216	P	0.142	0.124	P	0.266	0.179	P				0.226	0.258	P	P	None
19	B	girls lav, hall west, right	0.167	0.205	P	0.133	0.148	P	0.228	0.275	P				0.431	0.424	P	P	None
20	B	west wing, boys lav, center	0.231	0.223	P	0.201	0.186	P	0.229	0.275	P				0.464	0.467	P	P	None
21	B	main hall west	0.261	0.143	P	0.21	0.109	P	0.267	0.173	P				0.418	0.167	P	P	None
22	B	lunch room	0.213	0.133	P	0.161	0.105	P	0.178	0.105	P				0.31	0.131	P	P	None
23	BF	lunch room	0.21	0.174	P	0.155	0.083	P	0.194	0.079	P				0.276	0.087	P	P	None
24	B	hallway, main	0.23	0.22	P	0.173	0.142	P	0.235	0.176	P				0.279	0.126	P	P	None
25	B	preschool	0.214	0.265	P	0.233	0.23	P	0.269	0.28	P				0.383	0.304	P	P	None
25A	S	sink by 25, in preschool				0.209	0.2	P	0.284	0.27	P				0.334	0.344	P	P	None
27	B	girls lav, NE wing, center	0.308	0.298	P	0.213	0.232	P	0.194	0.214	P				0.348	0.364	P	P	None
31	S	teachers lounge	0.203	0.076	P	0.166	0.22	P	0.053	0.028	P				0.051	0.031	P	P	None
32A	S	kitchen, left	0.184	0.244	P	0.142	0.037	P	0.19	0.157	P				0.213	0.091	P	P	None
32B	S	kitchen, right	0.137	0.247	P	0.044	0.043	P	0.157	0.162	P				0.147	0.086	P	P	None
33	S	nurses office	0.185	0.198	P	0.101	0.094	P	0.199	0.108	P				0.337	0.124	P	P	None
34	S	room 17	0.254	0.258	P	0.212	0.252	P	0.265	0.291	P				0.313	0.358	P	P	None
35	S	room 18	0.335	0.304	P	0.246	0.267	P	0.292	0.332	P				0.365	0.404	P	P	None
36	S	room 15	0.27	0.232	P	0.177	0.171	P	0.212	0.297	P				0.322	0.349	P	P	None
37	S	room 16	0.312	0.266	P	0.199	0.218	P	0.28	0.258	P				0.332	0.413	P	P	None
38	S	room 13	0.255	0.273	P	0.158	0.212	P	0.206	0.298	P				0.326	0.235	P	P	None
39	S	room 14	0.252	0.318	P	0.25	0.261	P	0.306	0.323	P				0.287	0.35	P	P	None
40	S	room 12	0.24	0.22	P	0.167	0.203	P	0.2	0.281	P				0.173	0.235	P	P	None
41	S	room 11	0.218	0.305	P	0.221	0.261	P	0.251	0.229	P				0.311	0.297	P	P	None
42	S	room 7	0.296	0.182	P	0.256	0.291	P	0.239	0.3	P				0.34	0.291	P	P	None
43	S	room 6	0.258	0.175	P	0.31	0.217	P	0.173	0.237	P				0.276	0.246	P	P	None
44	S	kindergarten, room 4, left	0.192	0.263	P	0.247	0.183	P	0.237	0.189	P				0.339	0.364	P	P	None
45	S	kindergarten, room 4, right	0.26	0.178	P	0.203	0.152	P	0.255	0.198	P				0.382	0.296	P	P	None
46	S	room 3	0.282	0.166	P	0.216	0.301	P	0.29	0.302	P				0.371	0.368	P	P	None
48	S	room 1	0.232	0.222	P	0.208	0.272	P	0.292	0.268	P				0.301	0.342	P	P	None
49	S	room 5	0.228	0.175	P		0.225	P	0.237	0.222	P				0.202	0.199	P	P	None
50	S	kitchen handwash	0.217	0.239	P	0.128	0.218	P	0.209	0.303	P				0.241	0.371	P	P	None
51	S	computer room	0.222	0.159	P	0.172	0.125	P							0.425	0.126	P	P	None
52	B	west wing, boys lav, left	0.247	0.269	P	0.182	0.185	P	0.266	0.263	P				0.449	0.477	P	P	None
53	B	west wing, boys lav, right	0.26	0.283	P	0.205	0.214	P	0.245	0.275	P				0.453	0.449	P	P	None

54	B	girls lav, hall west, middle	0.222	0.241	P	0.166	0.16	P	0.209	0.22	P				0.43	0.421	P	P	None
55	B	girls lav, hall west, left	0.248	0.279	P	0.156	0.178	P	0.243	0.261	P				0.408	0.419	P	P	None
56	B	girls lav, NE wing, left	0.259	0.319	P	0.247	0.264	P	0.218	0.22	P				0.464	0.44	P	P	None
57	B	girls lav, NE Wig, right	0.313	0.331	P	0.241	0.253	P	0.209	0.22	P				0.369	0.391	P	P	None
58	B	boys lav, NE hall, left	0.245	0.196	P	0.175	0.174	P	0.214	0.208	P				0.374	0.331	P	P	None
59	B	boys lav, NE hall, right	0.186	0.189	P	0.168	0.168	P	0.211	0.221	P				0.299	0.277	P	P	None
60	S	preschool	0.248	0.272	P	0.222	0.236	P	0.277	0.296	P				0.428	0.381	P	P	None
61	S	office	0.315	0.32	P	0.193	0.171	P	0.173	0.246	P				0.367	0.365	P	P	None
62	S	room 8	0.299	0.166	P	0.217	0.235	P	0.256	0.273	P				0.364	0.42	P	P	None
63	S	gym office	0.237	0.069	P	0.228	0.246	P							0.33	0.199	P	P	None
64	S	kitchen	0.315	0.16	P	0.048	0.046	P	0.188	0.197	P				0.405	0.134	P	P	None
65	S	Portable 4	0.3	0.244	P	0.185	0.186	P	0.26	0.262	P	0.193	0.199	P	0.359	0.288	P	P	None
66	B	Kindergarten	0.232	0.157	P				0.245	0.261	P							P	None
67	S	portable 3				0.156	0.173	P	0.232	0.242	P	0.267		P	0.139	0.269	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			2/18/2010		6/20/2013		7/13/2016		2/20/2020		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	S/B	room # 25									P	None
02	B	hallway									P	None
03	S/B	room # 26	<0.05	P							P	None
04	S/B	room # 23			<0.05	P					P	None
05	S/B	room # 24					<0.05	P			P	None
06	S/B	room # 22									P	None
07	S/B	room # 21							<0.05	P	P	None
08	S/B	room # 20									P	None
09	B	hallway near rm # 20									P	None
10	S/B	room # 19									P	None
12	B	hallway - NE wing, near boys lav									P	None
13	B	boys lav, NE wing									P	None
15	B	boys lav, NE hall, center									P	None
16	B	west wing hall									P	None
17	B	west wing hall									P	None
18	B	west wing hall									P	None
19	B	girls lav, hall west, right							<0.05	P	P	None
20	B	west wing, boys lav, center									P	None
21	B	main hall west									P	None
22	B	lunch room									P	None
23	BF	lunch room									P	None
24	B	hallway, main									P	None
25	B	preschool									P	None
25A	S	sink by 25, in preschool										
27	B	girls lav, NE wing, center									P	None
31	S	teachers lounge									P	None
32A	S	kitchen, left									P	None
32B	S	kitchen, right									P	None
33	S	nurses office									P	None
34	S	room 17							<0.05	P	P	None
35	S	room 18	<0.05	P							P	None
36	S	room 15			<0.05	P					P	None
37	S	room 16					<0.05	P			P	None
38	S	room 13									P	None
39	S	room 14									P	None
40	S	room 12									P	None
41	S	room 11	<0.05	P							P	None
42	S	room 7									P	None
43	S	room 6									P	None
44	S	kindergarten, room 4, left									P	None
45	S	kindergarten, room 4, right									P	None
46	S	room 3									P	None
48	S	room 1	<0.05	P							P	None
49	S	room 5			<0.05	P	<0.05	P			P	None
50	S	kitchen handwash										
51	S	computer room							<0.05	P	P	None
52	B	west wing, boys lav, left										
53	B	west wing, boys lav, right										

54	B	girls lav, hall west, middle										
55	B	girls lav, hall west, left			<0.05	P					P	None
56	B	girls lav, NE wing, left					<0.05	P			P	None
57	B	girls lav, NE Wig, right										
58	B	boys lav, NE hall, left										
59	B	boys lav, NE hall, right										
60	S	preschool										
61	S	office			<0.05	P					P	None
62	S	room 8					<0.05	P			P	None
63	S	gym office										
64	S	kitchen										
65	S	Portable 4							<0.05	P	P	None
66	B	Kindergarten										
67	S	portable 3										

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	boiler room	Arsenic	20-Feb-20	2 ppb	P
00	SE	boiler room	Cadmium	20-Feb-20	1 ppb	P
00	SE	boiler room	Chlorine	12-May-04	<0.02 ppm	P
00	SE	boiler room	Copper	20-Feb-20	0.026 ppm	P
00	SE	boiler room	E coli	12-May-04	<1 Colonies	P
00	SE	boiler room	Iron	20-Feb-20	<0.05 ppm	P
00	SE	boiler room	Lead	20-Feb-20	1 ppb	P
00	SE	boiler room	Total Coliforms	12-Dec-07	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

**Bacteriological Characteristics**

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.