

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
Washington Middle School**

Updated September 2, 2019

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All sources meet the policy criteria.

Follow-up monitoring: Will be performed in 2021-2022

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	hallway near 106	P	None	P	None	P	None	P	None	Yes
02	B	hallway near wellness ctr.	P	None	P	None	P	None	P	None	Yes
03	B	lunch room (south)	P	None	P	None	P	None	P	None	Yes
04	B	lunch room (north)	P	None	P	None	P	None	P	None	Yes
05	B	north end hallway	P	None	P	None	P	None	P	None	Yes
06	B	hallway near 136	P	None	P	None	P	None	P	None	Yes
07	B	hallway near 128	P	None	P	None	P	None	P	None	Yes
08	B	hallway near 121	P	None	P	None	P	None	P	None	Yes
09	B	hallway near 115	P	None	P	None	P	None			Yes
10	B	hallway near 110	P	None	P	None	P	None	P	None	Yes
11	B	boys locker room	P	None	P	None	P	None	P	None	Yes
13	B	gym, by girls locker room	P	None	P	None	P	None	P	None	Yes
14	B	girls locker room	P	None	P	None	P	None	P	None	Yes
15	B	hallway near room 6	P	None	P	None	P	None	P	None	Yes
16	B	hallway near room 7	P	None	P	None	P	None	P	None	Yes
18	B	hallway near stairs	P	None	P	None	P	None	P	None	Yes
24	S	nurses office (lobby)	P	None	P	None	P	None	P	None	Yes
25	S	nurses office (rm. 117-06) - small room @ back: wellness center	P	None	P	None	P	None	P	None	Yes
26A	S	kitchen (cooking supply) - E wall (left sink), sampled southern of 2 faucet	P	None	P	None	P	None	P	None	Yes
26B	S	Kitchen (East wall, right sink)	P	None	P	None	P	None	P	None	Yes
27	S	teachers lounge	P	None	P	None	P	None	P	None	Yes
28	SK	Kitchen	P	None	P	None	P	None	P	None	Yes
29a	S	Kitchen (north wall, left sink)	P	None	P	None	P	None	P	None	Yes
29b	S	Kitchen (north wall, right sink)	P	None	P	None	P	None	P	None	Yes
34	S	room 3	P	None	P	None	P	None	P	None	Yes
35	S	room 1	P	None	P	None	P	None	P	None	Yes
36	S	room 7	P	None	P	None	P	None	P	None	Yes
37	S	room 10	P	None	P	None	P	None	P	None	Yes
38	S	band room	P	None	P	None	P	None	P	None	Yes
39	S	room 106	P	None	P	None	P	None	P	None	Yes
40	S	main office	P	None	P	None	P	None			Yes
48	S	CE lunch room	P	None	P	None	P	None			Yes
49	S	room 139	P	None	P	None	P	None			Yes
53	S	room 137	P	None	P	None	P	None			Yes
54	S	Conselors office, room 134	P	None	P	None	P	None			Yes
55	S	room 133	P	None	P	None	P	None			Yes
56	S	room 132	P	None	P	None	P	None			Yes
57	S	room 131	P	None	P	None	P	None			Yes
58	S	room 130	P	None	P	None	P	None			Yes
59	S	room 129	P	None	P	None	P	None			Yes
60	S	room 128B	P	None	P	None	P	None	P	None	Yes
61	S	room 128A	P	None	P	None	P	None			Yes
62	S	room 127	P	None	P	None	P	None	P	None	Yes
65	S	room 115 left	P	None	P	None	P	None	P	None	Yes
66	S	room 115, right	P	None	P	None	P	None	P	None	Yes
67	S	library	P	None	P	None	P	None	P	None	Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			9/29/2010			6/28/2011			4/17/2012			4/17/2015			7/25/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	hallway near 106				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
02	B	hallway near wellness ctr.				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
03	B	lunch room (south)				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
04	B	lunch room (north)				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
05	B	north end hallway				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
06	B	hallway near 136				<1		P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
07	B	hallway near 128				<1	<1	P	<1	<1	P	<1	<1	P				P	None
08	B	hallway near 121				<1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
09	B	hallway near 115				1	1	P	1	<1	P	2	<1	P	1	1	P	P	None
10	B	hallway near 110				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
11	B	boys locker room				1	<1	P	<1	<1	P	<1	<1	P	1	<1	P	P	None
13	B	gym, by girls locker room				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
14	B	girls locker room				<1	<1	P	<1	<1	P	<1	<1	P	3	1	P	P	None
15	B	hallway near room 6				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	B	hallway near room 7				2	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
18	B	hallway near stairs				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
24	S	nurses office (lobby)				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
25	S	nurses office (rm. 117-06) – small l room @ back: wellness center				2	<1	P	2	<1	P	1	<1	P	<1	<1	P	P	None
26A	S	kitchen (cooking supply) - E wall (left sink), sampled southern of 2 faucet				<1	<1	P	2	<1	P	<1	<1	P	<1	<1	P	P	None
26B	S	Kitchen (East wall, right sink)				<1	<1	P	<1	<1	P	1	<1	P	<1	<1	P	P	None
27	S	teachers lounge				1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
28	SK	Kitchen				<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
29a	S	Kitchen (north wall, left sink)				<1	<1	P	<1	<1	P	<1	<1	P	2	<1	P	P	None
29b	S	Kitchen (north wall, right sink)				1	<1	P	1	<1	P	<1	<1	P	3	<1	P	P	None
34	S	room 3				3	<1	P	3	<1	P	2	<1	P	<1	<1	P	P	None
35	S	room 1				2	<1	P	1	<1	P	2	<1	P	<1	<1	P	P	None
36	S	room 7				<1	<1	P	<1	<1	P	6	<1	P	<1	<1	P	P	None
37	S	room 10				4	<1	P	4	<1	P	<1	<1	P	2	<1	P	P	None
38	S	band room				2	<1	P	1	<1	P	2	<1	P	<1	<1	P	P	None
39	S	room 106																P	None
40	S	main office				<1	<1	P	<1	<1	P	3	<1	P	1	<1	P	P	None
48	S	CE lunch room				1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
49	S	room 139				3	<1	P	3	1	P	3	3	P	2	1	P	P	None
53	S	room 137				<1	<1	P	<1	<1	P	1	<1	P	<1	<1	P	P	None
54	S	Conselors office, room 134				1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
55	S	room 133				1	<1	P	2	<1	P	<1	<1	P	<1	<1	P	P	None
56	S	room 132				2	<1	P	2	<1	P	3	<1	P	<1	<1	P	P	None
57	S	room 131				1	<1	P	<1	<1	P	3	<1	P	1	<1	P	P	None
58	S	room 130				<1	<1	P	1	<1	P	1	<1	P	1	<1	P	P	None
59	S	room 129	2	<1	P	2	<1	P	1	<1	P	1	<1	P	<1	<1	P	P	None
60	S	room 128B				2	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
61	S	room 128A				<1	<1	P	<1	<1	P				<1	<1	P	P	None
62	S	room 127				2	<1	P	2	<1	P	2	<1	P	<1	<1	P	P	None
65	S	room 115 left				1	<1	P	2	<1	P	4	<1	P	<1	<1	P	P	None
66	S	room 115, right				2	<1	P	1	<1	P	3	<1	P	1	<1	P	P	None
67	S	library				4	3	P	2	3	P	4	3	P	3	1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			6/28/2011			4/17/2012			4/17/2015			7/25/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	hallway near 106	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
02	B	hallway near wellness ctr.	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
03	B	lunch room (south)	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
04	B	lunch room (north)	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
05	B	north end hallway	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
06	B	hallway near 136	<1		P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
07	B	hallway near 128	<1	<1	P	<1	<1	P	<1	<1	P				P	None
08	B	hallway near 121	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
09	B	hallway near 115	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
10	B	hallway near 110	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
11	B	boys locker room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
13	B	gym, by girls locker room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
14	B	girls locker room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
15	B	hallway near room 6	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	B	hallway near room 7	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
18	B	hallway near stairs	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
24	S	nurses office (lobby)	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
25	S	nurses office (rm. 117-06) - small room @ back: wellness center	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
26A	S	kitchen (cooking supply) - E wall (left sink), sampled southern of 2 faucet	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
26B	S	Kitchen (East wall, right sink)	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
27	S	teachers lounge	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
28	SK	Kitchen	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
29a	S	Kitchen (north wall, left sink)	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
29b	S	Kitchen (north wall, right sink)	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
34	S	room 3	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
35	S	room 1	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
36	S	room 7	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
37	S	room 10	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
38	S	band room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
39	S	room 106													P	None
40	S	main office	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
48	S	CE lunch room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
49	S	room 139	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
53	S	room 137	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
54	S	Conselors office, room 134	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
55	S	room 133	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
56	S	room 132	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
57	S	room 131	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
58	S	room 130	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
59	S	room 129	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
60	S	room 128B	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
61	S	room 128A	<1	<1	P	<1	<1	P				<1	<1	P	P	None
62	S	room 127	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
65	S	room 115 left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
66	S	room 115, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
67	S	library	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			6/28/2011			4/17/2012			4/17/2015			7/25/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	hallway near 106	0.151	0.151	P	0.158	0.054	P	0.122	0.194	P	0.1	0.09	P	P	None
02	B	hallway near wellness ctr.	0.194	0.184	P	0.071	0.168	P	0.146	0.149	P	0.11	0.098	P	P	None
03	B	lunch room (south)	0.303	0.318	P	0.33	0.131	P	0.406	0.404	P	0.134	0.133	P	P	None
04	B	lunch room (north)	0.316	0.272	P	0.371	0.406	P	0.329	0.427	P	0.144	0.141	P	P	None
05	B	north end hallway	0.184	0.181	P	0.208	0.244	P	0.157	0.189	P	0.137	0.106	P	P	None
06	B	hallway near 136	0.171		P	0.148	0.165	P	0.136	0.135	P	0.089	0.083	P	P	None
07	B	hallway near 128	0.196	0.191	P	0.152	0.14	P	0.177	0.199	P				P	None
08	B	hallway near 121	0.182	0.183	P	0.155	0.125	P	0.127	0.104	P	0.096	0.088	P	P	None
09	B	hallway near 115	0.153	0.146	P	0.158	0.156	P	0.145	0.126	P	0.124	0.127	P	P	None
10	B	hallway near 110	0.007	0.003	P	0.005	0.002	P	0.005	<0.002	P	0.008	<0.002	P	P	None
11	B	boys locker room	0.156	0.136	P	0.19	0.178	P	0.151	0.154	P	0.126	0.135	P	P	None
13	B	gym, by girls locker room	0.269	0.248	P	0.25	0.203	P	0.265	0.265	P	0.241	0.252	P	P	None
14	B	girls locker room	0.278	0.283	P	0.275	0.247	P	0.231	0.274	P	0.338	0.418	P	P	None
15	B	hallway near room 6	0.18	0.104	P	0.168	0.108	P	0.126	0.119	P	0.115	0.106	P	P	None
16	B	hallway near room 7	0.298	0.272	P	0.254	1.04	P	0.368	0.299	P	0.429	0.41	P	P	None
18	B	hallway near stairs	0.157	0.14	P	0.143	0.134	P	0.107	0.099	P	0.12	0.109	P	P	None
24	S	nurses office (lobby)	0.158	0.154	P	0.167	0.138	P	0.098	0.086	P	0.1	0.081	P	P	None
25	S	nurses office (rm. 117-06) - small room @ back: wellness center	0.214	0.101	P	0.207	0.118	P	0.18	0.119	P	0.164	0.078	P	P	None
26A	S	kitchen (cooking supply) - E wall (left sink), sampled southern of 2 faucet	0.098	0.164	P	0.124	0.139	P	0.08	0.093	P	0.114	0.086	P	P	None
26B	S	Kitchen (East wall, right sink)	0.151	0.172	P	0.114	0.128	P	0.103	0.104	P	0.072	0.101	P	P	None
27	S	teachers lounge	0.13	0.13	P	0.129	0.152	P	0.123	0.11	P	0.113	0.081	P	P	None
28	SK	Kitchen	0.264	0.242	P	0.263	0.178	P	0.342	0.286	P	0.195	0.084	P	P	None
29a	S	Kitchen (north wall, left sink)	0.131	0.18	P	0.129	0.1	P	0.087	0.094	P	0.137	0.081	P	P	None
29b	S	Kitchen (north wall, right sink)	0.167	0.164	P	0.151	0.129	P	0.11	0.078	P	0.163	0.089	P	P	None
34	S	room 3	0.308	0.278	P	0.259	0.199	P	0.26	0.117	P	0.224	0.085	P	P	None
35	S	room 1	0.246	0.261	P	0.277	0.237	P	0.208	0.192	P	0.22	0.119	P	P	None
36	S	room 7	0.315	0.372	P	0.294	0.385	P	0.298	0.376	P	0.375	0.438	P	P	None
37	S	room 10	0.307	0.353	P	0.358	0.324	P	0.294	0.387	P	0.212	0.415	P	P	None
38	S	band room	0.383	0.5	P	0.364	0.42	P	0.328	0.457	P	0.331	0.442	P	P	None
39	S	room 106													P	None
40	S	main office	0.223	0.168	P	0.105	0.124	P	0.178	0.213	P	0.107	0.107	P	P	None
48	S	CE lunch room	0.185	0.176	P	0.092	0.171	P	0.144	0.145	P	0.095	0.091	P	P	None
49	S	room 139	0.098	0.183	P	0.073	0.061	P	0.214	0.277	P	0.117	0.104	P	P	None
53	S	room 137	0.251	0.271	P	0.299	0.344	P	0.204	0.33	P	0.186	0.143	P	P	None
54	S	Conselors office, room 134	0.22	0.193	P	0.16	0.137	P	0.177	0.165	P	0.109	0.093	P	P	None
55	S	room 133	0.205	0.19	P	0.14	0.132	P	0.311	0.43	P	0.302	0.283	P	P	None
56	S	room 132	0.313	0.389	P	0.28	0.319	P	0.313	0.322	P	0.31	0.299	P	P	None
57	S	room 131	0.323	0.262	P	0.305	0.199	P	0.265	0.258	P	0.264	0.157	P	P	None
58	S	room 130	0.593	0.681	P	0.438	0.489	P	0.551	0.408	P	0.171	0.119	P	P	None
59	S	room 129	0.227	0.254	P	0.206	0.173	P	0.199	0.181	P	0.13	0.112	P	P	None
60	S	room 128B	0.38	0.256	P	0.215	0.166	P	0.197	0.312	P	0.11	0.113	P	P	None
61	S	room 128A	0.279	0.195	P	0.156	0.129	P				0.124	0.118	P	P	None
62	S	room 127	0.345	0.308	P	0.31	0.181	P	0.505	0.348	P	0.271	0.13	P	P	None
65	S	room 115 left	0.389	0.395	P	0.382	0.36	P	0.315	0.399	P	0.262	0.3	P	P	None
66	S	room 115, right	0.306	0.395	P	0.344	0.345	P	0.33	0.399	P	0.246	0.302	P	P	None
67	S	library	0.289	0.31	P	0.256	0.244	P	0.291	0.336	P	0.268	0.126	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			6/28/2011		4/17/2012		4/17/2015		7/25/2019		Summary Status		
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status	
01	B	hallway near 106						<0.05	P		P	None	
02	B	hallway near wellness ctr.							<0.05	P	P	None	
03	B	lunch room (south)									P	None	
04	B	lunch room (north)									P	None	
05	B	north end hallway									P	None	
06	B	hallway near 136									P	None	
07	B	hallway near 128									P	None	
08	B	hallway near 121									P	None	
09	B	hallway near 115											
10	B	hallway near 110									P	None	
11	B	boys locker room	<0.05	P							P	None	
13	B	gym, by girls locker room			<0.05	P					P	None	
14	B	girls locker room					<0.05	P			P	None	
15	B	hallway near room 6							<0.05	P	P	None	
16	B	hallway near room 7									P	None	
18	B	hallway near stairs									P	None	
24	S	nurses office (lobby)									P	None	
25	S	nurses office (rm. 117-06) - small room @ back: wellness center									P	None	
26A	S	kitchen (cooking supply) - E wall (left sink), sampled southern of 2 faucet									P	None	
26B	S	Kitchen (East wall, right sink)									P	None	
27	S	teachers lounge									P	None	
28	SK	Kitchen									P	None	
29a	S	Kitchen (north wall, left sink)	<0.05	P							P	None	
29b	S	Kitchen (north wall, right sink)			<0.05	P					P	None	
34	S	room 3						<0.05	P		P	None	
35	S	room 1	<0.05	P						0.055	P	P	None
36	S	room 7			<0.05	P					P	None	
37	S	room 10						0.058	P		P	None	
38	S	band room							<0.05	P	P	None	
39	S	room 106									P	None	
40	S	main office											
48	S	CE lunch room											
49	S	room 139											
53	S	room 137											
54	S	Conselors office, room 134											
55	S	room 133											
56	S	room 132											
57	S	room 131											
58	S	room 130											
59	S	room 129											
60	S	room 128B							<0.05	P	P	None	
61	S	room 128A											
62	S	room 127	<0.05	P							P	None	
65	S	room 115 left	<0.05	P							P	None	
66	S	room 115, right			<0.05	P					P	None	
67	S	library			<0.05	P					P	None	

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	boiler room	Arsenic	17-Apr-15	2 ppb	P
00	SE	boiler room	Cadmium	25-Jul-19	1 ppb	P
00	SE	boiler room	Chlorine	21-Apr-04	0.1 ppm	P
00	SE	boiler room	Copper	25-Jul-19	0.083 ppm	P
00	SE	boiler room	E coli	21-Apr-04	<1 Colonies	P
00	SE	boiler room	Iron	25-Jul-19	<0.05 ppm	P
00	SE	boiler room	Lead	25-Jul-19	1 ppb	P
00	SE	boiler room	Total Coliforms	28-Jun-11	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.