

Seattle Public Schools  
Drinking Water Quality Program

Results of Water Quality Testing  
for  
West Woodland Elementary

Updated March 21, 2018

**General Information:**

Plumbing piping materials: mainly galvanized steel

**Remediation plan:**

*This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.*

Status:

Policy Criteria: All sources meet the policy criteria.

Bottled water will be removed from the nurse office sink (#34)

Follow-up monitoring: Will be performed in school year 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

**Water Quality Testing Results:**

<b>Legend</b>	
<b>Symbol</b>	<b>Definition</b>
SE	service entry (main)
B	Bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

CURRENT STATUS											
FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	1st floor hall	P	None	P	None	P	None	P	None	Yes
02	B	1st floor hall	P	None	P	None	P	None	P	None	Yes
03	S/B	room 101	P	None	P	None	P	None	P	None	Yes
04	S/B	room 102	P	None	P	None	P	None	P	None	Yes
05	S/B	room 103	P	None	P	None	P	None	P	None	Yes
06	S/B	room 104, kindergarten	P	None	P	None	P	None	P	None	Yes
07	S/B	room 105	P	None	P	None	P	None	P	None	Yes
08	S/B	room 107	P	None	P	None	P	None	P	None	Yes
09	S/B	room 106, kindergarten	P	None	P	None	P	None	P	None	Yes
10	S/B	room 108, kindergarten	P	None	P	None	P	None			Yes
11	S/B	room 109	P	None	P	None	P	None	P	None	Yes
12	S/B	room 212	P	None	P	None	P	None	P	None	Yes
13	S/B	room 211	P	None	P	None	P	None	P	None	Yes
14	S	room 209, art	P	None	P	None	P	None			Yes
15	S/B	room 210	P	None	P	None	P	None	P	None	Yes
16	S/B	room 208	P	None	P	None	P	None	P	None	Yes
17	S/B	room 207	P	None	P	None	P	None	P	None	Yes
18	S/B	room 206	P	None	P	None	P	None	P	None	Yes
19	S/B	room 205	P	None	P	None	P	None	P	None	Yes
20	S/B	room 203	P	None	P	None	P	None	P	None	Yes
21	S/B	room 204	P	None	P	None	P	None	P	None	Yes
22	S/B	room 202	P	None	P	None	P	None	P	None	Yes
23	S/B	room 201	P	None	P	None	P	None	P	None	Yes
24	B	2nd floor hall	P	None	P	None	P	None	P	None	Yes
27	S/B	AV room/library	P	None	P	None	P	None	P	None	Yes
28	S	teacher's lounge	P	None	P	None	P	None	P	None	Yes
29	S/B	room 110	P	None	P	None	P	None	P	None	Yes
32	S	kitchen, sink	P	None	P	None	P	None	P	None	Yes
33	S	kitchen, sink	P	None	P	None	P	None	P	None	Yes
34	S	nurse office	P	None	P	None	P	None			Yes
35	S	work room	P	None	P	None	P	None			Yes
36	S	room 223	P	None	P	None	P	None	P	None	Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B	1st floor hall	4/30/2004	16	<1		4/18/2005	39	<1		7/11/2005	15	4						2/12/2008	<1	<1	P
02	B	1st floor hall	4/30/2004	27	<1		4/18/2005	24	<1		7/11/2005	19	5		5/19/2006	2		P	2/12/2008	<1	<1	P
03	S/B	room 101	4/30/2004	9	2	P													2/12/2008	3	1	P
04	S/B	room 102	4/30/2004	47	4		4/18/2005	2	<1	P									2/12/2008	<1	<1	P
05	S/B	room 103	4/30/2004	5	2	P													2/12/2008	3	1	P
06	S/B	room 104, kindergarten	4/30/2004	4	1	P													2/12/2008	3	<1	P
07	S/B	room 105	4/30/2004	8	3	P													2/12/2008	5	1	P
08	S/B	room 107	4/30/2004	8	2	P													2/12/2008	<1	<1	P
09	S/B	room 106, kindergarten	4/30/2004	18	2		4/18/2005	1	<1	P									2/12/2008	2	<1	P
10	S/B	room 108, kindergarten									7/11/2005				5/19/2006	5	<1	P	2/12/2008	4	<1	P
11	S/B	room 109	4/30/2004	29	2		4/18/2005	9	2	P									2/12/2008	2	<1	P
12	S/B	room 212	4/30/2004	8	2	P	4/18/2005	2	<1	P									2/12/2008	<1	<1	P
13	S/B	room 211	4/30/2004	62	2		4/18/2005	4	<1	P									2/12/2008	<1	<1	P
14	S	room 209, art	4/30/2004	4	2	P													2/12/2008	4	<1	P
15	S/B	room 210	4/30/2004	15	3		4/18/2005	3	<1	P									2/12/2008	1	<1	P
16	S/B	room 208	4/30/2004	120	2		4/18/2005	1	<1	P									2/12/2008	<1	<1	P
17	S/B	room 207	4/30/2004	14	2		4/18/2005	2	<1	P									2/12/2008	<1	<1	P
18	S/B	room 206	4/30/2004	5	2	P													2/12/2008	3	<1	P
19	S/B	room 205	4/30/2004	28	3		4/18/2005	3	2	P									2/12/2008	<1	<1	P
20	S/B	room 203	4/30/2004	7	2	P													2/12/2008	3	<1	P
21	S/B	room 204	4/30/2004	55	2		4/18/2005	1	<1	P									2/12/2008	<1	<1	P
22	S/B	room 202	4/30/2004	27	2		4/18/2005	<1	<1	P									2/12/2008	<1	<1	P
23	S/B	room 201	4/30/2004	32	2		4/18/2005	1	<1	P									2/12/2008	<1	<1	P
24	B	2nd floor hall									7/11/2005				5/19/2006	<1	<1	P	2/12/2008	<1	<1	P
27	S/B	AV room/library	4/30/2004	29	2		4/18/2005	4	<1	P									2/12/2008	<1	<1	P
28	S	teacher's lounge	4/30/2004	2	<1	P													2/12/2008	5	<1	P
29	S/B	room 110	4/30/2004	9	3	P													2/12/2008	10	2	P
32	S	kitchen, sink																	2/12/2008	<1	<1	P
33	S	kitchen, sink																	2/12/2008	4	<1	P
34	S	nurse office																	2/12/2008	10	<1	P
35	S	work room																	2/12/2008	<1	<1	P
36	S	room 223																	2/12/2008	5	<1	P

Table 2. Lead Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Follow-up Sampling 8			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B	1st floor hall					12/10/2008	3	<1	P	3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
02	B	1st floor hall					12/10/2008	4	<1	P	3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
03	S/B	room 101									3/2/2011	2	<1	P	3/28/2014	3	<1	P
04	S/B	room 102									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
05	S/B	room 103									3/2/2011	2	<1	P	3/28/2014	4	<1	P
06	S/B	room 104, kindergarten									3/2/2011	2	<1	P	3/28/2014	4	<1	P
07	S/B	room 105									3/2/2011	3	1	P	3/28/2014	2	1	P
08	S/B	room 107									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
09	S/B	room 106, kindergarten									3/2/2011	1	<1	P	3/28/2014	1	<1	P
10	S/B	room 108, kindergarten	3/13/2008	9	2	P					3/2/2011	1	<1	P	3/28/2014	2	<1	P
11	S/B	room 109									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
12	S/B	room 212									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
13	S/B	room 211									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
14	S	room 209, art													3/28/2014	<1	<1	P
15	S/B	room 210									3/2/2011	<1	<1	P	3/28/2014	1	<1	P
16	S/B	room 208									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
17	S/B	room 207									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
18	S/B	room 206									3/2/2011	1	<1	P	3/28/2014	2	<1	P
19	S/B	room 205									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
20	S/B	room 203									3/2/2011	2	<1	P	3/28/2014	3	<1	P
21	S/B	room 204									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
22	S/B	room 202									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
23	S/B	room 201									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
24	B	2nd floor hall					12/10/2008	4	<1	P	3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
27	S/B	AV room/library									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
28	S	teacher's lounge									3/2/2011	3	<1	P	3/28/2014	5	<1	P
29	S/B	room 110									3/2/2011	2	<1	P	3/28/2014	2	<1	P
32	S	kitchen, sink									3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
33	S	kitchen, sink									3/2/2011	<1	<1	P	3/28/2014	7	<1	P
34	S	nurse office									3/2/2011	6	<1	P	3/28/2014	11	<1	
35	S	work room									3/2/2011	<1	<1	P	3/28/2014	1	<1	P
36	S	room 223									3/2/2011	4	<1	P	3/28/2014	3	<1	P

Table 2. Lead Test Results (continued-2)

FIXTURE INFORMATION			Follow-up Sampling 9				Follow-up Sampling 10				Follow-up Sampling 11				Follow-up Sampling 12				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	1st floor hall													11/21/2017	<1	<1	P	P	None
02	B	1st floor hall									2/13/2015	<1		P	11/21/2017	<1	<1	P	P	None
03	S/B	room 101													11/21/2017	2	<1	P	P	None
04	S/B	room 102													11/21/2017	<1	<1	P	P	None
05	S/B	room 103													11/21/2017	2	<1	P	P	None
06	S/B	room 104, kindergarten													11/21/2017	3	<1	P	P	None
07	S/B	room 105													11/21/2017	2	<1	P	P	None
08	S/B	room 107													11/21/2017	<1	<1	P	P	None
09	S/B	room 106, kindergarten													11/21/2017	<1	<1	P	P	None
10	S/B	room 108, kindergarten													11/21/2017	1	<1	P	P	None
11	S/B	room 109													11/21/2017	<1	<1	P	P	None
12	S/B	room 212													11/21/2017	<1	<1	P	P	None
13	S/B	room 211													11/21/2017	<1	<1	P	P	None
14	S	room 209, art													11/21/2017	2	<1	P	P	None
15	S/B	room 210													11/21/2017	<1	<1	P	P	None
16	S/B	room 208													11/21/2017	<1	<1	P	P	None
17	S/B	room 207													11/21/2017	<1	<1	P	P	None
18	S/B	room 206													11/21/2017	<1	<1	P	P	None
19	S/B	room 205													11/21/2017	<1	<1	P	P	None
20	S/B	room 203													11/21/2017	<1	<1	P	P	None
21	S/B	room 204													11/21/2017	<1	<1	P	P	None
22	S/B	room 202													11/21/2017	<1	<1	P	P	None
23	S/B	room 201													11/21/2017	<1	<1	P	P	None
24	B	2nd floor hall													11/21/2017	<1	<1	P	P	None
27	S/B	AV room/library													11/21/2017	<1	<1	P	P	None
28	S	teacher's lounge													11/21/2017	<1	<1	P	P	None
29	S/B	room 110													11/21/2017	2	<1	P	P	None
32	S	kitchen, sink					2/10/2015	<1	<1	P	2/13/2015	3	<1	P	11/21/2017	<1	<1	P	P	None
33	S	kitchen, sink					2/10/2015	<1	<1	P	2/13/2015	<1	2	P	11/21/2017	<1	<1	P	P	None
34	S	nurse office	5/9/2014	19	<1										11/21/2017	8	<1	P	P	None
35	S	work room													11/21/2017	<1	<1	P	P	None
36	S	room 223													11/21/2017	3	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B	1st floor hall	4/30/2004	<1	<1	P	4/18/2005	<1	<1	P	7/11/2005	<1	<1	P				
02	B	1st floor hall					4/18/2005	<1	<1	P	7/11/2005	<1	<1	P				
03	S/B	room 101									7/11/2005	<1	<1	P				
04	S/B	room 102					4/18/2005	<1	<1	P								
05	S/B	room 103									7/11/2005	<1	<1	P				
06	S/B	room 104, kindergarten									7/11/2005	<1	<1	P				
07	S/B	room 105									7/11/2005	<1	<1	P				
08	S/B	room 107									7/11/2005	<1	<1	P				
09	S/B	room 106, kindergarten					4/18/2005	<1	<1	P								
10	S/B	room 108, kindergarten									7/11/2005				5/19/2006	<1	<1	P
11	S/B	room 109					4/18/2005	<1	<1	P								
12	S/B	room 212	4/30/2004	<1	<1	P	4/18/2005	<1	<1	P								
13	S/B	room 211					4/18/2005	<1	<1	P								
14	S	room 209, art									7/11/2005				5/19/2006	<1	<1	P
15	S/B	room 210					4/18/2005	<1	<1	P								
16	S/B	room 208					4/18/2005	<1	<1	P								
17	S/B	room 207					4/18/2005	<1	<1	P								
18	S/B	room 206									7/11/2005	<1	<1	P				
19	S/B	room 205					4/18/2005	<1	<1	P								
20	S/B	room 203									7/11/2005	<1	<1	P				
21	S/B	room 204					4/18/2005	<1	<1	P								
22	S/B	room 202					4/18/2005	<1	<1	P								
23	S/B	room 201					4/18/2005	<1	<1	P								
24	B	2nd floor hall									7/11/2005				5/19/2006	<1	<1	P
27	S/B	AV room/library					4/18/2005	<1	<1	P								
28	S	teacher's lounge	4/30/2004	<1	<1	P												
29	S/B	room 110	4/30/2004	<1	<1	P												
32	S	kitchen, sink																
33	S	kitchen, sink																
34	S	nurse office																
35	S	work room																
36	S	room 223																

Table 3. Cadmium Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B	1st floor hall	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
02	B	1st floor hall	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
03	S/B	room 101	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
04	S/B	room 102	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
05	S/B	room 103	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
06	S/B	room 104, kindergarten	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
07	S/B	room 105	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
08	S/B	room 107	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
09	S/B	room 106, kindergarten	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
10	S/B	room 108, kindergarten	2/12/2008	<1	<1	P	3/13/2008	<1	<1	P	3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
11	S/B	room 109	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
12	S/B	room 212	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
13	S/B	room 211	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
14	S	room 209, art	2/12/2008	<1	<1	P									3/28/2014	<1	<1	P
15	S/B	room 210	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
16	S/B	room 208	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
17	S/B	room 207	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
18	S/B	room 206	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
19	S/B	room 205	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
20	S/B	room 203	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
21	S/B	room 204	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
22	S/B	room 202	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
23	S/B	room 201	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
24	B	2nd floor hall	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
27	S/B	AV room/library	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
28	S	teacher's lounge	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
29	S/B	room 110	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
32	S	kitchen, sink	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
33	S	kitchen, sink	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
34	S	nurse office	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
35	S	work room	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P
36	S	room 223	2/12/2008	<1	<1	P					3/2/2011	<1	<1	P	3/28/2014	<1	<1	P



Table 3. Cadmium Test Results (continued-2)

FIXTURE INFORMATION			Follow-up Sampling 8				Follow-up Sampling 9				Follow-up Sampling 10				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	1st floor hall									11/21/2017	<1	<1	P	P	None
02	B	1st floor hall					2/13/2015	<1		P	11/21/2017	<1	<1	P	P	None
03	S/B	room 101									11/21/2017	<1	<1	P	P	None
04	S/B	room 102									11/21/2017	<1	<1	P	P	None
05	S/B	room 103									11/21/2017	<1	<1	P	P	None
06	S/B	room 104, kindergarten									11/21/2017	<1	<1	P	P	None
07	S/B	room 105									11/21/2017	<1	<1	P	P	None
08	S/B	room 107									11/21/2017	<1	<1	P	P	None
09	S/B	room 106, kindergarten									11/21/2017	<1	<1	P	P	None
10	S/B	room 108, kindergarten									11/21/2017	<1	<1	P	P	None
11	S/B	room 109									11/21/2017	<1	<1	P	P	None
12	S/B	room 212									11/21/2017	<1	<1	P	P	None
13	S/B	room 211									11/21/2017	<1	<1	P	P	None
14	S	room 209, art									11/21/2017	<1	<1	P	P	None
15	S/B	room 210									11/21/2017	<1	<1	P	P	None
16	S/B	room 208									11/21/2017	<1	<1	P	P	None
17	S/B	room 207									11/21/2017	<1	<1	P	P	None
18	S/B	room 206									11/21/2017	<1	<1	P	P	None
19	S/B	room 205									11/21/2017	<1	<1	P	P	None
20	S/B	room 203									11/21/2017	<1	<1	P	P	None
21	S/B	room 204									11/21/2017	<1	<1	P	P	None
22	S/B	room 202									11/21/2017	<1	<1	P	P	None
23	S/B	room 201									11/21/2017	<1	<1	P	P	None
24	B	2nd floor hall									11/21/2017	<1	<1	P	P	None
27	S/B	AV room/library									11/21/2017	<1	<1	P	P	None
28	S	teacher's lounge									11/21/2017	<1	<1	P	P	None
29	S/B	room 110									11/21/2017	<1	<1	P	P	None
32	S	kitchen, sink	2/10/2015	<1	<1	P	2/13/2015	<1	<1	P	11/21/2017	<1	<1	P	P	None
33	S	kitchen, sink	2/10/2015	<1	<1	P	2/13/2015	<1	<1	P	11/21/2017	<1	<1	P	P	None
34	S	nurse office									11/21/2017	<1	<1	P	P	None
35	S	work room									11/21/2017	<1	<1	P	P	None
36	S	room 223									11/21/2017	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B	1st floor hall	4/30/2004	0.87	0.016	P	4/18/2005	1.7	0.067		7/11/2005	0.043	0.012	P				
02	B	1st floor hall					4/18/2005	0.99	0.076	P	7/11/2005	0.04	0.014	P				
03	S/B	room 101									7/11/2005	0.32	0.42	P				
04	S/B	room 102					4/18/2005	0.94	0.42	P								
05	S/B	room 103									7/11/2005	0.3	0.13	P				
06	S/B	room 104, kindergarten									7/11/2005	0.34	0.28	P				
07	S/B	room 105									7/11/2005	0.38	0.19	P				
08	S/B	room 107									7/11/2005	0.29	0.39	P				
09	S/B	room 106, kindergarten					4/18/2005	0.4	0.35	P								
10	S/B	room 108, kindergarten													5/19/2006	0.166	0.102	P
11	S/B	room 109					4/18/2005	0.37	0.13	P								
12	S/B	room 212	4/30/2004	0.26	0.03	P	4/18/2005	0.14	0.088	P								
13	S/B	room 211					4/18/2005	0.61	0.39	P								
14	S	room 209, art									7/11/2005				5/19/2006	0.186	0.099	P
15	S/B	room 210					4/18/2005	0.8	0.18	P								
16	S/B	room 208					4/18/2005	0.21	0.063	P								
17	S/B	room 207					4/18/2005	0.62	0.079	P								
18	S/B	room 206									7/11/2005	0.37	0.071	P				
19	S/B	room 205					4/18/2005	0.58	0.098	P								
20	S/B	room 203									7/11/2005	0.4	0.29	P				
21	S/B	room 204					4/18/2005	0.36	0.054	P								
22	S/B	room 202					4/18/2005	0.078	0.033	P								
23	S/B	room 201					4/18/2005	0.46	0.12	P								
24	B	2nd floor hall													5/19/2006	0.005	0.008	P
27	S/B	AV room/library					4/18/2005	0.44	0.1	P								
28	S	teacher's lounge	4/30/2004	0.064		P					7/11/2005		0.2	P				
29	S/B	room 110	4/30/2004	0.35	0.062	P					7/11/2005		0.3	P				
32	S	kitchen, sink																
33	S	kitchen, sink																
34	S	nurse office																
35	S	work room																
36	S	room 223																

Table 4. Copper Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B	1st floor hall	2/12/2008	0.002	<0.002	P					3/2/2011	0.117	0.099	P	3/28/2014	0.098	0.062	P
02	B	1st floor hall	2/12/2008	0.002	<0.002	P					3/2/2011	0.132	0.071	P	3/28/2014	0.093	0.088	P
03	S/B	room 101	2/12/2008	0.377	0.388	P					3/2/2011	0.224	0.142	P	3/28/2014	0.187	0.182	P
04	S/B	room 102	2/12/2008	0.403	0.236	P					3/2/2011	0.234	0.079	P	3/28/2014	0.168	0.058	P
05	S/B	room 103	2/12/2008	0.32	0.349	P					3/2/2011	0.164	0.15	P	3/28/2014	0.132	0.113	P
06	S/B	room 104, kindergarten	2/12/2008	0.328	0.312	P					3/2/2011	0.186	0.142	P	3/28/2014	0.139	0.122	P
07	S/B	room 105	2/12/2008	0.243	0.136	P					3/2/2011	0.142	0.065	P	3/28/2014	0.092	0.058	P
08	S/B	room 107	2/12/2008	0.384	0.149	P					3/2/2011	0.234	0.108	P	3/28/2014	0.123	0.089	P
09	S/B	room 106, kindergarten	2/12/2008	0.336	0.295	P					3/2/2011	0.159	0.207	P	3/28/2014	0.096	0.13	P
10	S/B	room 108, kindergarten	2/12/2008	0.269	0.136	P	3/13/2008	0.31	0.186	P	3/2/2011	0.186	0.069	P	3/28/2014	0.146	0.104	P
11	S/B	room 109	2/12/2008	0.42	0.149	P					3/2/2011	0.159	0.058	P	3/28/2014	0.094	0.063	P
12	S/B	room 212	2/12/2008	0.266	0.141	P					3/2/2011	0.223	0.064	P	3/28/2014	0.13	0.056	P
13	S/B	room 211	2/12/2008	0.442	0.142	P					3/2/2011	0.25	0.105	P	3/28/2014	0.159	0.12	P
14	S	room 209, art	2/12/2008	0.319	0.15	P									3/28/2014	0.188	0.223	P
15	S/B	room 210	2/12/2008	0.299	0.117	P					3/2/2011	0.19	0.069	P	3/28/2014	0.14	0.092	P
16	S/B	room 208	2/12/2008	0.371	0.106	P					3/2/2011	0.211	0.069	P	3/28/2014	0.129	0.113	P
17	S/B	room 207	2/12/2008	0.347	0.069	P					3/2/2011	0.201	0.134	P	3/28/2014	0.132	0.08	P
18	S/B	room 206	2/12/2008	0.316	0.038	P					3/2/2011	0.123	0.073	P	3/28/2014	0.113	0.096	P
19	S/B	room 205	2/12/2008	0.377	0.056	P					3/2/2011	0.224	0.11	P	3/28/2014	0.118	0.12	P
20	S/B	room 203	2/12/2008	0.394	0.047	P					3/2/2011	0.224	0.243	P	3/28/2014	0.165	0.125	P
21	S/B	room 204	2/12/2008	0.363	0.02	P					3/2/2011	0.196	0.041	P	3/28/2014	0.12	0.035	P
22	S/B	room 202	2/12/2008	0.378	0.019	P					3/2/2011	0.205	0.056	P	3/28/2014	0.129	0.017	P
23	S/B	room 201	2/12/2008	0.427	0.042	P					3/2/2011	0.248	0.076	P	3/28/2014	0.158	0.102	P
24	B	2nd floor hall	2/12/2008	0.002	0.006	P					3/2/2011	0.246	0.23	P	3/28/2014	0.289	0.268	P
27	S/B	AV room/library	2/12/2008	0.318	0.074	P					3/2/2011	0.219	0.067	P	3/28/2014	0.193	0.041	P
28	S	teacher's lounge	2/12/2008	0.244	0.263	P					3/2/2011	0.116	0.082	P	3/28/2014	0.084	0.039	P
29	S/B	room 110	2/12/2008	0.383	0.318	P					3/2/2011	0.25	0.17	P	3/28/2014	0.188	0.179	P
32	S	kitchen, sink	2/12/2008	0.106	0.091	P					3/2/2011	0.203	0.065	P	3/28/2014	0.056	0.047	P
33	S	kitchen, sink	2/12/2008	0.305	0.091	P					3/2/2011	0.068	0.113	P	3/28/2014	0.15	0.102	P
34	S	nurse office	2/12/2008	0.316	<0.002	P					3/2/2011	0.228	0.185	P	3/28/2014	0.152	0.033	P
35	S	work room	2/12/2008	0.231	0.121	P					3/2/2011	0.129	0.166	P	3/28/2014	0.1	0.074	P
36	S	room 223	2/12/2008	0.351	0.507	P					3/2/2011	0.241	0.333	P	3/28/2014	0.224	0.306	P

Table 4. Copper Test Results (continued-2)

FIXTURE INFORMATION			Follow-up Sampling 8				Follow-up Sampling 9				Follow-up Sampling 10				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	1st floor hall									11/21/2017	0.086	0.046	P	P	None
02	B	1st floor hall					2/13/2015	0.136		P	11/21/2017	0.055	0.042	P	P	None
03	S/B	room 101									11/21/2017	0.125	0.137	P	P	None
04	S/B	room 102									11/21/2017	0.097	0.062	P	P	None
05	S/B	room 103									11/21/2017	0.076	0.099	P	P	None
06	S/B	room 104, kindergarten									11/21/2017	0.086	0.062	P	P	None
07	S/B	room 105									11/21/2017	0.067	0.024	P	P	None
08	S/B	room 107									11/21/2017	0.098	0.077	P	P	None
09	S/B	room 106, kindergarten									11/21/2017	0.089	0.106	P	P	None
10	S/B	room 108, kindergarten									11/21/2017	0.089	0.068	P	P	None
11	S/B	room 109									11/21/2017	0.065	0.042	P	P	None
12	S/B	room 212									11/21/2017	0.113	0.089	P	P	None
13	S/B	room 211									11/21/2017	0.128	0.894	P	P	None
14	S	room 209, art									11/21/2017	0.168	0.152	P	P	None
15	S/B	room 210									11/21/2017	0.078	0.06	P	P	None
16	S/B	room 208									11/21/2017	0.113	0.073	P	P	None
17	S/B	room 207									11/21/2017	0.029	0.026	P	P	None
18	S/B	room 206									11/21/2017	0.09	0.02	P	P	None
19	S/B	room 205									11/21/2017	0.111	0.081	P	P	None
20	S/B	room 203									11/21/2017	0.132	0.092	P	P	None
21	S/B	room 204									11/21/2017	0.024	0.016	P	P	None
22	S/B	room 202									11/21/2017	0.094	0.017	P	P	None
23	S/B	room 201									11/21/2017	0.149	0.107	P	P	None
24	B	2nd floor hall									11/21/2017	0.248	0.259	P	P	None
27	S/B	AV room/library									11/21/2017	0.141	0.046	P	P	None
28	S	teacher's lounge									11/21/2017	0.051	0.096	P	P	None
29	S/B	room 110									11/21/2017	0.174	0.116	P	P	None
32	S	kitchen, sink	2/10/2015	0.095	0.069	P	2/13/2015	0.209	0.157	P	11/21/2017	0.164	0.052	P	P	None
33	S	kitchen, sink	2/10/2015	0.071	0.065	P	2/13/2015	0.078	0.125	P	11/21/2017	0.114	0.05	P	P	None
34	S	nurse office									11/21/2017	0.165	0.06	P	P	None
35	S	work room									11/21/2017	0.065	0.048	P	P	None
36	S	room 223									11/21/2017	0.207	0.134	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail
01	B	1st floor hall	4/30/2004	0.06	0.07	P	4/18/2005	<0.05	0.05	P	7/11/2005		<0.05	P				
02	B	1st floor hall					4/18/2005	<0.05	<0.05	P	7/11/2005		<0.05	P				
03	S/B	room 101									7/11/2005		0.18	P				
04	S/B	room 102					4/18/2005	<0.05	<0.05	P	7/11/2005		0.17	P				
05	S/B	room 103									7/11/2005		0.17	P				
06	S/B	room 104, kindergarten									7/11/2005		<0.05	P				
07	S/B	room 105									7/11/2005		<0.05	P				
08	S/B	room 107									7/11/2005		<0.05	P				
09	S/B	room 106, kindergarten					4/18/2005	<0.05	<0.05	P	7/11/2005		<0.05	P				
10	S/B	room 108, kindergarten									7/11/2005							
11	S/B	room 109					4/18/2005	<0.05	<0.05	P	7/11/2005		<0.05	P	3/2/2011		<0.05	P
12	S/B	room 212	4/30/2004	0.08	0.05	P	4/18/2005	<0.05	<0.05	P	7/11/2005		<0.05	P				
13	S/B	room 211					4/18/2005	<0.05	<0.05	P	7/11/2005		<0.05	P	3/2/2011		<0.05	P
14	S	room 209, art									7/11/2005							
15	S/B	room 210					4/18/2005	<0.05	<0.05	P	7/11/2005		0.06	P				
16	S/B	room 208					4/18/2005	<0.05	<0.05	P	7/11/2005		0.1	P				
17	S/B	room 207					4/18/2005	0.06	0.08	P	7/11/2005		0.12	P				
18	S/B	room 206									7/11/2005		0.09	P				
19	S/B	room 205					4/18/2005	<0.05	<0.05	P	7/11/2005		0.06	P				
20	S/B	room 203									7/11/2005		0.06	P				
21	S/B	room 204					4/18/2005	<0.05	<0.05	P	7/11/2005		0.09	P				
22	S/B	room 202					4/18/2005	<0.05	<0.05	P	7/11/2005		0.11	P				
23	S/B	room 201					4/18/2005	<0.05	<0.05	P	7/11/2005		0.17	P				
24	B	2nd floor hall									7/11/2005				3/2/2011		<0.05	P
27	S/B	AV room/library					4/18/2005	<0.05	<0.05	P	7/11/2005		<0.05	P				
28	S	teacher's lounge	4/30/2004	<0.05		P					7/11/2005		0.14	P				
29	S/B	room 110	4/30/2004	<0.05	0.05	P					7/11/2005		<0.05	P				
32	S	kitchen, sink																
33	S	kitchen, sink																
34	S	nurse office																
35	S	work room																
36	S	room 223																

Table 5. Iron Test Results(continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B	1st floor hall																	P	None
02	B	1st floor hall									2/13/2015	<0.05		P					P	None
03	S/B	room 101																	P	None
04	S/B	room 102																	P	None
05	S/B	room 103																	P	None
06	S/B	room 104, kindergarten																	P	None
07	S/B	room 105																	P	None
08	S/B	room 107																	P	None
09	S/B	room 106, kindergarten													11/21/2017	0.096		P	P	None
10	S/B	room 108, kindergarten																		
11	S/B	room 109																	P	None
12	S/B	room 212	3/28/2014		<0.05	P													P	None
13	S/B	room 211																	P	None
14	S	room 209, art																		
15	S/B	room 210	3/28/2014		<0.05	P									11/21/2017		0.074	P	P	None
16	S/B	room 208																	P	None
17	S/B	room 207																	P	None
18	S/B	room 206																	P	None
19	S/B	room 205																	P	None
20	S/B	room 203																	P	None
21	S/B	room 204																	P	None
22	S/B	room 202													11/21/2017		0.174	P	P	None
23	S/B	room 201																	P	None
24	B	2nd floor hall																	P	None
27	S/B	AV room/library	3/28/2014		0.052	P													P	None
28	S	teacher's lounge																	P	None
29	S/B	room 110													11/21/2017		0.065	P	P	None
32	S	kitchen, sink					2/10/2015	<0.05	<0.05	P	2/13/2015	<0.05	<0.05	P					P	None
33	S	kitchen, sink					2/10/2015	<0.05	<0.05	P	2/13/2015	<0.05	<0.05	P					P	None
34	S	nurse office																		
35	S	work room																		
36	S	room 223													11/21/2017		0.067	P	P	None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	boiler room (South East corner)	Arsenic	21-Nov-17	2 ppb	P
00	SE	boiler room (South East corner)	Cadmium	21-Nov-17	1 ppb	P
00	SE	boiler room (South East corner)	Copper	21-Nov-17	0.015 ppm	P
00	SE	boiler room (South East corner)	E coli	30-Apr-04	<1 Colonies	P
00	SE	boiler room (South East corner)	Iron	21-Nov-17	0.12 ppm	P
00	SE	boiler room (South East corner)	Lead	21-Nov-17	1 ppb	P
00	SE	boiler room (South East corner)	Total Coliforms	02-Mar-11	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

**Bacteriological Characteristics**

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.