

Seattle Public Schools
 Drinking Water Quality Program

Summary Status
 for
 Broadview-Thomson Elementary

Updated Sept 14, 2017

Status:

All sources meet the policy except:

Signs will be posted:

10	S	room 116, kindergarten-1, code
18	S	kitchen - kettle sink
34	S	room 114 teachers sink south, right
35	S	room 114 teachers sink north, left
44	S	rm 203 NW sink window, 5th
45	S	rm 203 W/NW sink (middle), 5th
46	S	rm 203 W/SW sink, 5th
47	S	rm 203 SW/N sink, 5th
48	S	rm 203 SW/S sink, 5th
49	S	rm 203 S sink, 5th
50	S	rm 203 E sink, 5th
60	S	room 101, 2nd grade
64	S	room 105, occupational and Physical therapy
68	S	room 111
71	S	room 113, kindergarten
74	S	room 115, headstart, 2-heads, cold
77	S	room 209, 6th grade, left
78	S	room 209, 6th grade, right
80	S	room 206, 4th grade
81A	S	room 205, 4th grade, right
82A	S	room 204, right
83	S	room 220, copy room
84	S	room 218, 3rd, left
84A	S	room 218, right
85	S	room 210, 3rd grade, left
86	S	room 210, 3rd grade, right

The school will be flushed after any breaks longer than five days.

Follow-up monitoring: Will be performed in school year 2019-2020.