

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
Sacajawea Elementary

Updated March 15, 2018

General Information:

Plumbing piping materials: mainly galvanized steel

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria:

All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

CURRENT STATUS											
FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B/S	room 101	P	None	P	None	P	None	P	None	Yes
02	B	hall (front entrance)	P	None	P	None	P	None	P	None	Yes
03	B/S	room 102	P	None	P	None	P	None	P	None	Yes
04	B/S	room 103	P	None	P	None	P	None	P	None	Yes
05	B/S	room 104	P	None	P	None	P	None	P	None	Yes
06	B/S	room 105	P	None	P	None	P	None	P	None	Yes
07	B	hallway, part of 3-head	P	None	P	None	P	None	P	None	Yes
09	B	hallway, part of 3-head	P	None	P	None	P	None	P	None	Yes
10	B/S	library	P	None	P	None	P	None	P	None	Yes
11	S	library	P	None	P	None	P	None	P	None	Yes
12	B/S	room 108	P	None	P	None	P	None	P	None	Yes
13	B/S	room 7	P	None	P	None	P	None	P	None	Yes
14	B/S	room 6	P	None	P	None	P	None	P	None	Yes
15	B/S	room 5	P	None	P	None	P	None	P	None	Yes
16	B/S	room 4	P	None	P	None	P	None	P	None	Yes
17	B/S	room 3	P	None	P	None	P	None	P	None	Yes
18	B/S	room 2 Kindergarten	P	None	P	None	P	None	P	None	Yes
19	B/S	room 1, kindergarten	P	None	P	None	P	None	P	None	Yes
20	S	staff lounge	P	None	P	None	P	None	P	None	Yes
21	S	staff work room / conference room	P	None	P	None	P	None	P	None	Yes
22	S	office sink	P	None	P	None	P	None	P	None	Yes
23	S	kitchen, south, right	P	None	P	None	P	None	P	None	Yes
24	S	kitchen, south, left	P	None	P	None	P	None	P	None	Yes
25	S	Kitchen, west, left	P	None	P	None	P	None			Yes
26	S	Kitchen, west, right	P	None	P	None	P	None	P	None	Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B/S	room 101	5/13/2004	250	4		4/7/05	6	7	P	7/20/05	5	3	P								
02	B	hall (front entrance)	5/13/2004	17	3		4/7/05	22	1		7/20/05	16	4		8/11/05	10	6	P				
03	B/S	room 102	5/13/2004	71	6		4/7/05	13	17		7/20/05	9	3	P	8/11/05	6	5	P				
04	B/S	room 103	5/13/2004	100	16		4/7/05	12	2		7/20/05	71	2		8/11/05	7	5	P				
05	B/S	room 104	5/13/2004	56	1		4/7/05	25	6		7/20/05	4	3	P	8/11/05	6	8	P				
06	B/S	room 105	5/13/2004	18	1		4/7/05	110	29		7/20/05	8	4	P	8/11/05	8	7	P				
07	B	hallway, part of 3-head	5/13/2004	150	7		4/7/05	380	84		7/20/05	11	2		8/11/05	11	6		11/10/05	1	6	P
09	B	hallway, part of 3-head	5/13/2004	25	6		4/7/05	31	3		7/20/05	4	2	P	8/11/05	10	3	P				
10	B/S	library	5/13/2004	420	6		4/7/05	9	1	P												
11	S	library	5/13/2004	110	15		4/7/05	11	7		7/20/05	13	2		8/11/05	14	3		11/10/05	1	2	P
12	B/S	room 108	5/13/2004	21	2		4/7/05	19	3		7/20/05	5	2	P	8/11/05	5	1	P				
13	B/S	room 7	5/13/2004	15	2		4/7/05	120	5		7/20/05	5	2	P	8/11/05	5	2	P				
14	B/S	room 6	5/13/2004	84	3		4/7/05	49	12		7/20/05	6	3	P	8/11/05	3	2	P				
15	B/S	room 5	5/13/2004	180	15		4/7/05	79	13		7/20/05	10	3	P	8/11/05	10	6	P				
16	B/S	room 4					4/7/05	170	86		7/20/05	11	6		8/11/05	10	12		11/10/05	2	5	P
17	B/S	room 3	5/13/2004	29	2		4/7/05	94	22		7/20/05	10	3	P	8/11/05	10	6	P				
18	B/S	room 2 Kindergarten	5/13/2004	290	11		4/7/05	200	25		7/20/05	8	3	P	8/11/05	10	5	P				
19	B/S	room 1, kindergarten	5/13/2004	15	2		4/7/05	15	8		7/20/05	17	3		8/11/05	16	2		11/10/05	<1	3	P
20	S	staff lounge	5/13/2004	2	<1	P																
21	S	staff work room / conference room	5/13/2004	4	<1	P																
22	S	office sink	5/13/2004	13	2										8/11/05				11/10/05	11	1	
23	S	kitchen, south, right	5/13/2004	35	2										8/11/05				11/10/05	2	<1	P
24	S	kitchen, south, left	5/13/2004	2	<1	P																
25	S	Kitchen, west, left																				
26	S	Kitchen, west, right																				

Table 2. Lead Test Results (Continued)

FIXTURE INFORMATION			Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Follow-up Sampling 8				Follow-up Sampling 9				
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	
01	B/S	room 101																					
02	B	hall (front entrance)																					
03	B/S	room 102	1/31/2006	29	2		2/1/2006	26	2		2/2/2006	25	1		2/3/2006	26	2		5/12/2006	6	<1	P	
04	B/S	room 103																					
05	B/S	room 104																					
06	B/S	room 105	1/31/2006	7	4	P	2/1/2006	7	2	P	2/2/2006	6	1	P	2/3/2006	5	1	P					
07	B	hallway, part of 3-head																					
09	B	hallway, part of 3-head	1/31/2006	<1	5	P	2/1/2006	<1	2	P	2/2/2006	<1	2	P	2/3/2006	<1	<1	P					
10	B/S	library																					
11	S	library																					
12	B/S	room 108	1/31/2006	3	<1	P	2/1/2006	2	<1	P	2/2/2006	3	<1	P	2/3/2006	3	<1	P					
13	B/S	room 7																					
14	B/S	room 6	1/31/2006	2	1	P	2/1/2006	1	1	P	2/2/2006	2	<1	P	2/3/2006	2	<1	P					
15	B/S	room 5																					
16	B/S	room 4																					
17	B/S	room 3																					
18	B/S	room 2 Kindergarten	1/31/2006	6	3	P	2/1/2006	6	1	P	2/2/2006	6	<1	P	2/3/2006	6	<1	P					
19	B/S	room 1, kindergarten																					
20	S	staff lounge																					
21	S	staff work room / conference room																					
22	S	office sink																	5/12/2006	15	2		
23	S	kitchen, south, right																					
24	S	kitchen, south, left																					
25	S	Kitchen, west, left																					
26	S	Kitchen, west, right																					

Table 2. Lead Test Results (Continued-2)

FIXTURE INFORMATION			Follow-up Sampling 10				Follow-up Sampling 11				Follow-up Sampling 12				Follow-up Sampling 13				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B/S	room 101	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
02	B	hall (front entrance)	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
03	B/S	room 102	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
04	B/S	room 103	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
05	B/S	room 104	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
06	B/S	room 105	2/29/2008	4	<1	P	4/7/2011	<1	<1	P	4/24/2014	3	<1	P	1/10/2018	<1	<1	P	P	None
07	B	hallway, part of 3-head	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
09	B	hallway, part of 3-head	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	2	<1	P	1/10/2018	<1	<1	P	P	None
10	B/S	library	2/29/2008	4	1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
11	S	library	2/29/2008	10	2	P	4/7/2011	8	2	P	4/24/2014	10	4	P	1/10/2018	7	2	P	P	None
12	B/S	room 108	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
13	B/S	room 7	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
14	B/S	room 6	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
15	B/S	room 5	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
16	B/S	room 4	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
17	B/S	room 3	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
18	B/S	room 2 Kindergarten	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	2	<1	P	1/10/2018	<1	<1	P	P	None
19	B/S	room 1, kindergarten	2/29/2008	<1	<1	P	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
20	S	staff lounge	2/29/2008	5	2	P	4/7/2011	4	<1	P	4/24/2014	3	<1	P	1/10/2018	3	<1	P	P	None
21	S	staff work room / conference room	2/29/2008	5	<1	P	4/7/2011	4	1	P	4/24/2014	3	<1	P	1/10/2018	4	2	P	P	None
22	S	office sink	2/29/2008	8	<1	P	4/7/2011	2	<1	P	4/24/2014	4	<1	P	1/10/2018	4	<1	P	P	None
23	S	kitchen, south, right	2/29/2008	<1	4	P	4/7/2011	4	<1	P	4/24/2014	4	<1	P	1/10/2018	6	<1	P	P	None
24	S	kitchen, south, left	2/29/2008	2	<1	P	4/7/2011	3	<1	P	4/24/2014	4	<1	P	1/10/2018	<1	<1	P	P	None
25	S	Kitchen, west, left	2/29/2008	10	<1	P	4/7/2011	4	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
26	S	Kitchen, west, right	2/29/2008	6	<1	P	4/7/2011	1	<1	P	4/24/2014	<1	<1	P	1/10/2018	1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B/S	room 101	5/13/2004	<1	<1	P	4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
02	B	hall (front entrance)					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
03	B/S	room 102					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
04	B/S	room 103					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
05	B/S	room 104	5/13/2004	<1	<1	P	4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
06	B/S	room 105					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
07	B	hallway, part of 3-head					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
09	B	hallway, part of 3-head					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
10	B/S	library	5/13/2004	<1	<1	P	4/7/05	<1	<1	P					2/29/2008	<1	<1	P
11	S	library					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
12	B/S	room 108	5/13/2004	<1	<1	P	4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
13	B/S	room 7	5/13/2004	<1	<1	P	4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
14	B/S	room 6					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
15	B/S	room 5					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
16	B/S	room 4					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
17	B/S	room 3					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
18	B/S	room 2 Kindergarten					4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
19	B/S	room 1, kindergarten	5/13/2004	<1	<1	P	4/7/05	<1	<1	P	7/20/05	<1	<1	P	2/29/2008	<1	<1	P
20	S	staff lounge	5/13/2004	<1	<1	P									2/29/2008	<1	<1	P
21	S	staff work room / conference room	5/13/2004	<1	<1	P									2/29/2008	<1	<1	P
22	S	office sink	5/13/2004	<1	<1	P									2/29/2008	<1	<1	P
23	S	kitchen, south, right	5/13/2004	<1	<1	P									2/29/2008	<1	<1	P
24	S	kitchen, south, left	5/13/2004	<1	<1	P									2/29/2008	<1	<1	P
25	S	Kitchen, west, left													2/29/2008	<1	<1	P
26	S	Kitchen, west, right													2/29/2008	<1	<1	P

Table 3. Cadmium Test Results(continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B/S	room 101	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
02	B	hall (front entrance)	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
03	B/S	room 102	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
04	B/S	room 103	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
05	B/S	room 104	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
06	B/S	room 105	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
07	B	hallway, part of 3-head	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
09	B	hallway, part of 3-head	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
10	B/S	library	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
11	S	library	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
12	B/S	room 108	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
13	B/S	room 7	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
14	B/S	room 6	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
15	B/S	room 5	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
16	B/S	room 4	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
17	B/S	room 3	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
18	B/S	room 2 Kindergarten	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
19	B/S	room 1, kindergarten	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
20	S	staff lounge	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
21	S	staff work room / conference room	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
22	S	office sink	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
23	S	kitchen, south, right	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
24	S	kitchen, south, left	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
25	S	Kitchen, west, left	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None
26	S	Kitchen, west, right	4/7/2011	<1	<1	P	4/24/2014	<1	<1	P	1/10/2018	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail
01	B/S	room 101	5/13/2004	5.4	0.1		4/7/05	0.64	0.57	P	7/20/05	0.024	0.03	P	2/29/2008	0.004	<0.002	P
02	B	hall (front entrance)					4/7/05	0.41	0.049	P	7/20/05	0.03	0.011	P	2/29/2008	0.002	<0.002	P
03	B/S	room 102					4/7/05	0.38	0.06	P	7/20/05	0.26	0.015	P	2/29/2008	0.005	<0.002	P
04	B/S	room 103					4/7/05	0.45	0.07	P	7/20/05	0.07	0.015	P	2/29/2008	0.008	<0.002	P
05	B/S	room 104	5/13/2004	0.38		P	4/7/05	0.25	0.037	P	7/20/05	0.039	0.013	P	2/29/2008	0.005	<0.002	P
06	B/S	room 105					4/7/05	0.68	0.14	P	7/20/05	0.032	0.017	P	2/29/2008	0.016	<0.002	P
07	B	hallway, part of 3-head					4/7/05	1.2	0.07	P	7/20/05	0.054	0.014	P	2/29/2008	0.059	0.002	P
09	B	hallway, part of 3-head					4/7/05	1.7	0.082		7/20/05	0.14	0.018	P	2/29/2008	0.042	0.006	P
10	B/S	library	5/13/2004	0.97		P	4/7/05	0.54	0.19	P	7/20/05		0.034	P	2/29/2008	0.033	0.004	P
11	S	library					4/7/05	0.48	0.3	P	7/20/05	0.056	0.025	P	2/29/2008	0.327	0.209	P
12	B/S	room 108	5/13/2004	0.7	0.2	P	4/7/05	2.5	0.69		7/20/05	0.065	0.064	P	2/29/2008	0.003	<0.002	P
13	B/S	room 7	5/13/2004	0.47	0.36	P	4/7/05	0.67	0.52	P	7/20/05	0.041	0.027	P	2/29/2008	0.003	<0.002	P
14	B/S	room 6					4/7/05	0.82	0.35	P	7/20/05	0.029	0.024	P	2/29/2008	0.002	<0.002	P
15	B/S	room 5					4/7/05	1.8	0.45		7/20/05	0.034	0.027	P	2/29/2008	0.003	<0.002	P
16	B/S	room 4					4/7/05	0.73	0.29	P	7/20/05	0.045	0.02	P	2/29/2008	0.003	<0.002	P
17	B/S	room 3					4/7/05	1.2	0.22	P	7/20/05	0.078	0.025	P	2/29/2008	0.005	0.003	P
18	B/S	room 2 Kindergarten					4/7/05	0.93	0.22	P	7/20/05	0.1	0.015	P	2/29/2008	0.003	<0.002	P
19	B/S	room 1, kindergarten	5/13/2004	0.54	0.051	P	4/7/05	0.95	0.22	P	7/20/05	0.16	0.015	P	2/29/2008	0.005	0.003	P
20	S	staff lounge	5/13/2004	0.02		P					7/20/05		0.087	P	2/29/2008	0.1	0.054	P
21	S	staff work room / conference room	5/13/2004	0.45		P					7/20/05		0.29	P	2/29/2008	0.154	0.107	P
22	S	office sink	5/13/2004	0.3		P					7/20/05		0.34	P	2/29/2008	0.39	0.331	P
23	S	kitchen, south, right	5/13/2004	0.33		P					7/20/05		0.026	P	2/29/2008	0.014	0.138	P
24	S	kitchen, south, left	5/13/2004	0.052		P					7/20/05		0.027	P	2/29/2008	0.075	0.012	P
25	S	Kitchen, west, left													2/29/2008	0.291	0.015	P
26	S	Kitchen, west, right													2/29/2008	0.212	0.012	P

Table 4. Copper Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B/S	room 101	4/7/2011	0.005	<0.002	P	4/24/2014	0.008	0.003	P	1/10/2018	0.002	<0.002	P	P	None
02	B	hall (front entrance)	4/7/2011	<0.002	<0.002	P	4/24/2014	<0.002	<0.002	P	1/10/2018	0.004	<0.002	P	P	None
03	B/S	room 102	4/7/2011	<0.002	<0.002	P	4/24/2014	<0.002	<0.002	P	1/10/2018	0.003	<0.002	P	P	None
04	B/S	room 103	4/7/2011	<0.002	<0.002	P	4/24/2014	0.004	<0.002	P	1/10/2018	0.004	<0.002	P	P	None
05	B/S	room 104	4/7/2011	0.002	<0.002	P	4/24/2014	<0.002	<0.002	P	1/10/2018	<0.002	<0.002	P	P	None
06	B/S	room 105	4/7/2011	0.002	<0.002	P	4/24/2014	0.013	0.004	P	1/10/2018	<0.002	<0.002	P	P	None
07	B	hallway, part of 3-head	4/7/2011	0.002	<0.002	P	4/24/2014	<0.002	<0.002	P	1/10/2018	0.002	<0.002	P	P	None
09	B	hallway, part of 3-head	4/7/2011	<0.002	<0.002	P	4/24/2014	0.008	<0.002	P	1/10/2018	0.002	<0.002	P	P	None
10	B/S	library	4/7/2011	<0.002	<0.002	P	4/24/2014	0.002	<0.002	P	1/10/2018	0.003	<0.002	P	P	None
11	S	library	4/7/2011	0.363	0.192	P	4/24/2014	0.299	0.164	P	1/10/2018	0.965	0.223	P	P	None
12	B/S	room 108	4/7/2011	0.007	0.003	P	4/24/2014	0.015	0.012	P	1/10/2018	<0.002	<0.002	P	P	None
13	B/S	room 7	4/7/2011	0.005	0.004	P	4/24/2014	0.008	0.011	P	1/10/2018	0.002	<0.002	P	P	None
14	B/S	room 6	4/7/2011	<0.002	<0.002	P	4/24/2014	0.009	0.003	P	1/10/2018	<0.002	<0.002	P	P	None
15	B/S	room 5	4/7/2011	0.003	<0.002	P	4/24/2014	0.005	<0.002	P	1/10/2018	0.002	<0.002	P	P	None
16	B/S	room 4	4/7/2011	<0.002	<0.002	P	4/24/2014	0.009	0.002	P	1/10/2018	<0.002	<0.002	P	P	None
17	B/S	room 3	4/7/2011	0.002	<0.002	P	4/24/2014	0.005	<0.002	P	1/10/2018	<0.002	<0.002	P	P	None
18	B/S	room 2 Kindergarten	4/7/2011	<0.002	<0.002	P	4/24/2014	0.198	0.182	P	1/10/2018	<0.002	<0.002	P	P	None
19	B/S	room 1, kindergarten	4/7/2011	<0.002	<0.002	P	4/24/2014	0.016	0.009	P	1/10/2018	<0.002	<0.002	P	P	None
20	S	staff lounge	4/7/2011	0.081	0.041	P	4/24/2014	0.055	0.012	P	1/10/2018	0.072	0.04	P	P	None
21	S	staff work room / conference room	4/7/2011	0.139	0.067	P	4/24/2014	0.124	0.035	P	1/10/2018	0.214	0.149	P	P	None
22	S	office sink	4/7/2011	0.376	0.144	P	4/24/2014	0.214	0.087	P	1/10/2018	0.296	0.082	P	P	None
23	S	kitchen, south, right	4/7/2011	0.152	0.043	P	4/24/2014	0.117	0.037	P	1/10/2018	0.129	0.041	P	P	None
24	S	kitchen, south, left	4/7/2011	0.103	0.067	P	4/24/2014	0.112	0.034	P	1/10/2018	0.068	0.018	P	P	None
25	S	Kitchen, west, left	4/7/2011	0.179	0.068	P	4/24/2014	0.062	0.042	P	1/10/2018	0.147	0.02	P	P	None
26	S	Kitchen, west, right	4/7/2011	0.189	0.064	P	4/24/2014	0.203	0.042	P	1/10/2018	0.265	0.021	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4				Follow-up Sampling 5				Summary Status	
Fixture ID	Type	Location	Date	1st Draw	Flush 2m	Pass/Fail	Date	1st Draw	Flush 30s	Pass/Fail	Date	1st Draw	Flush 2m	Pass/Fail	Date	1st Draw	Flush 2m	Pass/Fail	Date	1st Draw	Flush 2m	Pass/Fail	Date	1st Draw	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B/S	room 101	5/13/04	0.08	<0.05	P	4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
02	B	hall (front entrance)					4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
03	B/S	room 102					4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
04	B/S	room 103					4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
05	B/S	room 104	5/13/04	<0.05		P	4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
06	B/S	room 105					4/7/05	<0.05	<0.05	P	7/20/05		0.06	P	4/7/11		<0.05	P	4/24/14		<0.05	P					P	None
07	B	hallway, part of 3-head					4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P									1/10/18		<0.05	P	P	None
09	B	hallway, part of 3-head					4/7/05	<0.05	<0.05	P	7/20/05		0.07	P													P	None
10	B/S	library	5/13/04	<0.05		P	4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
11	S	library					4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
12	B/S	room 108	5/13/04	<0.05	<0.05	P	4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
13	B/S	room 7	5/13/04	<0.05	<0.05	P	4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P	4/7/11		<0.05	P									P	None
14	B/S	room 6					4/7/05	0.08	<0.05	P	7/20/05		0.08	P					4/24/14		<0.05	P					P	None
15	B/S	room 5					4/7/05	0.05	<0.05	P	7/20/05		0.07	P									1/10/18		<0.05	P	P	None
16	B/S	room 4					4/7/05	0.12	<0.05	P	7/20/05		0.08	P													P	None
17	B/S	room 3					4/7/05	<0.05	<0.05	P	7/20/05		0.06	P													P	None
18	B/S	room 2 Kindergarten					4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P													P	None
19	B/S	room 1, kindergarten	5/13/04	<0.05	<0.05	P	4/7/05	<0.05	<0.05	P	7/20/05		<0.05	P	4/7/11		<0.05	P									P	None
20	S	staff lounge	5/13/04	<0.05		P					7/20/05		<0.05	P	4/7/11		<0.05	P									P	None
21	S	staff work room / conference room	5/13/04	<0.05		P					7/20/05		0.05	P					4/24/14		<0.05	P					P	None
22	S	office sink	5/13/04	<0.05		P					7/20/05		0.05	P									1/10/18		<0.05	P	P	None
23	S	kitchen, south, right	5/13/04	<0.05		P					7/20/05		0.11	P													P	None
24	S	kitchen, south, left	5/13/04	<0.05		P					7/20/05		0.12	P													P	None
25	S	Kitchen, west, left																										Sample
26	S	Kitchen, west, right																	4/24/14		<0.05	P					P	None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	can room	Arsenic	10-Jan-18	2 ppb	P
00	SE	can room	Cadmium	10-Jan-18	1 ppb	P
00	SE	can room	Copper	10-Jan-18	0.033 ppm	P
00	SE	can room	E coli	13-May-04	<1 Colonies	P
00	SE	can room	Iron	10-Jan-18	0.116 ppm	P
00	SE	can room	Lead	10-Jan-18	1 ppb	P
00	SE	can room	Total Coliforms	29-Apr-11	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).
 "n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.