

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
Arbor Heights Elementary**

Updated September 24, 2020

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All sources that do not meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S/B	room 121	P	None	P	None	P	None			Yes
02	S/B	room 121	P	None	P	None	P	None			Yes
03	S/B	room 122	P	None	P	None	P	None			Yes
04	S/B	room 122	P	None	P	None	P	None			Yes
05	S/B	room 123	P	None	P	None	P	None	P	None	Yes
06	S/B	ROOM 123	P	None	P	None	P	None			Yes
07	S/B	KINDERGARTEN FLEX	P	None	P	None	P	None	P	None	Yes
08	S/B	ROOM 124	P	None	P	None	P	None			Yes
09	S/B	ROOM 124	P	None	P	None	P	None			Yes
10	S/B	ROOM 112	P	None	P	None	P	None	P	None	Yes
11	S/B	SPEC ED 115	P	None	P	None	P	None			Yes
12	S	SPEC ED KITCHEN	P	None	P	None	P	None			Yes
13	S/B	SPEC ED 117	P	None	P	None	P	None			Yes
14	S	TEACHER'S LOUNGE 109	P	None	P	None	P	None			Yes
15	S/B	PSYH OFFICE 119A	P	None	P	None	P	None	P	None	Yes
16	S/B	OT/PT 119	P	None	P	None	P	None	P	None	Yes
17	S	DAYCARE KITCHEN	P	None	P	None	P	None			Yes
18	S	DAYCARE KITCHEN	P	None	P	None	P	None			Yes
19	S/B	ROOM 131, LEFT	P	None	P	None	P	None			Yes
20	S/B	ROOM 131, RIGHT	P	None	P	None	P	None	P	None	Yes
21	S/B	ROOM 133, LEFT	P	None	P	None	P	None			Yes
22	S/B	ROOM 133, RIGHT	P	None	P	None	P	None			Yes
23	S/B	ROOM 273	P	None	P	None	P	None			Yes
24	S/B	ROOM 274	P	None	P	None	P	None	P	None	Yes
25	S/B	ROOM 275	P	None	P	None	P	None	P	None	Yes
26	S/B	SOUTHWING 2ND FLOOR FLEX, OUTSIDE 275	P	None	P	None	P	None			Yes
27	S/B	ROOM 272	P	None	P	None	P	None			Yes
28	S	ROOM 277, LEFT	P	None	P	None	P	None			Yes
29	S	ROOM 277, RIGHT	P	None	P	None	P	None			Yes
30	S/B	ROOM 271	P	None	P	None	P	None	P	None	Yes
31	S	ROOM 279A	P	None	P	None	P	None			Yes
32	S	ART ROOM 287	P	None	P	None	P	None	P	None	Yes
33	S	ART ROOM 287	P	None	P	None	P	None			Yes
34	S	ART ROOM 287	P	None	P	None	P	None			Yes
35	S	ART ROOM 287	P	None	P	None	P	None	P	None	Yes
36	S/B	ROOM 281	P	None	P	None	P	None			Yes
37	S/B	ROOM 282	P	None	P	None	P	None			Yes
38	S/B	OPEN LEARNING 280	P	None	P	None	P	None			Yes
39	S/B	ROOM 285	P	None	P	None	P	None			Yes
40	S/B	ROOM 284	P	None	P	None	P	None	P	None	Yes
41	S/B	ROOM 283	P	None	P	None	P	None			Yes
42	S/B	ROOM 323	P	None	P	None	P	None	P	None	Yes
43	S/B	ROOM 324	P	None	P	None	P	None			Yes
44	S/B	ROOM 325	P	None	P	None	P	None			Yes
45	S/B	3RD FLOOR FLEX OUTSIDE 325	P	None	P	None	P	None	P	None	Yes
46	S/B	ROOM 322	P	None	P	None	P	None			Yes

47	S/B	ROOM 321	P	None	P	None	P	None			Yes
48	S	ROOM 327	P	None	P	None	P	None			Yes
49	S	ROOM 327	P	None	P	None	P	None	P	None	Yes
50	S	ROOM 327	P	None	P	None	P	None	P	None	Yes
51	S	ROOM 327	P	None	P	None	P	None			Yes
52	S	329A	P	None	P	None	P	None			Yes
53	S	ART ROOM 337	P	None	P	None	P	None			Yes
54	S	ART ROOM 337	P	None	P	None	P	None			Yes
55	S	ART ROOM 337	P	None	P	None	P	None			Yes
56	S	ART ROOM 337	P	None	P	None	P	None			Yes
57	S/B	ROOM 331	P	None	P	None	P	None	P	None	Yes
58	S/B	ROOM 332	P	None	P	None	P	None			Yes
59	S/B	OPEN LEARNING 330	P	None	P	None	P	None			Yes
60	S/B	ROOM 335	P	None	P	None	P	None	P	None	Yes
61	S/B	ROOM 334	P	None	P	None	P	None			Yes
62	S/B	ROOM 333	P	None	P	None	P	None			Yes
63	S	LIBRARY OFFICE	P	None	P	None	P	None			Yes
64	B	NORTHWING 3RD FLOOR HALLWAY, LEFT	P	None	P	None	P	None			Yes
65	B	NORTHWING 3RD FLOOR HALLWAY, RIGHT	P	None	P	None	P	None	P	None	Yes
66	S	MAIN OFFICE	P	None	P	None	P	None			Yes
67	S/B	NURSE OFFICE 203	P	None	P	None	P	None	P	None	Yes
68	B	NORTHWING 2ND FLOOR HALLWAY, LEFT	P	None	P	None	P	None			Yes
69	B	NORTHWING 2ND FLOOR HALLWAY, RIGHT	P	None	P	None	P	None			Yes
70	S	KITCHEN, LEFT	P	None	P	None	P	None	P	None	Yes
71	S	KITCHEN, RIGHT	P	None	P	None	P	None			Yes
72	S	KITCHEN	P	None	P	None	P	None			Yes
73	B	HALLWAY OUTSIDE GYM, LEFT	P	None	P	None	P	None			Yes
74	B	HALLWAY OUTSIDE GYM, RIGHT	P	None	P	None	P	None	P	None	Yes
75	S/B	WORKROOM 241C	P	None	P	None	P	None	P	None	Yes
76	B	GYM, LEFT	P	None	P	None	P	None			Yes
77	B	GYM, RIGHT	P	None	P	None	P	None			Yes
78	S	ROOM 277	P	None	P	None	P	None			Yes
79	S	ROOM 277	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			8/16/2016			9/20/2016			8/7/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	room 121	<1	<1	P				<1	<1	P	P	None
02	S/B	room 121	<1	<1	P				<1	<1	P	P	None
03	S/B	room 122	<1	<1	P				<1	<1	P	P	None
04	S/B	room 122	<1	<1	P				<1	<1	P	P	None
05	S/B	room 123	<1	<1	P				<1	<1	P	P	None
06	S/B	ROOM 123	<1	<1	P				<1	<1	P	P	None
07	S/B	KINDERGARTEN FLEX	<1	<1	P				<1	<1	P	P	None
08	S/B	ROOM 124	<1	<1	P				<1	<1	P	P	None
09	S/B	ROOM 124	<1	<1	P				<1	<1	P	P	None
10	S/B	ROOM 112	<1	<1	P				<1	<1	P	P	None
11	S/B	SPEC ED 115	<1	<1	P				<1	<1	P	P	None
12	S	SPEC ED KITCHEN	<1	<1	P							P	None
13	S/B	SPEC ED 117	<1	<1	P				<1	<1	P	P	None
14	S	TEACHER'S LOUNGE 109	<1	<1	P				<1	<1	P	P	None
15	S/B	PSYH OFFICE 119A	<1	<1	P				<1	<1	P	P	None
16	S/B	OT/PT 119	<1	<1	P				<1	<1	P	P	None
17	S	DAYCARE KITCHEN	<1	<1	P				<1	<1	P	P	None
18	S	DAYCARE KITCHEN	<1	<1	P	<1	<1	P	<1	<1	P	P	None
19	S/B	ROOM 131, LEFT	<1	<1	P				<1	<1	P	P	None
20	S/B	ROOM 131, RIGHT	<1	<1	P				<1	<1	P	P	None
21	S/B	ROOM 133, LEFT	<1	<1	P				<1	<1	P	P	None
22	S/B	ROOM 133, RIGHT	<1	<1	P				<1	<1	P	P	None
23	S/B	ROOM 273	<1	<1	P				<1	<1	P	P	None
24	S/B	ROOM 274	<1	<1	P				<1	<1	P	P	None
25	S/B	ROOM 275	<1	<1	P				<1	<1	P	P	None
26	S/B	SOUTHWING 2ND FLOOR FLEX, OUTSIDE 275	<1	<1	P				<1	<1	P	P	None
27	S/B	ROOM 272	<1	<1	P				<1	<1	P	P	None
28	S	ROOM 277, LEFT	<1	<1	P				<1	<1	P	P	None
29	S	ROOM 277, RIGHT	<1	<1	P				<1	<1	P	P	None
30	S/B	ROOM 271	<1	<1	P				<1	<1	P	P	None
31	S	ROOM 279A	<1	<1	P				<1	<1	P	P	None
32	S	ART ROOM 287	1	<1	P				1	<1	P	P	None
33	S	ART ROOM 287	<1	<1	P				<1	<1	P	P	None
34	S	ART ROOM 287	<1	<1	P				<1	<1	P	P	None
35	S	ART ROOM 287	<1	<1	P				<1	<1	P	P	None
36	S/B	ROOM 281	<1	<1	P				<1	<1	P	P	None
37	S/B	ROOM 282	<1	<1	P				<1	<1	P	P	None
38	S/B	OPEN LEARNING 280	<1	<1	P				<1	<1	P	P	None
39	S/B	ROOM 285	<1	<1	P				<1	<1	P	P	None
40	S/B	ROOM 284	<1	<1	P				<1	<1	P	P	None
41	S/B	ROOM 283	<1	<1	P				<1	<1	P	P	None
42	S/B	ROOM 323	<1	<1	P				<1	<1	P	P	None
43	S/B	ROOM 324	<1	<1	P				1	<1	P	P	None
44	S/B	ROOM 325	<1	<1	P				<1	<1	P	P	None
45	S/B	3RD FLOOR FLEX OUTSIDE 325	<1	<1	P				<1	<1	P	P	None
46	S/B	ROOM 322	<1	<1	P				<1	<1	P	P	None
47	S/B	ROOM 321	<1	<1	P				<1	<1	P	P	None
48	S	ROOM 327	<1	<1	P				<1	<1	P	P	None

49	S	ROOM 327	<1	<1	P				<1	<1	P	P	None
50	S	ROOM 327	<1	<1	P				<1	<1	P	P	None
51	S	ROOM 327	<1	<1	P				<1	<1	P	P	None
52	S	329A	<1	<1	P				<1	<1	P	P	None
53	S	ART ROOM 337	<1	<1	P				<1	<1	P	P	None
54	S	ART ROOM 337	<1	<1	P				<1	<1	P	P	None
55	S	ART ROOM 337	3	<1	P	<1	<1	P	<1	<1	P	P	None
56	S	ART ROOM 337	1	<1	P				<1	<1	P	P	None
57	S/B	ROOM 331	<1	<1	P				<1	<1	P	P	None
58	S/B	ROOM 332	<1	<1	P				<1	<1	P	P	None
59	S/B	OPEN LEARNING 330	<1	<1	P				<1	<1	P	P	None
60	S/B	ROOM 335	<1	<1	P				<1	<1	P	P	None
61	S/B	ROOM 334	<1	<1	P				<1	<1	P	P	None
62	S/B	ROOM 333	<1	<1	P				<1	<1	P	P	None
63	S	LIBRARY OFFICE	<1	<1	P				<1	<1	P	P	None
64	B	NORTHWING 3RD FLOOR HALLWAY, LEFT	<1	<1	P				<1	<1	P	P	None
65	B	NORTHWING 3RD FLOOR HALLWAY, RIGHT	<1	<1	P				<1	<1	P	P	None
66	S	MAIN OFFICE	<1	<1	P				<1	<1	P	P	None
67	S/B	NURSE OFFICE 203	<1	<1	P				<1	<1	P	P	None
68	B	NORTHWING 2ND FLOOR HALLWAY, LEFT	<1	<1	P				<1	<1	P	P	None
69	B	NORTHWING 2ND FLOOR HALLWAY, RIGHT	<1	<1	P				<1	<1	P	P	None
70	S	KITCHEN, LEFT	<1	<1	P	<1	<1	P	<1	<1	P	P	None
71	S	KITCHEN, RIGHT	<1	<1	P				<1	<1	P	P	None
72	S	KITCHEN	<1	<1	P				<1	<1	P	P	None
73	B	HALLWAY OUTSIDE GYM, LEFT	<1	<1	P				<1	<1	P	P	None
74	B	HALLWAY OUTSIDE GYM, RIGHT	<1	<1	P				<1	<1	P	P	None
75	S/B	WORKROOM 241C	<1	<1	P				<1	<1	P	P	None
76	B	GYM, LEFT	<1	<1	P				<1	<1	P	P	None
77	B	GYM, RIGHT	<1	<1	P				<1	<1	P	P	None
78	S	ROOM 277							<1	<1	P	P	None
79	S	ROOM 277							<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			8/16/2016			9/20/2016			8/7/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	room 121	<1	<1	P				<1	<1	P	P	None
02	S/B	room 121	<1	<1	P				<1	<1	P	P	None
03	S/B	room 122	<1	<1	P				<1	<1	P	P	None
04	S/B	room 122	<1	<1	P				<1	<1	P	P	None
05	S/B	room 123	<1	<1	P				<1	<1	P	P	None
06	S/B	ROOM 123	<1	<1	P				<1	<1	P	P	None
07	S/B	KINDERGARTEN FLEX	<1	<1	P				<1	<1	P	P	None
08	S/B	ROOM 124	<1	<1	P				<1	<1	P	P	None
09	S/B	ROOM 124	<1	<1	P				<1	<1	P	P	None
10	S/B	ROOM 112	<1	<1	P				<1	<1	P	P	None
11	S/B	SPEC ED 115	<1	<1	P				<1	<1	P	P	None
12	S	SPEC ED KITCHEN	<1	<1	P							P	None
13	S/B	SPEC ED 117	<1	<1	P				<1	<1	P	P	None
14	S	TEACHER'S LOUNGE 109	<1	<1	P				<1	<1	P	P	None
15	S/B	PSYH OFFICE 119A	<1	<1	P				<1	<1	P	P	None
16	S/B	OT/PT 119	<1	<1	P				<1	<1	P	P	None
17	S	DAYCARE KITCHEN	<1	<1	P				<1	<1	P	P	None
18	S	DAYCARE KITCHEN	<1	<1	P	<1	<1	P	<1	<1	P	P	None
19	S/B	ROOM 131, LEFT	<1	<1	P				<1	<1	P	P	None
20	S/B	ROOM 131, RIGHT	<1	<1	P				<1	<1	P	P	None
21	S/B	ROOM 133, LEFT	<1	<1	P				<1	<1	P	P	None
22	S/B	ROOM 133, RIGHT	<1	<1	P				<1	<1	P	P	None
23	S/B	ROOM 273	<1	<1	P				<1	<1	P	P	None
24	S/B	ROOM 274	<1	<1	P				<1	<1	P	P	None
25	S/B	ROOM 275	<1	<1	P				<1	<1	P	P	None
26	S/B	SOUTHWING 2ND FLOOR FLEX, OUTSIDE 275	<1	<1	P				<1	<1	P	P	None
27	S/B	ROOM 272	<1	<1	P				<1	<1	P	P	None
28	S	ROOM 277, LEFT	<1	<1	P				<1	<1	P	P	None
29	S	ROOM 277, RIGHT	<1	<1	P				<1	<1	P	P	None
30	S/B	ROOM 271	<1	<1	P				<1	<1	P	P	None
31	S	ROOM 279A	<1	<1	P				<1	<1	P	P	None
32	S	ART ROOM 287	<1	<1	P				<1	<1	P	P	None
33	S	ART ROOM 287	<1	<1	P				<1	<1	P	P	None
34	S	ART ROOM 287	<1	<1	P				<1	<1	P	P	None
35	S	ART ROOM 287	<1	<1	P				<1	<1	P	P	None
36	S/B	ROOM 281	<1	<1	P				<1	<1	P	P	None
37	S/B	ROOM 282	<1	<1	P				<1	<1	P	P	None
38	S/B	OPEN LEARNING 280	<1	<1	P				<1	<1	P	P	None
39	S/B	ROOM 285	<1	<1	P				<1	<1	P	P	None
40	S/B	ROOM 284	<1	<1	P				<1	<1	P	P	None
41	S/B	ROOM 283	<1	<1	P				<1	<1	P	P	None
42	S/B	ROOM 323	<1	<1	P				<1	<1	P	P	None
43	S/B	ROOM 324	<1	<1	P				<1	<1	P	P	None
44	S/B	ROOM 325	<1	<1	P				<1	<1	P	P	None
45	S/B	3RD FLOOR FLEX OUTSIDE 325	<1	<1	P				<1	<1	P	P	None
46	S/B	ROOM 322	<1	<1	P				<1	<1	P	P	None
47	S/B	ROOM 321	<1	<1	P				<1	<1	P	P	None

48	S	ROOM 327	<1	<1	P				<1	<1	P	P	None
49	S	ROOM 327	<1	<1	P				<1	<1	P	P	None
50	S	ROOM 327	<1	<1	P				<1	<1	P	P	None
51	S	ROOM 327	<1	<1	P				<1	<1	P	P	None
52	S	329A	<1	<1	P				<1	<1	P	P	None
53	S	ART ROOM 337	<1	<1	P				<1	<1	P	P	None
54	S	ART ROOM 337	<1	<1	P				<1	<1	P	P	None
55	S	ART ROOM 337	<1	<1	P	<1	<1	P	<1	<1	P	P	None
56	S	ART ROOM 337	<1	<1	P				<1	<1	P	P	None
57	S/B	ROOM 331	<1	<1	P				<1	<1	P	P	None
58	S/B	ROOM 332	<1	<1	P				<1	<1	P	P	None
59	S/B	OPEN LEARNING 330	<1	<1	P				<1	<1	P	P	None
60	S/B	ROOM 335	<1	<1	P				<1	<1	P	P	None
61	S/B	ROOM 334	<1	<1	P				<1	<1	P	P	None
62	S/B	ROOM 333	<1	<1	P				<1	<1	P	P	None
63	S	LIBRARY OFFICE	<1	<1	P				<1	<1	P	P	None
64	B	NORTHWING 3RD FLOOR HALLWAY, LEFT	<1	<1	P				<1	<1	P	P	None
65	B	NORTHWING 3RD FLOOR HALLWAY, RIGHT	<1	<1	P				<1	<1	P	P	None
66	S	MAIN OFFICE	<1	<1	P				<1	<1	P	P	None
67	S/B	NURSE OFFICE 203	<1	<1	P				<1	<1	P	P	None
68	B	NORTHWING 2ND FLOOR HALLWAY, LEFT	<1	<1	P				<1	<1	P	P	None
69	B	NORTHWING 2ND FLOOR HALLWAY, RIGHT	<1	<1	P				<1	<1	P	P	None
70	S	KITCHEN, LEFT	<1	<1	P	<1	<1	P	<1	<1	P	P	None
71	S	KITCHEN, RIGHT	<1	<1	P				<1	<1	P	P	None
72	S	KITCHEN	<1	<1	P				<1	<1	P	P	None
73	B	HALLWAY OUTSIDE GYM, LEFT	<1	<1	P				<1	<1	P	P	None
74	B	HALLWAY OUTSIDE GYM, RIGHT	<1	<1	P				<1	<1	P	P	None
75	S/B	WORKROOM 241C	<1	<1	P				<1	<1	P	P	None
76	B	GYM, LEFT	<1	<1	P				<1	<1	P	P	None
77	B	GYM, RIGHT	<1	<1	P				<1	<1	P	P	None
78	S	ROOM 277							<1	<1	P	P	None
79	S	ROOM 277							<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			8/16/2016			9/20/2016			8/7/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S/B	room 121	0.265	0.22	P				0.263	0.258	P	P	None
02	S/B	room 121	0.254	0.195	P				0.282	0.312	P	P	None
03	S/B	room 122	0.209	0.179	P				0.254	0.291	P	P	None
04	S/B	room 122	0.206	0.166	P				0.376	0.375	P	P	None
05	S/B	room 123	0.19	0.197	P				0.189	0.215	P	P	None
06	S/B	ROOM 123	0.2	0.239	P				0.217	0.213	P	P	None
07	S/B	KINDERGARTEN FLEX	0.208	0.204	P				0.264	0.177	P	P	None
08	S/B	ROOM 124	0.249	0.114	P				0.352	0.247	P	P	None
09	S/B	ROOM 124	0.196	0.172	P				0.299	0.299	P	P	None
10	S/B	ROOM 112	0.292	0.202	P				0.298	0.315	P	P	None
11	S/B	SPEC ED 115	0.165	0.217	P				0.276	0.187	P	P	None
12	S	SPEC ED KITCHEN	0.1	0.205	P							P	None
13	S/B	SPEC ED 117	0.22	0.185	P				0.19	0.256	P	P	None
14	S	TEACHER'S LOUNGE 109	0.197	0.19	P				0.233	0.102	P	P	None
15	S/B	PSYH OFFICE 119A	0.202	0.19	P				0.249	0.158	P	P	None
16	S/B	OT/PT 119	0.224	0.19	P				0.269	0.281	P	P	None
17	S	DAYCARE KITCHEN	0.18	0.133	P				0.308	0.101	P	P	None
18	S	DAYCARE KITCHEN	2.08	0.153		0.167	0.091	P	0.233	0.078	P	P	None
19	S/B	ROOM 131, LEFT	0.174	0.183	P				0.294	0.229	P	P	None
20	S/B	ROOM 131, RIGHT	0.17	0.16	P				0.223	0.265	P	P	None
21	S/B	ROOM 133, LEFT	0.181	0.218	P				0.232	0.254	P	P	None
22	S/B	ROOM 133, RIGHT	0.17	0.202	P				0.252	0.231	P	P	None
23	S/B	ROOM 273	0.204	0.186	P				0.253	0.319	P	P	None
24	S/B	ROOM 274	0.22	0.18	P				0.347	0.249	P	P	None
25	S/B	ROOM 275	0.193	0.208	P				0.278	0.257	P	P	None
26	S/B	SOUTHWING 2ND FLOOR FLEX, OUTSIDE 275	0.199	0.203	P				0.501	0.335	P	P	None
27	S/B	ROOM 272	0.141	0.139	P				0.29	0.395	P	P	None
28	S	ROOM 277, LEFT	0.136	0.202	P				0.294	0.145	P	P	None
29	S	ROOM 277, RIGHT	0.252	0.141	P				0.204	0.081	P	P	None
30	S/B	ROOM 271	0.184	0.149	P				0.226	0.155	P	P	None
31	S	ROOM 279A	0.143	0.214	P				0.207	0.099	P	P	None
32	S	ART ROOM 287	0.17	0.178	P				0.191	0.113	P	P	None
33	S	ART ROOM 287	0.066	0.207	P				0.145	0.152	P	P	None
34	S	ART ROOM 287	0.083	0.205	P				0.145	0.204	P	P	None
35	S	ART ROOM 287	0.086	0.205	P				0.155	0.084	P	P	None
36	S/B	ROOM 281	0.26	0.205	P				0.262	0.191	P	P	None
37	S/B	ROOM 282	0.191	0.21	P				0.27	0.246	P	P	None
38	S/B	OPEN LEARNING 280	0.264	0.209	P				0.254	0.297	P	P	None
39	S/B	ROOM 285	0.187	0.245	P				0.27	0.263	P	P	None
40	S/B	ROOM 284	0.197	0.271	P				0.285	0.261	P	P	None
41	S/B	ROOM 283	0.214	0.215	P				0.283	0.325	P	P	None
42	S/B	ROOM 323	0.211	0.221	P				0.327	0.384	P	P	None
43	S/B	ROOM 324	0.179	0.184	P				0.261	0.275	P	P	None
44	S/B	ROOM 325	0.164	0.183	P				0.238	0.25	P	P	None
45	S/B	3RD FLOOR FLEX OUTSIDE 325	0.261	0.188	P				0.315	0.242	P	P	None
46	S/B	ROOM 322	0.21	0.173	P				0.27	0.248	P	P	None
47	S/B	ROOM 321	0.259	0.156	P				0.382	0.206	P	P	None

48	S	ROOM 327	0.142	0.18	P				0.297	0.272	P	P	None
49	S	ROOM 327	0.159	0.158	P				0.385	0.075	P	P	None
50	S	ROOM 327	0.165	0.188	P				0.268	0.134	P	P	None
51	S	ROOM 327	0.171	0.208	P				0.252	0.147	P	P	None
52	S	329A	0.152	0.192	P				0.349	0.094	P	P	None
53	S	ART ROOM 337	0.196	0.165	P				0.222	0.121	P	P	None
54	S	ART ROOM 337	0.132	0.219	P				0.304	0.166	P	P	None
55	S	ART ROOM 337	4.33	0.256		0.17	0.16	P	0.221	0.19	P	P	None
56	S	ART ROOM 337	0.951	0.208	P				0.17	0.261	P	P	None
57	S/B	ROOM 331	0.311	0.176	P				0.345	0.226	P	P	None
58	S/B	ROOM 332	0.245	0.193	P				0.355	0.217	P	P	None
59	S/B	OPEN LEARNING 330	0.214	0.246	P				0.226	0.29	P	P	None
60	S/B	ROOM 335	0.203	0.214	P				0.321	0.287	P	P	None
61	S/B	ROOM 334	0.233	0.231	P				0.296	0.386	P	P	None
62	S/B	ROOM 333	0.209	0.207	P				0.46	0.335	P	P	None
63	S	LIBRARY OFFICE	0.138	0.252	P				0.046	0.179	P	P	None
64	B	NORTHWING 3RD FLOOR HALLWAY, LEFT	0.236	0.191	P				0.275	0.166	P	P	None
65	B	NORTHWING 3RD FLOOR HALLWAY, RIGHT	0.237	0.198	P				0.165	0.204	P	P	None
66	S	MAIN OFFICE	0.215	0.193	P				0.207	0.116	P	P	None
67	S/B	NURSE OFFICE 203	0.23	0.218	P				0.263	0.2	P	P	None
68	B	NORTHWING 2ND FLOOR HALLWAY, LEFT	0.758	0.189	P				0.515	0.158	P	P	None
69	B	NORTHWING 2ND FLOOR HALLWAY, RIGHT	0.319	0.186	P				0.351	0.217	P	P	None
70	S	KITCHEN, LEFT	7.56	0.289		0.137	0.146	P	0.514	0.073	P	P	None
71	S	KITCHEN, RIGHT	0.283	0.449	P				0.16	0.086	P	P	None
72	S	KITCHEN	1.23	0.166	P				0.18	0.054	P	P	None
73	B	HALLWAY OUTSIDE GYM, LEFT	1.02	0.258	P				0.123	0.092	P	P	None
74	B	HALLWAY OUTSIDE GYM, RIGHT	0.289	0.21	P				0.153	0.072	P	P	None
75	S/B	WORKROOM 241C	0.351	0.221	P				0.068	0.086	P	P	None
76	B	GYM, LEFT	0.317	0.353	P				0.124	0.101	P	P	None
77	B	GYM, RIGHT	0.255	0.331	P				0.14	0.129	P	P	None
78	S	ROOM 277							0.269	0.067	P	P	None
79	S	ROOM 277							0.276	0.064	P	P	None

Table 5. Iron Test Results

Test Results (Iron/Fe, ppm)								
FIXTURE INFORMATION			8/16/2016		8/7/2020		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	S/B	room 121						Sample
02	S/B	room 121						Sample
03	S/B	room 122						Sample
04	S/B	room 122						Sample
05	S/B	room 123	0.069	P			P	None
06	S/B	ROOM 123						Sample
07	S/B	KINDERGARTEN FLEX			<0.05	P	P	None
08	S/B	ROOM 124						Sample
09	S/B	ROOM 124						Sample
10	S/B	ROOM 112	<0.05	P			P	None
11	S/B	SPEC ED 115						Sample
12	S	SPEC ED KITCHEN						Sample
13	S/B	SPEC ED 117						Sample
14	S	TEACHER'S LOUNGE 109						Sample
15	S/B	PSYH OFFICE 119A	<0.05	P			P	None
16	S/B	OT/PT 119			<0.05	P	P	None
17	S	DAYCARE KITCHEN						Sample
18	S	DAYCARE KITCHEN						Sample
19	S/B	ROOM 131, LEFT						Sample
20	S/B	ROOM 131, RIGHT	<0.05	P			P	None
24	S/B	ROOM 274			<0.05	P	P	None
25	S/B	ROOM 275	<0.05	P			P	None
30	S/B	ROOM 271	0.153	P			P	None
32	S	ART ROOM 287			<0.05	P	P	None
35	S	ART ROOM 287	<0.05	P			P	None
40	S/B	ROOM 284	<0.05	P			P	None
42	S/B	ROOM 323			<0.05	P	P	None
45	S/B	3RD FLOOR FLEX OUTSIDE 325	<0.05	P			P	None
49	S	ROOM 327			<0.05	P	P	None
50	S	ROOM 327	<0.05	P			P	None
57	S/B	ROOM 331	0.156	P			P	None
60	S/B	ROOM 335			<0.05	P	P	None
65	B	NORTHWING 3RD FLOOR HALLWAY, RIGHT	<0.05	P			P	None
67	S/B	NURSE OFFICE 203			<0.05	P	P	None
70	S	KITCHEN, LEFT	<0.05	P			P	None
74	B	HALLWAY OUTSIDE GYM, RIGHT			0.069	P	P	None
75	S/B	WORKROOM 241C	0.061	P			P	None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	Boiler room	Arsenic	07-Aug-20	2 ppb	P
00	SE	Boiler room	Cadmium	07-Aug-20	1 ppb	P
00	SE	Boiler room	Copper	07-Aug-20	0.075 ppm	P
00	SE	Boiler room	Iron	07-Aug-20	0.078 ppm	P
00	SE	Boiler room	Lead	07-Aug-20	1 ppb	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.