

**Seattle Public Schools  
Drinking Water Quality Program**

**Results of Water Quality Testing  
for  
Beacon Hill Elementary**

Updated September 3, 2019

**General Information:**

Plumbing piping materials: mainly copper

**Remediation plan:**

*This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.*

Status:

Health Criteria: This school has one sources that do not meet the policy criteria. Signs will be posted at:), Rm242, librarian office (#48),

Follow-up monitoring: Will be performed in school year 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

**Water Quality Testing Results:**

<b>Legend</b>	
<b>Symbol</b>	<b>Definition</b>
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	Main entry	P	None	P	None	P	None	P	None	Yes
02	B	Adult men's lav	P	None	P	None	P	None	P	None	Yes
03	B/S	K2	P	None	P	None	P	None	P	None	Yes
04	B/S	LAVK1, left	P	None	P	None	P	None	P	None	Yes
05	B/S	LAV/K1, right	P	None	P	None	P	None	P	None	Yes
06	B/S	K3	P	None	P	None	P	None	P	None	Yes
07	B/S	A2	P	None	P	None	P	None	P	None	Yes
08	B/S	A3/B	P	None	P	None	P	None	P	None	Yes
09	B/S	A3/B	P	None	P	None	P	None	P	None	Yes
10	S/B	B2	P	None	P	None	P	None	P	None	Yes
11A	B/S	bottle filler	P	None	P	None	P	None	P	None	Yes
11B	B/S	GYM, right	P	None	P	None	P	None	P	None	Yes
12	B/S	D2	P	None	P	None	P	None	P	None	Yes
13	B/S	C3/D3	P	None	P	None	P	None	P	None	Yes
14	B/S	C3/D3	P	None	P	None	P	None	P	None	Yes
15	B/S	C1/C2	P	None	P	None	P	None	P	None	Yes
22	S	Nurses office	P	None	P	None	P	None	P	None	Yes
23	S	Volunteer room	P	None	P	None	P	None	P	None	PS
28	S	Kitchen-west wall (left sink)	P	None	P	None	P	None	P	None	Yes
29	S	Kitchen-west wall (right sink)	P	None	P	None	P	None	P	None	Yes
31	S/B	Rm 112B-north, right	P	None	P	None	P	None	P	None	Yes
32	S	Rm 112B-middle	P	None	P	None	P	None			Yes
33	S	Rm 112B-south, left	P	None	P	None	P	None			Yes
34	S/B	Rm 112A, multipurpose room A	P	None	P	None	P	None	P	None	Yes
36	S/B	Rm 125	P	None	P	None	P	None			Yes
37	S/B	Rm 217	P	None	P	None	P	None			Yes
38	S/B	Rm 130	P	None	P	None	P	None			Yes
39	B	Hall	P	None	P	None	P	None	P	None	Yes
40	B	Hall	P	None	P	None	P	None	P	None	Yes
41	S/B	Rm 132	P	None	P	None	P	None	P	None	Yes
42	S/B	Rm 131, resource	P	None	P	None	P	None	P	None	Yes
43	S	Staff lounge (Rm 135)	P	None	P	None	P	None	P	None	Yes
45	S	Kitchen - Food prep/vegetable wash sink	P	None	P	None	P	None	P	None	Yes
46	S	Rm 215 - Teacher workroom, D pod	P	None	P	None	P	None	P	None	Yes
47	S	Rm 250 - Teacher workroom, K pod	P	None	P	None	P	None	P	None	Yes
48	S	Rm 242 - Librarian office	F	PS	P	None	P	None	P	None	PS
49	S	Rm 241 - Teacher workroom, c-pod	P	None	P	None	P	None	P	None	Yes
50	S	Rm 243A - School psychologist, AV room	P	None	P	None	P	None	P	None	Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			12/20/2011			8/14/2014			10/28/2016			8/9/2017			8/29/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	Main entry	<1	<1	P	1	<1	P				<1	<1	P				P	None
02	B	Adult men's lav	<1	<1	P	<1	<1	P				<1	<1	P				P	None
03	B/S	K2	2	<1	P	3	1	P				3	<1	P				P	None
04	B/S	LAVK1, left	<1	<1	P	<1	<1	P				<1	<1	P				P	None
05	B/S	LAV/K1, right	<1	<1	P	<1	<1	P				<1	<1	P				P	None
06	B/S	K3		1	P	8	3	P				<1	<1	P				P	None
07	B/S	A2	5	2	P	8	2	P				<1	2	P				P	None
08	B/S	A3/B	<1	<1	P	<1	<1	P				<1	<1	P				P	None
09	B/S	A3/B	<1	<1	P	<1	<1	P				<1	<1	P				P	None
10	S/B	B2	22	4		9	6	P	5	1	P	7	2	P				P	None
11A	B/S	bottle filler	3	<1	P	3	<1	P	2	<1	P							P	None
11B	B/S	GYM, right	<1	<1	P	<1	<1	P										P	None
12	B/S	D2	2	<1	P	1	<1	P				<1	<1	P				P	None
13	B/S	C3/D3	<1	<1	P	<1	<1	P				<1	<1	P				P	None
14	B/S	C3/D3	8	2	P	4	<1	P				2	<1	P				P	None
15	B/S	C1/C2	3	<1	P	4	2	P				4	2	P				P	None
22	S	Nurses office	<1	<1	P	<1	<1	P				<1	<1	P				P	None
23	S	Volunteer room	13	1		25	3					21	4		8	2	P	P	None
28	S	Kitchen-west wall (left sink)	3	<1	P	<1	2	P				2	2	P				P	None
29	S	Kitchen-west wall (right sink)	1	1	P	2	<1	P				<1	1	P				P	None
31	S/B	Rm 112B-north, right	2	<1	P	2	<1	P				2	<1	P				P	None
32	S	Rm 112B-middle	2	<1	P	5	<1	P				3	<1	P				P	None
33	S	Rm 112B-south, left	4	<1	P	1	<1	P				2	<1	P				P	None
34	S/B	Rm 112A, multipurpose room A	2	<1	P	1	<1	P				1	<1	P				P	None
36	S/B	Rm 125	<1	<1	P	6	1	P				2	<1	P				P	None
37	S/B	Rm 217	2	<1	P	9	3	P				4	<1	P				P	None
38	S/B	Rm 130	1	<1	P	3	<1	P				3	<1	P				P	None
39	B	Hall	<1	<1	P	<1	<1	P				<1	<1	P				P	None
40	B	Hall	<1	<1	P	<1	<1	P				<1	<1	P				P	None
41	S/B	Rm 132	2	<1	P	3	<1	P				2	<1	P				P	None
42	S/B	Rm 131, resource	4	2	P	5	1	P				5	1	P				P	None
43	S	Staff lounge (Rm 135)	1	<1	P	1	<1	P										P	None
45	S	Kitchen - Food prep/vegetable wash sink	3	<1	P	9	3	P				2	<1	P				P	None
46	S	Rm 215 - Teacher workroom, D pod	25	7		9	7	P				4	2	P				P	None
47	S	Rm 250 - Teacher workroom, K pod	24	2		5	1	P				10	<1	P				P	None
48	S	Rm 242 - Librarian office	15	2		11	3					13	3		15	4		F	PS
49	S	Rm 241 - Teacher workroom, c-pod	22	1		10	1	P				9	1	P				P	None
50	S	Rm 243A - School psychologist, AV room	34	3		36	3					8	5	P				P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4				
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	
01	B	Main entry					7/8/2005	<1	<1	P													
02	B	Adult men's lav					7/8/2005	<1	<1	P													
03	B/S	K2					7/8/2005	<1	<1	P													
04	B/S	LAVK1, left	4/15/2004	<1	<1	P	7/8/2005	<1	<1	P													
05	B/S	LAV/K1, right					7/8/2005	<1	<1	P													
06	B/S	K3					7/8/2005	<1	<1	P													
07	B/S	A2					7/8/2005	<1	<1	P													
08	B/S	A3/B	4/15/2004	<1	<1	P																	
09	B/S	A3/B					7/8/2005	<1	<1	P													
10	S/B	B2					7/8/2005	<1	<1	P													
11A	B/S	bottle filler	4/15/2004	<1	<1	P																	
11B	B/S	GYM, right																					
12	B/S	D2					7/8/2005	<1	<1	P													
13	B/S	C3/D3					7/8/2005	<1	<1	P													
14	B/S	C3/D3					7/8/2005	<1	<1	P													
15	B/S	C1/C2					7/8/2005	<1	<1	P													
22	S	Nurses office	4/15/2004	<1	<1	P	7/8/2005	<1	<1	P													
23	S	Volunteer room	4/15/2004		<1	P	7/8/2005	<1	<1	P													
28	S	Kitchen-west wall (left sink)									5/25/2006	<1	<1	P									
29	S	Kitchen-west wall (right sink)									5/25/2006	<1	<1	P									
31	S/B	Rm 112B-north, right													6/1/2006	3	<1	P					
32	S	Rm 112B-middle													6/1/2006	<1	<1	P					
33	S	Rm 112B-south, left													6/1/2006	<1	<1	P					
34	S/B	Rm 112A, multipurpose room A													6/1/2006	<1	<1	P					
36	S/B	Rm 125													6/1/2006	<1	<1	P					
37	S/B	Rm 217													6/1/2006	<1	<1	P					
38	S/B	Rm 130													6/1/2006	<1	<1	P					
39	B	Hall													6/1/2006	<1	<1	P					
40	B	Hall													6/1/2006	<1	<1	P					
41	S/B	Rm 132													6/1/2006	<1	<1	P					
42	S/B	Rm 131, resource													6/1/2006	<1	<1	P					
43	S	Staff lounge (Rm 135)													6/1/2006	<1	<1	P					
45	S	Kitchen - Food prep/vegetable wash sink																		3/7/2007	<1	<1	P
46	S	Rm 215 - Teacher workroom, D pod																		3/7/2007	<1	<1	P
47	S	Rm 250 - Teacher workroom, K pod																		3/7/2007	<1	<1	P
48	S	Rm 242 - Librarian office																		3/7/2007	<1	<1	P
49	S	Rm 241 - Teacher workroom, c-pod																		3/7/2007	<1	<1	P
50	S	Rm 243A - School psychologist, AV room																		3/7/2007	3	<1	P

Table 3. Cadmium Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Follow-up Sampling 8				Follow-up Sampling 9				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
01	B	Main entry	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
02	B	Adult men's lav	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
03	B/S	K2	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
04	B/S	LAVK1, left	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
05	B/S	LAV/K1, right	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
06	B/S	K3	10/3/2008	<1	<1	P	12/20/2011		<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
07	B/S	A2	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
08	B/S	A3/B	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
09	B/S	A3/B	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
10	S/B	B2	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P	10/28/2016	<1	<1	P	8/9/2017	<1	<1	P	P	None
11A	B/S	bottle filler	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P	10/28/2016	<1	<1	P					P	None
11B	B/S	GYM, right	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P									P	None
12	B/S	D2	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
13	B/S	C3/D3	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
14	B/S	C3/D3	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
15	B/S	C1/C2	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
22	S	Nurses office	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	1	<1	P					8/9/2017	<1	<1	P	P	None
23	S	Volunteer room	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
28	S	Kitchen-west wall (left sink)	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
29	S	Kitchen-west wall (right sink)	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
31	S/B	Rm 112B-north, right	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
32	S	Rm 112B-middle	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
33	S	Rm 112B-south, left	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
34	S/B	Rm 112A, multipurpose room A	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
36	S/B	Rm 125	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
37	S/B	Rm 217	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
38	S/B	Rm 130	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
39	B	Hall	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
40	B	Hall	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
41	S/B	Rm 132	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
42	S/B	Rm 131, resource	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
43	S	Staff lounge (Rm 135)	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P									P	None
45	S	Kitchen - Food prep/vegetable wash sink	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
46	S	Rm 215 - Teacher workroom, D pod	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
47	S	Rm 250 - Teacher workroom, K pod	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
48	S	Rm 242 - Librarian office	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
49	S	Rm 241 - Teacher workroom, c-pod	10/3/2008	1	<1	P	12/20/2011	<1	<1	P	8/14/2014	<1	<1	P					8/9/2017	<1	<1	P	P	None
50	S	Rm 243A - School psychologist, AV room	10/3/2008	<1	<1	P	12/20/2011	<1	<1	P	8/14/2014	7	<1						8/9/2017	<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3				Follow-up Sampling 4				
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	Sampled	1st Draw	Flush 30s	Pass/Fail	
01	B	Main entry					7/8/2005	0.27	0.15	P													
02	B	Adult men's lav					7/8/2005	0.013	0.025	P													
03	B/S	K2					7/8/2005	0.13	0.08	P													
04	B/S	LAVK1, left	4/15/2004	0.1	0.019	P	7/8/2005	0.1	0.043	P													
05	B/S	LAV/K1, right					7/8/2005	0.23	0.11	P													
06	B/S	K3					7/8/2005	0.35	0.37	P													
07	B/S	A2					7/8/2005	0.85	0.25	P													
08	B/S	A3/B	4/15/2004	0.67	0.027	P					8/22/2005		0.32	P									
09	B/S	A3/B					7/8/2005	0.036	0.019	P													
10	S/B	B2					7/8/2005	1.3	0.52	P													
11A	B/S	bottle filler	4/15/2004	0.16	0.015	P	7/8/2005		0.092	P													
11B	B/S	GYM, right																					
12	B/S	D2					7/8/2005	0.13	0.12	P													
13	B/S	C3/D3					7/8/2005	0.007	0.023	P													
14	B/S	C3/D3					7/8/2005	0.16	0.12	P													
15	B/S	C1/C2					7/8/2005	0.14	0.12	P													
22	S	Nurses office	4/15/2004	0.24		P	7/8/2005	0.035	0.045	P													
23	S	Volunteer room					7/8/2005	0.37	0.09	P													
28	S	Kitchen-west wall (left sink)																	3/7/2007	0.287	0.398	P	
29	S	Kitchen-west wall (right sink)																	3/7/2007	0.248	0.386	P	
31	S/B	Rm 112B-north, right													6/1/2006		0.367	P					
32	S	Rm 112B-middle													6/1/2006	0.34	0.275	P					
33	S	Rm 112B-south, left													6/1/2006	0.416	0.323	P					
34	S/B	Rm 112A, multipurpose room A													6/1/2006	0.59	0.455	P					
36	S/B	Rm 125													6/1/2006	0.335	0.338	P					
37	S/B	Rm 217													6/1/2006	0.348	0.354	P					
38	S/B	Rm 130													6/1/2006	0.381	0.4	P					
39	B	Hall													6/1/2006	0.426	0.315	P					
40	B	Hall													6/1/2006	0.417	0.313	P					
41	S/B	Rm 132													6/1/2006	0.424	0.55	P					
42	S/B	Rm 131, resource													6/1/2006	0.348		P					
43	S	Staff lounge (Rm 135)																	3/7/2007	0.39	0.304	P	
45	S	Kitchen - Food prep/vegetable wash sink																	3/7/2007	0.262	0.424	P	
46	S	Rm 215 - Teacher workroom, D pod																	3/7/2007	0.229	0.338	P	
47	S	Rm 250 - Teacher workroom, K pod																	3/7/2007	0.244	0.099	P	
48	S	Rm 242 - Librarian office																	3/7/2007	0.342	0.328	P	
49	S	Rm 241 - Teacher workroom, c-pod																	3/7/2007	0.154	0.141	P	
50	S	Rm 243A - School psychologist, AV room																	3/7/2007	0.257	0.443	P	



Table 4. Copper Test Results (Continued)

FIXTURE INFORMATION			Follow-up Sampling 5				Follow-up Sampling 6				Follow-up Sampling 7				Follow-up Sampling 8				Follow-up Sampling 9				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Sampled	1st Draw	Flush 30s	Pass /Fail	Pass /Fail	Status
01	B	Main entry	10/3/2008	0.177	0.063	P	12/20/2011	0.137	0.11	P	8/14/2014	0.172	0.132	P					8/9/2017	0.123	0.111	P	P	None
02	B	Adult men's lav	10/3/2008	0.002	<0.002	P	12/20/2011	<0.002	<0.002	P	8/14/2014	0.005	<0.002	P					8/9/2017	0.013	0.005	P	P	None
03	B/S	K2	10/3/2008	0.098	0.062	P	12/20/2011	0.113	0.087	P	8/14/2014	0.082	0.127	P					8/9/2017	0.086	0.076	P	P	None
04	B/S	LAVK1, left	10/3/2008	0.003	0.003	P	12/20/2011	0.002	<0.002	P	8/14/2014	0.002	<0.002	P					8/9/2017	0.004	<0.002	P	P	None
05	B/S	LAV/K1, right	10/3/2008	0.005	0.004	P	12/20/2011	0.003	<0.002	P	8/14/2014	0.006	<0.002	P					8/9/2017	<0.002	<0.002	P	P	None
06	B/S	K3	10/3/2008	0.266	0.119	P	12/20/2011		0.159	P	8/14/2014	0.227	0.209	P					8/9/2017	0.011	<0.002	P	P	None
07	B/S	A2	10/3/2008	0.176	0.144	P	12/20/2011	0.166	0.053	P	8/14/2014	0.186	0.163	P					8/9/2017	0.134	0.135	P	P	None
08	B/S	A3/B	10/3/2008	0.269	0.245	P	12/20/2011	0.328	0.335	P	8/14/2014	0.238	0.281	P					8/9/2017	0.208	0.237	P	P	None
09	B/S	A3/B	10/3/2008	0.002	0.003	P	12/20/2011	0.004	<0.002	P	8/14/2014	0.003	<0.002	P					8/9/2017	0.213	0.237	P	P	None
10	S/B	B2	10/3/2008	0.243	0.283	P	12/20/2011	0.231	0.267	P	8/14/2014	0.23	0.193	P	10/28/2016	0.127	0.125	P	8/9/2017	0.169	0.186	P	P	None
11A	B/S	bottle filler	10/3/2008	0.066	0.055	P	12/20/2011	0.071	0.08	P	8/14/2014	0.064	0.062	P	10/28/2016	0.049	0.044	P					P	None
11B	B/S	GYM, right	10/3/2008	<0.002	<0.002	P	12/20/2011	<0.002	<0.002	P	8/14/2014	<0.002	<0.002	P									P	None
12	B/S	D2	10/3/2008	0.104	0.07	P	12/20/2011	0.138	0.124	P	8/14/2014	0.093	0.08	P					8/9/2017	0.069	0.067	P	P	None
13	B/S	C3/D3	10/3/2008	0.004	0.004	P	12/20/2011	<0.002	<0.002	P	8/14/2014	<0.002	<0.002	P					8/9/2017	0.003	<0.002	P	P	None
14	B/S	C3/D3	10/3/2008	0.094	0.082	P	12/20/2011	0.152	0.14	P	8/14/2014	0.078	0.088	P					8/9/2017	0.061	0.067	P	P	None
15	B/S	C1/C2	10/3/2008	0.107	0.096	P	12/20/2011	0.125	0.115	P	8/14/2014	0.085	0.085	P					8/9/2017	0.103	0.091	P	P	None
22	S	Nurses office	10/3/2008	0.025	0.005	P	12/20/2011	0.012	0.003	P	8/14/2014	0.032	0.003	P					8/9/2017	<0.002	0.002	P	P	None
23	S	Volunteer room	10/3/2008	0.285	0.058	P	12/20/2011	0.26	0.079	P	8/14/2014	0.294	0.1	P					8/9/2017	0.277	0.108	P	P	None
28	S	Kitchen-west wall (left sink)	10/3/2008	0.215	0.216	P	12/20/2011	0.31	0.255	P	8/14/2014	0.308	0.355	P					8/9/2017	0.275	0.216	P	P	None
29	S	Kitchen-west wall (right sink)	10/3/2008	0.186	0.186	P	12/20/2011	0.396	0.26	P	8/14/2014	0.356	0.326	P					8/9/2017	0.265	0.16	P	P	None
31	S/B	Rm 112B-north, right	10/3/2008	0.249	0.286	P	12/20/2011	0.266	0.286	P	8/14/2014	0.272	0.318	P					8/9/2017	0.213	0.244	P	P	None
32	S	Rm 112B-middle	10/3/2008	0.21	0.201	P	12/20/2011	0.352	0.231	P	8/14/2014	0.3	0.337	P					8/9/2017	0.247	0.229	P	P	None
33	S	Rm 112B-south, left	10/3/2008	0.202	0.199	P	12/20/2011	0.311	0.27	P	8/14/2014	0.35	0.313	P					8/9/2017	0.257	0.218	P	P	None
34	S/B	Rm 112A, multipurpose room A	10/3/2008	0.287	0.29	P	12/20/2011	0.377	0.407	P	8/14/2014	0.298	0.311	P					8/9/2017	0.303	0.314	P	P	None
36	S/B	Rm 125	10/3/2008	0.238	0.254	P	12/20/2011	0.3	0.42	P	8/14/2014	0.269	0.468	P					8/9/2017	0.306	0.486	P	P	None
37	S/B	Rm 217	10/3/2008	0.262	0.293	P	12/20/2011	0.304	0.337	P	8/14/2014	0.312	0.335	P					8/9/2017	0.249	0.268	P	P	None
38	S/B	Rm 130	10/3/2008	0.269	0.246	P	12/20/2011	0.275	0.271	P	8/14/2014	0.273	0.321	P					8/9/2017	0.229	0.249	P	P	None
39	B	Hall	10/3/2008	0.342	0.226	P	12/20/2011	0.052	0.052	P	8/14/2014	0.249	0.244	P					8/9/2017	0.248	0.26	P	P	None
40	B	Hall	10/3/2008	0.428	0.239	P	12/20/2011	0.05	0.051	P	8/14/2014	0.294	0.26	P					8/9/2017	0.238	0.237	P	P	None
41	S/B	Rm 132	10/3/2008	0.299	0.293	P	12/20/2011	0.221	0.244	P	8/14/2014	0.424	0.491	P					8/9/2017	0.48	0.552	P	P	None
42	S/B	Rm 131, resource	10/3/2008	0.294	0.224	P	12/20/2011	0.361	0.461	P	8/14/2014	0.354	0.359	P					8/9/2017	0.322	0.331	P	P	None
43	S	Staff lounge (Rm 135)	10/3/2008	0.192	0.185	P	12/20/2011	0.335	0.28	P	8/14/2014	0.236	0.174	P									P	None
45	S	Kitchen - Food prep /vegetable wash sink	10/3/2008	0.286	0.06	P	12/20/2011	0.361	0.074	P	8/14/2014	0.326	0.307	P					8/9/2017	0.27	0.285	P	P	None
46	S	Rm 215 - Teacher workroom, D pod	10/3/2008	0.126	0.142	P	12/20/2011	0.203	0.251	P	8/14/2014	0.289	0.314	P					8/9/2017	0.164	0.078	P	P	None
47	S	Rm 250 - Teacher workroom, K pod	10/3/2008	0.256	0.092	P	12/20/2011	0.243	0.112	P	8/14/2014	0.403	0.135	P					8/9/2017	0.184	0.081	P	P	None
48	S	Rm 242 - Librarian office	10/3/2008	0.408	0.521	P	12/20/2011	0.502	0.521	P	8/14/2014	0.398	0.22	P					8/9/2017	0.293	0.4	P	P	None
49	S	Rm 241 - Teacher workroom, c-pod	10/3/2008	0.141	0.09	P	12/20/2011	0.166	0.109	P	8/14/2014	0.163	0.11	P					8/9/2017	0.143	0.104	P	P	None
50	S	Rm 243A - School psychologist, AV room	10/3/2008	0.436	0.329	P	12/20/2011	0.406	0.327	P	8/14/2014	0.278	0.46	P					8/9/2017	0.37	0.388	P	P	None



Table 5. Iron Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2				Follow-up Sampling 3			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail
01	B	Main entry					7/8/2005		0.07	P								
02	B	Adult men's lav					7/8/2005		<0.05	P								
03	B/S	K2					7/8/2005		0.09	P								
04	B/S	LAVK1, left	4/15/2004	0.08	0.07	P	7/8/2005		0.08	P								
05	B/S	LAV/K1, right					7/8/2005		0.07	P								
06	B/S	K3					7/8/2005		0.11	P								
07	B/S	A2					7/8/2005		<0.05	P								
08	B/S	A3/B	4/15/2004	0.18	0.06	P	7/8/2005		<0.05	P								
09	B/S	A3/B					7/8/2005		<0.05	P								
10	S/B	B2					7/8/2005		<0.05	P								
11A	B/S	bottle filler	4/15/2004	0.06	0.06	P	7/8/2005		<0.05	P					10/3/2008		<0.05	P
11B	B/S	GYM, right																
12	B/S	D2					7/8/2005		0.14	P								
13	B/S	C3/D3					7/8/2005		<0.05	P								
14	B/S	C3/D3					7/8/2005		0.07	P					10/3/2008		<0.05	P
15	B/S	C1/C2					7/8/2005		0.05	P								
22	S	Nurses office	4/15/2004	<0.05		P	7/8/2005		<0.05	P					10/3/2008		<0.05	P
23	S	Volunteer room					7/8/2005		0.1	P								
28	S	Kitchen-west wall (left sink)													10/3/2008		<0.05	P
29	S	Kitchen-west wall (right sink)																
31	S/B	Rm 112B-north, right																
32	S	Rm 112B-middle																
33	S	Rm 112B-south, left																
34	S/B	Rm 112A, multipurpose room A																
36	S/B	Rm 125																
37	S/B	Rm 217																
38	S/B	Rm 130																
39	B	Hall													10/3/2008		<0.05	P
40	B	Hall																
41	S/B	Rm 132													10/3/2008		<0.05	P
42	S/B	Rm 131, resource																
43	S	Staff lounge (Rm 135)																
45	S	Kitchen - Food prep/vegetable wash sink									3/7/2007		0.075	P				
46	S	Rm 215 - Teacher workroom, D pod									3/7/2007		0.071	P				
47	S	Rm 250 - Teacher workroom, K pod									3/7/2007		0.067	P				
48	S	Rm 242 - Librarian office									3/7/2007		0.073	P				
49	S	Rm 241 - Teacher workroom, c-pod									3/7/2007		0.073	P				
50	S	Rm 243A - School psychologist, AV room									3/7/2007		0.07	P				

Table 5. Iron Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 4				Follow-up Sampling 5				Follow-up Sampling 6				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B	Main entry													P	None
02	B	Adult men's lav									8/9/2017		<0.05	P	P	None
03	B/S	K2													P	None
04	B/S	LAVK1, left													P	None
05	B/S	LAV/K1, right													P	None
06	B/S	K3													P	None
07	B/S	A2													P	None
08	B/S	A3/B													P	None
09	B/S	A3/B													P	None
10	S/B	B2													P	None
11A	B/S	bottle filler													P	None
11B	B/S	GYM, right	12/20/2011		<0.05	P									P	None
12	B/S	D2					8/14/2014		<0.05	P					P	None
13	B/S	C3/D3	12/20/2011		<0.05	P					8/9/2017		<0.05	P	P	None
14	B/S	C3/D3					8/14/2014		<0.05	P					P	None
15	B/S	C1/C2													P	None
22	S	Nurses office	12/20/2011		<0.05	P					8/9/2017		<0.05	P	P	None
23	S	Volunteer room					8/14/2014		0.078	P					P	None
28	S	Kitchen-west wall (left sink)													P	None
29	S	Kitchen-west wall (right sink)	12/20/2011		<0.05	P									P	None
31	S/B	Rm 112B-north, right					8/14/2014		<0.05	P					P	None
32	S	Rm 112B-middle														
33	S	Rm 112B-south, left														
34	S/B	Rm 112A, multipurpose room A									8/9/2017		<0.05	P	P	None
36	S/B	Rm 125														
37	S/B	Rm 217														
38	S/B	Rm 130														
39	B	Hall													P	None
40	B	Hall	12/20/2011		<0.05	P									P	None
41	S/B	Rm 132					8/14/2014		<0.05	P					P	None
42	S/B	Rm 131, resource	12/20/2011		<0.05	P									P	None
43	S	Staff lounge (Rm 135)					8/14/2014		<0.05	P					P	None
45	S	Kitchen - Food prep/vegetable wash sink									8/9/2017		<0.05	P	P	None
46	S	Rm 215 - Teacher workroom, D pod													P	None
47	S	Rm 250 - Teacher workroom, K pod													P	None
48	S	Rm 242 - Librarian office													P	None
49	S	Rm 241 - Teacher workroom, c-pod													P	None
50	S	Rm 243A - School psychologist, AV room													P	None

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	custodian office, new building	Arsenic	09-Aug-17	2 ppb	P
00	SE	custodian office, new building	Cadmium	09-Aug-17	1 ppb	P
00	SE	custodian office, new building	Copper	09-Aug-17	0.019 ppm	P
00	SE	custodian office, new building	E coli	26-May-04	<1 Colonies	P
00	SE	custodian office, new building	Iron	09-Aug-17	<0.05 ppm	P
00	SE	custodian office, new building	Lead	09-Aug-17	1 ppb	P
00	SE	custodian office, new building	Total Coliforms	03-Oct-08	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

**Bacteriological Characteristics**

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.