

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
Cleveland High School**

Revised October 1, 2020

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria:

There is one source that doesn't meet the policy criteria. A sign will be posted at Kitchen handwash sink 3117 (#147)

Follow-up monitoring: Will be performed in school year 2022-2023

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
101	B	outside men's restroom 2064	P	None	P	None	P	None	P	None	Yes
102	B	outside women's restroom 2066	P	None	P	None	P	None			Yes
103	S	utility room 2060H, left	P	None	P	None	P	None			Yes
104	S	utility room 2060H, right	P	None	P	None	P	None			Yes
105	S	nurse room, 2060C	P	None	P	None	P	None	P	None	Yes
106	S	2060L	P	None	P	None	P	None			Yes
107	S	2060M	P	None	P	None	P	None	P	None	Yes
108	S	workroom 2050D	P	None	P	None	P	None			Yes
109	S	workroom 2002E	P	None	P	None	P	None			Yes
110	S	special Ed classroom 2010A	P	None	P	None	P	None	P	None	Yes
112	S	classroom 2114	P	None	P	None	P	None	P	None	Yes
113	B	outside women restroom 2107	P	None	P	None	P	None			Yes
114	B	outside men restroom 2105	P	None	P	None	P	None	P	None	Yes
117	S/IH	faculty 2253	P	None	P	None	P	None	P	None	Yes
119	S	room 2264 east	P	None	P	None	P	None			Yes
120	S	family and consumer sciences lab 2264 center	P	None	P	None	P	None	P	None	Yes
121	S	family and consumer sciences lab 2264 center	P	None	P	None	P	None			Yes
122	S	family and consumer sciences lab 2264 center	P	None	P	None	P	None			Yes
123	S	family and consumer sciences lab 2264 center	P	None	P	None	P	None			Yes
124	S	family and consumer sciences lab 2264 west	P	None	P	None	P	None			Yes
125	S	family and consumer sciences lab 2264 west	P	None	P	None	P	None			Yes
126	S	classroom 2258	P	None	P	None	P	None			Yes
127	B	outside men restroom 2205	P	None	P	None	P	None	P	None	Yes
128	B	outside women restroom 2207	P	None	P	None	P	None	P	None	Yes
129	S/IH	faculty 2215	P	None	P	None	P	None			Yes
131	B	girls locker 3027	P	None	P	None	P	None	P	None	Yes
132	B	girls locker 3027	P	None	P	None	P	None			Yes
133	S	coach's locker room 3027B	P	None	P	None	P	None			Yes
134	B	boys locker 3031	P	None	P	None	P	None	P	None	Yes
135	B	boys locker 3031	P	None	P	None	P	None	P	None	Yes
136	S	coach's lockerroom 3031B	P	None	P	None	P	None			Yes
137	B	cor.3004 outside restroom 3009	P	None	P	None	P	None			Yes
138	B	cor. 3004 outside restroom 3007	P	None	P	None	P	None	P	None	Yes
139	S	tickets and concession 3003	P	None	P	None	P	None	P	None	Yes
140	S	tickets and concession 3003	P	None	P	None	P	None			Yes
143	BF	hallway 3108, outside 3111A, bottle filler	P	None	P	None	P	None	P	None	Yes
144	B	hallway 3108, outside 3111A	P	None	P	None	P	None	P	None	Yes
145	S	kitchen 3117	P	None	P	None	P	None			Yes
146	S	kitchen: cooking pot fill 3117 right	P	None	P	None	P	None			Yes
147	S	kitchen handwash 3117		Pending	P	None	P	None			Yes
148	S	kitchen 3117	P	None	P	None	P	None	P	None	Yes
149	S	kitchen handwash 3117	P	None	P	None	P	None			Yes
150	S	kitchen handwash 3117	P	None	P	None	P	None	P	None	Yes
152	S	kitchen dishwasher sink 3117	P	None	P	None	P	None			Yes
153	S	kitchen dishwasher sink 3117	P	None	P	None	P	None			Yes
154	B	weightroom 3121 S.E. corner, left	P	None	P	None	P	None	P	None	Yes
155	S	faculty 1113	P	None	P	None	P	None	P	None	Yes

156	B	weightroom 3121 S.E. corner, right	P	None	P	None	P	None			Yes
157	B	outside staff toilet 1105	P	None	P	None	P	None	P	None	Yes
159	S	workarea 1103A	P	None	P	None	P	None			Yes
160	S	workarea 1131A	P	None	P	None	P	None	P	None	Yes
162	B	outside 1135A	P	None	P	None	P	None	P	None	Yes
164	S	faculty 1141	P	None	P	None	P	None			Yes
165	S	kitchen 1140	P	None	P	None	P	None			Yes
166	S	project lab 1136	P	None	P	None	P	None			Yes
167	S	dressing 1161	P	None	P	None	P	None			Yes
168	S	dressing 1167	P	None	P	None	P	None			Yes
169	S/B	Drama classroom 1162	P	None	P	None	P	None			Yes
170	S	storage room 1166A	P	None	P	None	P	None			Yes
171	S	classroom 1170	P	None	P	None	P	None			Yes
172	S	classroom 1172	P	None	P	None	P	None			Yes
173	S	classroom 1176	P	None	P	None	P	None	P	None	Yes
174	S/B	music classroom 1180	P	None	P	None	P	None	P	None	Yes
175	S/IH	faculty 1211	P	None	P	None	P	None	P	None	Yes
176	S	project lab 1207	P	None	P	None	P	None	P	None	Yes
178	B	outside 1205 right	P	None	P	None	P	None	P	None	Yes
179	B	outside 1205 left	P	None	P	None	P	None	P	None	Yes
180	S	student store 1201A,2-faucet, left	P	None	P	None	P	None			Yes
181	S	student store 1201A,2-faucet, right	P	None	P	None	P	None			Yes
182	S	student store 1201A	P	None	P	None	P	None			Yes
185	S	classroom 1240	P	None	P	None	P	None			Yes
186	S	classroom 1242	P	None	P	None	P	None			Yes
187	S/IH	faculty 1239	P	None	P	None	P	None	P	None	Yes
188	B	vestibule 1331	P	None	P	None	P	None	P	None	Yes
190	S	workarea 1301A	P	None	P	None	P	None	P	None	Yes
192	B	vestibule 1302	P	None	P	None	P	None	P	None	Yes
193	S	Servery Prep handwash 3115A	P	None	P	None	P	None			Yes
194	S	classroom 2214	P	None	P	None	P	None	P	None	Yes
195	S	room 3029 training room	P	None	P	None	P	None			Yes
199	S	kitchen, right kettle	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			7/7/2010			8/6/2013			10/30/2013			8/9/2016			8/27/2019			8/27/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	Pass /Fail	Status
101	B	outside men's restroom 2064	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
102	B	outside women's restroom 2066	<1	<1	P	<1	<1	P				<1	<1	P				2	1	P	P	None
103	S	utility room 2060H, left	2	<1	P							2	<1	P				1	<1	P	P	None
104	S	utility room 2060H, right	2	<1	P							2	<1	P				3	<1	P	P	None
105	S	nurse room, 2060C	2	<1	P							2	<1	P				<1	<1	P	P	None
106	S	2060L	2	<1	P							2	<1	P				2	<1	P	P	None
107	S	2060M	4	<1	P	1	5	P				5	1	P				2	<1	P	P	None
108	S	workroom 2050D	2	<1	P	4	<1	P				1	<1	P				2	<1	P	P	None
109	S	workroom 2002E	2	<1	P	2	<1	P				2	<1	P				3	<1	P	P	None
110	S	special Ed classroom 2010A	3	<1	P	3	<1	P				1	<1	P				<1	1	P	P	None
112	S	classroom 2114	<1	<1	P	2	<1	P				3	<1	P				3	<1	P	P	None
113	B	outside women restroom 2107	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
114	B	outside men restroom 2105	1	<1	P	<1	<1	P				<1	<1	P				1	<1	P	P	None
117	S/IH	faculty 2253	4	1	P	4	<1	P				<1	2	P				1	<1	P	P	None
119	S	room 2264 east	4	5	P	2	<1	P				<1	2	P				1	<1	P	P	None
120	S	family and consumer sciences lab 2264 center	2	<1	P	<1	<1	P				<1	<1	P							P	None
121	S	family and consumer sciences lab 2264 center	3	1	P	6	<1	P				<1	<1	P							P	None
122	S	family and consumer sciences lab 2264 center	4	2	P	4	<1	P				3	<1	P				<1	<1	P	P	None
123	S	family and consumer sciences lab 2264 center	3	1	P	3	<1	P				2	<1	P				<1	<1	P	P	None
124	S	family and consumer sciences lab 2264 west	5	1	P	3	<1	P				2	<1	P				<1	<1	P	P	None
125	S	family and consumer sciences lab 2264 west	2	1	P	2	<1	P				1	<1	P				1	<1	P	P	None
126	S	classroom 2258	4	1	P	2	<1	P				2	<1	P				1	<1	P	P	None
127	B	outside men restroom 2205	1	2	P	<1	<1	P				<1	<1	P							P	None
128	B	outside women restroom 2207	1	1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
129	S/IH	faculty 2215	2	<1	P	2	1	P				2	<1	P				2	<1	P	P	None
131	B	girls locker 3027	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
132	B	girls locker 3027	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
133	S	coach's locker room 3027B	2	<1	P	3	<1	P										1	<1	P	P	None
134	B	boys locker 3031	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
135	B	boys locker 3031	<1	<1	P	<1	<1	P				<1	<1	P				1	<1	P	P	None
136	S	coach's locker room 3031B	<1	<1	P																P	None
137	B	cor.3004 outside restroom 3009	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
138	B	cor. 3004 outside restroom 3007	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
139	S	tickets and concession 3003	3	<1	P	<1	<1	P				6	<1	P				<1	<1	P	P	None
140	S	tickets and concession 3003	3	<1	P	<1	<1	P				4	<1	P				1	<1	P	P	None
143	BF	hallway 3108, outside 3111A, bottle filler	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
144	B	hallway 3108, outside 3111A	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
145	S	kitchen 3117	<1	<1	P	3	<1	P				6	<1	P				2	<1	P	P	None
146	S	kitchen: cooking pot fill 3117 right	<1	<1	P	6	2	P													P	None
147	S	kitchen handwash 3117	<1	<1	P	21	3		5	1	P							15	2			Pending
148	S	kitchen 3117	<1	<1	P	3	<1	P				<1	<1	P				2	<1	P	P	None
149	S	kitchen handwash 3117	<1	<1	P	12	2		4	<1	P							<1	<1	P	P	None
150	S	kitchen handwash 3117	3	<1	P	20	2		8	2	P							9	2	P	P	None
152	S	kitchen dishwasher sink 3117	<1	<1	P	76	2		6	<1	P	54	1		2	<1	P	3	<1	P	P	None
153	S	kitchen dishwasher sink 3117	<1	2	P	37	2		23	3		28	<1		1	<1	P	<1	<1	P	P	None
154	B	weightroom 3121 S.E. corner, left	<1	<1	P	<1	<1	P				<1	<1	P				3	<1	P	P	None
155	S	faculty 1113	2	<1	P							2	<1	P				3	<1	P	P	None

156	B	weightroom 3121 S.E. corner, right	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
157	B	outside staff toilet 1105	1	<1	P	<1	<1	P				<1	<1	P				2	<1	P	P	None
159	S	workarea 1103A	1	<1	P	2	<1	P				<1	<1	P				2	<1	P	P	None
160	S	workarea 1131A	2	<1	P	2	<1	P				3	<1	P				4	1	P	P	None
162	B	outside 1135A	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
164	S	faculty 1141	2	<1	P	2	1	P				2	<1	P				2	1	P	P	None
165	S	kitchen 1140	3	<1	P	<1	<1	P				1	<1	P				1	<1	P	P	None
166	S	project lab 1136	2	<1	P	2	<1	P													P	None
167	S	dressing 1161	3	<1	P	4	<1	P				4	<1	P				<1	3	P	P	None
168	S	dressing 1167	2	<1	P	6	<1	P				4	<1	P				3	<1	P	P	None
169	S/B	Drama classroom 1162	3	<1	P	3	<1	P				1	<1	P				<1	<1	P	P	None
170	S	storage room 1166A	16	<1														1	<1	P	P	None
171	S	classroom 1170	1	<1	P	2	<1	P				2	<1	P				2	<1	P	P	None
172	S	classroom 1172	3	<1	P	5	<1	P				3	<1	P				2	<1	P	P	None
173	S	classroom 1176	5	<1	P	4	<1	P				5	<1	P				6	<1	P	P	None
174	S/B	music classroom 1180	2	<1	P	2	<1	P				2	<1	P				3	<1	P	P	None
175	S/IH	faculty 1211	2	<1	P	2	<1	P				2	<1	P				2	<1	P	P	None
176	S	project lab 1207	5	<1	P	2	<1	P				2	<1	P				2	<1	P	P	None
178	B	outside 1205 right	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
179	B	outside 1205 left	<1	<1	P	<1	<1	P				<1	<1	P				1	<1	P	P	None
180	S	student store 1201A,2-faucet, left	5	<1	P							7	<1	P				3	<1	P	P	None
181	S	student store 1201A,2-faucet, right	2	<1	P							6	<1	P				4	<1	P	P	None
182	S	student store 1201A	4	<1	P							3	<1	P				4	<1	P	P	None
185	S	classroom 1240	1	<1	P	6	<1	P				7	1	P				2	<1	P	P	None
186	S	classroom 1242	2	<1	P	3	<1	P				2	<1	P				<1	<1	P	P	None
187	S/IH	faculty 1239	<1	<1	P	1	<1	P				2	<1	P				1	<1	P	P	None
188	B	vestibule 1331	1	2	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
190	S	workarea 1301A	2	<1	P	4	1	P				2	1	P				<1	<1	P	P	None
192	B	vestibule 1302	<1	<1	P	<1	<1	P				<1	<1	P				<1	<1	P	P	None
193	S	Servery Prep handwash 3115A	<1	<1	P	2	<1	P				2	<1	P				<1	<1	P	P	None
194	S	classroom 2214	4	<1	P	3	<1	P				1	<1	P				1	<1	P	P	None
195	S	room 3029 training room	<1	<1	P	4	1	P				2	<1	P				1	<1	P	P	None
199	S	kitchen, right kettle	<1	<1	P	8	3	P													P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			7/7/2010			8/6/2013			8/9/2016			8/27/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
101	B	outside men's restroom 2064	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
102	B	outside women's restroom 2066	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
103	S	utility room 2060H, left	<1	<1	P				<1	<1	P	<1	<1	P	P	None
104	S	utility room 2060H, right	<1	<1	P				<1	<1	P	<1	<1	P	P	None
105	S	nurse room, 2060C	<1	<1	P				<1	<1	P	<1	<1	P	P	None
106	S	2060L	<1	<1	P				<1	<1	P	<1	<1	P	P	None
107	S	2060M	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
108	S	workroom 2050D	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
109	S	workroom 2002E	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
110	S	special Ed classroom 2010A	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
112	S	classroom 2114	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
113	B	outside women restroom 2107	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
114	B	outside men restroom 2105	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
117	S/IH	faculty 2253	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
119	S	room 2264 east	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
120	S	family and consumer sciences lab 2264 center	<1	<1	P	<1	<1	P	<1	<1	P				P	None
121	S	family and consumer sciences lab 2264 center	<1	<1	P	<1	<1	P	<1	<1	P				P	None
122	S	family and consumer sciences lab 2264 center	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
123	S	family and consumer sciences lab 2264 center	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
124	S	family and consumer sciences lab 2264 west	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
125	S	family and consumer sciences lab 2264 west	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
126	S	classroom 2258	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
127	B	outside men restroom 2205	<1	<1	P	<1	<1	P	<1	<1	P				P	None
128	B	outside women restroom 2207	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
129	S/IH	faculty 2215	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
131	B	girls locker 3027	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
132	B	girls locker 3027	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
133	S	coach's locker room 3027B	<1	<1	P	<1	<1	P				<1	<1	P	P	None
134	B	boys locker 3031	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
135	B	boys locker 3031	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
136	S	coach's locker room 3031B	<1	<1	P										P	None
137	B	cor.3004 outside restroom 3009	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
138	B	cor. 3004 outside restroom 3007	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
139	S	tickets and concession 3003	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
140	S	tickets and concession 3003	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
143	BF	hallway 3108, outside 3111A, bottle filler	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
144	B	hallway 3108, outside 3111A	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
145	S	kitchen 3117	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
146	S	kitchen: cooking pot fill 3117 right	<1	<1	P	<1	<1	P							P	None
147	S	kitchen handwash 3117	<1	<1	P	<1	<1	P				<1	<1	P	P	None
148	S	kitchen 3117	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
149	S	kitchen handwash 3117	<1	<1	P	<1	<1	P				<1	<1	P	P	None
150	S	kitchen handwash 3117	<1	<1	P	<1	<1	P				<1	<1	P	P	None
152	S	kitchen dishwasher sink 3117	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
153	S	kitchen dishwasher sink 3117	<1	<1	P	<1	<1	P	2	<1	P	<1	<1	P	P	None
154	B	weightroom 3121 S.E. corner, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
155	S	faculty 1113	<1	<1	P				<1	<1	P	<1	<1	P	P	None
156	B	weightroom 3121 S.E. corner, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None

157	B	outside staff toilet 1105	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
159	S	workarea 1103A	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
160	S	workarea 1131A	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
162	B	outside 1135A	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
164	S	faculty 1141	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
165	S	kitchen 1140	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
166	S	project lab 1136	<1	<1	P	<1	<1	P							P	None
167	S	dressing 1161	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
168	S	dressing 1167	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
169	S/B	Drama classroom 1162	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
170	S	storage room 1166A	<1	<1	P							<1	<1	P	P	None
171	S	classroom 1170	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
172	S	classroom 1172	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
173	S	classroom 1176	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
174	S/B	music classroom 1180	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
175	S/IH	faculty 1211	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
176	S	project lab 1207	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
178	B	outside 1205 right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
179	B	outside 1205 left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
180	S	student store 1201A,2-faucet, left	<1	<1	P				<1	<1	P	<1	<1	P	P	None
181	S	student store 1201A,2-faucet, right	<1	<1	P				<1	<1	P	<1	<1	P	P	None
182	S	student store 1201A	<1	<1	P				<1	<1	P	<1	<1	P	P	None
185	S	classroom 1240	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
186	S	classroom 1242	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
187	S/IH	faculty 1239	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
188	B	vestibule 1331	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
190	S	workarea 1301A	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
192	B	vestibule 1302	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
193	S	Servery Prep handwash 3115A	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
194	S	classroom 2214	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
195	S	room 3029 training room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
199	S	kitchen, right kettle	<1	<1	P	<1	<1	P							P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			7/7/2010			8/6/2013			8/9/2016			8/27/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
101	B	outside men's restroom 2064	0.134	0.124	P	0.255	0.242	P	0.14	0.137	P	0.101	0.084	P	P	None
102	B	outside women's restroom 2066	0.257	0.139	P	0.276	0.258	P	0.211	0.136	P	0.181	0.103	P	P	None
103	S	utility room 2060H, left	0.19	0.1	P				0.179	0.122	P	0.212	0.112	P	P	None
104	S	utility room 2060H, right	0.191	0.099	P				0.195	0.114	P	0.231	0.095	P	P	None
105	S	nurse room, 2060C	0.273	0.24	P				0.296	0.211	P	0.315	0.24	P	P	None
106	S	2060L	0.232	0.217	P				0.21	0.15	P	0.163	0.134	P	P	None
107	S	2060M	0.178	0.216	P	0.311	0.16	P	0.144	0.201	P	0.315	0.096	P	P	None
108	S	workroom 2050D	0.188	0.181	P	0.223	0.238	P	0.19	0.216	P	0.214	0.224	P	P	None
109	S	workroom 2002E	0.226	0.211	P	0.242	0.348	P	0.208	0.346	P	0.288	0.349	P	P	None
110	S	special Ed classroom 2010A	0.194	0.216	P	0.192	0.274	P	0.221	0.212	P	0.268	0.4	P	P	None
112	S	classroom 2114	0.046	0.048	P	0.235	0.217	P	0.245	0.266	P	0.251	0.199	P	P	None
113	B	outside women restroom 2107	0.111	0.058	P	0.154	0.059	P	0.063	0.028	P	0.101	0.042	P	P	None
114	B	outside men restroom 2105	0.197	0.057	P	0.068	0.053	P	0.073	0.096	P	0.177	0.065	P	P	None
117	S/IH	faculty 2253	0.159	0.13	P	0.237	0.304	P	0.026	0.203	P	0.191	0.141	P	P	None
119	S	room 2264 east	0.268	0.095	P	0.347	0.33	P	0.247	0.074	P	0.141	0.1	P	P	None
120	S	family and consumer sciences lab 2264 center	0.269	0.113	P	0.251	0.249	P	0.193	0.099	P				P	None
121	S	family and consumer sciences lab 2264 center	0.249	0.106	P	0.265	0.289	P	0.217	0.101	P				P	None
122	S	family and consumer sciences lab 2264 center	0.128	0.082	P	0.31	0.373	P	0.175	0.097	P	0.283	0.073	P	P	None
123	S	family and consumer sciences lab 2264 center	0.189	0.097	P	0.205	0.355	P	0.201	0.103	P	0.218	0.114	P	P	None
124	S	family and consumer sciences lab 2264 west	0.226	0.082	P	0.284	0.357	P	0.218	0.108	P	0.448	0.085	P	P	None
125	S	family and consumer sciences lab 2264 west	0.241	0.077	P	0.281	0.347	P	0.204	0.138	P	0.539	0.345	P	P	None
126	S	classroom 2258	0.167	0.185	P	0.273	0.278	P	0.109	0.124	P	0.175	0.154	P	P	None
127	B	outside men restroom 2205	0.06	0.049	P	0.205	0.179	P	0.087	0.082	P				P	None
128	B	outside women restroom 2207	0.19	0.052	P	0.175	0.163	P	0.123	0.077	P	0.089	0.048	P	P	None
129	S/IH	faculty 2215	0.32	0.238	P	0.249	0.309	P	0.193	0.27	P	0.246	0.246	P	P	None
131	B	girls locker 3027	0.245	0.065	P	0.386	0.268	P	0.271	0.184	P	0.21	0.126	P	P	None
132	B	girls locker 3027	0.208	0.063	P	0.396	0.291	P	0.274	0.225	P	0.197	0.098	P	P	None
133	S	coach's locker room 3027B	0.18	0.167	P	0.279	0.338	P				0.176	0.198	P	P	None
134	B	boys locker 3031	0.166	0.086	P	0.341	0.247	P	0.239	0.22	P	0.147	0.095	P	P	None
135	B	boys locker 3031	0.172	0.09	P	0.297	0.222	P	2.18	0.192		0.122	0.097	P	P	None
136	S	coach's locker room 3031B	0.143	0.166	P										P	None
137	B	cor.3004 outside restroom 3009	0.168	0.162	P	0.333	0.262	P	0.283	0.254	P	0.056	0.065	P	P	None
138	B	cor. 3004 outside restroom 3007	0.164	0.186	P	0.308	0.278	P	0.211	0.187	P	0.061	0.05	P	P	None
139	S	tickets and concession 3003	0.193	0.176	P	0.041	0.041	P	0.265	0.242	P	0.142	0.142	P	P	None
140	S	tickets and concession 3003	0.188	0.195	P	0.041	0.04	P	0.2	0.213	P	0.162	0.128	P	P	None
143	BF	hallway 3108, outside 3111A, bottle filler	0.159	0.122	P	0.145	0.144	P	0.119	0.184	P	0.059	0.031	P	P	None
144	B	hallway 3108, outside 3111A	0.121	0.138	P	0.147	0.143	P	0.14	0.096	P	0.059	0.05	P	P	None
145	S	kitchen 3117	0.024	0.018	P	0.384	0.106	P	0.208	0.113	P	0.217	0.074	P	P	None
146	S	kitchen: cooking pot fill 3117 right	0.018	0.02	P	0.101	0.127	P							P	None
147	S	kitchen handwash 3117	0.022	0.019	P	0.304	0.331	P				0.19	0.158	P	P	None
148	S	kitchen 3117	0.017	0.017	P	0.169	0.326	P	0.158	0.107	P	0.103	0.075	P	P	None
149	S	kitchen handwash 3117	0.016	0.016	P	0.237	0.235	P				0.132	0.078	P	P	None
150	S	kitchen handwash 3117	0.084	0.053	P	0.23	0.377	P				0.176	0.233	P	P	None
152	S	kitchen dishwasher sink 3117	0.017	0.021	P	0.138	0.239	P	0.11	0.116	P	0.179	0.096	P	P	None
153	S	kitchen dishwasher sink 3117	0.018	0.025	P	0.115	0.259	P	0.102	0.11	P	0.199	0.096	P	P	None
154	B	weightroom 3121 S.E. corner, left	0.241	0.137	P	0.347	0.327	P	0.208	0.203	P	0.264	0.291	P	P	None
155	S	faculty 1113	0.212	0.148	P				0.247	0.267	P	0.332	0.21	P	P	None
156	B	weightroom 3121 S.E. corner, right	0.202	0.189	P	0.325	0.346	P	0.223	0.217	P	0.219	0.316	P	P	None

157	B	outside staff toilet 1105	0.269	0.212	P	0.268	0.265	P	0.198	0.128	P	0.2	0.172	P	P	None
159	S	workarea 1103A	0.204	0.157	P	0.2	0.295	P	0.104	0.164	P	0.127	0.14	P	P	None
160	S	workarea 1131A	0.2	0.133	P	0.259	0.326	P	0.225	0.296	P	0.186	0.196	P	P	None
162	B	outside 1135A	0.162	0.2	P	0.329	0.272	P	0.253	0.21	P	0.208	0.18	P	P	None
164	S	faculty 1141	0.244	0.21	P	0.322	0.497	P	0.288	0.319	P	0.499	0.462	P	P	None
165	S	kitchen 1140	0.244	0.188	P	0.274	0.287	P	0.253	0.31	P	0.448	0.228	P	P	None
166	S	project lab 1136	0.223	0.197	P	0.3	0.362	P							P	None
167	S	dressing 1161	0.127	0.101	P	0.179	0.245	P	0.153	0.182	P	0.171	0.144	P	P	None
168	S	dressing 1167	0.165	0.194	P	0.3	0.226	P	0.223	0.132	P	0.208	0.156	P	P	None
169	S/B	Drama classroom 1162	0.189	0.116	P	0.241	0.228	P	0.182	0.208	P	0.09	0.083	P	P	None
170	S	storage room 1166A	0.285	0.065	P							0.188	0.055	P	P	None
171	S	classroom 1170	0.163	0.113	P	0.171	0.092	P	0.151	0.207	P	0.157	0.109	P	P	None
172	S	classroom 1172	0.183	0.19	P	0.21	0.25	P	0.19	0.299	P	0.154	0.11	P	P	None
173	S	classroom 1176	0.19	0.231	P	0.187	0.276	P	0.215	0.362	P	0.174	0.262	P	P	None
174	S/B	music classroom 1180	0.171	0.159	P	0.238	0.236	P	0.219	0.218	P	0.222	0.268	P	P	None
175	S/IH	faculty 1211	0.257	0.125	P	0.323	0.318	P	0.297	0.239	P	0.25	0.245	P	P	None
176	S	project lab 1207	0.212	0.16	P	0.258	0.242	P	0.194	0.341	P	0.28	0.202	P	P	None
178	B	outside 1205 right	0.246	0.197	P	0.237	0.194	P	0.245	0.2	P	0.261	0.217	P	P	None
179	B	outside 1205 left	0.225	0.197	P	0.259	0.216	P	0.297	0.231	P	0.278	0.154	P	P	None
180	S	student store 1201A,2-faucet, left	0.19	0.195	P				0.158	0.251	P	0.224	0.108	P	P	None
181	S	student store 1201A,2-faucet, right	0.225	0.192	P				0.208	0.282	P	0.222	0.116	P	P	None
182	S	student store 1201A	0.158	0.175	P				0.184	0.248	P	0.252	0.235	P	P	None
185	S	classroom 1240	0.232	0.297	P	0.216	0.542	P	0.18	0.268	P	0.284	0.175	P	P	None
186	S	classroom 1242	0.237	0.206	P	0.407	0.397	P	0.411	0.404	P	0.263	0.412	P	P	None
187	S/IH	faculty 1239	0.247	0.24	P	0.252	0.377	P	0.256	0.36	P	0.278	0.283	P	P	None
188	B	vestibule 1331	0.328	0.362	P	0.636	0.597	P	0.37	0.419	P	0.34	0.438	P	P	None
190	S	workarea 1301A	0.3	0.232	P	0.304	0.428	P	0.26	0.363	P	0.32	0.273	P	P	None
192	B	vestibule 1302	0.302	0.234	P	0.297	0.25	P	0.38	0.332	P	0.253	0.123	P	P	None
193	S	Servery Prep handwash 3115A	0.02	0.022	P	0.309	0.308	P	0.277	0.254	P	0.22	0.189	P	P	None
194	S	classroom 2214	0.26	0.045	P	0.25	0.294	P	0.269	0.284	P	0.287	0.252	P	P	None
195	S	room 3029 training room	0.067	0.048	P	0.175	0.175	P	0.122	0.115	P	0.102	0.087	P	P	None
199	S	kitchen, right kettle	0.017	0.016	P	0.096	0.12	P							P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			7/7/2010		8/6/2013		8/9/2016		8/27/2020		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
101	B	outside men's restroom 2064									P	None
102	B	outside women's restroom 2066										
103	S	utility room 2060H, left										
104	S	utility room 2060H, right										
105	S	nurse room, 2060C							<0.05	P	P	None
106	S	2060L										
107	S	2060M					<0.05	P			P	None
108	S	workroom 2050D										
109	S	workroom 2002E										
110	S	special Ed classroom 2010A	<0.05	P							P	None
112	S	classroom 2114			<0.05	P					P	None
113	B	outside women restroom 2107										
114	B	outside men restroom 2105									P	None
117	S/IH	faculty 2253							<0.05	P	P	None
119	S	room 2264 east										
120	S	family and consumer sciences lab 2264 center					<0.05	P			P	None
121	S	family and consumer sciences lab 2264 center										
122	S	family and consumer sciences lab 2264 center										
123	S	family and consumer sciences lab 2264 center										
124	S	family and consumer sciences lab 2264 west										
125	S	family and consumer sciences lab 2264 west										
126	S	classroom 2258										
127	B	outside men restroom 2205									P	None
128	B	outside women restroom 2207							<0.05	P	P	None
129	S/IH	faculty 2215										
131	B	girls locker 3027									P	None
132	B	girls locker 3027										
133	S	coach's locker room 3027B										
134	B	boys locker 3031									P	None
135	B	boys locker 3031	<0.05	P							P	None
136	S	coach's lockerroom 3031B										
137	B	cor.3004 outside restroom 3009										
138	B	cor. 3004 outside restroom 3007									P	None
139	S	tickets and concession 3003							<0.05	P	P	None
140	S	tickets and concession 3003										
143	BF	hallway 3108, outside 3111A, bottle filler	<0.05	P							P	None
144	B	hallway 3108, outside 3111A			<0.05	P					P	None
145	S	kitchen 3117										
146	S	kitchen: cooking pot fill 3117 right										
147	S	kitchen handwash 3117										
148	S	kitchen 3117					<0.05	P			P	None
149	S	kitchen handwash 3117										
150	S	kitchen handwash 3117							<0.05	P	P	None
152	S	kitchen dishwasher sink 3117										
153	S	kitchen dishwasher sink 3117										
154	B	weightroom 3121 S.E. corner, left									P	None
155	S	faculty 1113	<0.05	P							P	None
156	B	weightroom 3121 S.E. corner, right										

157	B	outside staff toilet 1105			<0.05	P					P	None
159	S	workarea 1103A										
160	S	workarea 1131A					<0.05	P			P	None
162	B	outside 1135A							<0.05	P	P	None
164	S	faculty 1141										
165	S	kitchen 1140										
166	S	project lab 1136										
167	S	dressing 1161										
168	S	dressing 1167										
169	S/B	Drama classroom 1162										
170	S	storage room 1166A										
171	S	classroom 1170										
172	S	classroom 1172										
173	S	classroom 1176					<0.05	P			P	None
174	S/B	music classroom 1180	<0.05	P							P	None
175	S/IH	faculty 1211	<0.05	P							P	None
176	S	project lab 1207			<0.05	P					P	None
178	B	outside 1205 right			<0.05	P					P	None
179	B	outside 1205 left							<0.05	P	P	None
180	S	student store 1201A,2-faucet, left										
181	S	student store 1201A,2-faucet, right										
182	S	student store 1201A										
185	S	classroom 1240										
186	S	classroom 1242										
187	S/IH	faculty 1239									P	None
188	B	vestibule 1331									P	None
190	S	workarea 1301A									P	None
192	B	vestibule 1302									P	None
193	S	Servery Prep handwash 3115A										
194	S	classroom 2214							<0.05	P	P	None
195	S	room 3029 training room										
199	S	kitchen, right kettle										

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			<i>Most Recent Sampling</i>			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
100	SE	Boiler's room 1S07	Arsenic	09-Aug-16	2 ppb	P
100	SE	Boiler's room 1S07	Cadmium	09-Aug-16	1 ppb	P
100	SE	Boiler's room 1S07	Copper	09-Aug-16	0.007 ppm	P
100	SE	Boiler's room 1S07	Iron	09-Aug-16	<0.05 ppm	P
100	SE	Boiler's room 1S07	Lead	09-Aug-16	1 ppb	P
100	SE	Boiler's room 1S07	Total Coliforms	20-Dec-07	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).
 "n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.