

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
GREENWOOD ELEMENTARY SCHOOL**

Updated March 02, 2020

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria:

All fixtures meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2022-2023

Service: The school will be returned to regular service and will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
03	S/B	room 106	P	None	P	None	P	None	P	None	Yes
04	S/B	room 105	P	None	P	None	P	None	P	None	Yes
05	S/B	room 104	P	None	P	None	P	None	P	None	Yes
06	S/B	room 103	P	None	P	None	P	None	P	None	Yes
07	S	room 102, s. wall, w. sink, right of 40	P	None	P	None	P	None	P	None	Yes
08	B	near assembly hall,	P	None	P	None	P	None	P	None	Yes
09	BF	hallway entrance	P	None	P	None	P	None			Yes
10	S	room 101, s. wall, e. sink, left	P	None	P	None	P	None	P	None	Yes
11	B	2nd floor hall, left	P	None	P	None	P	None	P	None	Yes
12	B	2nd floor hall, right	P	None	P	None	P	None	P	None	Yes
13	S/B	room 203	P	None	P	None	P	None	P	None	Yes
14	S/B	room 204	P	None	P	None	P	None	P	None	Yes
15	S/B	room 205	P	None	P	None	P	None			Yes
16	S/B	room 305	P	None	P	None	P	None	P	None	Yes
17	S/B	room 307	P	None	P	None	P	None	P	None	Yes
18	S/B	room 306	P	None	P	None	P	None	P	None	Yes
19	S/B	room 308	P	None	P	None	P	None	P	None	Yes
20	S/B	room 304	P	None	P	None	P	None	P	None	Yes
21	S/B	staff lounge (3rd floor)	P	None	P	None	P	None	P	None	Yes
22	B	3rd floor hall, left	P	None	P	None	P	None	P	None	Yes
23	B	3rd floor hall, right	P	None	P	None	P	None	P	None	Yes
24	S/B	room 303	P	None	P	None	P	None	P	None	Yes
25	S/B	room 302	P	None	P	None	P	None	P	None	Yes
26	S/B	room 301	P	None	P	None	P	None	P	None	Yes
27	S	nurses office	P	None	P	None	P	None	P	None	Yes
28	S	kitchen, n. wall	P	None	P	None	P	None	P	None	Yes
28B	S	kitchen - s. wall, e. sink	P	None	P	None	P	None	P	None	Yes
28C	S	kitchen - s. wall, w. sink	P	None	P	None	P	None			Yes
36	S	room 101, s. wall, w. sink, right	P	None	P	None	P	None			Yes
37	S	room 101 west wall	P	None	P	None	P	None			Yes
39	S	room 202 south wall	P	None	P	None	P	None	P	None	Yes
40	S/B	room 102 - s. wall - e. sink, left of 07	P	None	P	None	P	None	P	None	Yes
41	S	room 102 east wall	P	None	P	None	P	None	P	None	Yes
42	S	3rd floor staff workroom	P	None	P	None	P	None	P	None	Yes
43	S	library office	P	None	P	None	P	None			Yes
44	S	volunteer room	P	None	P	None	P	None			Yes
45	S	Childcare kitchen	P	None	P	None	P	None			Yes
46	S	Childcare kitchen, left	P	None	P	None	P	None			Yes
47	S	Childcare kitchen, right	P	None	P	None	P	None			Yes
48	B	Childcare drinking fountain, left	P	None	P	None	P	None			Yes
49	B	Childcare drinking fountain, right	P	None	P	None	P	None			Yes
50	S	childcare kitchen, handwash	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			11/3/2009			11/15/2012			11/24/2015			2/15/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
03	S/B	room 106	1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
04	S/B	room 105	1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
05	S/B	room 104	<1	<1	P	<1	<1	P		<1	P	<1	<1	P	P	None
06	S/B	room 103	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
07	S	room 102, s. wall, w. sink, right of 40	<1	<1	P	<1	<1	P	1	<1	P	<1	<1	P	P	None
08	B	near assembly hall,	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
09	BF	hallway entrance	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
10	S	room 101, s. wall, e. sink, left	1	<1	P	2	<1	P	<1	<1	P	<1	<1	P	P	None
11	B	2nd floor hall, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
12	B	2nd floor hall, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
13	S/B	room 203	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
14	S/B	room 204	1	<1	P	<1	<1	P	<1	<1	P	1	<1	P	P	None
15	S/B	room 205	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	S/B	room 305	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
17	S/B	room 307	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
18	S/B	room 306	1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
19	S/B	room 308	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
20	S/B	room 304	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
21	S/B	staff lounge (3rd floor)	2	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
22	B	3rd floor hall, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
23	B	3rd floor hall, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
24	S/B	room 303	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
25	S/B	room 302	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
26	S/B	room 301	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
27	S	nurses office	<1	<1	P				<1	<1	P	<1	<1	P	P	None
28	S	kitchen, n. wall	1	1	P	<1	<1	P	1	<1	P	<1	<1	P	P	None
28B	S	kitchen - s. wall, e. sink	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
28C	S	kitchen - s. wall, w. sink	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
36	S	room 101, s. wall, w. sink, right	<1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
37	S	room 101 west wall	1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
39	S	room 202 south wall	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
40	S/B	room 102 - s. wall - e. sink, left of 07	1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
41	S	room 102 east wall	3	<1	P	4	<1	P	3	<1	P	<1	<1	P	P	None
42	S	3rd floor staff workroom	4	<1	P	4	<1	P	2	<1	P	1	<1	P	P	None
43	S	library office	2	<1	P	2	<1	P	2	<1	P	1	1	P	P	None
44	S	volunteer room	1	<1	P	1	<1	P	<1	<1	P	<1	<1	P	P	None
45	S	Childcare kitchen										<1	<1	P	P	None
46	S	Childcare kitchen, left										<1	<1	P	P	None
47	S	Childcare kitchen, right										<1	<1	P	P	None
48	B	Childcare drinking fountain, left										<1	<1	P	P	None
49	B	Childcare drinking fountain, right										<1	<1	P	P	None
50	S	childcare kitchen, handwash										<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			11/3/2009			11/15/2012			11/24/2015			2/15/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
03	S/B	room 106	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
04	S/B	room 105	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
05	S/B	room 104	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
06	S/B	room 103	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
07	S	room 102, s. wall, w. sink, right of 40	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
08	B	near assembly hall,	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
09	BF	hallway entrance	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
10	S	room 101, s. wall, e. sink, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
11	B	2nd floor hall, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
12	B	2nd floor hall, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
13	S/B	room 203	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
14	S/B	room 204	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
15	S/B	room 205	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	S/B	room 305	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
17	S/B	room 307	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
18	S/B	room 306	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
19	S/B	room 308	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
20	S/B	room 304	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
21	S/B	staff lounge (3rd floor)	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
22	B	3rd floor hall, left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
23	B	3rd floor hall, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
24	S/B	room 303	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
25	S/B	room 302	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
26	S/B	room 301	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
27	S	nurses office	<1	<1	P				<1	<1	P	<1	<1	P	P	None
28	S	kitchen, n. wall	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
28B	S	kitchen - s. wall, e. sink	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
28C	S	kitchen - s. wall, w. sink	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
36	S	room 101, s. wall, w. sink, right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
37	S	room 101 west wall	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
39	S	room 202 south wall	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
40	S/B	room 102 - s. wall - e. sink, left of 07	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
41	S	room 102 east wall	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
42	S	3rd floor staff workroom	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
43	S	library office	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
44	S	volunteer room	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
45	S	Childcare kitchen										<1	<1	P	P	None
46	S	Childcare kitchen, left										<1	<1	P	P	None
47	S	Childcare kitchen, right										<1	<1	P	P	None
48	B	Childcare drinking fountain, left										<1	<1	P	P	None
49	B	Childcare drinking fountain, right										<1	<1	P	P	None
50	S	childcare kitchen, handwash										<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			11/3/2009			11/15/2012			11/24/2015			2/15/2020			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
03	S/B	room 106	0.518	0.633	P	0.157	0.15	P	0.115	0.118	P	0.363	0.34	P	P	None
04	S/B	room 105	0.435	0.467	P	0.213	0.204	P	0.147	0.114	P	0.396	0.421	P	P	None
05	S/B	room 104	0.616	0.584	P	0.141	0.155	P		0.141	P	0.408	0.372	P	P	None
06	S/B	room 103	0.446	0.469	P	0.15	0.11	P	0.126	0.117	P	0.361	0.367	P	P	None
07	S	room 102, s. wall, w. sink, right of 40	<0.002	<0.002	P	0.126	0.082	P	0.131	0.129	P	0.356	0.166	P	P	None
08	B	near assembly hall,	0.426	0.298	P	0.098	0.088	P	0.073	0.079	P	0.192	0.199	P	P	None
09	BF	hallway entrance	0.249	0.221	P	0.093	0.067	P	0.07	0.072	P	0.183	0.217	P	P	None
10	S	room 101, s. wall, e. sink, left	0.093	<0.002	P	0.176	0.132	P	0.14	0.116	P	0.431	0.282	P	P	None
11	B	2nd floor hall, left	0.364	0.346	P	0.124	0.068	P	0.114	0.137	P	0.247	0.341	P	P	None
12	B	2nd floor hall, right	0.436	0.306	P	0.117	0.062	P	0.116	0.108	P	0.278	0.235	P	P	None
13	S/B	room 203	0.501	0.53	P	0.126	0.143	P	0.116	0.134	P	0.353	0.353	P	P	None
14	S/B	room 204	<0.002	<0.002	P	0.116	0.133	P	<0.002	<0.002	P	0.403	0.398	P	P	None
15	S/B	room 205	<0.002	<0.002	P	<0.002	<0.002	P	<0.002	<0.002	P	0.003	0.002	P	P	None
16	S/B	room 305	0.624	0.607	P	0.127	0.115	P	0.106	0.107	P	0.351	0.376	P	P	None
17	S/B	room 307	0.492	0.546	P	0.133	0.121	P	0.126	0.162	P	0.366	0.37	P	P	None
18	S/B	room 306	0.535	0.6	P	0.119	0.129	P	0.135	0.128	P	0.393	0.374	P	P	None
19	S/B	room 308	0.502	0.453	P	0.139	0.155	P	0.145	0.151	P	0.388	0.344	P	P	None
20	S/B	room 304	0.431	0.473	P	0.12	0.116	P	0.114	0.109	P	0.29	0.289	P	P	None
21	S/B	staff lounge (3rd floor)	0.303	0.48	P	0.141	0.142	P	0.103	0.135	P	0.279	0.249	P	P	None
22	B	3rd floor hall, left	0.323	0.335	P	0.089	0.02	P	0.086	0.076	P	0.202	0.181	P	P	None
23	B	3rd floor hall, right	0.27	0.241	P	0.043	0.019	P	0.077	0.075	P	0.185	0.174	P	P	None
24	S/B	room 303	0.51	0.489	P	0.134	0.141	P	0.138	0.151	P	0.379	0.359	P	P	None
25	S/B	room 302	<0.002	<0.002	P	0.012	0.004	P	0.022	0.003	P	0.003	0.008	P	P	None
26	S/B	room 301	<0.002	<0.002	P	0.005	<0.002	P	0.13	<0.002	P	0.381	0.392	P	P	None
27	S	nurses office	0.424	0.324	P				0.087	0.084	P	0.308	0.211	P	P	None
28	S	kitchen, n. wall	0.389	0.43	P	0.038	0.054	P	0.114	0.114	P	0.295	0.26	P	P	None
28B	S	kitchen - s. wall, e. sink	0.183	0.292	P	0.124	0.024	P	0.118	0.081	P	0.365	0.207	P	P	None
28C	S	kitchen - s. wall, w. sink	0.296	0.144	P	0.039	0.035	P	0.127	0.083	P	0.233	0.22	P	P	None
36	S	room 101, s. wall, w. sink, right	0.395	0.391	P	0.124	0.138	P	0.012	0.004	P	0.337	0.323	P	P	None
37	S	room 101 west wall	0.498	0.311	P	0.138	0.086	P	0.139	0.081	P	0.218	0.309	P	P	None
39	S	room 202 south wall	0.012	0.013	P	0.043	0.009	P	0.003	<0.002	P	0.002	0.002	P	P	None
40	S/B	room 102 - s. wall - e. sink, left of 07	0.363	0.435	P	0.028	0.022	P	0.041	0.018	P	0.275	0.149	P	P	None
41	S	room 102 east wall	0.362	0.253	P	0.169	0.07	P	0.144	0.07	P	0.37	0.134	P	P	None
42	S	3rd floor staff workroom	0.516	0.422	P	0.169	0.183	P	0.169	0.212	P	0.608	0.248	P	P	None
43	S	library office	0.355	0.501	P	0.155	0.182	P	0.141	0.174	P	0.5	0.575	P	P	None
44	S	volunteer room	0.402	0.366	P	0.165	0.163	P	0.164	0.149	P	0.478	0.28	P	P	None
45	S	Childcare kitchen										0.294	0.193	P	P	None
46	S	Childcare kitchen, left										0.191	0.151	P	P	None
47	S	Childcare kitchen, right										0.18	0.156	P	P	None
48	B	Childcare drinking fountain, left										0.279	0.276	P	P	None
49	B	Childcare drinking fountain, right										0.24	0.192	P	P	None
50	S	childcare kitchen, handwash										0.384	0.149	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			11/3/2009		11/15/2012		11/24/2015		2/15/2020		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
03	S/B	room 106									P	None
04	S/B	room 105	<0.05	P							P	None
05	S/B	room 104			<0.05	P					P	None
06	S/B	room 103					<0.05	P			P	None
07	S	room 102, s. wall, w. sink, right of 40							<0.05	P	P	None
08	B	near assembly hall,									P	None
09	BF	hallway entrance										
10	S	room 101, s. wall, e. sink, left	<0.05	P							P	None
11	B	2nd floor hall, left			<0.05	P					P	None
12	B	2nd floor hall, right					<0.05	P			P	None
13	S/B	room 203	<0.05	P					<0.05	P	P	None
14	S/B	room 204									P	None
15	S/B	room 205										
16	S/B	room 305	<0.05	P							P	None
17	S/B	room 307			<0.05	P					P	None
18	S/B	room 306					<0.05	P			P	None
19	S/B	room 308							<0.05	P	P	None
20	S/B	room 304									P	None
21	S/B	staff lounge (3rd floor)									P	None
22	B	3rd floor hall, left									P	None
23	B	3rd floor hall, right									P	None
24	S/B	room 303									P	None
25	S/B	room 302									P	None
26	S/B	room 301	<0.05	P							P	None
27	S	nurses office									P	None
28	S	kitchen, n. wall					<0.05	P			P	None
28B	S	kitchen - s. wall, e. sink							<0.05	P	P	None
28C	S	kitchen - s. wall, w. sink										
36	S	room 101, s. wall, w. sink, right										
37	S	room 101 west wall										
39	S	room 202 south wall	<0.05	P							P	None
40	S/B	room 102 - s. wall - e. sink, left of 07			<0.05	P					P	None
41	S	room 102 east wall					<0.05	P			P	None
42	S	3rd floor staff workroom							<0.05	P	P	None
43	S	library office										
44	S	volunteer room										
45	S	Childcare kitchen										
46	S	Childcare kitchen, left										
47	S	Childcare kitchen, right										
48	B	Childcare drinking fountain, left										
49	B	Childcare drinking fountain, right										
50	S	childcare kitchen, handwash										

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	boiler room (east wall) outside service door (brass door)	Arsenic	15-Feb-20	2 ppb	P
00	SE	boiler room (east wall) outside service door (brass door)	Cadmium	15-Feb-20	1 ppb	P
00	SE	boiler room (east wall) outside service door (brass door)	Chlorine	14-May-04	0.1 ppm	P
00	SE	boiler room (east wall) outside service door (brass door)	Copper	15-Feb-20	0.195 ppm	P
00	SE	boiler room (east wall) outside service door (brass door)	E coli	14-May-04	<1 Colonies	P
00	SE	boiler room (east wall) outside service door (brass door)	Iron	15-Feb-20	<0.05 ppm	P
00	SE	boiler room (east wall) outside service door (brass door)	Lead	15-Feb-20	1 ppb	P
00	SE	boiler room (east wall) outside service door (brass door)	Total Coliforms	03-Nov-09	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.