

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
Robert Eagle Staff middle school

Updated July 24, 2017

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria: All sources meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2020-2021.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend	
Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S	ROOM 110S	P	None	P	None	P	None			Yes
02	S	ROOM 111D	P	None	P	None	P	None			Yes
03	S	ROOM 111K	P	None	P	None	P	None			Yes
04	B	1ST FLOOR, BY BOYS	P	None	P	None	P	None			Yes
05	B	1ST FLOOR, BY GIRLS	P	None	P	None	P	None			Yes
06	S/B	ROOM 154	P	None	P	None	P	None	P	None	Yes
07	S/B	ROOM 158	P	None	P	None	P	None			Yes
08	S/B	ROOM 157	P	None	P	None	P	None			Yes
09	S/B	ROOM 161	P	None	P	None	P	None			Yes
10	B	1ST FLOOR HALLWAY, BY BOYS	P	None	P	None	P	None			Yes
11	B	1ST FLOOR HALLWAY, BY GIRLS	P	None	P	None	P	None			Yes
12	S	ROOM 162	P	None	P	None	P	None			Yes
13	S	ROOM 164	P	None	P	None	P	None	P	None	Yes
14	S	ART ROOM 166	P	None	P	None	P	None			Yes
15	S	ART ROOM 166	P	None	P	None	P	None			Yes
16	S	KITCHEN, LEFT	P	None	P	None	P	None			Yes
17	S	KITCHEN, RIGHT	P	None	P	None	P	None			Yes
19	S	KITCHEN	P	None	P	None	P	None			Yes
20	S	KITCHEN	P	None	P	None	P	None			Yes
21	S	ROOM 136	P	None	P	None	P	None	P	None	Yes
22	B	GYM, LEFT	P	None	P	None	P	None			Yes
23	B	GYM, RIGHT	P	None	P	None	P	None			Yes
24	B	COMMONS, LEFT	P	None	P	None	P	None			Yes
25	B	COMMONS, RIGHT	P	None	P	None	P	None			Yes
26	B	COMMONS, LEFT	P	None	P	None	P	None			Yes
27	B	COMMONS, RIGHT	P	None	P	None	P	None	P	None	Yes
28	B	170 HALLWAY, GIRLS	P	None	P	None	P	None			Yes
29	B	170 HALLWAY, BOYS	P	None	P	None	P	None			Yes
30	B	270 HALLWAY, GIRLS	P	None	P	None	P	None			Yes
31	B	270 HALLWAY, BOYS	P	None	P	None	P	None			Yes
32	S	LIBRARY OFFICE, 220A	P	None	P	None	P	None			Yes
33	S/B	ROOM 261	P	None	P	None	P	None			Yes
34	B	260 HALLWAY, GIRLS	P	None	P	None	P	None	P	None	Yes
35	B	260 HALLWAY, BOYS	P	None	P	None	P	None			Yes
36	S	TEACHER WORKROOM 262	P	None	P	None	P	None			Yes
37	S	ROOM 264	P	None	P	None	P	None			Yes
38	S	ROOM 266	P	None	P	None	P	None			Yes
39	S	ROOM 268	P	None	P	None	P	None	P	None	Yes
40	S	ROOM 200C	P	None	P	None	P	None			Yes
41	B	250 HALLWAY, GIRLS	P	None	P	None	P	None			Yes
42	B	250 HALLWAY, BOYS	P	None	P	None	P	None			Yes
43	S/B	ROOM 258	P	None	P	None	P	None			Yes
44	S/B	ROOM 257	P	None	P	None	P	None			Yes
45	S	ROOM 212	P	None	P	None	P	None	P	None	Yes
46	B	350 HALLWAY, BOYS	P	None	P	None	P	None			Yes

47	B	350 HALLWAY, GIRLS	P	None	P	None	P	None			Yes
48	S	ROOM 361	P	None	P	None	P	None			Yes
49	S/B	ROOM 361	P	None	P	None	P	None			Yes
50	B	360 HALLWAY, GIRLS	P	None	P	None	P	None			Yes
51	B	360 HALLWAY, BOYS	P	None	P	None	P	None	P	None	Yes
52	S	ROOM 362	P	None	P	None	P	None			Yes
53	S	ROOM 364	P	None	P	None	P	None			Yes
54	S	ROOM 331, TEACHER'S LOUNGE	P	None	P	None	P	None			Yes
55	S	ROOM 331, TEACHER'S LOUNGE	P	None	P	None	P	None			Yes
56	B	370 HALLWAY, GIRLS	P	None	P	None	P	None			Yes
57	B	370 HALLWAY, BOYS	P	None	P	None	P	None	P	None	Yes
58	S/B	ROOM 374	P	None	P	None	P	None			Yes
60	S	room 111H	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			Initial Sampling						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 110S	7/14/2017	<1	<1		P		P	None
02	S	ROOM 111D	7/14/2017	<1	<1		P		P	None
03	S	ROOM 111K	7/14/2017	<1	<1		P		P	None
04	B	1ST FLOOR, BY BOYS	7/14/2017	<1	<1		P		P	None
05	B	1ST FLOOR, BY GIRLS	7/14/2017	<1	<1		P		P	None
06	S/B	ROOM 154	7/14/2017	<1	<1		P		P	None
07	S/B	ROOM 158	7/14/2017	<1	<1		P		P	None
08	S/B	ROOM 157	7/14/2017	<1	<1		P		P	None
09	S/B	ROOM 161	7/14/2017	<1	<1		P		P	None
10	B	1ST FLOOR HALLWAY, BY BOYS	7/14/2017	<1	<1		P		P	None
11	B	1ST FLOOR HALLWAY, BY GIRLS	7/14/2017	<1	<1		P		P	None
12	S	ROOM 162	7/14/2017	<1	<1		P		P	None
13	S	ROOM 164	7/14/2017	<1	<1		P		P	None
14	S	ART ROOM 166	7/14/2017	<1	<1		P		P	None
15	S	ART ROOM 166	7/14/2017	<1	<1		P		P	None
16	S	KITCHEN, LEFT	7/14/2017	<1	<1		P		P	None
17	S	KITCHEN, RIGHT	7/14/2017	<1	<1		P		P	None
19	S	KITCHEN	7/14/2017	<1	<1		P		P	None
20	S	KITCHEN	7/14/2017	<1	<1		P		P	None
21	S	ROOM 136	7/14/2017	<1	1		P		P	None
22	B	GYM, LEFT	7/14/2017	<1	<1		P		P	None
23	B	GYM, RIGHT	7/14/2017	<1	<1		P		P	None
24	B	COMMONS, LEFT	7/14/2017	<1	<1		P		P	None
25	B	COMMONS, RIGHT	7/14/2017	<1	<1		P		P	None
26	B	COMMONS, LEFT	7/14/2017	<1	<1		P		P	None
27	B	COMMONS, RIGHT	7/14/2017	<1	<1		P		P	None
28	B	170 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
29	B	170 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
30	B	270 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
31	B	270 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
32	S	LIBRARY OFFICE, 220A	7/14/2017	<1	<1		P		P	None
33	S/B	ROOM 261	7/14/2017	<1	<1		P		P	None
34	B	260 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
35	B	260 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
36	S	TEACHER WORKROOM 262	7/14/2017	<1	<1		P		P	None
37	S	ROOM 264	7/14/2017	<1	<1		P		P	None
38	S	ROOM 266	7/14/2017	<1	<1		P		P	None
39	S	ROOM 268	7/14/2017	<1	<1		P		P	None
40	S	ROOM 200C	7/14/2017	<1	<1		P		P	None
41	B	250 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
42	B	250 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
43	S/B	ROOM 258	7/14/2017	<1	<1		P		P	None
44	S/B	ROOM 257	7/14/2017	<1	<1		P		P	None
45	S	ROOM 212	7/14/2017	<1	<1		P		P	None
46	B	350 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
47	B	350 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
48	S	ROOM 361	7/14/2017	<1	<1		P		P	None
49	S/B	ROOM 361	7/14/2017	<1	<1		P		P	None

50	B	360 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
51	B	360 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
52	S	ROOM 362	7/14/2017	<1	<1		P		P	None
53	S	ROOM 364	7/14/2017	<1	<1		P		P	None
54	S	ROOM 331, TEACHER'S LOUNGE	7/14/2017	<1	<1		P		P	None
55	S	ROOM 331, TEACHER'S LOUNGE	7/14/2017	<1	<1		P		P	None
56	B	370 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
57	B	370 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
58	S/B	ROOM 374	7/14/2017	<1	<1		P		P	None
60	S	room 111H	7/14/2017	<1	<1		P		P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			Initial Sampling						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 110S	7/14/2017	<1	<1		P		P	None
02	S	ROOM 111D	7/14/2017	<1	<1		P		P	None
03	S	ROOM 111K	7/14/2017	<1	<1		P		P	None
04	B	1ST FLOOR, BY BOYS	7/14/2017	<1	<1		P		P	None
05	B	1ST FLOOR, BY GIRLS	7/14/2017	<1	<1		P		P	None
06	S/B	ROOM 154	7/14/2017	<1	<1		P		P	None
07	S/B	ROOM 158	7/14/2017	<1	<1		P		P	None
08	S/B	ROOM 157	7/14/2017	<1	<1		P		P	None
09	S/B	ROOM 161	7/14/2017	<1	<1		P		P	None
10	B	1ST FLOOR HALLWAY, BY BOYS	7/14/2017	<1	<1		P		P	None
11	B	1ST FLOOR HALLWAY, BY GIRLS	7/14/2017	<1	<1		P		P	None
12	S	ROOM 162	7/14/2017	<1	<1		P		P	None
13	S	ROOM 164	7/14/2017	<1	<1		P		P	None
14	S	ART ROOM 166	7/14/2017	<1	<1		P		P	None
15	S	ART ROOM 166	7/14/2017	<1	<1		P		P	None
16	S	KITCHEN, LEFT	7/14/2017	<1	<1		P		P	None
17	S	KITCHEN, RIGHT	7/14/2017	<1	<1		P		P	None
19	S	KITCHEN	7/14/2017	<1	<1		P		P	None
20	S	KITCHEN	7/14/2017	<1	<1		P		P	None
21	S	ROOM 136	7/14/2017	<1	1		P		P	None
22	B	GYM, LEFT	7/14/2017	<1	<1		P		P	None
23	B	GYM, RIGHT	7/14/2017	<1	<1		P		P	None
24	B	COMMONS, LEFT	7/14/2017	<1	<1		P		P	None
25	B	COMMONS, RIGHT	7/14/2017	<1	<1		P		P	None
26	B	COMMONS, LEFT	7/14/2017	<1	<1		P		P	None
27	B	COMMONS, RIGHT	7/14/2017	<1	<1		P		P	None
28	B	170 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
29	B	170 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
30	B	270 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
31	B	270 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
32	S	LIBRARY OFFICE, 220A	7/14/2017	<1	<1		P		P	None
33	S/B	ROOM 261	7/14/2017	<1	<1		P		P	None
34	B	260 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
35	B	260 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
36	S	TEACHER WORKROOM 262	7/14/2017	<1	<1		P		P	None
37	S	ROOM 264	7/14/2017	<1	<1		P		P	None
38	S	ROOM 266	7/14/2017	<1	<1		P		P	None
39	S	ROOM 268	7/14/2017	<1	<1		P		P	None
40	S	ROOM 200C	7/14/2017	<1	<1		P		P	None
41	B	250 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
42	B	250 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
43	S/B	ROOM 258	7/14/2017	<1	<1		P		P	None
44	S/B	ROOM 257	7/14/2017	<1	<1		P		P	None
45	S	ROOM 212	7/14/2017	<1	<1		P		P	None
46	B	350 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
47	B	350 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
48	S	ROOM 361	7/14/2017	<1	<1		P		P	None
49	S/B	ROOM 361	7/14/2017	<1	<1		P		P	None

50	B	360 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
51	B	360 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
52	S	ROOM 362	7/14/2017	<1	<1		P		P	None
53	S	ROOM 364	7/14/2017	<1	<1		P		P	None
54	S	ROOM 331, TEACHER'S LOUNGE	7/14/2017	<1	<1		P		P	None
55	S	ROOM 331, TEACHER'S LOUNGE	7/14/2017	<1	<1		P		P	None
56	B	370 HALLWAY, GIRLS	7/14/2017	<1	<1		P		P	None
57	B	370 HALLWAY, BOYS	7/14/2017	<1	<1		P		P	None
58	S/B	ROOM 374	7/14/2017	<1	<1		P		P	None
60	S	room 111H	7/14/2017	<1	<1		P		P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			Initial Sampling						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 110S	7/14/2017	0.131	0.123		P		P	None
02	S	ROOM 111D	7/14/2017	0.15	0.176		P		P	None
03	S	ROOM 111K	7/14/2017	0.136	0.084		P		P	None
04	B	1ST FLOOR, BY BOYS	7/14/2017	0.172	0.104		P		P	None
05	B	1ST FLOOR, BY GIRLS	7/14/2017	0.12	0.107		P		P	None
06	S/B	ROOM 154	7/14/2017	0.131	0.025		P		P	None
07	S/B	ROOM 158	7/14/2017	0.167	0.168		P		P	None
08	S/B	ROOM 157	7/14/2017	0.143	0.204		P		P	None
09	S/B	ROOM 161	7/14/2017	0.182	0.126		P		P	None
10	B	1ST FLOOR HALLWAY, BY BOYS	7/14/2017	0.148	0.12		P		P	None
11	B	1ST FLOOR HALLWAY, BY GIRLS	7/14/2017	0.113	0.109		P		P	None
12	S	ROOM 162	7/14/2017	0.133	0.117		P		P	None
13	S	ROOM 164	7/14/2017	0.174	0.131		P		P	None
14	S	ART ROOM 166	7/14/2017	0.175	0.138		P		P	None
15	S	ART ROOM 166	7/14/2017	0.179	0.126		P		P	None
16	S	KITCHEN, LEFT	7/14/2017	0.125	0.346		P		P	None
17	S	KITCHEN, RIGHT	7/14/2017	0.115	0.288		P		P	None
19	S	KITCHEN	7/14/2017	0.12	0.061		P		P	None
20	S	KITCHEN	7/14/2017	0.186	0.214		P		P	None
21	S	ROOM 136	7/14/2017	0.14	0.067		P		P	None
22	B	GYM, LEFT	7/14/2017	0.17	0.172		P		P	None
23	B	GYM, RIGHT	7/14/2017	0.162	0.162		P		P	None
24	B	COMMONS, LEFT	7/14/2017	0.166	0.17		P		P	None
25	B	COMMONS, RIGHT	7/14/2017	0.19	0.188		P		P	None
26	B	COMMONS, LEFT	7/14/2017	0.169	0.156		P		P	None
27	B	COMMONS, RIGHT	7/14/2017	0.208	0.15		P		P	None
28	B	170 HALLWAY, GIRLS	7/14/2017	0.14	0.123		P		P	None
29	B	170 HALLWAY, BOYS	7/14/2017	0.141	0.12		P		P	None
30	B	270 HALLWAY, GIRLS	7/14/2017	0.189	0.18		P		P	None
31	B	270 HALLWAY, BOYS	7/14/2017	0.196	0.168		P		P	None
32	S	LIBRARY OFFICE, 220A	7/14/2017	0.153	0.151		P		P	None
33	S/B	ROOM 261	7/14/2017	0.144	0.108		P		P	None
34	B	260 HALLWAY, GIRLS	7/14/2017	0.186	0.172		P		P	None
35	B	260 HALLWAY, BOYS	7/14/2017	0.17	0.11		P		P	None
36	S	TEACHER WORKROOM 262	7/14/2017	0.11	0.132		P		P	None
37	S	ROOM 264	7/14/2017	0.198	0.089		P		P	None
38	S	ROOM 266	7/14/2017	0.174	0.035		P		P	None
39	S	ROOM 268	7/14/2017	0.166	0.033		P		P	None
40	S	ROOM 200C	7/14/2017	0.218	0.148		P		P	None
41	B	250 HALLWAY, GIRLS	7/14/2017	0.187	0.156		P		P	None
42	B	250 HALLWAY, BOYS	7/14/2017	0.171	0.126		P		P	None
43	S/B	ROOM 258	7/14/2017	0.192	0.065		P		P	None
44	S/B	ROOM 257	7/14/2017	0.185	0.056		P		P	None
45	S	ROOM 212	7/14/2017	0.147	0.152		P		P	None
46	B	350 HALLWAY, BOYS	7/14/2017	0.141	0.14		P		P	None
47	B	350 HALLWAY, GIRLS	7/14/2017	0.194	0.153		P		P	None
48	S	ROOM 361	7/14/2017	0.138	0.176		P		P	None

49	S/B	ROOM 361	7/14/2017	0.155	0.113		P		P	None
50	B	360 HALLWAY, GIRLS	7/14/2017	0.147	0.159		P		P	None
51	B	360 HALLWAY, BOYS	7/14/2017	0.156	0.161		P		P	None
52	S	ROOM 362	7/14/2017	0.113	0.079		P		P	None
53	S	ROOM 364	7/14/2017	0.134	0.139		P		P	None
54	S	ROOM 331, TEACHER'S LOUNGE	7/14/2017	0.138	0.185		P		P	None
55	S	ROOM 331, TEACHER'S LOUNGE	7/14/2017	0.146	0.139		P		P	None
56	B	370 HALLWAY, GIRLS	7/14/2017	0.159	0.152		P		P	None
57	B	370 HALLWAY, BOYS	7/14/2017	0.167	0.144		P		P	None
58	S/B	ROOM 374	7/14/2017	0.134	0.145		P		P	None
60	S	room 111H	7/14/2017	0.131	0.099		P		P	None

Table 5. Iron Test Results

Test Results (Iron/Fe, ppm)										
FIXTURE INFORMATION			Initial Sampling						Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 30s	Flush 2m	Pass/Fail	Status	Pass/Fail	Status
01	S	ROOM 110S						Sample		
02	S	ROOM 111D						Sample		
03	S	ROOM 111K						Sample		
04	B	1ST FLOOR, BY BOYS						Sample		
05	B	1ST FLOOR, BY GIRLS						Sample		
06	S/B	ROOM 154	7/14/2017			<0.05	P		P	None
07	S/B	ROOM 158						Sample		
08	S/B	ROOM 157						Sample		
09	S/B	ROOM 161						Sample		
10	B	1ST FLOOR HALLWAY, BY BOYS						Sample		
11	B	1ST FLOOR HALLWAY, BY GIRLS						Sample		
12	S	ROOM 162						Sample		
13	S	ROOM 164	7/14/2017			<0.05	P		P	None
14	S	ART ROOM 166						Sample		
15	S	ART ROOM 166						Sample		
16	S	KITCHEN, LEFT						Sample		
17	S	KITCHEN, RIGHT						Sample		
19	S	KITCHEN						Sample		
20	S	KITCHEN						Sample		
21	S	ROOM 136	7/14/2017			0.087	P		P	None
22	B	GYM, LEFT						Sample		
23	B	GYM, RIGHT						Sample		
24	B	COMMONS, LEFT						Sample		
25	B	COMMONS, RIGHT						Sample		
26	B	COMMONS, LEFT						Sample		
27	B	COMMONS, RIGHT	7/14/2017			<0.05	P		P	None
28	B	170 HALLWAY, GIRLS						Sample		
29	B	170 HALLWAY, BOYS						Sample		
30	B	270 HALLWAY, GIRLS						Sample		
31	B	270 HALLWAY, BOYS						Sample		
32	S	LIBRARY OFFICE, 220A						Sample		
33	S/B	ROOM 261						Sample		
34	B	260 HALLWAY, GIRLS	7/14/2017			<0.05	P		P	None
35	B	260 HALLWAY, BOYS						Sample		
36	S	TEACHER WORKROOM 262						Sample		
37	S	ROOM 264						Sample		
38	S	ROOM 266						Sample		
39	S	ROOM 268	7/14/2017			<0.05	P		P	None
40	S	ROOM 200C						Sample		
41	B	250 HALLWAY, GIRLS						Sample		
42	B	250 HALLWAY, BOYS						Sample		
43	S/B	ROOM 258						Sample		
44	S/B	ROOM 257						Sample		
45	S	ROOM 212	7/14/2017			<0.05	P		P	None
46	B	350 HALLWAY, BOYS						Sample		
47	B	350 HALLWAY, GIRLS						Sample		

48	S	ROOM 361						Sample		
49	S/B	ROOM 361						Sample		
50	B	360 HALLWAY, GIRLS						Sample		
51	B	360 HALLWAY, BOYS	7/14/2017			<0.05	P		P	None
52	S	ROOM 362						Sample		
53	S	ROOM 364						Sample		
54	S	ROOM 331, TEACHER'S LOUNGE						Sample		
55	S	ROOM 331, TEACHER'S LOUNGE						Sample		
56	B	370 HALLWAY, GIRLS						Sample		
57	B	370 HALLWAY, BOYS	7/14/2017	<0.05			P		P	None
58	S/B	ROOM 374						Sample		
60	S	room 111H						Sample		

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	same as location 21	Arsenic	14-Jul-17	2 ppb	P
00	SE	same as location 21	Cadmium	14-Jul-17	1 ppb	P
00	SE	same as location 21	Copper	14-Jul-17	0.014 ppm	P
00	SE	same as location 21	Iron	14-Jul-17	0.086 ppm	P
00	SE	same as location 21	Lead	14-Jul-17	1 ppb	P
00	SE	same as location 21	Total Coliforms	14-Jul-17	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.