

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
Queen Anne elementary school**

Updated August 15, 2019

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria: All locations meet the policy criteria.

Follow-up monitoring: Will be performed in school year 2021-2022

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S	kitchen (right) fixture	P	None	P	None	P	None	P	None	Yes
03	S/B	103, library	P	None	P	None	P	None			Yes
04	B	near girls lav (brick building), left	P	None	P	None	P	None	P	None	Yes
05	S/B	105, classroom 9	P	None	P	None	P	None	P	None	Yes
06	B	near girls lav (brick building), middle	P	None	P	None	P	None	P	None	Yes
07	S	106B staff Lounge, left	P	None	P	None	P	None	P	None	Yes
08	S/B	136, classroom 16	P	None	P	None	P	None			Yes
09	B	near girls lav (brick building), right	P	None	P	None	P	None	P	None	Yes
10	S/B	137, classroom 15	P	None	P	None	P	None			Yes
12	S/B	138, classroom 14	P	None	P	None	P	None	P	None	Yes
13	B	near boys lav (brick building), left	P	None	P	None	P	None	P	None	Yes
14	S/B	140, classroom 13	P	None	P	None	P	None	P	None	Yes
15	B	near boys lav (brick building), middle	P	None	P	None	P	None			Yes
16	B	near boys lav (brick building), right	P	None	P	None	P	None			Yes
17	S/B	307, classroom 7	P	None	P	None	P	None			Yes
19	S/B	309, classroom 6	P	None	P	None	P	None	P	None	Yes
20	S/B	205, classroom 4	P	None	P	None	P	None	P	None	Yes
21	S/B	210, classroom 2	P	None	P	None	P	None	P	None	Yes
22	S/B	109, woodbuilding basement,	P	None	P	None	P	None	P	None	Yes
23	S/B	142, classroom 12	P	None	P	None	P	None	P	None	Yes
31	B	2nd floor hallway (wood building)	P	None	P	None	P	None	P	None	Yes
32	S/B	305, classroom 8	P	None	P	None	P	None			Yes
33	S/B	304, classroom 5	P	None	P	None	P	None			Yes
34	B/S	1/2 floor landing, office 207 (wood building)	P	None	P	None	P	None	P	None	Yes
35	B	first floor hall (wood building)	P	None	P	None	P	None			Yes
36	S/B	204, classroom 3	P	None	P	None	P	None			Yes
37	S/B	203, classroom 1	P	None	P	None	P	None	P	None	Yes
42	S	Kitchen in brick bldg left	P	None	P	None	P	None	P	None	Yes
43	S	Kitchen in brick bldg middle	P	None	P	None	P	None	P	None	Yes
44	S	kitchen, south wall	P	None	P	None	P	None			Yes
45	S	308, Teacher's lounge	P	None	P	None	P	None	P	None	Yes
46	S	Portable P-3	P	None	P	None	P	None			Yes
49	S	111, basement South (wood building) left	P	None	P	None	P	None			Yes
50	S	111,basement South (wood building) right	P	None	P	None	P	None			Yes
51	S	106B staff Lounge, right	P	None	P	None	P	None			Yes
52	B	bottle filler	P	None	P	None	P	None			Yes
60	S	101C, NURSE OFFCE	P	None	P	None	P	None			Yes
61	S	101E, LOUNGE	P	None	P	None	P	None			Yes
62	B	DRINKING FOUNTAIN, OUTSIDE GYM, LEFT	P	None	P	None	P	None			Yes
63	B	DRINKING FOUNTAIN, OUTSIDE GYM, RIGHT	P	None	P	None	P	None			Yes
64	BF	BOTTLE FILLER, OUTSIDE GYM	P	None	P	None	P	None			Yes
65	S/B	ROOM 113	P	None	P	None	P	None			Yes
66	S/B	ROOM 125	P	None	P	None	P	None			Yes
67	S/B	ROOM 127	P	None	P	None	P	None			Yes
68	S/B	ROOM 129	P	None	P	None	P	None			Yes
69	S/B	ROOM 131	P	None	P	None	P	None			Yes
70	S/B	ROOM 134	P	None	P	None	P	None			Yes
71	S/B	ROOM 136	P	None	P	None	P	None			Yes
72	S/B	ROOM 138	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			8/31/2011			7/17/2014			1/31/2018			8/6/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	kitchen (right) fixture	32	1		4	<1	P	3	<1	P				P	None
03	S/B	103, library	4	1	P	1	<1	P	<1	<1	P				P	None
04	B	near girls lav (brick building), left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
05	S/B	105, classroom 9	4	1	P	1	<1	P	<1	<1	P				P	None
06	B	near girls lav (brick building), middle	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
07	S	106B staff Lounge, left	6	4	P	2	<1	P	<1	<1	P				P	None
08	S/B	136, classroom 16	7	<1	P	<1	<1	P	<1	<1	P				P	None
09	B	near girls lav (brick building), right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
10	S/B	137, classroom 15	8	1	P	2	<1	P	<1	<1	P				P	None
12	S/B	138, classroom 14	8	1	P	1	<1	P	<1	<1	P				P	None
13	B	near boys lav (brick building), left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
14	S/B	140, classroom 13	8	<1	P	1	<1	P	<1	<1	P				P	None
15	B	near boys lav (brick building), middle	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	B	near boys lav (brick building), right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
17	S/B	307, classroom 7	5	1	P	2	<1	P	<1	<1	P				P	None
19	S/B	309, classroom 6	6	2	P	2	3	P	<1	<1	P				P	None
20	S/B	205, classroom 4	3	1	P	2	<1	P	<1	<1	P				P	None
21	S/B	210, classroom 2	7	7	P	2	<1	P	<1	<1	P				P	None
22	S/B	109, woodbuilding basement,	8	<1	P	<1	<1	P	<1	<1	P				P	None
23	S/B	142, classroom 12	6	<1	P	1	<1	P	<1	<1	P				P	None
31	B	2nd floor hallway (wood building)	4	1	P	3	<1	P	1	<1	P				P	None
32	S/B	305, classroom 8	2	<1	P	<1	<1	P	<1	<1	P				P	None
33	S/B	304, classroom 5	2	1	P	<1	<1	P	<1	<1	P				P	None
34	B/S	1/2 floor landing, office 207 (wood building)	<1	<1	P	<1	<1	P	<1	<1	P				P	None
35	B	first floor hall (wood building)	<1	<1	P	<1	<1	P	<1	<1	P				P	None
36	S/B	204, classroom 3	4	2	P	3	<1	P	<1	<1	P				P	None
37	S/B	203, classroom 1	4	<1	P	<1	<1	P	<1	1	P				P	None
42	S	Kitchen in brick bldg left	7	<1	P	4	<1	P	<1	<1	P				P	None
43	S	Kitchen in brick bldg middle	36	1		4	<1	P	1	<1	P				P	None
44	S	kitchen, south wall	23	1		3	<1	P	2	<1	P				P	None
45	S	308, Teacher's lounge	21	2		6	1	P	<1	<1	P				P	None
46	S	Portable P-3	3	1	P										P	None
49	S	111, basement South (wood building) left	7	2	P	1	<1	P	<1	<1	P				P	None
50	S	111,basement South (wood building) right	8	1	P	1	<1	P	<1	<1	P				P	None
51	S	106B staff Lounge, right	5	4	P	1	1	P	<1	<1	P				P	None
52	B	bottle filler							<1	<1	P				P	None
60	S	101C, NURSE OFFCE										<1	<1	P	P	None
61	S	101E, LOUNGE										<1	<1	P	P	None
62	B	DRINKING FOUNTAIN, OUTSIDE GYM, LEFT										<1	<1	P	P	None
63	B	DRINKING FOUNTAIN, OUTSIDE GYM, RIGHT										<1	<1	P	P	None
64	BF	BOTTLE FILLER, OUTSIDE GYM										<1	<1	P	P	None
65	S/B	ROOM 113										<1	2	P	P	None
66	S/B	ROOM 125										<1	2	P	P	None
67	S/B	ROOM 127										<1	<1	P	P	None
68	S/B	ROOM 129										<1	<1	P	P	None
69	S/B	ROOM 131										<1	<1	P	P	None
70	S/B	ROOM 134										<1	<1	P	P	None
71	S/B	ROOM 136										<1	<1	P	P	None
72	S/B	ROOM 138										<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			8/31/2011			7/17/2014			1/31/2018			8/6/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	kitchen (right) fixture	3	<1	P	<1	<1	P	<1	<1	P				P	None
03	S/B	103, library	<1	<1	P	<1	<1	P	<1	<1	P				P	None
04	B	near girls lav (brick building), left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
05	S/B	105, classroom 9	<1	<1	P	<1	<1	P	<1	<1	P				P	None
06	B	near girls lav (brick building), middle	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
07	S	106B staff Lounge, left	<1	<1	P	<1	<1	P	<1	<1	P				P	None
08	S/B	136, classroom 16	<1	<1	P	<1	<1	P	<1	<1	P				P	None
09	B	near girls lav (brick building), right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
10	S/B	137, classroom 15	<1	<1	P	<1	<1	P	<1	<1	P				P	None
12	S/B	138, classroom 14	<1	<1	P	<1	<1	P	<1	<1	P				P	None
13	B	near boys lav (brick building), left	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
14	S/B	140, classroom 13	<1	<1	P	<1	<1	P	<1	<1	P				P	None
15	B	near boys lav (brick building), middle	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
16	B	near boys lav (brick building), right	<1	<1	P	<1	<1	P	<1	<1	P	<1	<1	P	P	None
17	S/B	307, classroom 7	<1	<1	P	<1	<1	P	<1	<1	P				P	None
19	S/B	309, classroom 6	<1	<1	P	<1	<1	P	<1	<1	P				P	None
20	S/B	205, classroom 4	<1	<1	P	<1	<1	P	<1	<1	P				P	None
21	S/B	210, classroom 2	<1	<1	P	<1	<1	P	<1	<1	P				P	None
22	S/B	109, woodbuilding basement,	<1	<1	P	<1	<1	P	<1	<1	P				P	None
23	S/B	142, classroom 12	<1	<1	P	<1	<1	P	<1	<1	P				P	None
31	B	2nd floor hallway (wood building)	<1	<1	P	<1	<1	P	<1	<1	P				P	None
32	S/B	305, classroom 8	<1	<1	P	<1	<1	P	<1	<1	P				P	None
33	S/B	304, classroom 5	<1	<1	P	<1	<1	P	<1	<1	P				P	None
34	B/S	1/2 floor landing, office 207 (wood building)	<1	<1	P	<1	<1	P	<1	<1	P				P	None
35	B	first floor hall (wood building)	<1	<1	P	<1	<1	P	<1	<1	P				P	None
36	S/B	204, classroom 3	<1	<1	P	<1	<1	P	<1	<1	P				P	None
37	S/B	203, classroom 1	<1	<1	P	<1	<1	P	<1	<1	P				P	None
42	S	Kitchen in brick bldg left	<1	<1	P	<1	<1	P	<1	<1	P				P	None
43	S	Kitchen in brick bldg middle	2	<1	P	<1	<1	P	<1	<1	P				P	None
44	S	kitchen, south wall	<1	<1	P	<1	<1	P	<1	<1	P				P	None
45	S	308, Teacher's lounge	<1	<1	P	<1	<1	P	<1	<1	P				P	None
46	S	Portable P-3	<1	<1	P										P	None
49	S	111, basement South (wood building) left	<1	<1	P	<1	<1	P	<1	<1	P				P	None
50	S	111,basement South (wood building) right	<1	<1	P	<1	<1	P	<1	<1	P				P	None
51	S	106B staff Lounge, right	<1	<1	P	<1	<1	P	<1	<1	P				P	None
52	B	bottle filler							<1	<1	P				P	None
60	S	101C, NURSE OFFCE										<1	<1	P	P	None
61	S	101E, LOUNGE										<1	<1	P	P	None
62	B	DRINKING FOUNTAIN, OUTSIDE GYM, LEFT										<1	<1	P	P	None
63	B	DRINKING FOUNTAIN, OUTSIDE GYM, RIGHT										<1	<1	P	P	None
64	BF	BOTTLE FILLER, OUTSIDE GYM										<1	<1	P	P	None
65	S/B	ROOM 113										<1	<1	P	P	None
66	S/B	ROOM 125										<1	<1	P	P	None
67	S/B	ROOM 127										<1	<1	P	P	None
68	S/B	ROOM 129										<1	<1	P	P	None
69	S/B	ROOM 131										<1	<1	P	P	None
70	S/B	ROOM 134										<1	<1	P	P	None
71	S/B	ROOM 136										<1	<1	P	P	None
72	S/B	ROOM 138										<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			8/31/2011			7/17/2014			1/31/2018			8/6/2019			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	kitchen (right) fixture	0.324	0.372	P	0.198	0.133	P	0.197	0.129	P				P	None
03	S/B	103, library	0.392	0.4	P	0.197	0.223	P	0.262	0.258	P				P	None
04	B	near girls lav (brick building), left	0.008	0.008	P	<0.002	<0.002	P	0.004	0.005	P	0.03	0.022	P	P	None
05	S/B	105, classroom 9	0.4	0.513	P	0.184	0.256	P	0.183	0.283	P				P	None
06	B	near girls lav (brick building), middle	0.004	0.015	P	<0.002	<0.002	P	<0.002	0.003	P	0.018	0.018	P	P	None
07	S	106B staff Lounge, left	0.556	0.563	P	0.228	0.268	P	0.226	0.286	P				P	None
08	S/B	136, classroom 16	0.53	0.402	P	0.218	0.287	P	0.261	0.348	P				P	None
09	B	near girls lav (brick building), right	0.01	0.007	P	<0.002	<0.002	P	0.003	0.005	P	0.018	0.019	P	P	None
10	S/B	137, classroom 15	0.458	0.429	P	0.246	0.298	P	0.266	0.234	P				P	None
12	S/B	138, classroom 14	0.514	0.47	P	0.238	0.333	P	0.245	0.268	P				P	None
13	B	near boys lav (brick building), left	0.003	0.003	P	<0.002	<0.002	P	<0.002	0.002	P	0.135	0.009	P	P	None
14	S/B	140, classroom 13	0.561	0.512	P	0.23	0.156	P	0.25	0.273	P				P	None
15	B	near boys lav (brick building), middle	<0.002	0.006	P	<0.002	<0.002	P	<0.002	<0.002	P	0.012	0.011	P	P	None
16	B	near boys lav (brick building), right	0.005	<0.002	P	<0.002	<0.002	P	<0.002	0.003	P	0.016	0.013	P	P	None
17	S/B	307, classroom 7	0.368	0.517	P	0.271	0.246	P	0.2	0.205	P				P	None
19	S/B	309, classroom 6	0.346	0.447	P	0.222	0.261	P	0.155	0.174	P				P	None
20	S/B	205, classroom 4	0.337	0.425	P	0.227	0.264	P	0.235	0.232	P				P	None
21	S/B	210, classroom 2	0.338	0.347	P	0.204	0.254	P	0.178	0.204	P				P	None
22	S/B	109, woodbuilding basement,	0.334	0.358	P	0.21	0.233	P	0.213	0.245	P				P	None
23	S/B	142, classroom 12	0.426	0.51	P	0.182	0.224	P	0.21	0.232	P				P	None
31	B	2nd floor hallway (wood building)	0.285	0.311	P	0.245	0.245	P	0.224	0.249	P				P	None
32	S/B	305, classroom 8	0.226	0.492	P	0.221	0.274	P	0.226	0.243	P				P	None
33	S/B	304, classroom 5	0.342	0.34	P	0.197	0.148	P	0.23	0.254	P				P	None
34	B/S	1/2 floor landing, office 207 (wood building)	0.03	0.003	P	0.009	<0.002	P	0.004	<0.002	P				P	None
35	B	first floor hall (wood building)	0.268	0.418	P	0.239	0.237	P	0.211	0.213	P				P	None
36	S/B	204, classroom 3	0.369	0.282	P	0.245	0.243	P	0.216	0.249	P				P	None
37	S/B	203, classroom 1	0.294	0.231	P	0.217	0.191	P	0.12	0.085	P				P	None
42	S	Kitchen in brick bldg left	0.725	0.361	P	0.124	0.137	P	0.167	0.123	P				P	None
43	S	Kitchen in brick bldg middle	0.337	0.356	P	0.194	0.131	P	0.15	0.126	P				P	None
44	S	kitchen, south wall	0.541	0.422	P	0.26	0.139	P	0.45	0.137	P				P	None
45	S	308, Teacher's lounge	0.295	0.546	P	0.227	0.336	P	0.208	0.184	P				P	None
46	S	Portable P-3	0.157	0.231	P										P	None
49	S	111, basement South (wood building) left	0.577	0.513	P	0.366	0.322	P	0.247	0.234	P				P	None
50	S	111,basement South (wood building) right	0.561	0.429	P	0.326	0.256	P	0.198	0.165	P				P	None
51	S	106B staff Lounge, right	0.483	0.48	P	0.249	0.165	P	0.202	0.186	P				P	None
52	B	bottle filler							0.27	0.29	P				P	None
60	S	101C, NURSE OFFCE										0.445	0.516	P	P	None
61	S	101E, LOUNGE										0.204	0.264	P	P	None
62	B	DRINKING FOUNTAIN, OUTSIDE GYM, LEFT										0.292	0.145	P	P	None
63	B	DRINKING FOUNTAIN, OUTSIDE GYM, RIGHT										0.057	0.056	P	P	None
64	BF	BOTTLE FILLER, OUTSIDE GYM										0.067	0.044	P	P	None
65	S/B	ROOM 113										0.386	0.387	P	P	None
66	S/B	ROOM 125										0.296	0.444	P	P	None
67	S/B	ROOM 127										0.302	0.371	P	P	None
68	S/B	ROOM 129										0.362	0.326	P	P	None
69	S/B	ROOM 131										0.298	0.323	P	P	None
70	S/B	ROOM 134										0.305	0.322	P	P	None
71	S/B	ROOM 136										0.24	0.275	P	P	None
72	S/B	ROOM 138										0.288	0.271	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			8/31/2011		7/17/2014		1/31/2018		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	S	kitchen (right) fixture							P	None
03	S/B	103, library								
04	B	near girls lav (brick building), left							P	None
05	S/B	105, classroom 9	0.14	P					P	None
06	B	near girls lav (brick building), middle			<0.05	P			P	None
07	S	106B staff Lounge, left					0.057	P	P	None
08	S/B	136, classroom 16								
09	B	near girls lav (brick building), right							P	None
10	S/B	137, classroom 15								
12	S/B	138, classroom 14	0.069	P					P	None
13	B	near boys lav (brick building), left			<0.05	P			P	None
14	S/B	140, classroom 13					<0.05	P	P	None
15	B	near boys lav (brick building), middle								
16	B	near boys lav (brick building), right								
17	S/B	307, classroom 7								
19	S/B	309, classroom 6	0.096	P					P	None
20	S/B	205, classroom 4			<0.05	P			P	None
21	S/B	210, classroom 2			<0.05	P			P	None
22	S/B	109, woodbuilding basement,	<0.05	P			<0.05	P	P	None
23	S/B	142, classroom 12			<0.05	P			P	None
31	B	2nd floor hallway (wood building)					0.057	P	P	None
32	S/B	305, classroom 8								
33	S/B	304, classroom 5								
34	B/S	1/2 floor landing, office 207 (wood building)							P	None
35	B	first floor hall (wood building)								
36	S/B	204, classroom 3								
37	S/B	203, classroom 1	0.053	P					P	None
42	S	Kitchen in brick bldg left			<0.05	P			P	None
43	S	Kitchen in brick bldg middle					0.05	P	P	None
44	S	kitchen, south wall								
45	S	308, Teacher's lounge							P	None
46	S	Portable P-3								
49	S	111, basement South (wood building) left								
50	S	111,basement South (wood building) right								
51	S	106B staff Lounge, right								
52	B	bottle filler								
60	S	101C, NURSE OFFCE								
61	S	101E, LOUNGE								
62	B	DRINKING FOUNTAIN, OUTSIDE GYM, LEFT								
63	B	DRINKING FOUNTAIN, OUTSIDE GYM, RIGHT								
64	BF	BOTTLE FILLER, OUTSIDE GYM								
65	S/B	ROOM 113								
66	S/B	ROOM 125								
67	S/B	ROOM 127								
68	S/B	ROOM 129								
69	S/B	ROOM 131								
70	S/B	ROOM 134								
71	S/B	ROOM 136								
72	S/B	ROOM 138								

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	3/4 exterior hose bib	Arsenic	31-Jan-18	2 ppb	P
00	SE	3/4 exterior hose bib	Cadmium	31-Jan-18	1 ppb	P
00	SE	3/4 exterior hose bib	Copper	31-Jan-18	0.184 ppm	P
00	SE	3/4 exterior hose bib	E coli	25-Aug-04	<1 Colonies	P
00	SE	3/4 exterior hose bib	Iron	31-Jan-18	<0.05 ppm	P
00	SE	3/4 exterior hose bib	Lead	31-Jan-18	1 ppb	P
00	SE	3/4 exterior hose bib	Total Coliforms	31-Aug-11	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.