

Seattle Public Schools
Drinking Water Quality Program

Results of Water Quality Testing
for
Van Asselt Elementary school

Updated September 24, 2018

General Information:

Plumbing piping materials: galvanized steel

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Status:

Policy Criteria: All sources in the new building meet the policy criteria.

The Old (wood) building is not being used and was not tested, all fixtures in the Old building will be disabled or post signs.

Follow-up monitoring: Will be performed in school year 2021-2022.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			CURRENT STATUS								
			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	B	hallway, by room 20	P	None	P	None	P	None	P	None	Yes
02	B	hallway. By room 17	P	None	P	None	P	None	P	None	Yes
03	B	hallway, by room 14	P	None	P	None	P	None	P	None	Yes
04	B	hallway, by library	P	None	P	None	P	None	P	None	Yes
05	B	hallway, by room 10	P	None	P	None	P	None	P	None	Yes
06	B	hallway near office	P	None	P	None	P	None	P	None	Yes
07	B	hallway near office	P	None	P	None	P	None	P	None	Yes
08	B	next to gym boy's restroom	P	None	P	None	P	None	P	None	Yes
09	B	next to gym girl's restroom	P	None	P	None	P	None			Yes
10	B	hallway, by room 8, left	P	None	P	None	P	None	P	None	Yes
11	B	hallway, by room 8, right	P	None	P	None	P	None			Yes
12	B	hallway (top stairs), by room 6	P	None	P	None	P	None			Yes
13	B	hallway, by room 7	P	None	P	None	P	None	P	None	Yes
14	B	room # 2	P	None	P	None	P	None	P	None	Yes
15	B	hallway, by room 3	P	None	P	None	P	None	P	None	Yes
16	B	room # 1	P	None	P	None	P	None	P	None	Yes
17	B	old bldg basement room 22		OS		Pending	P	None	P	None	#NAME?
18	B	old bldg main floor	P	None	P	None	P	None	P	None	Yes
20	S	nurse's office, old bldg. Resource		Pending	P	None	P	None	P	None	#NAME?
21	S	kitchen (rear wall), East wall, left	P	None	P	None	P	None	P	None	Yes
26	S	Brick Bld, Rm 1 (West on South Wall), right	P	None	P	None	P	None	P	None	Yes
27	S	Brick Bld, Rm 2 (South Wall)	P	None	P	None	P	None	P	None	Yes
28	S	Brick Bld, Rm 2 (East on North Wall), right	P	None	P	None	P	None	P	None	Yes
29	S	Brick Bld, Rm 2 (West on North Wall), left	P	None	P	None	P	None	P	None	Yes
30	S	Brick Bld, Rm 3, North Wall	P	None	P	None	P	None	P	None	Yes
31	S	Brick Bld, Rm 4, South Wall	P	None	P	None	P	None	P	None	Yes
32	S	Brick Bld, Rm 5, North Wall	P	None	P	None	P	None	P	None	Yes
33	S	Brick Bld, Rm 6, South Wall	P	None	P	None	P	None	P	None	Yes
34	S	Brick Bld, Rm 7, North Wall	P	None	P	None	P	None	P	None	Yes
35	S	Brick Bld, Rm 8, South Wall	P	None	P	None	P	None	P	None	Yes
36	S	Brick Bld, Nurses Office, West Wall	P	None	P	None	P	None	P	None	Yes
37	S	Brick Bld, Faculty Lounge, North Wall	P	None	P	None	P	None	P	None	Yes
38	S	Brick Bld, Library, North Wall	P	None	P	None	P	None	P	None	Yes
39	S	Brick Bld, Rm 10, South Wall	P	None	P	None	P	None	P	None	Yes
40	S	Brick Bld, Rm 12, South Wall	P	None	P	None	P	None	P	None	Yes
41	S	Brick Bld, Rm 13, North Wall	P	None	P	None	P	None	P	None	Yes
42	S	Brick Bld, Rm 14, South Wall	P	None	P	None	P	None	P	None	Yes
43	S	Brick Bld, Rm 15, North Wall	P	None	P	None	P	None	P	None	Yes
44	S	Brick Bld, Rm 16, South Wall	P	None	P	None	P	None	P	None	Yes
45	S	Brick Bld, Rm 17, North Wall	P	None	P	None	P	None	P	None	Yes
46	S	Brick Bld, Rm 18, South Wall	P	None	P	None	P	None	P	None	Yes
47	S	Brick Bld, Rm 19, North Wall	P	None	P	None	P	None	P	None	Yes
48	S	Brick Bld, Rm 20, South Wall	P	None	P	None			P	None	Yes
49	B	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	P	None	P	None	P	None	P	None	Yes
50	S	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	P	None	P	None	P	None	P	None	Yes

51	S	Old (Wood) Bld, Rm 23 (Main Level), West Closet	P	None	P	None	P	None	P	None	Yes
52	S	Old (Wood) Bld, Rm 24 (Main Level), West Closet	P	None	P	None	P	None	P	None	Yes
53	S	Old (Wood) Bld, Rm 25 (Top Level), West Closet		Pending	P	None	P	None	P	None	#NAME?
54	S	Old (Wood) Bld, Rm 26 (Top Level), West Closet	P	None	P	None	P	None	P	None	Yes
56	S	kitchen (rear wall), East wall, right	P	None	P	None	P	None	P	None	Yes
58	S	kitchen, handwash	P	None	P	None	P	None			Yes
59	S	main office	P	None	P	None	P	None	P	None	Yes
65	S	room 1, kitchenette, left	P	None	P	None	P	None			Yes
66	S	room 1, kitchenette, middle	P	None	P	None	P	None			Yes
67	S	room 1, kitchenette, right	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

FIXTURE INFORMATION			6/28/2008			8/22/2008			9/12/2014			10/7/2014			1/21/2015			10/8/2015			9/11/2018			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
01	B	hallway, by room 20	<1	<1	P				1	<1	P										<1	<1	P	P	None
02	B	hallway. By room 17				<1	<1	P	2	<1	P										<1	<1	P	P	None
03	B	hallway, by room 14	<1	<1	P				1	<1	P						2	2	P		<1	<1	P	P	None
04	B	hallway, by library				<1	<1	P	3	<1	P										<1	<1	P	P	None
05	B	hallway, by room 10	<1	1	P				<1	<1	P										1	<1	P	P	None
06	B	hallway near office	<1	<1	P				1	<1	P										<1	<1	P	P	None
07	B	hallway near office	<1	<1	P				2	<1	P										1	<1	P	P	None
08	B	next to gym boy's restroom				<1	<1	P	4	2	P										1	<1	P	P	None
09	B	next to gym girl's restroom				4	<1	P	1	1	P										2	<1	P	P	None
10	B	hallway, by room 8, left	<1	<1	P				<1	1	P										<1	<1	P	P	None
11	B	hallway, by room 8, right							4	2	P										3	1	P	P	None
12	B	hallway (top stairs), by room 6	<1	1	P				3	1	P										<1	<1	P	P	None
13	B	hallway, by room 7	<1	<1	P				1	2	P										<1	<1	P	P	None
14	B	room # 2	<1	<1	P				<1	<1	P										<1	<1	P	P	None
15	B	hallway, by room 3				3	<1	P	2	1	P										2	<1	P	P	None
16	B	room # 1	<1	<1	P				5	2	P										2	<1	P	P	None
17	B	old bldg basement room 22	27	<1																					OS
18	B	old bldg main floor	<1	<1	P																			P	None
20	S	nurse's office, old bldg. Resource	15	2																					Pending
21	S	kitchen (rear wall), East wall, left	13	<1					13	8		22	2								5	<1	P	P	None
24	S	Brick Bld, Rm 1 (North Wall)	<1	<1	P				7	3	P										3	<1	P	P	None
27	S	Brick Bld, Rm 2 (South Wall)	1	<1	P				1	<1	P										<1	<1	P	P	None
28	S	Brick Bld, Rm 2 (East on North Wall), right	1	<1	P				4	<1	P										<1	<1	P	P	None
29	S	Brick Bld, Rm 2 (West on North Wall), left	2	<1	P				3	<1	P										<1	<1	P	P	None
30	S	Brick Bld, Rm 3, North Wall	2	<1	P				4	<1	P										<1	<1	P	P	None
31	S	Brick Bld, Rm 4, South Wall	2	<1	P				4	<1	P										3	<1	P	P	None
32	S	Brick Bld, Rm 5, North Wall	1	<1	P				3	<1	P										<1	<1	P	P	None
33	S	Brick Bld, Rm 6, South Wall	1	<1	P				3	<1	P										<1	<1	P	P	None
34	S	Brick Bld, Rm 7, North Wall	3	<1	P				3	<1	P										2	<1	P	P	None
35	S	Brick Bld, Rm 8, South Wall	4	<1	P				12	1		6	<1	P							4	<1	P	P	None
36	S	Brick Bld, Nurses Office, West Wall	<1	<1	P				2	<1	P										<1	<1	P	P	None
37	S	Brick Bld, Faculty Lounge, North Wall	<1	<1	P										1	<1	P				<1	<1	P	P	None
38	S	Brick Bld, Library, North Wall	2	<1	P				13	<1		12	10								2	2	P	P	None
39	S	Brick Bld, Rm 10, South Wall	<1	<1	P				9	<1	P										<1	<1	P	P	None
40	S	Brick Bld, Rm 12, South Wall	<1	<1	P				38	9											<1	<1	P	P	None
41	S	Brick Bld, Rm 13, North Wall	<1	<1	P				6	<1	P										<1	<1	P	P	None
42	S	Brick Bld, Rm 14, South Wall	2	<1	P				1	<1	P										<1	<1	P	P	None
43	S	Brick Bld, Rm 15, North Wall	<1	<1	P				5	<1	P										2	<1	P	P	None
44	S	Brick Bld, Rm 16, South Wall	6	<1	P				9	<1	P										3	<1	P	P	None
45	S	Brick Bld, Rm 17, North Wall	1	<1	P				3	<1	P										1	<1	P	P	None
46	S	Brick Bld, Rm 18, South Wall	<1	<1	P				4	1	P										<1	<1	P	P	None
47	S	Brick Bld, Rm 19, North Wall	1	<1	P				27	36		7	4	P							7	<1	P	P	None
48	S	Brick Bld, Rm 20, South Wall	<1	<1	P																9	<1	P	P	None
49	B	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	<1	<1	P																			P	None
50	S	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	<1	1	P																			P	None
51	S	Old (Wood) Bld, Rm 23 (Main Level), West Closet	5	<1	P																			P	None
52	S	Old (Wood) Bld, Rm 24 (Main Level), West Closet	5	1	P																			P	None
53	S	Old (Wood) Bld, Rm 25 (Top Level), West Closet	14	2																					Pending

54	S	Old (Wood) Bld, Rm 26 (Top Level), West Closet	3	2	P																P	None			
56	S	kitchen (rear wall), East wall, right	6	1	P			18	2		12	6									3	<1	P	P	None
58	S	kitchen, handwash	2	<1	P																1	1	P	P	None
59	S	main office	<1	<1	P			8	<1	P											1	1	P	P	None
65	S	room 1, kitchenette, left						5	2	P											<1	<1	P	P	None
66	S	room 1, kitchenette, middle						7	2	P											3	<1	P	P	None
67	S	room 1, kitchenette, right						5	2	P											<1	<1	P	P	None

Table 3. Cadmium Test Results

FIXTURE INFORMATION			6/28/2008			8/22/2008			9/12/2014			1/21/2015			10/8/2015			9/11/2018			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	B	hallway, by room 20	<1	<1	P				<1	<1	P							<1	<1	P	P	None
02	B	hallway. By room 17				<1	<1	P	<1	<1	P							<1	<1	P	P	None
03	B	hallway, by room 14	<1	<1	P				<1	<1	P				<1	<1	P	<1	<1	P	P	None
04	B	hallway, by library				<1	<1	P	<1	<1	P							<1	<1	P	P	None
05	B	hallway, by room 10	<1	<1	P				<1	<1	P							<1	<1	P	P	None
06	B	hallway near office	<1	<1	P				<1	<1	P							<1	<1	P	P	None
07	B	hallway near office	<1	<1	P				<1	<1	P							<1	<1	P	P	None
08	B	next to gym boy's restroom				<1	<1	P	<1	<1	P							<1	<1	P	P	None
09	B	next to gym girl's restroom				<1	<1	P	<1	<1	P							<1	<1	P	P	None
10	B	hallway, by room 8, left	<1	<1	P				<1	<1	P							<1	<1	P	P	None
11	B	hallway, by room 8, right							<1	<1	P							<1	<1	P	P	None
12	B	hallway (top stairs), by room 6	<1	<1	P				<1	<1	P							<1	<1	P	P	None
13	B	hallway, by room 7	<1	<1	P				<1	<1	P							<1	<1	P	P	None
14	B	room # 2	<1	<1	P				<1	<1	P							<1	<1	P	P	None
15	B	hallway, by room 3				<1	<1	P	<1	<1	P							<1	<1	P	P	None
16	B	room # 1	<1	<1	P				<1	<1	P							<1	<1	P	P	None
17	B	old bldg basement room 22	9	<1																		Pending
18	B	old bldg main floor	<1	<1	P																	P None
20	S	nurse's office, old bldg. Resource	5	1	P																	P None
21	S	kitchen (rear wall), East wall, left	<1	<1	P				<1	<1	P							<1	<1	P	P	None
24	S	Brick Bld, Rm 1 (North Wall)	<1	<1	P				<1	<1	P							<1	<1	P	P	None
27	S	Brick Bld, Rm 2 (South Wall)	<1	<1	P				<1	<1	P							<1	<1	P	P	None
28	S	Brick Bld, Rm 2 (East on North Wall), right	<1	<1	P				<1	<1	P							<1	<1	P	P	None
29	S	Brick Bld, Rm 2 (West on North Wall), left	<1	<1	P				<1	<1	P							<1	<1	P	P	None
30	S	Brick Bld, Rm 3, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
31	S	Brick Bld, Rm 4, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
32	S	Brick Bld, Rm 5, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
33	S	Brick Bld, Rm 6, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
34	S	Brick Bld, Rm 7, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
35	S	Brick Bld, Rm 8, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
36	S	Brick Bld, Nurses Office, West Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
37	S	Brick Bld, Faculty Lounge, North Wall	<1	<1	P							<1	<1	P				<1	<1	P	P	None
38	S	Brick Bld, Library, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
39	S	Brick Bld, Rm 10, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
40	S	Brick Bld, Rm 12, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
41	S	Brick Bld, Rm 13, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
42	S	Brick Bld, Rm 14, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
43	S	Brick Bld, Rm 15, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
44	S	Brick Bld, Rm 16, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
45	S	Brick Bld, Rm 17, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
46	S	Brick Bld, Rm 18, South Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
47	S	Brick Bld, Rm 19, North Wall	<1	<1	P				<1	<1	P							<1	<1	P	P	None
48	S	Brick Bld, Rm 20, South Wall	<1	<1	P													<1	<1	P	P	None
49	B	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	<1	<1	P																	P None
50	S	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	<1	1	P																	P None
51	S	Old (Wood) Bld, Rm 23 (Main Level), West Closet	<1	<1	P																	P None
52	S	Old (Wood) Bld, Rm 24 (Main Level), West Closet	<1	<1	P																	P None

53	S	Old (Wood) Bld, Rm 25 (Top Level), West Closet	2	<1	P															P	None	
54	S	Old (Wood) Bld, Rm 26 (Top Level), West Closet	1	<1	P															P	None	
56	S	kitchen (rear wall), East wall, right	<1	<1	P				<1	<1	P							<1	<1	P	P	None
58	S	kitchen, handwash	<1	<1	P													<1	<1	P	P	None
59	S	main office	<1	<1	P				<1	<1	P							<1	<1	P	P	None
65	S	room 1, kitchenette, left							<1	<1	P							<1	<1	P	P	None
66	S	room 1, kitchenette, middle							<1	<1	P							<1	<1	P	P	None
67	S	room 1, kitchenette, right							<1	<1	P							<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			6/28/2008			8/22/2008			9/12/2014			1/21/2015			10/8/2015			9/11/2018			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	1st Draw	Flush 30s	Pass /Fail	Pass/Fail	Status
01	B	hallway, by room 20	0.003	0.002	P				0.14	0.135	P							0.344	0.338	P	P	None
02	B	hallway. By room 17				0.1	0.052	P	0.161	0.132	P							0.308	0.28	P	P	None
03	B	hallway, by room 14	0.003	0.002	P				0.15	0.15	P				0.261	0.239	P	0.207	0.209	P	P	None
04	B	hallway, by library				0.145	0.034	P	1.25	0.169	P							0.268	0.233	P	P	None
05	B	hallway, by room 10	0.257	0.075	P				0.132	0.114	P							0.332	0.278	P	P	None
06	B	hallway near office	0.075	0.059	P				0.149	0.133	P							0.266	0.265	P	P	None
07	B	hallway near office	0.076	0.057	P				0.136	0.118	P							0.282	0.27	P	P	None
08	B	next to gym boy's restroom				<0.002	<0.002	P	0.251	0.191	P							0.212	0.247	P	P	None
09	B	next to gym girl's restroom				0.189	0.026	P	0.047	0.134	P							0.182	0.27	P	P	None
10	B	hallway, by room 8, left	0.006	0.005	P				0.12	0.11	P							0.11	0.08	P	P	None
11	B	hallway, by room 8, right							0.116	0.116	P							0.159	0.076	P	P	None
12	B	hallway (top stairs), by room 6	0.005	0.006	P				0.092	0.084	P							0.05	0.039	P	P	None
13	B	hallway, by room 7	0.008	0.006	P				0.062	0.104	P							0.17	0.168	P	P	None
14	B	room # 2	0.006	0.006	P				<0.002	<0.002	P							<0.002	<0.002	P	P	None
15	B	hallway, by room 3				0.14	0.021	P	0.096	0.06	P							1.17	0.388	P	P	None
16	B	room # 1	0.008	0.008	P				0.108	0.113	P							0.262	0.228	P	P	None
17	B	old bldg basement room 22	0.112	0.047	P																P	None
18	B	old bldg main floor	0.01	0.011	P																P	None
20	S	nurse's office, old bldg. Resource	0.034	0.067	P																P	None
21	S	kitchen (rear wall), East wall, left	0.751	0.047	P				0.086	0.129	P							0.136	0.088	P	P	None
24	S	Brick Bld, Rm 1 (North Wall)	0.376	0.086	P				0.308	1.84								0.355	0.274	P	P	None
27	S	Brick Bld, Rm 2 (South Wall)	0.351	0.054	P				0.105	0.084	P							0.166	0.188	P	P	None
28	S	Brick Bld, Rm 2 (East on North Wall), right	0.131	<0.002	P				0.136	0.043	P							0.068	0.041	P	P	None
29	S	Brick Bld, Rm 2 (West on North Wall), left	0.066	0.028	P				0.077	0.04	P							0.07	0.045	P	P	None
30	S	Brick Bld, Rm 3, North Wall	0.25	0.075	P				0.089	0.04	P							0.175	0.121	P	P	None
31	S	Brick Bld, Rm 4, South Wall	0.204	0.146	P				0.098	0.051	P							0.089	0.121	P	P	None
32	S	Brick Bld, Rm 5, North Wall	0.205	0.174	P				0.139	0.034	P							0.202	0.156	P	P	None
33	S	Brick Bld, Rm 6, South Wall	0.188	<0.002	P				0.049	0.02	P							0.056	0.02	P	P	None
34	S	Brick Bld, Rm 7, North Wall	0.302	0.043	P				0.179	0.035	P							0.267	0.167	P	P	None
35	S	Brick Bld, Rm 8, South Wall	0.198	0.148	P				0.099	0.142	P							0.164	0.179	P	P	None
36	S	Brick Bld, Nurses Office, West Wall	0.089	0.035	P				0.042	0.025	P							0.046	0.03	P	P	None
37	S	Brick Bld, Faculty Lounge, North Wall	0.123	0.034	P							0.083	0.065	P				0.053	0.034	P	P	None
38	S	Brick Bld, Library, North Wall	0.138	0.088	P				0.176	0.154	P							0.528	0.2	P	P	None
39	S	Brick Bld, Rm 10, South Wall	0.272	0.239	P				0.214	0.201	P							0.119	0.122	P	P	None
40	S	Brick Bld, Rm 12, South Wall	0.34	0.207	P				1.26	0.324	P							0.25	0.312	P	P	None
41	S	Brick Bld, Rm 13, North Wall	0.183	0.062	P				0.108	0.196	P							0.216	0.176	P	P	None
42	S	Brick Bld, Rm 14, South Wall	0.329	0.31	P				0.195	0.06	P							0.26	0.216	P	P	None
43	S	Brick Bld, Rm 15, North Wall	0.351	0.055	P				0.145	0.066	P							0.368	0.243	P	P	None
44	S	Brick Bld, Rm 16, South Wall	0.266	0.206	P				0.346	0.185	P							0.229	0.203	P	P	None
45	S	Brick Bld, Rm 17, North Wall	0.273	0.059	P				0.092	0.173	P							0.215	0.186	P	P	None
46	S	Brick Bld, Rm 18, South Wall	0.097	0.06	P				0.173	0.132	P							0.056	0.042	P	P	None
47	S	Brick Bld, Rm 19, North Wall	0.275	0.088	P				0.835	1.16	P							0.173	0.176	P	P	None
48	S	Brick Bld, Rm 20, South Wall	0.344	0.286	P																P	None
49	B	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	0.706	0.061	P																P	None
50	S	Old (Wood) Bld, Rm 21 (Ground Level), South Closet	0.173	0.027	P																P	None
51	S	Old (Wood) Bld, Rm 23 (Main Level), West Closet	0.058	0.049	P																P	None
52	S	Old (Wood) Bld, Rm 24 (Main Level), West Closet	0.058	0.062	P																P	None

53	S	Old (Wood) Bld, Rm 25 (Top Level), West Closet	0.027	0.059	P														P	None	
54	S	Old (Wood) Bld, Rm 26 (Top Level), West Closet	0.024	0.056	P														P	None	
56	S	kitchen (rear wall), East wall, right	0.162	0.067	P			0.079	0.12	P							0.166	0.078	P	P	None
58	S	kitchen, handwash	0.113	0.021	P												0.084	0.067	P	P	None
59	S	main office	0.1	0.046	P			0.087	0.052	P							0.18	0.16	P	P	None
65	S	room 1, kitchenette, left						0.104	0.056	P							0.17	0.168	P	P	None
66	S	room 1, kitchenette, middle						0.195	0.075	P							0.274	0.179	P	P	None
67	S	room 1, kitchenette, right						0.125	0.065	P							0.2	0.154	P	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			Initial Sampling				Follow-up Sampling 1				Follow-up Sampling 2			
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail
01	B	hallway, by room 20					5/18/2005		<0.05	P				
02	B	hallway. By room 17					5/18/2005		<0.05	P				
03	B	hallway, by room 14					5/18/2005		<0.05	P	7/27/2005		0.34	P
04	B	hallway, by library					5/18/2005		<0.05	P				
05	B	hallway, by room 10	3/31/2004	0.07	0.1	P	5/18/2005		<0.05	P	7/27/2005		0.29	P
06	B	hallway near office					5/18/2005		<0.05	P				
07	B	hallway near office					5/18/2005		<0.05	P				
08	B	next to gym boy's restroom					5/18/2005		0.06	P				
09	B	next to gym girl's restroom												
10	B	hallway, by room 8, left												
11	B	hallway, by room 8, right												
12	B	hallway (top stairs), by room 6												
13	B	hallway, by room 7					5/18/2005		<0.05	P	7/27/2005		0.48	P
14	B	room # 2												
15	B	hallway, by room 3	3/31/2004	0.08	<0.05	P	5/18/2005		<0.05	P				
16	B	room # 1	3/31/2004	0.13	<0.05	P	5/18/2005		<0.05	P	7/27/2005		0.13	P
21	S	kitchen (rear wall), East wall	3/31/2004	0.5		P	5/18/2005		<0.05	P				
24	S	Brick Bld, Rm 1 (North Wall)												
25	S	Brick Bld, Rm 1 (East on South Wall), left												
26	S	Brick Bld, Rm 1 (West on South Wall), right												
27	S	Brick Bld, Rm 2 (South Wall)												
28	S	Brick Bld, Rm 2 (East on North Wall), right												
29	S	Brick Bld, Rm 2 (West on North Wall), left												
30	S	Brick Bld, Rm 3, North Wall												
31	S	Brick Bld, Rm 4, South Wall												
32	S	Brick Bld, Rm 5, North Wall												
33	S	Brick Bld, Rm 6, South Wall												
34	S	Brick Bld, Rm 7, North Wall												
35	S	Brick Bld, Rm 8, South Wall												
36	S	Brick Bld, Nurses Office, West Wall												
37	S	Brick Bld, Faculty Lounge, North Wall												
38	S	Brick Bld, Library, North Wall												
39	S	Brick Bld, Rm 10, South Wall												
40	S	Brick Bld, Rm 12, South Wall												
41	S	Brick Bld, Rm 13, North Wall												
42	S	Brick Bld, Rm 14, South Wall												
43	S	Brick Bld, Rm 15, North Wall												
44	S	Brick Bld, Rm 16, South Wall												
45	S	Brick Bld, Rm 17, North Wall												
46	S	Brick Bld, Rm 18, South Wall												
47	S	Brick Bld, Rm 19, North Wall												
48	S	Brick Bld, Rm 20, South Wall												
56	S	kitchen (rear wall), East wall, right												
58	S	kitchen, handwash												
59	S	main office												
65	S	room 1, kitchenette, left												
66	S	room 1, kitchenette, middle												
67	S	room 1, kitchenette, right												

Table 5. Iron Test Results (continued)

FIXTURE INFORMATION			Follow-up Sampling 3				Follow-up Sampling 4				Follow-up Sampling 5				Summary Status	
Fixture ID	Type	Location	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Sampled	1st Draw	Flush 2m	Pass/Fail	Pass/Fail	Status
01	B	hallway, by room 20													P	None
02	B	hallway. By room 17													P	None
03	B	hallway, by room 14													P	None
04	B	hallway, by library													P	None
05	B	hallway, by room 10													P	None
06	B	hallway near office													P	None
07	B	hallway near office													P	None
08	B	next to gym boy's restroom									9/12/2014		<0.05	P	P	None
09	B	next to gym girl's restroom														
10	B	hallway, by room 8, left	9/1/2005		0.074	P									P	None
11	B	hallway, by room 8, right														
12	B	hallway (top stairs), by room 6														
13	B	hallway, by room 7													P	None
14	B	room # 2									9/12/2014		<0.05	P	P	None
15	B	hallway, by room 3													P	None
16	B	room # 1													P	None
21	S	kitchen (rear wall), East wall													P	None
24	S	Brick Bld, Rm 1 (North Wall)	9/1/2005		0.056	P	6/28/2008		<0.05	P					P	None
25	S	Brick Bld, Rm 1 (East on South Wall), left	9/1/2005		<0.05	P									P	None
26	S	Brick Bld, Rm 1 (West on South Wall), right	9/1/2005		0.065	P									P	None
27	S	Brick Bld, Rm 2 (South Wall)	9/1/2005		0.062	P									P	None
28	S	Brick Bld, Rm 2 (East on North Wall), right	9/1/2005		0.067	P					9/12/2014		<0.05	P	P	None
29	S	Brick Bld, Rm 2 (West on North Wall), left	9/1/2005		<0.05	P									P	None
30	S	Brick Bld, Rm 3, North Wall	9/1/2005		<0.05	P									P	None
31	S	Brick Bld, Rm 4, South Wall	9/1/2005		0.077	P									P	None
32	S	Brick Bld, Rm 5, North Wall	9/1/2005		<0.05	P									P	None
33	S	Brick Bld, Rm 6, South Wall	9/1/2005		0.074	P									P	None
34	S	Brick Bld, Rm 7, North Wall	9/1/2005		<0.05	P					9/12/2014		<0.05	P	P	None
35	S	Brick Bld, Rm 8, South Wall	9/1/2005		0.15	P									P	None
36	S	Brick Bld, Nurses Office, West Wall	9/1/2005		0.072	P									P	None
37	S	Brick Bld, Faculty Lounge, North Wall	9/1/2005		0.072	P									P	None
38	S	Brick Bld, Library, North Wall	9/1/2005		0.166	P									P	None
39	S	Brick Bld, Rm 10, South Wall	9/1/2005		0.084	P									P	None
40	S	Brick Bld, Rm 12, South Wall	9/1/2005		0.067	P									P	None
41	S	Brick Bld, Rm 13, North Wall	9/1/2005		0.057	P									P	None
42	S	Brick Bld, Rm 14, South Wall	9/1/2005		0.065	P					9/12/2014		<0.05	P	P	None
43	S	Brick Bld, Rm 15, North Wall	9/1/2005		0.06	P									P	None
44	S	Brick Bld, Rm 16, South Wall	9/1/2005		0.066	P									P	None
45	S	Brick Bld, Rm 17, North Wall	9/1/2005		0.062	P									P	None
46	S	Brick Bld, Rm 18, South Wall	9/1/2005		0.078	P									P	None
47	S	Brick Bld, Rm 19, North Wall	9/1/2005		0.066	P									P	None
48	S	Brick Bld, Rm 20, South Wall	9/1/2005		0.069	P	6/28/2008		<0.05	P					P	None
56	S	kitchen (rear wall), East wall, right					6/28/2008		0.086	P	9/12/2014		<0.05	P	P	None
58	S	kitchen, handwash														
59	S	main office					6/28/2008		0.05	P					P	None
65	S	room 1, kitchenette, left														
66	S	room 1, kitchenette, middle														
67	S	room 1, kitchenette, right														

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	boiler room (faucet on main)	Arsenic	11-Sep-18	2 ppb	P
00	SE	boiler room (faucet on main)	Cadmium	11-Sep-18	1 ppb	P
00	SE	boiler room (faucet on main)	Chlorine	31-Mar-04	0.2 ppm	P
00	SE	boiler room (faucet on main)	Copper	11-Sep-18	0.008 ppm	P
00	SE	boiler room (faucet on main)	E coli	15-Jun-04	<1 Colonies	P
00	SE	boiler room (faucet on main)	Iron	11-Sep-18	<0.05 ppm	P
00	SE	boiler room (faucet on main)	Lead	11-Sep-18	1 ppb	P
00	SE	boiler room (faucet on main)	Total Coliforms	12-Sep-14	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.