

**Seattle Public Schools
Drinking Water Quality Program**

**Results of Water Quality Testing
for
COE ELEMENTARY SCHOOL**

Updated February 09, 2022

General Information:

Plumbing piping materials: mainly copper

Remediation plan:

This remediation plan is based on a Water Quality policy approved by the School Board. The policy includes standards for the presence of lead, cadmium, copper, iron and other substances in drinking water.

Sinks (S in the report) are not considered drinking water sources. We recognize that there is the potential for students to want to drink from classroom hand-washing sinks, so we test all of those. Where a student's choice to drink from a sink could be a problem, we post a reminder sign, as we do at all restroom sinks.

Status:

Policy Criteria:

All sources meet the policy criteria.

Follow-up monitoring: TBD.

Service: The school will be flushed after any breaks longer than five days.

Water Quality Testing Results:

Legend

Symbol	Definition
SE	service entry (main)
B	bubbler
S	sink (faucet)
B/S	sink/bubbler combination
S/B	sink/bubbler combination
ppb	parts per billion
ppm	parts per million
NA	not applicable
None	no action required
Unk	unknown status or action
Sample	sample needs to be taken
Re-test	fixture needs to be resampled
Conf	resample to confirm measurement
No flush	not flushed before sampling
Sink	sampled faucet of S/B combo
Used	recently used; no 1st draw sample possible
PS	post sign
Disable(d)	fixture disabled in response to water quality testing
BDSS	Bubbler disabled, sign on sink
IF	install filter
RB	replace bubbler
RB/IF	replace bubbler and/or install filter
RF	replace faucet
RF/IF	replace faucet and/or install filter
BW	disable fixture and provide bottled water until remediated
Leaks	leaking fixture
NW	not working properly (sample S when B of S/B NW)
OS	out of service - disabled until fixed
RS	return to service - now passes testing
Rem	Removed from system - no longer exists

Table 1. Summary of Results

FIXTURE INFORMATION			LEAD		CADMIUM		COPPER		IRON		OK?
Fixture ID	Type	Location	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Pass/Fail	Status	Yes/No/Status
01	S	outside classroom 108	P	None	P	None	P	None	P	None	Yes
02	S	outside classroom 103	P	None	P	None	P	None			Yes
03	B	Childcare, classroom 110	P	None	P	None	P	None			Yes
04	B	Childcare, classroom 109	P	None	P	None	P	None			Yes
05	B	hallway near room 203, 2nd floor, S. hall	P	None	P	None	P	None			Yes
06	B	hallway near room 209, 2nd floor, N. hall	P	None	P	None	P	None			Yes
07	B	hallway near room 309, 3rd floor, N. Hall	P	None	P	None	P	None			Yes
08	B	hallway near room 303, 3rd floor, S. Hall	P	None	P	None	P	None	P	None	Yes
10	S	nurses office	P	None	P	None	P	None	P	None	Yes
11	S	staff lounge, room 301	P	None	P	None	P	None	P	None	Yes
14	S	kitchen (LH Fixture), 3 compartment sink	P	None	P	None	P	None	P	None	Yes
15	S	day care kitchen	P	None	P	None	P	None			Yes
16	S	room 110 - north sink, left	P	None	P	None	P	None			Yes
16A	S	room 110, north sink, right	P	None	P	None	P	None			Yes
17	S	room 109 south sink	P	None	P	None	P	None			Yes
17A	S	room 109, south sink, right	P	None	P	None	P	None			Yes
18	S	room 104	P	None	P	None	P	None	P	None	Yes
19	S	room 105	P	None	P	None	P	None	P	None	Yes
20	S	room 106	P	None	P	None	P	None	P	None	Yes
21	S	room 107	P	None	P	None	P	None	P	None	Yes
22	S	room 108	P	None	P	None	P	None	P	None	Yes
24	S	room 204	P	None	P	None	P	None			Yes
25	S	room 205	P	None	P	None	P	None	P	None	Yes
26	S	room 206	P	None	P	None	P	None	P	None	Yes
27	S	room 207	P	None	P	None	P	None	P	None	Yes
28	S	room 208	P	None	P	None	P	None	P	None	Yes
29	S	room 209	P	None	P	None	P	None	P	None	Yes
30	S	near conf room 214	P	None	P	None	P	None			Yes
31	S	room 302	P	None	P	None	P	None			Yes
32	S	room 303	P	None	P	None	P	None			Yes
33	S	room 304	P	None	P	None	P	None			Yes
34	S	room 305	P	None	P	None	P	None	P	None	Yes
35	S	near room 314	P	None	P	None	P	None	P	None	Yes
36	S	room 306	P	None	P	None	P	None	P	None	Yes
37	S	room 307	P	None	P	None	P	None	P	None	Yes
38	S	room 308	P	None	P	None	P	None			Yes
39	S	room 309	P	None	P	None	P	None			Yes
40	S	room 310	P	None	P	None	P	None	P	None	Yes
41	S	room 103	P	None	P	None	P	None	P	None	Yes
42	B	1st floor hall - south side	P	None	P	None	P	None	P	None	Yes
43	B	1st floor hall - north side	P	None	P	None	P	None	P	None	Yes
44	S	Library office, 201A	P	None	P	None	P	None	P	None	Yes
45	S	Staff work room 101F	P	None	P	None	P	None	P	None	Yes
60	B	gym entrance	P	None	P	None	P	None	P	None	Yes
61	S	ROOM 203, LEFT	P	None	P	None	P	None			Yes
62	S	ROOM 203, RIGHT	P	None	P	None	P	None			Yes

65	BF	GYM, BOTTLE FILLER	P	None	P	None	P	None			Yes
66	S	kitchen (RH Fixture), 3 compartment sink	P	None							Yes
67	B	KITCHEN, salad prep sink	P	None	P	None	P	None			Yes
68	S/B	ROOM 115	P	None	P	None	P	None			Yes
69	S/B	ROOM 118	P	None	P	None	P	None			Yes
70	S/B	ROOM 215	P	None	P	None	P	None			Yes
71	S/B	ROOM 218	P	None	P	None	P	None			Yes
72	S/B	ROOM 315	P	None	P	None	P	None			Yes
73	S/B	ROOM 318	P	None	P	None	P	None			Yes

Table 2. Lead Test Results

Test Results (Lead/Pb, ppb)																				
FIXTURE INFORMATION			5/21/2015		8/14/2019		9/3/2019		8/10/2021		11/23/2021		1/14/2022							
Fixture ID	Type	Location	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Pass/Fail
01	S	outside classroom 108	<1	P	2	<1	P	3	<1	P				2	P					
02	S	outside classroom 103	<1	P	2	<1	P	<1	<1	P										
03	B	Childcare, classroom 110						8	3	P				3	P					
04	B	Childcare, classroom 109						<1	<1	P										
05	B	hallway near room 203, 2nd floor, S. hall	<1	P	<1	<1	P	<1	<1	P										
06	B	hallway near room 209, 2nd floor, N. hall	<1	P	<1	<1	P	<1	<1	P										
07	B	hallway near room 309, 3rd floor, N. Hall	<1	P	<1	<1	P	<1	<1	P										
08	B	hallway near room 303, 3rd floor, S. Hall	<1	P	<1	<1	P	<1	<1	P										
10	S	nurses office	<1	P	1	<1	P	<1	<1	P										
11	S	staff lounge, room 301	<1	P	1	<1	P	2	<1	P				<1	P					
14	S	kitchen (LH Fixture), 3 compartment sink	<1	P	8	<1	P												1	P
15	S	day care kitchen						<1	<1	P										
16	S	room 110 - north sink, left						<1	<1	P										
16A	S	room 110, north sink, right						<1	<1	P										
17	S	room 109 south sink						<1	<1	P										
17A	S	room 109, south sink, right						<1	<1	P										
18	S	room 104	<1	P	<1	<1	P	1	<1	P										
19	S	room 105	<1	P	<1	<1	P	2	<1	P				1	P					
20	S	room 106	<1	P	<1	<1	P	<1	<1	P										
21	S	room 107	<1	P	2	<1	P	2	<1	P				<1	P					
22	S	room 108	<1	P	1	<1	P	1	<1	P										
24	S	room 204	1	P	<1	<1	P	<1	<1	P										
25	S	room 205	<1	P	1	<1	P	1	<1	P										
26	S	room 206	<1	P	1	<1	P	<1	<1	P										
27	S	room 207	<1	P	<1	<1	P	2	<1	P				<1	P					
28	S	room 208	<1	P	<1	<1	P	<1	<1	P										
29	S	room 209	<1	P	2	<1	P	1	<1	P										
30	S	near conf room 214	1	P	3	<1	P	<1	<1	P										
31	S	room 302	<1	P	<1	<1	P	<1	<1	P										
32	S	room 303	<1	P	2	<1	P	<1	<1	P										
33	S	room 304	<1	P	1	<1	P	1	<1	P										
34	S	room 305	<1	P	1	<1	P	2	<1	P				<1	P					
35	S	near room 314	1	P	3	<1	P	<1	<1	P										
36	S	room 306	<1	P	<1	<1	P	2	<1	P				<1	P					
37	S	room 307	<1	P	1	<1	P	<1	<1	P										
38	S	room 308	<1	P	1	<1	P	2	<1	P				<1	P					
39	S	room 309	<1	P	<1	<1	P	<1	<1	P										
40	S	room 310	<1	P	1	<1	P	<1	<1	P										
41	S	room 103	<1	P	<1	<1	P	<1	<1	P										
42	B	1st floor hall - south side	<1	P	<1	<1	P	<1	<1	P										
43	B	1st floor hall - north side	1	P	<1	<1	P	<1	<1	P										
44	S	Library office, 201A	<1	P	3	<1	P	2	<1	P				<1	P					
45	S	Staff work room 101F	<1	P	<1	<1	P	<1	<1	P										
60	B	gym entrance	<1	P	<1	<1	P	<1	<1	P										
61	S	ROOM 203, LEFT						2	<1	P				<1	P					
62	S	ROOM 203, RIGHT						2	<1	P				<1	P					

65	BF	GYM, BOTTLE FILLER						<1	<1	P									
66	S	kitchen (RH Fixture), 3 compartment sink									<1	<1	P						
67	B	KITCHEN, salad prep sink						<1	<1	P									
68	S/B	ROOM 115													<1	<1	P		
69	S/B	ROOM 118													<1	<1	P		
70	S/B	ROOM 215													<1	<1	P		
71	S/B	ROOM 218													<1	<1	P		
72	S/B	ROOM 315													<1	<1	P		
73	S/B	ROOM 318													<1	<1	P		

Table 3. Cadmium Test Results

FIXTURE INFORMATION			4/5/2012			5/21/2015			8/14/2019			11/23/2021			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	outside classroom 108	<1	<1	P	<1	<1	P	<1	<1	P				P	None
02	S	outside classroom 103	<1	<1	P	<1	<1	P	<1	<1	P				P	None
03	B	Childcare, classroom 110							<1	<1	P				P	None
04	B	Childcare, classroom 109							<1	<1	P				P	None
05	B	hallway near room 203, 2nd floor, S. hall	<1	<1	P	<1	<1	P	<1	<1	P				P	None
06	B	hallway near room 209, 2nd floor, N. hall	<1	<1	P	<1	<1	P	<1	<1	P				P	None
07	B	hallway near room 309, 3rd floor, N. Hall	<1	<1	P	<1	<1	P	<1	<1	P				P	None
08	B	hallway near room 303, 3rd floor, S. Hall	<1	<1	P	<1	<1	P	<1	<1	P				P	None
10	S	nurses office	<1	<1	P	<1	<1	P	<1	<1	P				P	None
11	S	staff lounge, room 301	<1	<1	P	<1	<1	P	<1	<1	P				P	None
14	S	kitchen (LH Fixture), 3 compartment sink	<1	<1	P	<1	<1	P							P	None
15	S	day care kitchen							<1	<1	P				P	None
16	S	room 110 - north sink, left							<1	<1	P				P	None
16A	S	room 110, north sink, right							<1	<1	P				P	None
17	S	room 109 south sink							<1	<1	P				P	None
17A	S	room 109, south sink, right							<1	<1	P				P	None
18	S	room 104	<1	<1	P	<1	<1	P	<1	<1	P				P	None
19	S	room 105	<1	<1	P	<1	<1	P	<1	<1	P				P	None
20	S	room 106	<1	<1	P	<1	<1	P	<1	<1	P				P	None
21	S	room 107	<1	<1	P	<1	<1	P	<1	<1	P				P	None
22	S	room 108	<1	<1	P	<1	<1	P	<1	<1	P				P	None
24	S	room 204	<1	<1	P	<1	<1	P	<1	<1	P				P	None
25	S	room 205	<1	<1	P	<1	<1	P	<1	<1	P				P	None
26	S	room 206	<1	<1	P	<1	<1	P	<1	<1	P				P	None
27	S	room 207	<1	<1	P	<1	<1	P	<1	<1	P				P	None
28	S	room 208	<1	<1	P	<1	<1	P	<1	<1	P				P	None
29	S	room 209	<1	<1	P	<1	<1	P	<1	<1	P				P	None
30	S	near conf room 214	<1	<1	P	<1	<1	P	<1	<1	P				P	None
31	S	room 302	<1	<1	P	<1	<1	P	<1	<1	P				P	None
32	S	room 303	<1	<1	P	<1	<1	P	<1	<1	P				P	None
33	S	room 304	<1	<1	P	<1	<1	P	<1	<1	P				P	None
34	S	room 305	<1	<1	P	<1	<1	P	<1	<1	P				P	None
35	S	near room 314	<1	<1	P	<1	<1	P	<1	<1	P				P	None
36	S	room 306	<1	<1	P	<1	<1	P	<1	<1	P				P	None
37	S	room 307	<1	<1	P	<1	<1	P	<1	<1	P				P	None
38	S	room 308	<1	<1	P	<1	<1	P	<1	<1	P				P	None
39	S	room 309	<1	<1	P	<1	<1	P	<1	<1	P				P	None
40	S	room 310	<1	<1	P	<1	<1	P	<1	<1	P				P	None
41	S	room 103	<1	<1	P	<1	<1	P	<1	<1	P				P	None
42	B	1st floor hall - south side	<1	<1	P	<1	<1	P	<1	<1	P				P	None
43	B	1st floor hall - north side	<1	<1	P	<1	<1	P	<1	<1	P				P	None
44	S	Library office, 201A	<1	<1	P	<1	<1	P	<1	<1	P				P	None
45	S	Staff work room 101F	<1	<1	P	<1	<1	P	<1	<1	P				P	None
60	B	gym entrance	<1	<1	P	<1	<1	P	<1	<1	P				P	None
61	S	ROOM 203, LEFT							<1	<1	P				P	None
62	S	ROOM 203, RIGHT							<1	<1	P				P	None

65	BF	GYM, BOTTLE FILLER							<1	<1	P				P	None
66	S	kitchen (RH Fixture), 3 compartment sink													p	None
67	B	KITCHEN, salad prep sink							<1	<1	P					
68	S/B	ROOM 115										<1	<1	P	P	None
69	S/B	ROOM 118										<1	<1	P	P	None
70	S/B	ROOM 215										<1	<1	P	P	None
71	S/B	ROOM 218										<1	<1	P	P	None
72	S/B	ROOM 315										<1	<1	P	P	None
73	S/B	ROOM 318										<1	<1	P	P	None

Table 4. Copper Test Results

FIXTURE INFORMATION			4/5/2012			5/21/2015			8/14/2019			11/23/2021			Summary Status	
Fixture ID	Type	Location	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	1st Draw	Flush 30s	Pass/Fail	Pass/Fail	Status
01	S	outside classroom 108	0.687	0.745	P	0.246	0.283	P	0.367	0.265	P				P	None
02	S	outside classroom 103	0.611	0.542	P	0.257	0.233	P	0.277	0.27	P				P	None
03	B	Childcare, classroom 110							1.02	0.367	P				P	None
04	B	Childcare, classroom 109							0.275	0.268	P				P	None
05	B	hallway near room 203, 2nd floor, S. hall	0.704	0.66	P	0.26	0.236	P	0.482	0.445	P				P	None
06	B	hallway near room 209, 2nd floor, N. hall	0.689	0.734	P	0.256	0.267	P	0.343	0.419	P				P	None
07	B	hallway near room 309, 3rd floor, N. Hall	0.668	0.614	P	0.237	0.276	P	0.34	0.343	P				P	None
08	B	hallway near room 303, 3rd floor, S. Hall	0.725	0.738	P	0.238	0.26	P	0.325	0.389	P				P	None
10	S	nurses office	0.714	0.705	P	0.289	0.291	P	0.415	0.386	P				P	None
11	S	staff lounge, room 301	0.621	0.545	P	0.354	0.38	P	0.347	0.447	P				P	None
14	S	kitchen (LH Fixture), 3 compartment sink	0.633	0.526	P	0.313	0.319	P							P	None
15	S	day care kitchen							0.206	0.234	P				P	None
16	S	room 110 - north sink, left							0.214	0.271	P				P	None
16A	S	room 110, north sink, right							0.256	0.228	P				P	None
17	S	room 109 south sink							0.279	0.209	P				P	None
17A	S	room 109, south sink, right							0.248	0.201	P				P	None
18	S	room 104	0.676	0.696	P	0.237	0.256	P	0.345	0.217	P				P	None
19	S	room 105	0.623	0.613	P	0.23	0.258	P	0.249	0.311	P				P	None
20	S	room 106	0.774	0.755	P	0.301	0.372	P	0.34	0.434	P				P	None
21	S	room 107	0.6	0.663	P	0.248	0.282	P	0.296	0.265	P				P	None
22	S	room 108	0.542	0.72	P	0.222	0.326	P	0.21	0.216	P				P	None
24	S	room 204	0.733	0.554	P	0.249	0.251	P	0.32	0.478	P				P	None
25	S	room 205	0.63	0.639	P	0.301	0.269	P	0.394	0.36	P				P	None
26	S	room 206	0.663	0.626	P	0.259	0.307	P	0.368	0.395	P				P	None
27	S	room 207	0.632	0.684	P	0.254	0.228	P	0.328	0.254	P				P	None
28	S	room 208	0.652	0.571	P	0.255	0.226	P	0.318	0.408	P				P	None
29	S	room 209	0.758	0.942	P	0.291	0.278	P	0.304	0.389	P				P	None
30	S	near conf room 214	0.719	0.479	P	0.255	0.196	P	0.397	0.215	P				P	None
31	S	room 302	0.739	0.753	P	0.277	0.314	P	0.386	0.427	P				P	None
32	S	room 303	0.718	0.787	P	0.291	0.32	P	0.378	0.499	P				P	None
33	S	room 304	0.615	0.747	P	0.261	0.308	P	0.431	0.476	P				P	None
34	S	room 305	0.674	0.796	P	0.283	0.322	P	0.43	0.526	P				P	None
35	S	near room 314	0.766	0.602	P	0.25	0.235	P	0.455	0.28	P				P	None
36	S	room 306	0.821	0.787	P	0.287	0.327	P	0.36	0.445	P				P	None
37	S	room 307	0.573	0.676	P	0.26	0.29	P	0.352	0.356	P				P	None
38	S	room 308	0.579	0.189	P	0.276	0.254	P	0.278	0.387	P				P	None
39	S	room 309	0.787	0.776	P	0.337	0.34	P	0.351	0.432	P				P	None
40	S	room 310	0.7	0.671	P	0.249	0.267	P	0.395	0.405	P				P	None
41	S	room 103	0.591	0.559	P	0.233	0.252	P	0.328	0.347	P				P	None
42	B	1st floor hall - south side	0.664	0.545	P	0.255	0.258	P	0.319	0.312	P				P	None
43	B	1st floor hall - north side	0.554	0.469	P	0.278	0.272	P	0.362	0.189	P				P	None
44	S	Library office, 201A	0.645	0.725	P	0.261	0.404	P	0.342	0.445	P				P	None
45	S	Staff work room 101F	0.617	0.806	P	0.308	0.366	P	0.433	0.448	P				P	None
60	B	gym entrance	0.601	0.622	P	0.254	0.123	P	0.101	0.091	P				P	None
61	S	ROOM 203, LEFT							0.322	0.437	P				P	None
62	S	ROOM 203, RIGHT							0.32	0.478	P				P	None
65	BF	GYM, BOTTLE FILLER							0.081	0.084	P				P	None
66	S	kitchen (RH Fixture), 3 compartment sink														

67	B	KITCHEN, salad prep sink							0.391	0.191	P			P	None
68	S/B	ROOM 115										0.223	0.237	P	None
69	S/B	ROOM 118										0.19	0.155	P	None
70	S/B	ROOM 215										0.2	0.216	P	None
71	S/B	ROOM 218										0.169	0.196	P	None
72	S/B	ROOM 315										0.193	0.231	P	None
73	S/B	ROOM 318										0.227	0.169	P	None

Table 5. Iron Test Results

FIXTURE INFORMATION			4/5/2012		5/21/2015		8/14/2019		Summary Status	
Fixture ID	Type	Location	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Flush 2m	Pass/Fail	Pass/Fail	Status
01	S	outside classroom 108							P	None
02	S	outside classroom 103								
03	B	Childcare, classroom 110								
04	B	Childcare, classroom 109								
05	B	hallway near room 203, 2nd floor, S. hall								
06	B	hallway near room 209, 2nd floor, N. hall								
07	B	hallway near room 309, 3rd floor, N. Hall								
08	B	hallway near room 303, 3rd floor, S. Hall							P	None
10	S	nurses office							P	None
11	S	staff lounge, room 301	0.062	P					P	None
14	S	kitchen (LH Fixture), 3 compartment sink			0.054	P			P	None
15	S	day care kitchen								
16	S	room 110 - north sink, left								
16A	S	room 110, north sink, right								
17	S	room 109 south sink								
17A	S	room 109, south sink, right								
18	S	room 104			<0.05	P			P	None
19	S	room 105					<0.05	P	P	None
20	S	room 106							P	None
21	S	room 107	0.068	P					P	None
22	S	room 108			<0.05	P			P	None
24	S	room 204								
25	S	room 205					<0.05	P	P	None
26	S	room 206							P	None
27	S	room 207	0.063	P					P	None
28	S	room 208			0.057	P			P	None
29	S	room 209					<0.05	P	P	None
30	S	near conf room 214								
31	S	room 302								
32	S	room 303								
33	S	room 304								
34	S	room 305							P	None
35	S	near room 314	0.068	P					P	None
36	S	room 306			0.051	P			P	None
37	S	room 307					<0.05	P	P	None
38	S	room 308								
39	S	room 309								
40	S	room 310							P	None
41	S	room 103	0.066	P					P	None
42	B	1st floor hall - south side			0.069	P			P	None
43	B	1st floor hall - north side					<0.05	P	P	None
44	S	Library office, 201A							P	None
45	S	Staff work room 101F	0.069	P					P	None
60	B	gym entrance			0.059	P			P	None
61	S	ROOM 203, LEFT								
62	S	ROOM 203, RIGHT								
65	BF	GYM, BOTTLE FILLER								
66	S	kitchen (RH Fixture), 3 compartment sink								

67	B	KITCHEN, salad prep sink									
68	S/B	ROOM 115									
69	S/B	ROOM 118									
70	S/B	ROOM 215									
71	S/B	ROOM 218									
72	S/B	ROOM 315									
73	S/B	ROOM 318									

Table 6. Service Entry Test Results

Test Results (Service Entry/SE, Units as Shown)						
SOURCE INFORMATION			Most Recent Sampling			
Fixture ID	Type	Location	Item	Sampled	Max Value	Pass/Fail
00	SE	outside S. Wall Boiler room	Arsenic	21-May-15	2 ppb	P
00	SE	outside S. Wall Boiler room	Cadmium	14-Aug-19	1 ppb	P
00	SE	outside S. Wall Boiler room	Chlorine	19-May-04	0.3 ppm	P
00	SE	outside S. Wall Boiler room	Copper	14-Aug-19	0.163 ppm	P
00	SE	outside S. Wall Boiler room	E coli	19-May-04	<1 Colonies	P
00	SE	outside S. Wall Boiler room	Iron	14-Aug-19	<0.05 ppm	P
00	SE	outside S. Wall Boiler room	Lead	14-Aug-19	1 ppb	P
00	SE	outside S. Wall Boiler room	Total Coliforms	28-Jan-09	<1 Colonies	P

"<" means: less than the value shown (below analytical detection limits).

"n/a" means: not applicable.

Table 7. Bacteriological Test Results

Bacteriological Characteristics

Bacteriological testing of selected samples indicated no (zero) coliform bacteria.