

# Lead in School Drinking Water Report

## Washington Middle School



### EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov).

## DEFINITIONS

Fixture Housing  
Location

Room/space where  
fixture is located  
(i.e. room number,  
gym, playground)

Fixture Housing Type

Structure that contains  
the individual fixtures  
where water samples  
were collected from.  
Fixture housing may  
contain one or more  
individual fixture for  
sampling.

Fixture Location  
Details

Location within a  
room or space where  
fixture housing is  
located, starting to the  
left of the entrance and  
rotating clockwise, of  
the total number of  
fixture housings in a  
room or space  
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water  
Fountain, Water Bottle  
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2025-11-14

Date(s) analyzed: 2025-11-21, 2025-11-24

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	417964	Main Building	Sink - Multi-Compartment	Kitchen	1 of 2	Tap	left	8
2	417970	Main Building	Pot Filler	Kitchen	2 of 2	Tap	center	6
3	417994	Main Building	Sink	Rm115	2 of 2	Tap	center	4
4	417966	Main Building	Sink - Multi-Compartment	Kitchen	1 of 2	Tap	right	3
5	417977	Main Building	Sink	Rm1	1 of 1	Tap	center	2
6	417965	Main Building	Sink	Staff Lounge	1 of 1	Tap	center	1
7	417971	Main Building	Sink	Rm117-06	1 of 1	Tap	center	1
8	417975	Main Building	Fountain	Across From Stairs (Bottom Floor)	1 of 1	Water Fountain	center	1
9	417960	Main Building	Water Bottle Filling Station	Commons	1 of 2	Water Bottle Filler	center	<1
10	417961	Main Building	Fountain	Across From Rm106	1 of 1	Water Fountain	center	<1
11	417962	Main Building	Fountain	Commons	2 of 2	Water Fountain	center	<1
12	417963	Main Building	Sink - Multi-Compartment	Rm106	1 of 1	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
13	417967	Main Building	Fountain	Next To Rm102	1 of 1	Water Fountain	center	<1
14	417968	Main Building	Sink - Multi-Compartment	Kitchen	1 of 2	Sprayer	right	<1
15	417969	Main Building	Sink	Rm117	1 of 1	Tap	center	<1
16	417972	Main Building	Fountain	Next To Rm139	1 of 1	Water Fountain	center	<1
17	417973	Main Building	Sink	Office Workroom	1 of 1	Tap	center	<1
18	417974	Main Building	Fountain	Across From Rm136	1 of 1	Water Fountain	center	<1
19	417976	Main Building	Sink	Rm133	1 of 1	Tap	center	<1
20	417978	Main Building	Sink	Rm134	1 of 1	Tap	center	<1
21	417979	Main Building	Fountain	Next To Rm10	1 of 1	Water Fountain	center	<1
22	417980	Main Building	Fountain	Across From Rm128	1 of 1	Water Fountain	center	<1
23	417981	Main Building	Fountain/Tap Combo	Rm4b	1 of 1	Water Bottle Filler	left	<1
24	417982	Main Building	Sink	Rm129	1 of 1	Tap	center	<1
25	417983	Main Building	Fountain/Tap Combo	Rm4b	1 of 1	Tap	right	<1
26	417984	Main Building	Sink	Rm128b	1 of 1	Tap	center	<1
27	417985	Main Building	Sink	Rm8	1 of 1	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
28	417986	Main Building	Sink	Rm128a	1 of 1	Tap	center	<1
29	417987	Main Building	Fountain/Tap Combo	Rm10	1 of 1	Water Bottle Filler	left	<1
30	417988	Main Building	Fountain	Across From Rm121	1 of 1	Water Fountain	center	<1
31	417989	Main Building	Fountain/Tap Combo	Rm10	1 of 1	Tap	right	<1
32	417990	Main Building	Fountain	Across From Rm116	1 of 1	Water Fountain	center	<1
33	417991	Main Building	Fountain	Next Rm6	1 of 1	Water Fountain	center	<1
34	417992	Main Building	Sink	Rm115	1 of 2	Tap	center	<1
35	417993	Main Building	Fountain	Outside Girls Locker Rm Fountain	1 of 1	Water Fountain	center	<1
36	417996	Main Building	Fountain	Next To Rm111	1 of 1	Water Fountain	center	<1
37	417998	Main Building	Sink	Library Office	1 of 1	Tap	center	<1