

# Lead in School Drinking Water Report

## Garfield High School



### EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov).

## DEFINITIONS

Fixture Housing  
Location

Room/space where  
fixture is located  
(i.e. room number,  
gym, playground)

Fixture Housing Type

Structure that contains  
the individual fixtures  
where water samples  
were collected from.  
Fixture housing may  
contain one or more  
individual fixture for  
sampling.

Fixture Location  
Details

Location within a  
room or space where  
fixture housing is  
located, starting to the  
left of the entrance and  
rotating clockwise, of  
the total number of  
fixture housings in a  
room or space  
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water  
Fountain, Water Bottle  
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2025-10-15

Date(s) analyzed: 2025-10-28, 2025-10-30

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	417233	Performing Arts Center Building	Sink - Multi-Compartment	Concessions	1 of 1	Tap	left	15
2	417184	Main Building	Sink	Rm106	4 of 8	Tap	center	14
3	417186	Main Building	Sink	Rm106	5 of 8	Tap	center	14
4	417192	Main Building	Sink	Rm106	8 of 8	Tap	center	13
5	417235	Performing Arts Center Building	Sink - Multi-Compartment	Concessions	1 of 1	Sprayer	right	10
6	417222	Main Building	Sink	Kitchen	3 of 4	Tap	center	7
7	417215	Performing Arts Center Building	Sink	Consessions	1 of 1	Tap	center	6
8	417182	Main Building	Sink	Rm106	3 of 8	Tap	center	5
9	417220	Main Building	Pot Filler	Kitchen	2 of 4	Tap	center	5
10	417178	Main Building	Sink	Rm106	1 of 8	Tap	center	4
11	417232	Main Building	Sink	Rm104a	1 of 1	Tap	center	4
12	417236	Main Building	Sink	Rm230	1 of 1	Tap	center	4
13	417177	Main Building	Fountain/Tap Combo	Rm217	1 of 1	Water Fountain	right	3

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
14	417163	Main Building	Sink	Rm101e	1 of 1	Tap	center	2
15	417171	Main Building	Sink	Rm215	1 of 1	Tap	center	2
16	417187	Main Building	Sink	Rm236	1 of 1	Tap	center	2
17	417188	Main Building	Sink	Rm106	6 of 8	Tap	center	2
18	417190	Main Building	Sink	Rm106	7 of 8	Tap	center	2
19	417205	Main Building	Sink	Rm331	1 of 1	Tap	center	2
20	417214	Main Building	Sink	Rm108 Workroom	1 of 1	Tap	center	2
21	417224	Main Building	Sink - Multi-Compartment	Kitchen	4 of 4	Tap	left	2
22	417226	Main Building	Sink - Multi-Compartment	Kitchen	4 of 4	Tap	right	2
23	417234	Main Building	Sink	Rm105	1 of 1	Tap	center	2
24	417175	Main Building	Fountain/Tap Combo	Rm217	1 of 1	Tap	left	1
25	417196	Main Building	Sink	Rm102a	1 of 1	Tap	center	1
26	417199	Main Building	Sink	Rm313	1 of 1	Tap	center	1
27	417218	Main Building	Sink - Multi-Compartment	Kitchen	1 of 4	Tap	center	1
28	417223	Performing Arts Center Building	Fountain	Women's Locker Rm	1 of 1	Water Fountain	center	1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
29	417230	Main Building	Sink	Rm104k	1 of 1	Tap	center	1
30	417161	Main Building	Fountain with Bottle Filler	Main Hallway	1 of 1	Water Fountain	right	<1
31	417165	Main Building	Sink	Rm120	1 of 1	Tap	center	<1
32	417167	Main Building	Sink	Rm213	1 of 1	Tap	center	<1
33	417169	Main Building	Sink - Multi-Compartment	Rm214	1 of 1	Tap	center	<1
34	417173	Main Building	Sink	Rm216	1 of 1	Tap	center	<1
35	417179	Main Building	Fountain - Multi-Level	Across From 217	1 of 1	Water Fountain	left	<1
36	417180	Main Building	Sink	Rm106	2 of 8	Tap	center	<1
37	417181	Main Building	Fountain - Multi-Level	Across From 217	1 of 1	Water Fountain	right	<1
38	417183	Main Building	Sink	Rm219	1 of 1	Tap	center	<1
39	417185	Main Building	Sink	Rm228	1 of 1	Tap	center	<1
40	417189	Main Building	Sink - Multi-Compartment	Rm241	1 of 1	Tap	center	<1
41	417191	Main Building	Fountain - Multi-Level	Next To 2nd Staff Bathroom	1 of 1	Water Fountain	left	<1
42	417193	Main Building	Fountain - Multi-Level	Next To 2nd Staff Bathroom	1 of 1	Water Fountain	right	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
43	417194	Main Building	Fountain with Bottle Filler	Commons	1 of 1	Water Bottle Filler	center	<1
44	417195	Main Building	Sink	Rm211	1 of 1	Tap	center	<1
45	417197	Main Building	Sink - Multi-Compartment	Rm237a	1 of 1	Tap	center	<1
46	417198	Main Building	Fountain with Bottle Filler	Main Hallway	1 of 1	Water Bottle Filler	center	<1
47	417201	Main Building	Fountain - Multi-Level	Next To 317	1 of 1	Water Fountain	left	<1
48	417203	Main Building	Fountain - Multi-Level	Next To 317	1 of 1	Water Fountain	right	<1
49	417207	Performing Arts Center Building	Fountain - Multi-Level	Across From 301	1 of 1	Water Fountain	left	<1
50	417209	Main Building	Fountain - Multi-Level	Across From 301	1 of 1	Water Fountain	right	<1
51	417211	Performing Arts Center Building	Fountain	Women Bathroom	1 of 1	Water Fountain	center	<1
52	417213	Performing Arts Center Building	Fountain	Men's Bathroom	1 of 1	Water Fountain	center	<1
53	417216	Main Building	Sink - Multi-Compartment	Staff Lounge 109	1 of 1	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
54	417217	Performing Arts Center Building	Fountain	Weight Rmq125	1 of 1	Water Fountain	center	<1
55	417219	Main Building	Fountain - Multi-Level	Next To Locker Rm	1 of 1	Water Fountain	left	<1
56	417221	Performing Arts Center Building	Fountain - Multi-Level	Next To Locker Rm	1 of 1	Water Fountain	right	<1
57	417225	Performing Arts Center Building	Fountain	Men's Locker Rm	1 of 1	Water Fountain	center	<1
58	417227	Performing Arts Center Building	Fountain - Multi-Level with Bottle Filler	Upstairs Fountains	1 of 1	Water Fountain	left	<1
59	417228	Main Building	Sink - Multi-Compartment	Kitchen	4 of 4	Sprayer	right	<1
60	417229	Performing Arts Center Building	Fountain - Multi-Level with Bottle Filler	Upstairs Fountains	1 of 1	Water Bottle Filler	center	<1
61	417231	Performing Arts Center Building	Fountain - Multi-Level with Bottle Filler	Upstairs Fountains	1 of 1	Water Fountain	right	<1
62	417238	Main Building	Sink	Rm239	1 of 1	Tap	center	<1