

# Lead in School Drinking Water Report

## Jane Addams Middle School



### EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: [leadfreetkids@doh.wa.gov](mailto:leadfreetkids@doh.wa.gov).

## DEFINITIONS

Fixture Housing Location	Room/space where fixture is located (i.e. room number, gym, playground)
Fixture Housing Type	Structure that contains the individual fixtures where water samples were collected from. Fixture housing may contain one or more individual fixture for sampling.
Fixture Location Details	Location within a room or space where fixture housing is located, starting to the left of the entrance and rotating clockwise, of the total number of fixture housings in a room or space (e.g. 1/5, 2/5)
Fixture Type	Tap, Sprayer, Water Fountain, Water Bottle Filler, Icemaker
Fixture Position	Left, Center, Right

Date(s) collected: 2025-10-30

Date(s) analyzed: 2025-11-07

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	412732	Main bldg	Sink	Rm221	1 of 1	Tap	center	6
2	412709	Main bldg	Sink	Rm104	1 of 1	Tap	center	5
3	412704	Main bldg	Pot Filler	Kitchen	2 of 2	Tap	center	2
4	412721	Main bldg	Sink	Rm114	1 of 1	Tap	center	2
5	412739	Main bldg	Sink	Rm203	1 of 1	Tap	center	2
6	412740	Main bldg	Sink	Rm207	1 of 1	Tap	center	2
7	412711	Main bldg	Sink	Rm105	1 of 1	Tap	center	1
8	412703	Main bldg	Sink - Multi-Compartment	Kitchen	1 of 2	Tap	center	<1
9	412705	Main bldg	Pot Filler	Kitchen	2 of 2	Sprayer	center	<1
10	412706	Main bldg	Fountain with Bottle Filler	Cafeteria	1 of 1	Water Fountain	center	<1
11	412707	Main bldg	Fountain with Bottle Filler	Cafeteria	1 of 1	Water Bottle Filler	center	<1
12	412708	Main bldg	Sink	Rm102	1 of 1	Tap	center	<1
13	412710	Main bldg	Fountain	Left Of Rm105	1 of 1	Water Fountain	center	<1
14	412712	Main bldg	Sink	Rm106	1 of 1	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
15	412713	Main bldg	Fountain with Bottle Filler	Left Of Cafeteria	1 of 1	Water Fountain	center	<1
16	412714	Main bldg	Fountain with Bottle Filler	Left Of Cafeteria	1 of 1	Water Bottle Filler	center	<1
17	412715	Main bldg	Sink	Rm107	1 of 1	Tap	center	<1
18	412716	Main bldg	Sink	Rm111	1 of 1	Tap	center	<1
19	412717	Main bldg	Fountain	Right Of Rm112	1 of 1	Water Fountain	center	<1
20	412718	Main bldg	Sink	Rm113	1 of 1	Tap	center	<1
21	412719	Main bldg	Sink	Rm121	1 of 1	Tap	left	<1
22	412720	Main bldg	Sink	Rm121	1 of 1	Tap	right	<1
23	412722	Main bldg	Fountain	Left Of Rm120	1 of 1	Water Fountain	center	<1
24	412723	Main bldg	Sink	Rm115	1 of 1	Tap	center	<1
25	412724	Main bldg	Sink	Rm142	1 of 1	Tap	center	<1
26	412725	Main bldg	Sink	Rm130	1 of 1	Tap	center	<1
27	412726	Main bldg	Sink	Rm141	1 of 1	Tap	center	<1
28	412727	Main bldg	Sink	Rm138	1 of 1	Tap	center	<1
29	412728	Main bldg	Fountain	North Gym	1 of 1	Tap	center	<1
30	412729	Main bldg	Fountain with Bottle Filler	Left Of Rm214	1 of 1	Water Fountain	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
31	412730	Main bldg	Fountain with Bottle Filler	Left Of Rm214	1 of 1	Water Bottle Filler	center	<1
32	412731	Main bldg	Sink	Rm213	1 of 1	Tap	center	<1
33	412733	Main bldg	Sink	Rm211	1 of 1	Tap	center	<1
34	412734	Main bldg	Sink	Rm210	1 of 1	Tap	center	<1
35	412735	Main bldg	Fountain with Bottle Filler	Left Of Rm202	1 of 1	Water Fountain	center	<1
36	412736	Main bldg	Fountain with Bottle Filler	Left Of Rm202	1 of 1	Water Bottle Filler	center	<1
37	412737	Main bldg	Sink	Rm209	1 of 1	Tap	center	<1
38	412738	Main bldg	Sink	Rm208	1 of 1	Tap	center	<1
39	412741	Main bldg	Sink	Rm205	1 of 1	Tap	center	<1