

Lead in School Drinking Water Report

Ingraham Int'l High School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2026-02-14

Date(s) analyzed: 2026-02-26, 2026-02-27

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	397224	2026-02-14	100 Building Main/Aud	Sink	Cafeteria Concessions	1 of 1	Tap	center	1110
2	397733	2026-02-14	100 Building Main/Aud	Sink	Exam Room 1	1 of 1	Tap	center	26
3	397734	2026-02-14	100 Building Main/Aud	Sink	Exam Room 2 (Through Exam Room 1)	1 of 1	Tap	center	5
4	397220	2026-02-14	100 Building Main/Aud	Sink	Kitchen	2 of 4 across from pot filler	Sprayer	center	3
5	397717	2026-02-14	100 Building Main/Aud	Sink - Multi-compartment	Kitchen	1 of 4 right of fridges	Sprayer	left	3
6	397718	2026-02-14	100 Building Main/Aud	Sink - Multi-compartment	Kitchen	1 of 4 right of fridges	Tap	right	3
7	397727	2026-02-14	100 Building Main/Aud	Fountain	Right Of Rm122	1 of 1	Water Fountain	center	3
8	397730	2026-02-14	100 Building Main/Aud	Sink	Learning Center	1 of 1	Tap	center	3

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
9	397221	2026-02-14	100 Building Main/Aud	Sink - Multi-compartment	Kitchen	3 of 4 right of single basin	Tap	left	2
10	397222	2026-02-14	100 Building Main/Aud	Sink - Multi-compartment	Kitchen	3 of 4 right of single basin	Tap	right	2
11	397223	2026-02-14	100 Building Main/Aud	Pot Filler	Kitchen	4 of 4	Tap	center	2
12	397234	2026-02-14	100 Building Main/Aud	Sink	Staff Lounge	1 of 1	Tap	center	2
13	397714	2026-02-14	100 Building Main/Aud	Fountain	Gym Right Of Girls Team Room	1 of 1	Water Fountain	center	2
14	397716	2026-02-14	100 Building Main/Aud	Sink - Multi-compartment	Kitchen	1 of 4 right of fridges	Tap	left	2
15	397719	2026-02-14	100 Building Main/Aud	Sink	Kitchen	2 of 4 across from pot filler	Tap	center	2
16	397252	2026-02-14	100 Building Main/Aud	Sink	Rm171	1 of 1	Tap	center	1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
17	397751	2026-02-14	100 Building Main/Aud	Sink	Rm068	1 of 1	Tap	center	1
18	397225	2026-02-14	100 Building Main/Aud	Fountain	Across Custodial Lunch Room	1 of 3 left	Water Fountain	center	<1
19	397226	2026-02-14	100 Building Main/Aud	Fountain	Across Custodial Lunch Room	2 of 3 center	Water Fountain	center	<1
20	397227	2026-02-14	100 Building Main/Aud	Fountain	Across Custodial Lunch Room	3 of 3 right	Water Fountain	center	<1
21	397228	2026-02-14	100 Building Main/Aud	Fountain	Backstage	1 of 1	Water Fountain	center	<1
22	397229	2026-02-14	100 Building Main/Aud	Fountain	Left Of Rm100	1 of 2	Water Fountain	center	<1
23	397230	2026-02-14	100 Building Main/Aud	Sink	Main Office Across From Copy Machine	1 of 1	Tap	center	<1
24	397231	2026-02-14	100 Building Main/Aud	Fountain	Main Office Between Restrooms	1 of 1	Water Fountain	center	<1
25	397232	2026-02-14	100 Building Main/Aud	Sink	Health Office	1 of 1	Tap	center	<1
26	397233	2026-02-14	100 Building Main/Aud	Fountain	Right Of Rm105	1 of 1	Water Fountain	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
27	397235	2026-02-14	100 Building Main/Aud	Sink	Rm105	1 of 1	Tap	center	<1
28	397236	2026-02-14	100 Building Main/Aud	Fountain	Across Rm113	1 of 1	Water Fountain	center	<1
29	397237	2026-02-14	100 Building Main/Aud	Sink	Rm114	1 of 8	Tap	center	<1
30	397238	2026-02-14	100 Building Main/Aud	Sink	Rm114	2 of 8	Tap	center	<1
31	397239	2026-02-14	100 Building Main/Aud	Sink	Rm114	3 of 8	Tap	center	<1
32	397240	2026-02-14	100 Building Main/Aud	Sink	Rm45	1 of 1	Tap	center	<1
33	397241	2026-02-14	100 Building Main/Aud	Fountain - Multi-level	Across From Rm48	1 of 1	Water Fountain	left	<1
34	397242	2026-02-14	100 Building Main/Aud	Fountain - Multi-level	Across From Rm48	1 of 1	Water Fountain	right	<1
35	397243	2026-02-14	100 Building Main/Aud	Sink	Rm145	1 of 1	Tap	center	<1
36	397244	2026-02-14	100 Building Main/Aud	Sink	Rm144	1 of 1	Tap	center	<1
37	397245	2026-02-14	100 Building Main/Aud	Sink	Rm143	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
38	397246	2026-02-14	100 Building Main/Aud	Sink	Rm182	1 of 1	Tap	center	<1
39	397247	2026-02-14	100 Building Main/Aud	Sink	Rm180	1 of 1	Tap	center	<1
40	397248	2026-02-14	100 Building Main/Aud	Sink	Rm178	1 of 1	Tap	center	<1
41	397249	2026-02-14	100 Building Main/Aud	Sink	Rm176	1 of 1	Tap	center	<1
42	397250	2026-02-14	100 Building Main/Aud	Sink	Rm174	1 of 1	Tap	center	<1
43	397251	2026-02-14	100 Building Main/Aud	Sink	Rm172	1 of 1	Tap	center	<1
44	397253	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Left Of Rm170	1 of 1	Water Fountain	left	<1
45	397254	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Left Of Rm170	1 of 1	Water Fountain	right	<1
46	397255	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Left Of Rm170	1 of 1	Water Bottle Filler	right	<1
47	397256	2026-02-14	100 Building Main/Aud	Sink	Rm170	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
48	397257	2026-02-14	100 Building Main/Aud	Sink	Rm168	1 of 1	Tap	center	<1
49	397258	2026-02-14	100 Building Main/Aud	Sink	Rm166	1 of 1	Tap	center	<1
50	397259	2026-02-14	100 Building Main/Aud	Sink	Rm164	1 of 1	Tap	center	<1
51	397704	2026-02-14	100 Building Main/Aud	Fountain - Multi-level	Outside Gym Right Of Women's Bathroom	1 of 1	Water Fountain	left	<1
52	397705	2026-02-14	100 Building Main/Aud	Fountain - Multi-level	Outside Gym Right Of Women's Bathroom	1 of 1	Water Fountain	right	<1
53	397706	2026-02-14	100 Building Main/Aud	Fountain	Outside Gym Right Of Men's Bathroom	1 of 3 left	Water Fountain	center	<1
54	397707	2026-02-14	100 Building Main/Aud	Fountain	Outside Gym Right Of Men's Bathroom	2 of 3 center	Water Fountain	center	<1
55	397708	2026-02-14	100 Building Main/Aud	Fountain	Outside Gym Right Of Men's Bathroom	3 of 3 right	Water Fountain	center	<1
56	397709	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Gym Left Of Boys Team Room	1 of 1	Water Fountain	left	<1
57	397710	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Gym Left Of Boys Team Room	1 of 1	Water Fountain	right	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
58	397711	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Gym Left Of Boys Team Room	1 of 1	Water Bottle Filler	right	<1
59	397712	2026-02-14	100 Building Main/Aud	Fountain	Boys Locker Room	1 of 1	Water Fountain	center	<1
60	397713	2026-02-14	100 Building Main/Aud	Fountain	Boys Gym	1 of 1	Water Fountain	center	<1
61	397715	2026-02-14	100 Building Main/Aud	Fountain	Girls Locker Room	1 of 1	Water Fountain	center	<1
62	397720	2026-02-14	100 Building Main/Aud	Sink	Rm114	4 of 8	Tap	center	<1
63	397721	2026-02-14	100 Building Main/Aud	Sink	Rm114	5 of 8	Tap	center	<1
64	397722	2026-02-14	100 Building Main/Aud	Sink	Rm114	6 of 8	Tap	center	<1
65	397723	2026-02-14	100 Building Main/Aud	Sink	Rm114	7 of 8	Tap	center	<1
66	397724	2026-02-14	100 Building Main/Aud	Sink	Rm114	8 of 8	Tap	center	<1
67	397725	2026-02-14	100 Building Main/Aud	Sink	Rm116	1 of 1	Tap	center	<1
68	397726	2026-02-14	100 Building Main/Aud	Sink	Rm118	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
69	397728	2026-02-14	100 Building Main/Aud	Fountain	Left Of Rm124	1 of 1	Water Fountain	center	<1
70	397729	2026-02-14	100 Building Main/Aud	Sink	Library Office	1 of 1	Tap	center	<1
71	397731	2026-02-14	100 Building Main/Aud	Fountain With Bottle Filler	Across From Learning Center	1 of 1	Water Fountain	center	<1
72	397732	2026-02-14	100 Building Main/Aud	Fountain With Bottle Filler	Across From Learning Center	1 of 1	Water Bottle Filler	center	<1
73	397735	2026-02-14	200 Building Business & Science	Fountain	Across From Rm202a	1 of 1	Water Fountain	center	<1
74	397736	2026-02-14	200 Building Business & Science	Fountain	Across From Rm205	1 of 1	Water Fountain	center	<1
75	397737	2026-02-14	200 Building Business & Science	Fountain - Multi-level	Across From Rm209	1 of 1	Water Fountain	left	<1
76	397738	2026-02-14	200 Building Business & Science	Fountain - Multi-level	Across From Rm209	1 of 1	Water Fountain	right	<1
77	397739	2026-02-14	100 Building Main/Aud	Sink	Rm43	1 of 1	Tap	center	<1
78	397740	2026-02-14	100 Building Main/Aud	Sink	Behind Rm087	1 of 2 left	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
79	397741	2026-02-14	100 Building Main/Aud	Sink	Behind Rm087	2 of 2 right	Tap	center	<1
80	397742	2026-02-14	100 Building Main/Aud	Sink	Rm078	1 of 1	Tap	center	<1
81	397743	2026-02-14	100 Building Main/Aud	Sink	Rm076	1 of 1	Tap	center	<1
82	397744	2026-02-14	100 Building Main/Aud	Sink	Rm074	1 of 1	Tap	center	<1
83	397745	2026-02-14	100 Building Main/Aud	Sink	Rm072	1 of 1	Tap	center	<1
84	397746	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Left Of Rm070	1 of 1	Water Fountain	left	<1
85	397747	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Left Of Rm070	1 of 1	Water Fountain	right	<1
86	397748	2026-02-14	100 Building Main/Aud	Fountain - Multi-level with Bottle Filler	Left Of Rm070	1 of 1	Water Bottle Filler	right	<1
87	397749	2026-02-14	100 Building Main/Aud	Sink	Rm071	1 of 1	Tap	center	<1
88	397750	2026-02-14	100 Building Main/Aud	Sink	Rm070	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
89	397752	2026-02-14	100 Building Main/Aud	Sink	Rm066	1 of 1	Tap	center	<1
90	397753	2026-02-14	100 Building Main/Aud	Sink	Rm064	1 of 1	Tap	center	<1
91	397754	2026-02-14	300 Building Shop	Sink	Rm305	1 of 1	Tap	center	<1
