

Lead in School Drinking Water Report

Ballard High School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2026-02-04

Date(s) analyzed: 2026-02-19

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	397068	2026-02-04	Main Building	Fountain - Multi-level	Outside Auxillary Gym	1 of 1	Water Fountain	left	17
2	397067	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Right Gym	1 of 1	Water Bottle Filler	right	6
3	397550	2026-02-04	Main Building	Sink - Multi-compartment	N222	1 of 7	Tap	center	4
4	397546	2026-02-04	Main Building	Sink - Multi-compartment	Sw209	1 of 2 right of oven	Tap	center	3
5	397056	2026-02-04	Main Building	Pot Filler	Kitchen	2 of 4	Sprayer	left	2
6	397057	2026-02-04	Main Building	Pot Filler	Kitchen	3 of 4	Tap	right	2
7	397048	2026-02-04	Main Building	Fountain - Multi-level	Sw Wing	1 of 1	Water Fountain	left	<1
8	397049	2026-02-04	Main Building	Fountain - Multi-level	Sw Wing	1 of 1	Water Fountain	right	<1
9	397050	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	South Wing	1 of 1	Water Fountain	left	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
10	397051	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	South Wing	1 of 1	Water Bottle Filler	left	<1
11	397052	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	South Wing	1 of 1	Water Fountain	right	<1
12	397053	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	South Wing	1 of 1	Water Bottle Filler	right	<1
13	397054	2026-02-04	Main Building	Sink - Multi-compartment	Kitchen	1 of 4 across fridges	Tap	center	<1
14	397055	2026-02-04	Main Building	Sink - Multi-compartment	Kitchen	1 of 4 across fridges	Sprayer	center	<1
15	397058	2026-02-04	Main Building	Sink - Multi-compartment	Kitchen	4 of 4 across pots	Tap	center	<1
16	397059	2026-02-04	Main Building	Sink - Multi-compartment	Kitchen	4 of 4 across pots	Sprayer	center	<1
17	397060	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Upstairs South Wing	1 of 1	Water Bottle Filler	right	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
18	397061	2026-02-04	Main Building	Sink	N205	1 of 1	Tap	center	<1
19	397062	2026-02-04	Main Building	Fountain - Multi-level	Gym Left	1 of 1	Water Fountain	left	<1
20	397063	2026-02-04	Main Building	Fountain - Multi-level	Gym Left	1 of 1	Water Fountain	right	<1
21	397064	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Right Gym	1 of 1	Water Fountain	left	<1
22	397065	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Right Gym	1 of 1	Water Bottle Filler	left	<1
23	397066	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Right Gym	1 of 1	Water Fountain	right	<1
24	397069	2026-02-04	Main Building	Fountain - Multi-level	Outside Auxillary Gym	1 of 1	Water Fountain	right	<1
25	397070	2026-02-04	Main Building	Fountain - Multi-level	Se Wing	1 of 1	Water Fountain	left	<1
26	397071	2026-02-04	Main Building	Fountain - Multi-level	Se Wing	1 of 1	Water Fountain	right	<1
27	397072	2026-02-04	Main Building	Sink	Se201	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
28	397540	2026-02-04	Main Building	Fountain With Bottle Filler	Cafeteria	1 of 1 fountain off	Water Bottle Filler	center	<1
29	397541	2026-02-04	Main Building	Sink	Se126	1 of 1	Tap	center	<1
30	397542	2026-02-04	Main Building	Fountain - Multi-level	Right Of Men's Pe Locker Room	1 of 1	Water Fountain	left	<1
31	397543	2026-02-04	Main Building	Fountain - Multi-level	Right Of Men's Pe Locker Room	1 of 1	Water Fountain	right	<1
32	397544	2026-02-04	Main Building	Fountain - Multi-level	Right Of Men's Varsity Locker Room	1 of 1	Water Fountain	left	<1
33	397545	2026-02-04	Main Building	Fountain - Multi-level	Right Of Men's Varsity Locker Room	1 of 1	Water Fountain	right	<1
34	397547	2026-02-04	Main Building	Sink - Multi-compartment	Sw209	2 of 2 left of fridge	Tap	center	<1
35	397548	2026-02-04	Main Building	Fountain With Bottle Filler	Upstairs Sw Wing	1 of 1	Water Fountain	center	<1
36	397549	2026-02-04	Main Building	Fountain With Bottle Filler	Upstairs Sw Wing	1 of 1	Water Bottle Filler	center	<1
37	397551	2026-02-04	Main Building	Sink - Multi-compartment	N222	2 of 7	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
38	397552	2026-02-04	Main Building	Sink - Multi-compartment	N222	3 of 7	Tap	center	<1
39	397553	2026-02-04	Main Building	Sink - Multi-compartment	N222	4 of 7	Tap	center	<1
40	397554	2026-02-04	Main Building	Sink - Multi-compartment	N222	5 of 7	Tap	center	<1
41	397555	2026-02-04	Main Building	Sink - Multi-compartment	N222	6 of 7	Tap	center	<1
42	397556	2026-02-04	Main Building	Sink - Multi-compartment	N222	7 of 7	Tap	center	<1
43	397557	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Upstairs South Wing	1 of 1	Water Fountain	left	<1
44	397558	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Upstairs South Wing	1 of 1	Water Bottle Filler	left	<1
45	397559	2026-02-04	Main Building	Fountain - Multi-level with Bottle Filler	Upstairs South Wing	1 of 1	Water Fountain	right	<1
