

Lead in School Drinking Water Report

Hamilton International Middle School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2026-02-06

Date(s) analyzed: 2026-02-21

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	397110	2026-02-06	Main Building	Pot Filler	Kitchen	2 of 3	Tap	center	132
2	397606	2026-02-06	Main Building	Sink	Rm104	1 of 1	Tap	center	17
3	397117	2026-02-06	Main Building	Sink	Rm113a	1 of 1	Tap	center	12
4	397131	2026-02-06	Main Building	Sink	Rm330	1 of 1	Tap	center	7
5	397603	2026-02-06	Main Building	Sink	Rm106i	1 of 1	Tap	center	7
6	397132	2026-02-06	Main Building	Fountain Tap Combo	Rm331	1 of 1 fountain off	Tap	center	4
7	397126	2026-02-06	Main Building	Fountain Tap Combo	Rm206	1 of 1 fountain off	Tap	center	3
8	397616	2026-02-06	Main Building	Sink - Multi-compartment	Rm221	1 of 1	Tap	center	3
9	397109	2026-02-06	Main Building	Sink - Multi-compartment	Kitchen	1 of 3 back wall	Tap	center	2
10	397114	2026-02-06	Main Building	Fountain	Cafeteria	1 of 2 bleacher side	Water Fountain	center	2
11	397133	2026-02-06	Main Building	Sink	Across Rm336	1 of 2	Tap	center	2

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
12	397613	2026-02-06	Gymnasium	Sink - Multi-compartment	Concessions	1 of 1	Tap	center	2
13	397615	2026-02-06	Main Building	Sink - Multi-compartment	Rm219	1 of 1	Tap	center	2
14	397130	2026-02-06	Main Building	Sink	Right Of Rm322	2 of 2	Tap	center	1
15	397139	2026-02-06	Main Building	Sink	Rm309	1 of 1	Tap	center	1
16	397601	2026-02-06	Main Building	Sink	Rm106f	1 of 2 right of rm106H	Tap	center	1
17	397619	2026-02-06	Main Building	Sink	2nd Floor Locker Area	1 of 2	Tap	center	1
18	397620	2026-02-06	Main Building	Fountain Tap Combo	Rm306	1 of 1 fountain off	Tap	center	1
19	397111	2026-02-06	Main Building	Sink	Kitchen	3 of 3 island counter	Tap	center	<1
20	397112	2026-02-06	Main Building	Fountain - Multi-level	Outside Kitchen	1 of 1	Water Fountain	left	<1
21	397113	2026-02-06	Main Building	Fountain - Multi-level	Outside Kitchen	1 of 1	Water Fountain	right	<1
22	397115	2026-02-06	Main Building	Sink - Multi-compartment	Staff Lounge	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
23	397116	2026-02-06	Main Building	Fountain	Cafeteria	2 of 2 stage side	Water Fountain	center	<1
24	397118	2026-02-06	Main Building	Fountain Tap Combo	Rm111	1 of 1	Tap	center	<1
25	397119	2026-02-06	Main Building	Fountain Tap Combo	Rm111	1 of 1	Water Fountain	right	<1
26	397120	2026-02-06	Main Building	Fountain - Multi-level	2nd Floor Locker Area	2 of 2	Water Fountain	left	<1
27	397121	2026-02-06	Main Building	Fountain - Multi-level	2nd Floor Locker Area	2 of 2	Water Fountain	right	<1
28	397122	2026-02-06	Main Building	Sink - Multi-compartment	Rm214	1 of 1	Tap	center	<1
29	397123	2026-02-06	Main Building	Sink - Multi-compartment	Rm215	1 of 1	Tap	center	<1
30	397124	2026-02-06	Main Building	Sink - Multi-compartment	Rm212b	1 of 1	Tap	center	<1
31	397125	2026-02-06	Main Building	Sink	Rm209	1 of 1	Tap	center	<1
32	397127	2026-02-06	Main Building	Sink	Across Rm203	1 of 1	Tap	center	<1
33	397128	2026-02-06	Main Building	Fountain - Multi-level	Right Of Rm322	1 of 2	Water Fountain	left	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
34	397129	2026-02-06	Main Building	Fountain - Multi-level	Right Of Rm322	1 of 2	Water Fountain	right	<1
35	397134	2026-02-06	Main Building	Fountain - Multi-level	Across Rm336	2 of 2	Water Fountain	left	<1
36	397135	2026-02-06	Main Building	Fountain - Multi-level	Across Rm336	2 of 2	Water Fountain	right	<1
37	397136	2026-02-06	Main Building	Sink	Left Of Rm314	1 of 2	Tap	center	<1
38	397137	2026-02-06	Main Building	Fountain - Multi-level	Left Of Rm314	2 of 2	Water Fountain	left	<1
39	397138	2026-02-06	Main Building	Fountain - Multi-level	Left Of Rm314	2 of 2	Water Fountain	right	<1
40	397600	2026-02-06	Main Building	Fountain Tap Combo	Rm112	1 of 1 fountain off	Tap	center	<1
41	397602	2026-02-06	Main Building	Sink	Rm106f	2 of 2 right of rm106l	Tap	center	<1
42	397604	2026-02-06	Main Building	Fountain Tap Combo	Rm107b	1 of 1	Tap	center	<1
43	397605	2026-02-06	Main Building	Fountain Tap Combo	Rm107b	1 of 1	Water Fountain	right	<1
44	397607	2026-02-06	Main Building	Sink	Rm101a	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
45	397608	2026-02-06	Main Building	Fountain - Multi-level	Right Of Rm102	1 of 1	Water Fountain	left	<1
46	397609	2026-02-06	Main Building	Fountain - Multi-level	Right Of Rm102	1 of 1	Water Fountain	right	<1
47	397610	2026-02-06	Main Building	Sink	Rm103b	1 of 1	Tap	center	<1
48	397611	2026-02-06	Gymnasium	Fountain - Multi-level	Gym	1 of 1	Water Fountain	left	<1
49	397612	2026-02-06	Gymnasium	Fountain - Multi-level	Gym	1 of 1	Water Fountain	right	<1
50	397614	2026-02-06	Main Building	Sink - Multi-compartment	Rm218	1 of 1	Tap	center	<1
51	397617	2026-02-06	Main Building	Sink	Rm226	1 of 1	Tap	center	<1
52	397618	2026-02-06	Main Building	Fountain Tap Combo	Rm227	1 of 1 fountain off	Tap	center	<1
53	397621	2026-02-06	Main Building	Sink	Across Rm333	1 of 1	Tap	center	<1