

Lead in School Drinking Water Report

Broadview-Thomson K-8 School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2026-02-07

Date(s) analyzed: 2026-02-23

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	397152	2026-02-07	Main Building	Sink - Multi-compartment	Rm203	3 of 7	Tap	center	94
2	397629	2026-02-07	Main Building	Sink	Concession Window Storage	1 of 1	Tap	center	70
3	397150	2026-02-07	Main Building	Sink - Multi-compartment	Rm203	1 of 7	Tap	center	54
4	397151	2026-02-07	Main Building	Sink - Multi-compartment	Rm203	2 of 7	Tap	center	38
5	397156	2026-02-07	Main Building	Sink - Multi-compartment	Rm203	7 of 7	Tap	center	29
6	397645	2026-02-07	Main Building	Sink	Rm206	1 of 1	Tap	center	16
7	397155	2026-02-07	Main Building	Sink - Multi-compartment	Rm203	6 of 7	Tap	center	14
8	397143	2026-02-07	Main Building	Pot Filler	Kitchen	4 of 4	Tap	center	13
9	397159	2026-02-07	Main Building	Sink	Rm218	1 of 2	Tap	left	13
10	397153	2026-02-07	Main Building	Sink - Multi-compartment	Rm203	4 of 7	Tap	center	12
11	397154	2026-02-07	Main Building	Sink - Multi-compartment	Rm203	5 of 7	Tap	center	12

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
12	397646	2026-02-07	Main Building	Sink	Rm205	1 of 2	Tap	left	10
13	397632	2026-02-07	Main Building	Sink	Rm113	1 of 1	Tap	center	7
14	397640	2026-02-07	Main Building	Sink	Rm218	2 of 2	Tap	right	7
15	397647	2026-02-07	Main Building	Sink	Rm205	2 of 2	Tap	right	7
16	397157	2026-02-07	Main Building	Sink	Rm202	1 of 1	Tap	center	6
17	397627	2026-02-07	Main Building	Sink	Rm108	1 of 1	Tap	center	6
18	397628	2026-02-07	Main Building	Sink	Library Book Room	1 of 1	Tap	center	6
19	397644	2026-02-07	Main Building	Sink	Rm208	1 of 1	Tap	center	6
20	397637	2026-02-07	Main Building	Sink	Rm117 Storage	1 of 1	Tap	center	4
21	397144	2026-02-07	Main Building	Sink	Rm102	1 of 1	Tap	center	3
22	397624	2026-02-07	Main Building	Fountain Tap Combo	Nurses Office	1 of 1	Tap	center	3
23	397634	2026-02-07	Main Building	Sink	Rm114 Office	1 of 2	Tap	left	3
24	397622	2026-02-07	Main Building	Sink	Staff Lounge	1 of 1	Tap	center	2
25	397623	2026-02-07	Main Building	Sink	Mail Room	1 of 1	Tap	center	2
26	397635	2026-02-07	Main Building	Sink	Rm114 Office	2 of 2	Tap	right	2
27	397636	2026-02-07	Main Building	Sink	Rm114	1 of 1	Tap	center	2
28	397146	2026-02-07	Main Building	Sink	Rm103	1 of 1	Tap	center	1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
29	397147	2026-02-07	Main Building	Sink	Rm104	1 of 1	Tap	center	1
30	397140	2026-02-07	Main Building	Sink - Multi-compartment	Kitchen	2 of 4	Tap	center	<1
31	397141	2026-02-07	Main Building	Sink - Multi-compartment	Kitchen	3 of 4	Tap	right	<1
32	397142	2026-02-07	Main Building	Sink - Multi-compartment	Kitchen	3 of 4	Sprayer	right	<1
33	397145	2026-02-07	Main Building	Fountain	Across Rm103	1 of 1	Water Fountain	center	<1
34	397148	2026-02-07	Main Building	Fountain	Left Of Front Entrance	1 of 1	Water Fountain	center	<1
35	397149	2026-02-07	Main Building	Fountain	Across Rm203	1 of 1	Water Fountain	center	<1
36	397158	2026-02-07	Main Building	Fountain	Across Rm202	1 of 1	Water Fountain	center	<1
37	397625	2026-02-07	Main Building	Fountain Tap Combo	Nurses Office	1 of 1	Water Fountain	right	<1
38	397626	2026-02-07	Main Building	Sink	Rm107	1 of 1	Tap	center	<1
39	397630	2026-02-07	Main Building	Fountain	Across Library	1 of 2	Water Fountain	center	<1
40	397631	2026-02-07	Main Building	Water Bottle Filling Station	Across Library	2 of 2	Water Bottle Filler	center	<1
41	397633	2026-02-07	Main Building	Fountain	Across Boiler Room	1pf1	Water Fountain	center	<1
42	397638	2026-02-07	Main Building	Sink - Multi-compartment	Kitchen	1 of 4	Tap	left	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
43	397639	2026-02-07	Main Building	Sink - Multi-compartment	Kitchen	1 of 4	Sprayer	left	<1
44	397641	2026-02-07	Main Building	Fountain	Across Rm218	1 of 1	Water Fountain	center	<1
45	397642	2026-02-07	Main Building	Fountain With Bottle Filler	Across Rm211	1 of 1	Water Fountain	center	<1
46	397643	2026-02-07	Main Building	Fountain With Bottle Filler	Across Rm211	1 of 1	Water Bottle Filler	center	<1
