

Lead in School Drinking Water Report

Eckstein Middle School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2026-03-25

Date(s) analyzed: 2026-04-03

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	406553	2026-03-25	Main Building	Sink - Multi-compartment	Kitchen	1 of 3 right of office	Tap	left	5
2	406625	2026-03-25	Main Building	Sink - Multi-compartment	Rm104	1 of 2 left	Tap	left	4
3	406559	2026-03-25	Main Building	Pot Filler	Kitchen	3 of 3	Sprayer	center	3
4	406636	2026-03-25	Main Building	Sink - Multi-compartment	Rm204	1 of 2 left	Tap	left	3
5	406554	2026-03-25	Main Building	Sink - Multi-compartment	Kitchen	1 of 3 right of office	Tap	right	2
6	406569	2026-03-25	Main Building	Sink	Rm125	4 of 10	Tap	center	2
7	406635	2026-03-25	Main Building	Fountain	Left Of Rm212	1 of 1	Water Fountain	center	2
8	406639	2026-03-25	Main Building	Sink - Multi-compartment	Rm205	1 of 2 left	Tap	left	2
9	406642	2026-03-25	Main Building	Sink	Rm206	1 of 1	Tap	center	2
10	406558	2026-03-25	Main Building	Sink - Multi-compartment	Kitchen	2 of 3 right of fridge	Tap	right	1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
11	406560	2026-03-25	Main Building	Sink	Faculty Lunch Room	1 of 1	Tap	center	1
12	406620	2026-03-25	Main Building	Sink	Office Work Room	1 of 1	Tap	center	1
13	406626	2026-03-25	Main Building	Sink - Multi-compartment	Rm104	1 of 2 left	Tap	right	1
14	406637	2026-03-25	Main Building	Sink - Multi-compartment	Rm204	1 of 2 left	Tap	right	1
15	406555	2026-03-25	Main Building	Sink - Multi-compartment	Kitchen	1 of 3 right of office	Sprayer	right	<1
16	406556	2026-03-25	Main Building	Sink - Multi-compartment	Kitchen	2 of 3 right of fridge	Tap	left	<1
17	406557	2026-03-25	Main Building	Sink - Multi-compartment	Kitchen	2 of 3 right of fridge	Sprayer	left	<1
18	406561	2026-03-25	Main Building	Fountain With Bottle Filler	Across Rm121	1 of 1	Water Fountain	center	<1
19	406562	2026-03-25	Main Building	Fountain With Bottle Filler	Across Rm121	1 of 1	Water Bottle Filler	center	<1
20	406563	2026-03-25	Main Building	Sink	Rm120	1 of 1	Tap	center	<1
21	406564	2026-03-25	Main Building	Sink	Rm121	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
22	406565	2026-03-25	Main Building	Fountain	Gym	1 of 1 girls locker	Water Fountain	center	<1
23	406566	2026-03-25	Main Building	Sink	Rm125	1 of 10	Tap	center	<1
24	406567	2026-03-25	Main Building	Sink	Rm125	2 of 10	Tap	center	<1
25	406568	2026-03-25	Main Building	Sink	Rm125	3 of 10	Tap	center	<1
26	406570	2026-03-25	Main Building	Sink	Rm125	5 of 10	Tap	center	<1
27	406571	2026-03-25	Main Building	Sink	Rm125	6 of 10	Tap	center	<1
28	406572	2026-03-25	Main Building	Sink	Rm125	7 of 10	Tap	center	<1
29	406573	2026-03-25	Main Building	Sink	Rm125	8 of 10	Tap	center	<1
30	406574	2026-03-25	Main Building	Sink	Rm125	9 of 10	Tap	center	<1
31	406575	2026-03-25	Main Building	Sink	Rm125	10 of 10	Tap	center	<1
32	406576	2026-03-25	Main Building	Fountain	Left Of Rm130	1 of 1	Water Fountain	center	<1
33	406577	2026-03-25	Main Building	Sink	Rm129	1 of 1	Tap	center	<1
34	406578	2026-03-25	Main Building	Fountain	Across Rm117	1 of 1	Water Fountain	center	<1
35	406579	2026-03-25	Main Building	Fountain	Left Of Staff Lounge	1 of 1	Water Fountain	center	<1
36	406621	2026-03-25	Main Building	Sink	Nurses Office	1 of 1	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
37	406622	2026-03-25	Main Building	Fountain	Right Of Nurses Office	1 of 1	Water Fountain	center	<1
38	406623	2026-03-25	Main Building	Fountain	Across From Receiving Room	1 of 1	Water Fountain	center	<1
39	406624	2026-03-25	Main Building	Fountain	Right Of Rm118	1 of 1	Water Fountain	center	<1
40	406627	2026-03-25	Main Building	Sink	Rm104	2 of 2 right	Tap	center	<1
41	406628	2026-03-25	Main Building	Fountain	Right Of Rm114	1 of 1	Water Fountain	center	<1
42	406629	2026-03-25	Main Building	Sink	Rm114	1 of 1	Tap	center	<1
43	406630	2026-03-25	Main Building	Fountain	Across Rm107	1 of 1	Water Fountain	center	<1
44	406631	2026-03-25	Main Building	Fountain	Across Rm111	1 of 1	Water Fountain	center	<1
45	406632	2026-03-25	Main Building	Fountain	Across Rm217	1 of 1	Water Fountain	center	<1
46	406633	2026-03-25	Main Building	Fountain	Across Rm201	1 of 1	Water Fountain	center	<1
47	406634	2026-03-25	Main Building	Fountain	Across Rm214	1 of 1	Water Fountain	center	<1
48	406638	2026-03-25	Main Building	Sink	Rm204	2 of 2 right	Tap	center	<1
49	406640	2026-03-25	Main Building	Sink - Multi-compartment	Rm205	1 of 2 left	Tap	right	<1
50	406641	2026-03-25	Main Building	Sink	Rm205	2 of 2 right	Tap	center	<1

	Sample ID	Sample Collected Date	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
51	406643	2026-03-25	Main Building	Fountain	Across Rm209	1 of 1	Water Fountain	center	<1
